





General information

Make	VOLKSWAGEN
Model	POLO SE
Colour	Silver
Year of manufacture	2010
Top speed	110 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power 85 BHP Max. torque 132 Nm at 3.800 rpm Engine capacity 1.390 cc Cylinders 4 Fuel type Petrol Consumption city 35.3 mpg Consumption extra urban 60.1 mpg Consumption combined 47.9 mpg C02 emission 139 g/km	
Max. torque 132 Nm at 3.800 rpm Engine capacity 1.390 cc Cylinders 4 Fuel type Petrol Consumption city 35.3 mpg Consumption extra urban 60.1 mpg 225+	
Engine capacity 1.390 cc Cylinders 4 Fuel type Petrol Consumption city 35.3 mpg Consumption extra urban 60.1 mpg Consumption combined 47.9 mpg	
Fuel typePetrol166 - 185Consumption city35.3 mpg186 - 225Consumption extra urban60.1 mpg225+Consumption combined47.9 mpg	P
Consumption city35.3 mpg186 - 225Consumption extra urban60.1 mpg225+Consumption combined47.9 mpg	F
Consumption extra urban60.1 mpg225+Consumption combined47.9 mpg	
Consumption combined 47.9 mpg	
CO2 emission 139 g/km	
CO2 label E	





Internet history

Entry 1	
Date	


2021-02-06

10

Listing price

Pictures

View report









source: autoonline.co.uk



MOT history

MOT expiry date	2024-06-24
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	57
Total items failed	3

MOT #15		2023-06-16 15:38
MOT test	number	835921269966
Result		✓ Passed
Next expi	ry date	2024-06-24
Advice	Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Offside Play in steering rack inner joint(s)	
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))	
Advice	Front Surface corrosion on subframe and both lower wishbones.	
Advice	Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))	
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))	





MOT #14	2023-06-15 11:43
MOT test	number 832071499599
Result	× Failed
DANGER (d) (ii))	OUS Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (5.2.3
Advice	Front Surface corrosion on subframe and both lower wishbones.
MAJOR	Reversing lamp inoperative (4.6.1 (a))
Advice	Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
MAJOR (b) (ii))	Nearside Front Lower Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
Advice	Offside Play in steering rack inner joint(s)
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))

MOT #1	
	P l

MOT	toct	number
	LESL	IIUIIDEI

202	2-06	-22	16:	00

373258563536

Result	✓ Passed
Advice (c) (i))	Offside Rear Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1
Advice	Coolant leak
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice (6.1.1 (c) (Nearside Rear Vehicle structure is corroded but structural rigidity is not significantly reduced (i))
Advice	Vehicles internal headlight adjuster altered to recheck lights
Advice	Nearside Front Outer Integral body structure is deformed but structural rigidity is not significantly

reduced (6.1.1 (a) (i))



KR10HDO report date: 2024-03-28

MOT #12		2022-06-22 13:54
MOT test	number	720981002546
Result		🗙 Failed
Advice	Coolant leak	
Advice reduced (6	Nearside Front Outer Integral body structure is deformed but structural 5.1.1 (a) (i))	rigidity is not significantly
Advice (c) (i))	Offside Rear Vehicle structure is corroded but structural rigidity is not si	ignificantly reduced (6.1.1
Advice	Vehicles internal headlight adjuster altered to recheck lights	
MAJOR (b) (ii))	Offside Front Upper Anti-roll bar ball joint dust cover no longer prevents	the ingress of dirt (5.3.4
Advice (6.1.1 (c) (Nearside Rear Vehicle structure is corroded but structural rigidity is not i))	significantly reduced
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)))
MOT #11		2021-06-25 17:40
MOT test	number	325397288366
Result		🗸 Passed

MOT #10	2020-09-11 15:04
MOT test number	474434437727
Result	✓ Passed

MOT #9	2019-05-01 14:34	4
MOT test	number 34121225072	L
Result	✓ Passed	k
Advice	Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))	
Advice	Nearside Play in steering rack inner joint(s)	
Advice	Rear exhaust silencer corroded/deteriorated	
Advice (i))	Nearside Front Power steering pipe/hose slightly corroded attached to inner chassis rail (2.1.5 (g)	
Advice	Nearside Front Nail in tyre	



KR10HDO report date: 2024-03-28

MOT #8		2019-04-30 09:05
MOT test	number	210708230661
Result		🗙 Failed
MAJOR	Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))	
Advice	Nearside Play in steering rack inner joint(s)	
MAJOR	Exhaust has a major leak of exhaust gases downpipe flexible section (6.1.2 (a))	
Advice	Offside Front Shock absorbers light misting of oil or has limited damping effect	(5.3.2 (b))
MAJOR	Reversing lamp inoperative (4.6.1 (a))	
Advice	Nearside Front Nail in tyre	
Advice (i))	Nearside Front Power steering pipe/hose slightly corroded attached to inner cha	assis rail (2.1.5 (g)
Advice	Rear exhaust silencer corroded/deteriorated	
MAJOR	Bonnet cannot be secured in the closed position (3.1 (b) (i))	

MOT #7	2018-05-18 12:25
MOT test number	106087009324
Result	Passed
AdviceUnder trays and engine covers fitted obscuring some testable items.AdviceExhaust flex joint at front deteriorated	



MOT #6	2018-05-12 08:13
MOT test number	492450872676
Result	🗙 Failed
Advice Exhaust rear silencer outer skin corroded	
Fail Nearside Headlamp insecure Brackets broken (1.7.3)	
Advice Exhaust front flexi pipe deteriorated	
Advice Plastic undertrays fitted	
Fail Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)	
Advice Both rear tyres wearing low on tread	
Fail Offside Headlamp insecure Brackets broken (1.7.3)	

MOT #5	2017-05-09 11:48
MOT test number	960326570664
Result	✓ Passed
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #4	2016-04-19 09:25
MOT test number	607790435593
Result	✓ Passed
Advice Nearside rear tyre perished	

MOT #3	2015-05-22 09:37
MOT test number	886192545172
Result	✓ Passed
Advice Offside Front Tie bar/rod has slight play in a pin/bush (2.4.G.2)	

KR10HDO

report date: 2024-03-28





MOT #2		2014-05-16 09:11
MOT test	number	355396534168
Result		✓ Passed
Notice	Under-trays fitted obscuring some underside components	
MOT #1		2013-06-07 10:10
MOT test	number	698168653136
Result		Passed
Advice Advice	Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2) Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)	



Tax & MOT check

√ Taxed	√ MOT
Tax due: 1 May 2025	Expires: 24 June 2024
Tax status	Valid until 1 May
Days left	368
MOT expiry date	24 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-





Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FETTOR
Category	Lamp
Туре	
Damage 2	AMPLE
Date	
Date	OLE .
Category	AM
Туре	

Extra VOLKSWAGEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.700
Auction value	4 10.000
Average private trade value	4 10 700

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	
Plate since	
Format maintration	
Carrient registration	
Parla since	





Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow



KR10HDO report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-06-09
Last registration	2023-06-16
Complete history	<u>See info</u>



Registration #1	2010-06-09	8 mi
Registration #2	2013-06-07	16.937 mi
Registration #3	2014-05-16	24.059 mi
Registration #4	2015-05-22	32.590 mi
Registration #5	2016-04-19	38.113 mi
Registration #6	2017-05-09	56.955 mi
Registration #7	2018-05-12	76.099 mi
Registration #8	2018-05-18	76.234 mi
Registration #9	2019-04-30	92.940 mi
Registration #10		11.777 est
Registration #11		11.707 esi
Registration #12		11.777 esi
Registration #13		11.707 est
Registration #14		11.777 est
Registration #15		11.707 esi
Registration #16		11.777 est
Registration #17		11.777 esi

More info \rightarrow





Car features

S0225	Air conditioning
S0295	
50482	
S0501	
\$0566	
\$0567	
S0569	

Safety ratings

NCAP rating	****
Adult	90%
Children	86%
Pedestrian	41%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight	
Width	1682 mm
Height	1485 mm
Length	3970 mm
Wheel base	2470 mm
Kerb weight	1070 kg
Max. allowed weight	1550 kg
Additional information	
Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	CGG 231658