



report date: 2024-03-28

General information

Make	VAUXHALL
Model	VECTRA LIFE 16V
Colour	Silver
Year of manufacture	-
Top speed	126 mph
0 - 60 mph	10.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	121 BHP
Max. torque	166 Nm at 3.800 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	27.2 mpg
Consumption extra urban	51.4 mpg
Consumption combined	38.7 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-24
Pictures	9
Listing price	View report



source: cargurus.co.uk

**MOT history**

MOT #23	2021-07-22 14:39
MOT test number	856269943453
Result	✓ Passed
Next expiry date	2022-07-21
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Rear Tyre slightly damaged/cracking or perishing BOTH (5.2.3 (d) (ii))
Advice	Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement SPRING ARM (5.3.4 (a) (i))
Advice	CENTRE AND REAR EXHAUST SHIELD INSECURE
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))
Advice	Rear Coil spring corroded BOTH (5.3.1 (b) (i))
Advice	Power steering component has slight seepage from a component STEERING RACK ALSO HAS SLIGHT PLAY (2.1.5 (a))

**MOT #22**

2021-07-14 11:37

MOT test number

962738815382

Result

✗ Failed

- Advice** Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Rear Tyre slightly damaged/cracking or perishing BOTH (5.2.3 (d) (ii))
- Fail** Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement SPRING ARM (5.3.4 (a) (i))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Power steering component has slight seepage from a component STEERING RACK ALSO HAS SLIGHT PLAY (2.1.5 (a))
- Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
- Advice** Rear Coil spring corroded BOTH (5.3.1 (b) (i))
- Advice** CENTRE AND REAR EXHAUST SHIELD INSECURE
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

MOT #21

2020-07-15 10:18

MOT test number

957467993416

Result

✓ Passed

- Advice** Rear Coil spring corroded both (5.3.1 (b) (i))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

**MOT #20** 2020-07-10 12:42**MOT test number** 502588903606**Result** ✗ Failed**Fail** Rear Axle swivel pins and bushes swivel pin and/or bush excessively worn both (5.1.2 (b) (i))**Fail** Offside Rear Brake hose ferrule excessively corroded (1.1.12 (f) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Advice** Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))**Advice** Rear Coil spring corroded both (5.3.1 (b) (i))**MOT #19** 2019-07-12 15:59**MOT test number** 238557188991**Result** ✓ Passed**MOT #18** 2018-07-12 13:33**MOT test number** 113404585485**Result** ✓ Passed**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #17** 2018-07-11 11:13**MOT test number** 679779816767**Result** ✗ Failed**Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #16** 2017-07-13 10:49**MOT test number** 842695522247**Result** ✓ Passed**MOT #15** 2017-07-12 15:34**MOT test number** 893272795859**Result** ✗ Failed**Fail** Offside Headlamp aim too high (1.8)**Fail** Nearside Headlamp aim too high (1.8)**Fail** Offside Front Lower Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**MOT #14** 2016-06-10 10:47**MOT test number** 795877792803**Result** ✓ Passed**MOT #13** 2016-06-03 08:23**MOT test number** 351370035829**Result** ✗ Failed**Fail** Rear Brake pipe excessively corroded above rear axle (3.6.B.2c)**Fail** Offside Brake pipe excessively corroded front to rear (3.6.B.2c)

**MOT #12** 2015-06-03 11:01**MOT test number** 816564555162**Result** ✓ Passed**Advice** Brake pipe slightly corroded (3.6.B.2c)**Advice** Nearside Front Direction indicators slightly discoloured (1.4.A.2f)**MOT #11** 2014-05-14 16:48**MOT test number** 236374634466**Result** ✓ Passed**Advice** Offside Rear Suspension arm has slight play in a pin/bush (2.4.G.2)**Notice** All exhaust mounting brackets corroded but exhaust system still supported**Notice** Slight corrosion to both main front to rear brake pipes**Advice** Nearside Rear Suspension arm has slight play in a pin/bush (2.4.G.2)**Notice** O/s/r tyre worn close to ply/cord on inner edge**MOT #10** 2013-06-05 13:19**MOT test number** 429996453157**Result** ✓ Passed**Notice** Items removed from driver's view prior to test**Advice** Rear Brake hose has slight corrosion to ferrules (3.6.B.4e)**Notice** Slight corrosion to front to rear brake pipes**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #9**

2013-06-05 09:25

MOT test number

867376953107

Result**✗ Failed**

Fail Nearside Front Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Notice Items removed from driver's view prior to test

Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Front Brake pad(s) wearing thin (3.5.1g)

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Notice Slight corrosion to front to rear brake pipes

Advice Rear Brake hose has slight corrosion to ferrules (3.6.B.4e)

MOT #8

2012-06-12 08:46

MOT test number

277744162114

Result**✓ Passed****MOT #7**

2012-06-07 16:04

MOT test number

837649652130

Result**✗ Failed**

Fail Front Exhaust system not adequately supported (7.1.1)

Fail Offside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)

Fail Nearside Steering rack gaiter insecure (2.2.D.2d)

MOT #6

2011-09-19 12:02

MOT test number

246122461266

Result**✓ Passed**

**MOT #5** 2010-09-09 12:31**MOT test number** 653392250274**Result** ✓ Passed**MOT #4** 2010-02-18 14:39**MOT test number** 721989240066**Result** ✓ Passed**Advice** Centre Exhaust has part of the system slightly deteriorated (7.1.1a)**Advice** Nearside Inner Ball joint has slight play (2.2.B.1f)**MOT #3** 2009-02-20 09:43**MOT test number** 293401159004**Result** ✓ Passed**MOT #2** 2008-01-30 09:57**MOT test number** 510600938013**Result** ✓ Passed**MOT #1** 2008-01-30 09:57**MOT test number** 864000338077**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too high (1.8)**Pass with rectification** Offside Headlamp aim too high (1.8)



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 DS54LXN
Plate since	2024-03-28
Current registration	 DS54LXN
Plate since	2024-03-28

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2005-02-28
Last registration	2021-07-22
Complete history	See info



Registration #1	2005-02-28	20 mi
Registration #2	2008-01-30	35.377 mi
Registration #3	2009-02-20	44.468 mi
Registration #4	2010-02-18	50.366 mi
Registration #5	2010-09-09	55.091 mi
Registration #6	2011-09-19	60.673 mi
Registration #7	2012-06-07	65.301 mi
Registration #8	2012-06-12	65.353 mi
Registration #9	2013-06-05	72.592 mi
Registration #10	2013-06-05	72.593 mi
Registration #11	2014-05-14	80.309 mi
Registration #12	2015-06-03	88.178 mi
Registration #13	2015-06-03	88.178 mi
Registration #14	2015-06-03	88.178 mi
Registration #15	2015-06-03	88.178 mi
Registration #16	2015-06-03	88.178 mi
Registration #17	2015-06-03	88.178 mi
Registration #18	2015-06-03	88.178 mi
Registration #19	2015-06-03	88.178 mi
Registration #20	2015-06-03	88.178 mi
Registration #21	2015-06-03	88.178 mi
Registration #22	2015-06-03	88.178 mi
Registration #23	2015-06-03	88.178 mi
Registration #24	2015-06-03	88.178 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2036 mm
Height	1460 mm
Length	4596 mm
Wheel base	2700 mm
Kerb weight	1379 kg
Max. allowed weight	1885 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	20EH1573