





General information

| Make | VOLVO |
|---------------------|-------------------|
| Model | V70 SE (170BHP) |
| Colour | Blue |
| Year of manufacture | 2003 |
| Top speed | 134 mph |
| 0 - 60 mph | 9.9 seconds |
| Gearbox | 5 speed automatic |

Engine & fuel consumption

| Power | 170 BHP |
|-------------------------|---------------------|
| Max. torque | 225 Nm at 4.500 rpm |
| Engine capacity | 2.435 cc |
| Cylinders | 5 |
| Fuel type | Petrol |
| Consumption city | 20.8 mpg |
| Consumption extra urban | 38.2 mpg |
| Consumption combined | 29.1 mpg |
| CO2 emission | 234 g/km |
| CO2 label | L |







MOT history

| MOT expiry date | 2025-03-01 |
|--------------------|------------|
| MOT pass rate | 64 % |
| MOT passed | 18 |
| Failed MOT tests | 10 |
| Total advice items | 54 |
| Total items failed | 20 |

| MOT #28 | 2024-03-01 09:02 |
|---|------------------|
| MOT test number | 578364555530 |
| Result | 🗸 Passed |
| Next expiry date | 2025-03-01 |
| Advice Play in steering rack inner joint(s) | |

| МОТ #27 | 2024-02-29 10:46 |
|--|------------------|
| MOT test number | 618065647768 |
| Result | 🗙 Failed |
| Fail Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i)) | |
| Fail Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i)) | |
| Advice Play in steering rack inner joint(s) | |

| MOT #26 | | 2023-02-28 15:19 |
|----------|---|------------------|
| MOT test | number | 826849040030 |
| Result | | ✓ Passed |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice | Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii | i)) |
| Advice | Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |





| MOT #25 | 2023-02-28 15:19 |
|--|------------------|
| MOT test number | 125910910538 |
| Result | 🗙 Failed |
| Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) | 1 |
| Pass with rectification Offside Stop lamp(s) not working (4.3.1 (a) (ii)) | |
| Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

| MOT #24 | 2022-03-02 11:45 |
|---|----------------------------|
| MOT test number | 195432370321 |
| Result | ✓ Passed |
| Advice Offside Rear Suspension arm damaged but not seriously weakened tra (b) (i)) | ck control arm bent (5.3.3 |

| MOT #23 | 2022-03-01 09:56 |
|---|-----------------------|
| MOT test number | 852674657639 |
| Result | 🗙 Failed |
| Fail Offside Stop lamp(s) not working (4.3.1 (a) (ii)) | |
| Fail Nearside Front Lower Suspension component ball joint excessively worn (5.3.4 (a)) | a) (i)) |
| Fail Offside Front Direction indicator incorrect colour (4.4.3 (a)) | |
| (b) (i)) Nearside Registration plate lamp inoperative in the case of multiple lamps or lamps or lamps and lamps are lamps and lamps are | light sources (4.7.1 |
| Fail Offside Front Service brake excessively binding (1.2.1 (f)) | |
| Advice Offside Rear Suspension arm damaged but not seriously weakened track con (b) (i)) | itrol arm bent (5.3.3 |





| MOT #22 | 2020-11-10 14:00 |
|--|------------------|
| MOT test number | 726458759999 |
| Result | ✓ Passed |
| Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b)) | |
| MOT #21 | 2020-11-10 09:30 |
| MOT test number | 289850568841 |
| Result | 🗙 Failed |
| | ~ |
| Fail Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii)) | |
| FailParking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))AdviceRear Registration plate deteriorated but not likely to be misread (0.1 (b)) | |

| МОТ #20 | 2019-07-22 09:52 |
|--|------------------|
| MOT test number | 661159648846 |
| Result | 🗸 Passed |
| MinorNearside Front Inner Drive shaft joint constant velocity boot severely deterioratedAdviceNearside Front Service brake binding but not excessively (1.2.1 (f)) | (6.1.7 (g) (i)) |

| MOT #19 | | 2018-08-23 09:27 |
|---------------|--|------------------------|
| MOT test | number | 206949325945 |
| Result | | ✓ Passed |
| Advice | Rear Registration plate deteriorated but not likely to be misread (0.1 (b)) | |
| Advice | Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Handbrake lever nearing limit of travel | |
| Minor (i)) | Offside Registration plate lamp inoperative in the case of multiple lamps or lig | ght sources (4.7.1 (b) |





| MOT #18 | 2018-08-20 12:00 |
|---|------------------------|
| MOT test number | 495873598855 |
| Result | 🗙 Failed |
| Advice Handbrake lever nearing limit of travel | |
| Fail Nearside Front Brake disc significantly and obviously worn (1.1.14 (a) (i)) | |
| Fail Offside Front Position lamp not working (4.2.1 (a)) | |
| (i)) Offside Registration plate lamp inoperative in the case of multiple lamps or lig | ght sources (4.7.1 (b) |
| Fail Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) | |
| Fail Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i)) | |
| Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b)) | |
| Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

| MOT #17 | 2017-08-10 08:13 |
|---|---------------------|
| MOT test number | 268573653948 |
| Result | ✓ Passed |
| Advice Nearside Front Lower Suspension arm rubber bush deteriorated but not resume movement (2.4.G.2) | Ilting in excessive |
| Advice Nearside Track rod end ball joint has slight play (2.2.B.1f) | |
| Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1) | |
| Advice Rear exhaust bracket broken | |
| Advice Offside Front Lower Suspension arm synthetic bush deteriorated but not res movement (2.4.G.2) | ulting in excessive |
| Advice Offside Front Tyre worn close to the legal limit (4.1.E.1) | |

| MOT #16 | 2016-08-12 14:34 |
|-----------------|------------------|
| MOT test number | 781984361407 |
| Result | ✓ Passed |





| MOT #15 | 2016-08-12 07:55 |
|---|-----------------------|
| MOT #15 MOT test number | 981174975430 |
| | |
| Result | 🗙 Failed |
| Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1) | |
| MOT #14 | 2015-07-31 15:42 |
| MOT test number | 776422515270 |
| Result | ✓ Passed |
| Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1) | |
| MOT #13 | 2014-08-04 15:13 |
| MOT test number | 647046114294 |
| Result | Passed |
| | |
| MOT #12 | 2013-08-08 16:53 |
| MOT test number | 605220723283 |
| Result | ✓ Passed |
| MOT #11 | 2012-08-07 12:59 |
| MOT test number | 227820622287 |
| Result | ✓ Passed |
| Advice Nearside Front Suspension arm rubber bush deteriorated but not resulting (2.4.G.2) | in excessive movement |
| Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in (2.4.G.2) | n excessive movement |





| MOT #10 | | 2012-08-07 11:03 |
|--------------------------|--|-------------------------|
| MOT test r | number | 475310222204 |
| Result | | 🗙 Failed |
| Advice | Offside Front Tyre worn close to the legal limit (4.1.E.1) | |
| Fail Ne | earside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1) | |
| Advice | Offside Rear position lamp(s) has light sources not illuminating, but not mo | ore than 50% (1.1.A.3b) |
| Advice (2.4.G.2) | Offside Front Suspension arm rubber bush deteriorated but not resulting in | n excessive movement |
| Advice (1.1.A.3b) | Nearside Rear position lamp(s) has light sources not illuminating, but not r | more than 50% |
| Advice (2.4.G.2) | Nearside Front Suspension arm rubber bush deteriorated but not resulting | in excessive movement |

| MOT #9 | 2011-08-15 11:24 |
|-------------------------|--|
| MOT test | number 716637821274 |
| Result | ✓ Passed |
| Notice | Both rear brake discs corroded |
| Advice (2.4.G.2) | Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement |
| Notice | Both front brake discs corroded and worn |
| Advice (2.4.G.2) | Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement |

| MOT #8 | 2011-08-15 11:24 |
|-----------------|------------------|
| MOT test number | 249827221254 |
| Result | 🗙 Failed |

| Advice (2.4.G.2) | Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement |
|-------------------------|--|
| Notice | Both front brake discs corroded and worn |
| Pass wit | th rectification Nearside Headlamp not working on dipped beam (1.7.5a) |
| Advice (2.4.G.2) | Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement |
| Notice | Both rear brake discs corroded |





| MOT #7 | 2010-08-02 1 | L4:39 |
|----------|--|-------|
| MOT test | a number 44302421 | 0291 |
| Result | 🗸 Pa | assed |
| Notice | All brake discs worn slighty | |
| Advice | Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.0 | G.2) |
| | | |

| MOT #6 | 2010-08-02 14:39 | |
|-------------------------------------|--|--|
| MOT test number | 221134910272 | |
| Result | × Failed | |
| Advice Front Suspension | n arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2) | |
| Pass with rectification | Registration plate lamp not illuminating the registration plate (1.1.C.1e) | |
| Pass with rectification | Fuel cap/sealing device sealing washer deteriorated (7.2.4c) | |
| Notice All brake discs worn slighty | | |
| Pass with rectification | Nearside Rear Exhaust system not adequately supported (7.1.1) | |

| MOT #5 | 2009-08-07 10:49 |
|-----------------|------------------|
| MOT test number | 580479119271 |
| Result | ✓ Passed |
| | |
| NOT "A | |

| МОТ #4 | | 2009-08-07 10:49 |
|-------------------------|--|------------------|
| MOT test number | | 834639819256 |
| Result | | 🗙 Failed |
| Pass with rectification | Nearside Front position lamp(s) not working (1.1.A.3b) | |





| MOT #3 | 2008-08-13 09:43 |
|---|------------------------------|
| MOT test number | 562716728284 |
| Result | ✓ Passed |
| Notice Slight play in nearside front inner track rod joint | |
| Advice Offside Front Suspension arm rubber bush deteriorated but not result (2.4.G.2) | ting in excessive movement |
| Advice Nearside Front Suspension arm rubber bush deteriorated but not result. (2.4.G.2) | ulting in excessive movement |
| MOT #2 | 2007-08-10 13:09 |
| MOT test number | 344602427277 |
| Result | ✓ Passed |
| | |
| MOT #1 | 2006-08-18 12:59 |
| MOT test number | 442500636282 |
| Result | ✓ Passed |



Tax & MOT check

| ✓ Taxed Tax due: 1 March 2025 | ✓ MOT Expires: 1 March 2025 |
|--|--------------------------------------|
| Tax status | Valid until 1 March |
| Days left | 305 |
| MOT expiry date | 1 March 2025 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|---|------------|
| Band | К |
| Single payment (12 months) | £ 395,00,- |
| Single six month payment | £ 217,25,- |
| Total payable by 12 monthly instalments | £ 414,75,- |





Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|----------------|
| Date | FEIDO |
| Category | L'ANN P |
| Туре | K K |
| | AMPLE |
| Damage 2 | 6 - at - D - D |
| Date | * |
| Category | AMPL |
| Туре | |

Extra VOLVO salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4.11.111 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 11 711 |

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| ****** | |
|--|-------------|
| *********** | |
| ******* | |
| ****** | |
| *********** | |
| ******* | |
| | More info > |
| Plate changes | |
| See in this check if this VOLVO had different number plates. | |
| Number of plates | |
| Current registration | |
| Plate since | |
| Current registration | |
| Plate since | |
| | |





Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info \rightarrow





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 26 |
| First mileage registration | 2003-11-27 |
| Last registration | 2024-03-01 |
| Complete history | See info |



| Registration #1 | 2003-11-27 | 14 mi |
|------------------|------------|------------|
| Registration #2 | 2006-08-18 | 36.487 mi |
| Registration #3 | 2007-08-10 | 47.638 mi |
| Registration #4 | 2008-08-13 | 58.902 mi |
| Registration #5 | 2009-08-07 | 69.871 mi |
| Registration #6 | 2010-08-02 | 82.259 mi |
| Registration #7 | 2011-08-15 | 92.704 mi |
| Registration #8 | 2012-08-07 | 100.155 mi |
| Registration #9 | 2012-08-07 | 100.155 mi |
| Registration #10 | 2013-08-08 | 109.111 mi |
| Registration #11 | 2014-08-04 | 116.849 mi |
| Registration #12 | 2015-07-31 | 126.185 mi |
| Registration #13 | 2016-08-12 | 146.726 mi |
| Registration #14 | | 11.777 est |
| Registration #15 | | 11.777 est |
| Registration #16 | | 11.777 est |
| Registration #17 | | 11.777 est |
| Registration #18 | | 11.777 est |
| Registration #19 | | 11.777 est |
| Registration #20 | | 11.777 est |
| Registration #21 | | 11.777 esi |
| Registration #22 | | 11.777 est |
| Registration #23 | | 11.777 esi |
| Registration #24 | | 11.317 mi |
| Registration #25 | | 11.777 mi |
| Registration #26 | | 11.777 est |
| CarCheck co.uk | | nago 15/16 |

CarCheck.co.uk

More info >





Car features

| S0225 | Air conditioning |
|--------|------------------|
| S0295 | |
| 50482 | |
| \$0501 | |
| \$0566 | |
| \$0567 | |
| S0569 | |

Dimensions & weight

| Width | 1720 mm |
|---------------------|---------|
| Height | 1400 mm |
| Length | 4520 mm |
| Wheel base | 2560 mm |
| Max. allowed weight | 2130 kg |

Additional information

| Fuel tank capacity | 70 |
|--------------------|-----------------------|
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of axles | 2 |
| Engine number | 3198983 |