



AV52TXH

report date: 2024-03-28

General information

Make	LAND ROVER
Model	DEFENDER TD5 COUNTY HARD TOP
Colour	Silver
Year of manufacture	2002
Top speed	82 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	121 BHP
Max. torque	300 Nm at 1.950 rpm
Engine capacity	2.495 cc
Cylinders	5
Fuel type	Diesel
Consumption city	23.3 mpg
Consumption extra urban	31.4 mpg
Consumption combined	28.0 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-09-14
Pictures	7
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-09-24
MOT pass rate	69 %
MOT passed	18
Failed MOT tests	8
Total advice items	90
Total items failed	24

MOT #26	2023-09-04 15:13
MOT test number	176460360207
Result	✓ Passed
Next expiry date	2024-09-24

MOT #25	2023-09-04 09:27
MOT test number	600553180327
Result	✗ Failed
Fail	Offside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

MOT #24	2022-09-23 12:18
MOT test number	982498170075
Result	✓ Passed

MOT #23	2021-09-07 14:33
MOT test number	181449600900
Result	✓ Passed
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened slight corrosion (1.1.14 (a) (ii))
Advice	Coil spring corroded all x 4 slight corrosion (5.3.1 (b) (i))
Minor	Offside Front Headlamp lens slightly defective slight crack (4.1.1 (b) (i))

**MOT #22**

2020-09-25 15:51

**MOT test number**

356532888482

**Result**

✓ Passed

- Advice** Brake disc worn, pitted or scored, but not seriously weakened both rear (1.1.14 (a) (ii))
- Advice** Shock absorbers has slight external damage to the casing all corroded (5.3.2 (b))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Coil spring corroded all x 4 (5.3.1 (b) (i))
- Advice** Anti-roll bar pin or bush worn but not resulting in excessive movement both rear (5.3.4 (a) (i))

**MOT #21**

2020-09-25 08:55

**MOT test number**

408442834988

**Result**

✗ Failed

- Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))
- Fail** Offside Rear Shock absorbers insecurely attached (5.3.2 (a) (i))
- Advice** Anti-roll bar pin or bush worn but not resulting in excessive movement both rear (5.3.4 (a) (i))
- Advice** Brake disc worn, pitted or scored, but not seriously weakened both rear (1.1.14 (a) (ii))
- Fail** Nearside Rear All direction indicators not working (4.4.1 (a) (ii))
- Advice** Coil spring corroded all x 4 (5.3.1 (b) (i))
- Advice** Shock absorbers has slight external damage to the casing all corroded (5.3.2 (b))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #20**

2019-09-03 09:22

**MOT test number**

937950427798

**Result**

✓ Passed

- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Nail in tyre
- Advice** Shock absorbers has slight external damage to the casing both front corroded (5.3.2 (b))
- Advice** Coil spring corroded both front (5.3.1 (b) (i))

**MOT #19**

2018-09-11 16:24

**MOT test number**

992535543885

**Result**

✓ Passed

- Advice** Offside Front joint weeping
- Advice** Nearside Rear Brake pipe slightly damaged (1.1.11 (c))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front joint weeping
- Advice** Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement x2 (5.3.4 (a) (i))

**MOT #18**

2018-09-07 12:26

**MOT test number**

713679298440

**Result****✗ Failed**

- Advice** Offside Front joint weeping
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Fail** Service brake efficiency below requirements (1.2.2 (a) (i))
- Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))
- Fail** Offside Front Brake pipe excessively corroded to caliper (1.1.11 (c))
- Fail** Offside Rear Brake pipe excessively corroded (1.1.11 (c))
- Advice** Nearside Front joint weeping
- Advice** Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement x2 (5.3.4 (a) (i))
- Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
- Fail** Offside Front Brake pipe excessively corroded (1.1.11 (c))
- Fail** Nearside Front Brake pipe excessively corroded to caliper (1.1.11 (c))
- Advice** Nearside Rear Brake pipe slightly damaged (1.1.11 (c))
- Fail** Front Brakes imbalanced across an axle by more than 50% Axle 1 (1.2.1 (b) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #17**

2017-09-08 15:42

**MOT test number**

775581501885

**Result****✓ Passed**

- Advice** Offside Rear Anti-roll bar has slight play in a pin/bush (2.4.G.2)
- Advice** Exhaust system corroded
- Advice** Body has slight corrosion (6.1.B.2)

**MOT #16**

2017-09-01 14:40

**MOT test number**

767389278911

**Result****✗ Failed**

- Fail** Windscreen washer provides insufficient washer liquid (8.2.3)
- Fail** Rear Body or chassis has excessive corrosion, seriously affecting its strength within 30cm of the body mountings chassis (6.1.B.2)
- Advice** Exhaust system corroded
- Fail** Nearside Rear Shock absorber has an excessively worn bush (2.7.4)
- Fail** Service brake: efficiency below requirements (3.7.B.7)
- Fail** Nearside Rear Direction indicator not working (1.4.A.2c)
- Advice** Offside Rear Anti-roll bar has slight play in a pin/bush (2.4.G.2)
- Advice** Body has slight corrosion (6.1.B.2)
- Fail** Offside Rear Shock absorber has an excessively worn bush (2.7.4)
- Fail** Parking brake: efficiency below requirements (3.7.B.7)

**MOT #15**

2016-07-04 09:07

**MOT test number**

394162820542

**Result****✓ Passed**

- Advice** Nearside Rear Shock absorber has a slightly worn bush (2.7.4)
- Advice** Oil leak
- Advice** Offside Rear Shock absorber has a slightly worn bush (2.7.4)
- Advice** Towbar component slightly corroded (6.6.1)

**MOT #14**

2015-07-03 16:33

**MOT test number**

495534485157

**Result**

✓ Passed

- Advice** Nearside Rear Shock absorber has a slightly worn bush (2.7.4)
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** Oil leak from rear diff
- Advice** Offside Rear Shock absorber has a slightly worn bush (2.7.4)
- Advice** Vehicle structure slightly corroded within 30cm of towbar mounting (6.6.6)
- Notice** Oil leak

**MOT #13**

2015-07-03 11:37

**MOT test number**

296514285196

**Result**

✗ Failed

- Notice** Oil leak
- Fail** Nearside Front Track rod end ball joint has excessive play (2.2.B.1f)
- Advice** Offside Rear Shock absorber has a slightly worn bush (2.7.4)
- Advice** Vehicle structure slightly corroded within 30cm of towbar mounting (6.6.6)
- Notice** Oil leak from rear diff
- Advice** Nearside Rear Shock absorber has a slightly worn bush (2.7.4)
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



**MOT #12** 2014-07-04 09:30**MOT test number** 127345884138**Result** ✓ Passed

- Notice** Clutch pedal anti-slip missing
- Notice** Oil leak
- Notice** Engine covers fitted obscuring some components in the engine bay
- Notice** Offside headlamp cracked

**MOT #11** 2013-07-05 09:30**MOT test number** 376026683177**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Clutch pedal anti-slip missing

**MOT #10** 2012-06-18 14:35**MOT test number** 956780672154**Result** ✓ Passed

- Notice** Clutch pedal anti-slip missing
- Notice** Oil leak

**MOT #9** 2012-06-18 09:39**MOT test number** 267740172495**Result** ✗ Failed

- Notice** Clutch pedal anti-slip missing
- Fail** Offside Rear Mechanical brake component has restricted free movement (3.5.1k)
- Notice** Oil leak
- Fail** Nearside Rear Mechanical brake component has restricted free movement (3.5.1k)



MOT #8	2011-06-10 12:48
MOT test number	878881561107
Result	✓ Passed
Notice	Clutch pedal anti-slip worn
Advice	Offside Rear Shock absorber has a slightly worn bush (2.7.4)
Advice	Offside Front Brake pad(s) wearing thin (3.5.1g)
Notice	Offside headlamp glass cracked
Advice	Nearside Rear Shock absorber has a slightly worn bush (2.7.4)
Advice	Nearside Front Brake pad(s) wearing thin (3.5.1g)

MOT #7	2011-06-10 09:24
MOT test number	279451261441
Result	✗ Failed
Fail	Nearside Rear Brake pipe leaking (3.6.A.1)
Advice	Offside Rear Shock absorber has a slightly worn bush (2.7.4)
Advice	Offside Front Brake pad(s) wearing thin (3.5.1g)
Notice	Clutch pedal anti-slip worn
Advice	Nearside Rear Shock absorber has a slightly worn bush (2.7.4)
Advice	Nearside Front Brake pad(s) wearing thin (3.5.1g)
Notice	Offside headlamp glass cracked



MOT #6	2010-06-21 10:13
MOT test number	513362170136
Result	✓ Passed
Advice	Nearside Rear Shock absorber has a slightly worn bush (2.7.4)
Notice	Oil leak
Advice	Nearside Rear Brake pad(s) wearing thin (3.5.1g)
Notice	Offside headlamp glass cracked

MOT #5	2009-04-27 16:53
MOT test number	120497719187
Result	✓ Passed
Notice	Oil leak
Advice	Nearside Rear Shock absorber has a slightly worn bush (2.7.4)
Advice	Offside Rear Brake pad(s) wearing thin (3.5.1g)
Notice	Fuel mist on the offside of the engine
Advice	Nearside Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #4** 2009-04-27 09:30**MOT test number** 553077019171**Result** ✗ Failed**Notice** Small cuts in the nearside rear tyre inner and outter walls**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**Notice** Fuel mist on the offside of the engine**Advice** Nearside Rear Shock absorber has a slightly worn bush (2.7.4)**Fail** Offside Rear Tyre has ply or cords exposed (4.1.D.1b)**Notice** Oil leak**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**MOT #3** 2008-04-29 11:22**MOT test number** 661010728162**Result** ✓ Passed**Notice** Offside headlamp glass cracked**Advice** Offside Power steering component(s) has slight seepage from a seal (2.3.3b)**MOT #2** 2007-04-17 09:27**MOT test number** 321097307181**Result** ✓ Passed**MOT #1** 2006-04-19 09:20**MOT test number** 533619906181**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 May 2025

✓  
**MOT**  
**Expires:**  
24 September 2024

Tax status		Valid until 1 May
Days left		368
MOT expiry date		24 September 2024
Full MOT history		<a href="#">See MOT history</a>



Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many owners did this LAND ROVER have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this LAND ROVER had different number plates.

Number of plates	1
Current registration	<b>AV52TXH</b>
Plate since	2019-09-29
Current registration	<b>AV52TXH</b>
Plate since	2019-09-29

More info >



Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this LAND ROVER is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >





Mileage check

Odometer	In miles
Mileage registrations	28
First mileage registration	2002-09-30
Last registration	2023-09-04
Complete history	<a href="#">See info</a>



Registration #1	2002-09-30	10 mi
Registration #2	2006-04-19	58.170 mi
Registration #3	2007-04-17	72.315 mi
Registration #4	2008-04-29	86.113 mi
Registration #5	2009-04-27	97.933 mi
Registration #6	2009-04-27	97.971 mi
Registration #7	2010-06-21	108.078 mi
Registration #8	2011-06-10	115.743 mi
Registration #9	2011-06-10	115.743 mi
Registration #10	2012-06-18	123.812 mi
Registration #11	2012-06-18	123.817 mi
Registration #12	2013-07-05	132.464 mi
Registration #13	2014-07-04	139.733 mi
Registration #14	2015-07-03	147.208 mi
Registration #15	2016-06-20	155.277 mi
Registration #16	2016-06-20	155.277 mi
Registration #17	2016-06-20	155.277 mi
Registration #18	2016-06-20	155.277 mi
Registration #19	2016-06-20	155.277 mi
Registration #20	2016-06-20	155.277 mi
Registration #21	2016-06-20	155.277 mi
Registration #22	2016-06-20	155.277 mi
Registration #23	2016-06-20	155.277 mi
Registration #24	2016-06-20	155.277 mi
Registration #25	2016-06-20	155.277 mi
Registration #26	2016-06-20	155.277 mi

Registration #27	2020-05-20	20,000,000
Registration #28	2020-05-20	20,000,000

More info >



Dimensions & weight

Width	2032 mm
Height	1956 mm
Length	3886 mm
Kerb weight	1800 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of axles	2
Engine number	15P36295A