





report date: 2024-03-28

# General information

Make	VOLKSWAGEN
Model	GOLF SE TDI
Colour	Blue
Year of manufacture	2009
Top speed	125 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

# Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.7 mpg
Consumption extra urban	60.1 mpg
Consumption combined	50.4 mpg
CO2 emission	135 g/km
CO2 label	Е



CarCheck.co.uk page 1/15



# Internet history


#### Entry 1

Date 2021-06-15

Pictures 9

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/15



MOT history

MOT expiry date	2024-06-01
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	46
Total items failed	9

MOT #14	2023-06-02 16:03
MOT test number	641834440011
Result	✓ Passed
Next expiry date	2024-06-01
Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in rear of arm (5.3.4 (a) (i))	excessive movement
Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear of arm (5.3.4 (a) (i))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #13		2023-06-02 16:03
MOT test number		605411314315
Result		<b>×</b> Failed
Advice Offside Front Lower rear of arm (5.3.4 (a) (i))	er Suspension arm pin or bush worn but not resultin	ng in excessive movement
Pass with rectification	Nearside Front Headlamp aim too low (4.1.2 (a))	
Advice Nearside Front Tyr	re worn close to legal limit/worn on edge (5.2.3 (e))	
Pass with rectification	Front Undertray insecure (8.1.1 (b) (i))	
Advice Nearside Front Low rear of arm (5.3.4 (a) (i))	ver Suspension arm pin or bush worn but not result	ting in excessive movement
Pass with rectification (b) (ii))	Nearside Front Windscreen wiper does not clear the	e windscreen effectively (3.4
Pass with rectification	Offside Front Headlamp aim too low (4.1.2 (a))	
Pass with rectification	Central Exhaust system insecure (6.1.2 (a))	

CarCheck.co.uk page 3/15



report date: 2024-03-28

**MOT #12** 2022-07-05 13:22

**MOT test number** 677818389034

**Result** ✓ Passed

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement

rear of arm (5.3.4 (a) (i))

**Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))

**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement

rear of arm (5.3.4 (a) (i))

**Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**Advice** Central Exhaust mounting defective clamp (6.1.2 (a))

CarCheck.co.uk page 4/15



report date: 2024-03-28

**MOT #11** 2022-07-05 12:00

MOT test number 858680743265

Result X Failed

Advice Central Exhaust mounting defective clamp (6.1.2 (a))

**Pass with rectification** Offside Front Headlamp aim too high (4.1.2 (a))

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear of arm (5.3.4 (a) (i))

**Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))

**Pass with rectification** Nearside Front Headlamp aim too high (4.1.2 (a))

**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))

Fail Nearside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear of arm (5.3.4 (a) (i))

**Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))

**MOT #10** 2021-07-16 15:28

MOT test number 871632150159

Result \( \sqrt{Passed} \)

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #9 2020-10-28 12:08

**MOT test number** 948760659628

Result 

Passed

CarCheck.co.uk page 5/15



MOT #8	2019-10-07 12:05
MOT test	number 888818141928
Result	✓ Passed
Advice (e))	Offside Front Tyre worn close to legal limit/worn on edge worn SERIOUSLY on inner edge (5.2.3
Advice	Offside Rear Tyre slightly damaged/cracking or perishing getting close to limit (5.2.3 (d) (ii))
Advice	Under trays fitted
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing getting close to limit (5.2.3 (d) (ii))
Advice	Engine cover fitted
Advice	Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))

MOT #7	2018-10-26 09:39
MOT test number	564388585697
Result	<b>✓</b> Passed
Advice Both rear lights have LED's not working less than 50%	
Advice Offside Front Wheel bearing slightly noisy slightly rough (5.1.3 (b) (i	i))
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d)	(ii))
Advice Under trays fitted	
Minor Nearside Rear Direction indicator with a multiple light source up to 1	/2 not functioning (4.4.1 (a) (i))
Advice Engine cover fitted	
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d	l) (ii))

CarCheck.co.uk page 6/15



**Advice** 

EO09JZM

report date: 2024-03-28

MOT test number
640186569722

Result

Advice Engine cover fitted

Advice Rattle on start up from gearbox area also clutch biting point low

Advice Nearside Rear Direction indicator has light sources not illuminating, but not more than 50% Some LEDs not working (1.4.A.2c)

Advice Under trays fitted

**MOT #5** 2016-10-26 11:00 **MOT** test number 709016380763 ✓ Passed Result **Advice** Nearside Front Lower CONSOLE BUSH STARTING TO SPLIT Advice Nearside Rear Direction indicators has light sources not illuminating, but not more than 50% some LED not working (1.4.A.2c) Advice Offside Rear Lower CONSOLE BUSH STARTING TO SPLIT **Advice** Nearside Rear Direction indicator obscured but not more than 50% HAS SOME LEDS NOT WORKING (1.4.A.2d)

MOT #4

MOT test number

Result

2015-10-23 08:29

114426542861

✓ Passed

MOT test number

Result

Advice (1.4.A.2c)

Offside Rear Direction indicator has light sources not illuminating, but not more than 50%

Offside Rear position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)

CarCheck.co.uk page 7/15



MOT #2	2013-10-25 10:55
MOT test number	728498793283
Result	<b>✓</b> Passed
MOT #1	2012-10-31 10:51
MOT test number	02755502222
MOT test number	837555602373

CarCheck.co.uk page 8/15



Tax & MOT check



Tax status	Valid until 1 July
Days left	62
MOT expiry date	1 June 2024
Full MOT history	See MOT history

# Tax calculation

Vehicle class	49
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 9/15



report date: 2024-03-28


### Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <u>here</u> for the results.

#### Damage 1

Date	
Category	
Туре	

Date Date	
Category	



#### Extra VOLKSWAGEN salvage check



**Type** 

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 11/15



report date: 2024-03-28

# For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report here. More info

# Plate changes

See in this check if this VOLKSWAGEN had different number plates.

More info >

CarCheck.co.uk page 12/15



report date: 2024-03-28

#### Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

**Contact info** 

More info >

CarCheck.co.uk page 13/15



Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-04-30
Last registration	2023-06-02
Complete history	See info



Registration #1	2009-04-30	14 mi
Registration #2	2012-10-31	30.411 mi
Registration #3	2013-10-25	38.266 mi
Registration #4	2014-10-15	47.940 mi
Registration #5	2015-10-23	61.453 mi
Registration #6	2016-10-26	72.386 mi
Registration #7	2017-10-26	80.530 mi
Registration #8	2018-10-26	87.582 mi
Registration #9		11.177 es
Registration #10		11.777 es
Registration #11		9.777 es
Registration #12		11.777 es
Registration #13		9.777 es
Registration #14		D.777 es
Registration #15		11.777 mi

7075.75.75

More info >

77. 777 mg

CarCheck.co.uk page 14/15



# Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	***
Adult	97%
Children	84%
Pedestrian	61%
Safety systems	71%
Overall rating	85%
Video	see crash video



# Dimensions & weight

Width	1759 mm
Height	1592 mm
Length	4204 mm
Wheel base	2578 mm
Kerb weight	1399 kg
Max. allowed weight	2040 kg

# Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
CarChack co.uk	220 15/15

CarCheck.co.uk page 15/15

Number of axles	2
Engine number	CBD 173732