





General information

Make	VOLKSWAGEN
Model	TRANSPORTER 888 P/V SWB 88BHP TDI
Colour	White
Year of manufacture	2002
Top speed	93 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	88 BHP
Max. torque	195 Nm at 1.900 rpm
Engine capacity	2.461 cc
Cylinders	5
Fuel type	Diesel







Internet history

Entry 1

Date Pictures

Listing price

2021-09-27

16 <u>View report</u>



source: autotrader.co.uk



MOT history

MOT expiry date	2025-03-30
MOT pass rate	63 %
MOT passed	19
Failed MOT tests	11
Total advice items	85
Total items failed	44

MOT #30	2024-03-26 08:56
MOT test number	619712948584
Result	Passed
Next expiry date	2025-03-30
Advice Nearside Rear Inner Vehicle structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security sill (6.2.2 (d) (i))	

MOT #29	2024-03-26 08:56
MOT test number	719234363787
Result	× Failed
Pass with rectification dirt (2.1.3 (g) (ii))	Nearside Front Steering rack gaiter missing or no longer prevents the ingress of
Pass with rectification	Rear Stop lamp(s) not working (4.3.1 (a) (ii))
Advice Nearside Rear In seriously affecting overall se	nner Vehicle structure or chassis corroded within 30cm of a mounting, but not ecurity sill (6.2.2 (d) (i))
MOT #28	2023-03-29 08:12
MOT #28 MOT test number	2023-03-29 08:12 140281864385
MOT test number Result	140281864385
MOT test number Result Advice Nearside Rear S excessive (5.3.6 (a) (i))	140281864385 ✓ Passed
MOT test number Result Advice Nearside Rear S excessive (5.3.6 (a) (i)) Advice Nearside Front T	140281864385 ✓ Passed uspension component mounting prescribed area is corroded but not considered





MOT #27		2022-03-31 10:51
MOT test	number	713006512102
Result		✓ Passed
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11	(c))
Advice	Steering column top bearing slightly worn (2.2.2 (b))	
Advice	Washer bottle leaking.	
Advice	Offside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))	
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (2))
Advice	Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))	
Minor (2.1.3 (g)	Nearside Front Steering rack gaiter damaged or deteriorated, but preventing the (i))	ingress of dirt
Advice	Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))	

МОТ #26	2021-03-24 17:52
MOT test number	647374549683
Result	✓ Passed
Advice Exhaust emits excessive smoke or vapour but not likely to obscure the vision (8.2.2.2 (c))	of other road users
Advice Offside Front Direction indicator slightly discoloured (4.4.3 (a))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Brake hose slightly deteriorated both front (1.1.12 (b) (ii))	





MOT #25	2021-03-24 15:56
MOT test number	332724968842
Result	🗙 Failed
Advice Exhaust emits excessive smoke or vapour but not likely to obscure the vision of (8.2.2.2 (c))	of other road users
Fail Nearside Front Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i))	
Fail Nearside Front Direction indicator incorrect colour (4.4.3 (a))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Registration plate lamp inoperative in the case of a single lamp or all lamps both ((4.7.1 (b) (ii))
Advice Brake hose slightly deteriorated both front (1.1.12 (b) (ii))	
Advice Offside Front Direction indicator slightly discoloured (4.4.3 (a))	

МОТ #24	2020-03-26 08:25
MOT test number	436456889610
Result	✓ Passed
Advice Brake hose slightly deteriorated both front (1.1.12 (b) (ii))	
Minor Offside Obligatory mirror slightly damaged (3.3 (b) (i))	
Advice Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))	
Advice Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in exc (5.3.4 (a) (i))	essive movement
Minor (b) (i)) Nearside Registration plate lamp inoperative in the case of multiple lamps or	light sources (4.7.1
Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.1	.1 (c))
Advice Oil leak, but not excessive (8.4.1 (a) (i))	
Advice Exhaust emits excessive smoke or vapour but not likely to obscure the visio (8.2.2.2 (c))	n of other road users





MOT #23 2020-03-25 14:00
MOT test number 150111081248
Result X Failed
Advice Oil leak, but not excessive (8.4.1 (a) (i))
Fail Windscreen wiper does not clear the windscreen effectively both front (3.4 (b) (ii))
Minor Offside Obligatory mirror slightly damaged (3.3 (b) (i))
FailOffside Front Lower Suspension component ball joint dust cover no longer prevents the ingress of dirt(5.3.4 (b) (ii))
Advice Brake hose slightly deteriorated both front (1.1.12 (b) (ii))
Advice Exhaust emits excessive smoke or vapour but not likely to obscure the vision of other road users (8.2.2.2 (c))
Fail Offside Headlamp aim too low (4.1.2 (a))
Advice Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))
Fail Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Minor (b) (i)) Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1
Fail Fuel pipe leaking no.1 injector spills (6.1.3 (b) (i))
Advice Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
FailPosition lamp not working both front (4.2.1 (a) (ii))
Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Fail Offside Headlamp insecure (4.1.1 (c))

MOT #22	2019-03-28 12:07
MOT test number	729205520794
Result	✓ Passed
Advice Oil leak, but not excessive (8.4.1 (a) (i))	
Advice Front Exhaust has a minor leak of exhaust gases exhaust pipe section (6.1.	2 (a))
Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lan (4.7.1 (b) (i))	nps or light sources





MOT #21	2019-03-20 13:45
MOT test number	631822777777
Result	🗙 Failed
Fail Nearside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.	.3 (g) (ii))
Advice Front Exhaust has a minor leak of exhaust gases exhaust pipe section (6.1.2 (a))
Advice Oil leak, but not excessive (8.4.1 (a) (i))	
Fail Offside Steering locking device ineffective steering track rod end lock nut not tighted	ened (2.1.3 (d))
Fail Front Exhaust system insecure exhaust mounting bracket fractured & detached (6.	1.2 (a))
Fail Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))	
Fail Nearside Front Tyre not fitted in accordance with side wall instructions inner sidewa (5.2.3 (i))	all facing outwards
Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps of (4.7.1 (b) (i))	or light sources
Fail Nearside Front Position lamp not working (4.2.1 (a))	
MOT #20	2018-03-29 15:15

MOT #20	2018-03-29 15:15
MOT test number	582220286274
Result	✓ Passed

MOT #19	2017-03-16 13:18
MOT test number	546790274280
Result	✓ Passed
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #18		2016-03-18 16:10
MOT test	number	423609622947
Result		✓ Passed
Advice	Offside Rear Brake pad(s) wearing thin (3.5.1g)	
Advice	Rear Tyre worn close to the legal limit offside & nearside (4.1.E.1)	



CW02JTX	
report date: 2024-03-29	

MOT #17	2016-03-14 13:59
MOT test number	636471465895
Result	🗙 Failed
Advice Offside Rear Brake pad(s) wearing thin (3.5.1g)	
Fail Offside Rear Registration plate lamp not working (1.1.C.1d)	
FailRear registration plate delaminated (6.3.1d)	
Advice Rear Tyre worn close to the legal limit offside & nearside (4.1.E.1)	
Fail Offside Rear fog lamp not working (1.3.2b)	

2015-03-03 15:38
378322665075

MOT test number

Result

MOT #16

MOT #15	2015-03-02 15:06
MOT test number	439321965026
Result	🗙 Failed
Fail Offside Front Direction indicator incorrect colour (1.4.A.2f)	
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Fail Nearside Front Direction indicator incorrect colour (1.4.A.2f)	
Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	

🗸 Passed





MOT #14		2014-01-08 17:06
MOT test	number	198478404030
Result		✓ Passed
Advice	Steering system has slight free play detected at steering wheel (2.2.A.1b)	
Notice	Has cam belt been replaced?	
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.	1i)
Advice	Rear registration plate deteriorated but not likely to be misread (6.3.1d)	
Notice	Engine oil level low.	
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.	5.1i)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Notice	Brake pedal anti-slip rubber worn on edge.	





MOT #13 2014-01-03 1	3:07
MOT test number 647493904	1022
Result X F	ailed
Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Fail Exhaust emits an excessive level of metered smoke for a turbo charged engine (7.4.B.3b)	
Notice Engine oil level low.	
Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Fail Nearside Track rod end ball joint dust cover excessively deteriorated so that it no longer prevents ingress of dirt (2.2.C.1c)	the
FailDriver's seat insecure (6.2.A.1)	
Notice Brake pedal anti-slip rubber worn on edge.	
Advice Steering system has slight free play detected at steering wheel (2.2.A.1b)	
Notice Has cam belt been replaced?	
Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Fail Offside Track rod end ball joint has excessive play (2.2.B.1f)	
Advice Rear registration plate deteriorated but not likely to be misread (6.3.1d)	

MOT #12		2012-12-18 10:33
MOT test	number	796263052363
Result		✓ Passed
Advice	Offside Obligatory mirror damaged, but not seriously affecting the rear view (8.3	1.2a)
Notice	Brake pedal anti-slip rubber wearing on edge.	
Advice	Rear registration plate deteriorated but not likely to be misread (6.3.1d)	





MOT #11		2011-08-11 16:13
MOT test	number	448063321256
Result		Passed
Advice	Steering system has slight free play detected at steering wheel (2.2.A.1b)	
Notice	All tyre outer sidewalls have minor damage.	

MOT #10		2011-08-11 16:13
MOT test number		986663821229
Result		🗙 Failed
Pass with rectification	Offside Rear fog lamp not working (1.3.2b)	
Pass with rectification	Offside Front position lamp(s) not working (1.1.A.3b)	
Advice Steering system	has slight free play detected at steering wheel (2.2.A.1b)	
Notice All tyre outer sid	ewalls have minor damage.	

МОТ #9	2010-06-30 08:38
MOT test number	163171380138
Result	✓ Passed

MOT #8	2010-06-23 08:57
MOT test number	200194570406
Result	🗙 Failed
Fail Rear Exhaust system not adequately supported (7.1.1)	
Advice Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)	
Fail Stop lamp not working (1.2.1b)	
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Fail Nearside Front Front position lamp(s) adversely affected by the operation of and	other lamp (1.1.A.3f)





MOT #7		2009-06-19 15:52
MOT test	number	190460479147
Result		✓ Passed
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5	.1i)
Advice	Rear Exhaust has a minor leak of exhaust gases (7.1.2)	
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3	.5.1i)
Advice	Nearside Inner Front Road wheel with a slightly distorted bead rim (4.2.A.1a)	

МОТ #6	2008-04-22 15:50
MOT test number	273403018107
Result	✓ Passed

MOT #5	2008-04-17 16:50
MOT test number	224388408184
Result	🗙 Failed
AdviceWindscreen has damage to an area less than a 40mm circle outside zorFailFront registration plate character(s) likely to be misread (6.3.4b)FailOffside Rear fog lamp excessively deteriorated so that it is not visible from (1.3.2d)	

MOT #4	2007-04-10 12:09
MOT test number	513590607138
Result	✓ Passed





MOT #3	2007-04-03 14:47
MOT test number	354973997020
Result	🗙 Failed
Fail Windscreen has a sticker or other obstruction encroaching by more than 10mm with (8.3.1b)	in zone 'A'
Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3	.1d)
Fail Offside Headlamp aim too low (1.8)	
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
FailPower steering component(s) leaking (2.3.3b)	
FailNearside Front constant velocity joint gaiter split (2.5.C.1a)	
Fail Windscreen has a sticker or other obstruction encroaching into the swept area by mo outside zone 'A' (8.3.1e)	ore than 40mm
Fail Offside Stop lamp not working (1.2.1b)	
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Notice Slight play in rack	
Fail Nearside Headlamp aim too low (1.8)	
Fail Offside Front constant velocity joint gaiter split (2.5.C.1a)	

MOT #2	2006-04-19 15:55
MOT test number	351979206107
Result	✓ Passed
Advice Front Windscreen has damage to an area	less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #1	2005-08-19 12:49
MOT test number	152661235207
Result	✓ Passed



Tax & MOT check







Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FERRE
Category	Lamp
Туре	
Damage 2	AMPLE
Date	
Date	OLE
Category	AM
Туре	

Extra VOLKSWAGEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second s	
and the second sec	

And a second s	
	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	
Carrent registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	31
First mileage registration	2002-07-31
Last registration	2024-03-26
Complete history	See info



Registration #1	2002-07-31	15 mi
Registration #2	2005-08-19	88.927 mi
Registration #3	2006-04-19	96.086 mi
Registration #4	2007-04-03	107.037 mi
Registration #5	2007-04-10	107.040 mi
Registration #6	2008-04-17	117.161 mi
Registration #7	2008-04-22	117.197 mi
Registration #8	2009-06-19	127.062 mi
Registration #9	2010-06-23	133.247 mi
Registration #10	2010-06-30	133.271 mi
Registration #11	2011-08-11	140.299 mi
Registration #12	2012-12-18	147.715 mi
Registration #13	2014-01-03	151.684 mi
Registration #14	2014-01-08	151.684 mi
Registration #15	2015-03-02	155.979 mi
Registration #16	2015-03-03	155.979 mi
Registration #17		11.777 esi
Registration #18		11.277 est
Registration #19		11.777 mi
Registration #20		11.777 est
Registration #21		11.777 mi
Registration #22		11.777 est
Registration #23		11.777 mi
Registration #24		11.117 mi
Registration #25		11.777 mi
Registration #26		10.317 est
CarCheck.co.uk		page 18/19

Registration #27	11.777 esi
Registration #28	11.777 est
Registration #29	11.777 est
Registration #30	11.777 est
Registration #31	11.117 esi

More info \rightarrow





Car features

S0225	Air conditioning
S0295	
50482	
\$0501	
\$0566	
\$0567	
S0569	

Dimensions & weight

Width	2175 mm
Height	1940 mm
Length	4707 mm
Kerb weight	1635 kg

Additional information

Fuel tank capacity	80 I
Fuel delivery	Direct Injection
Number of doors	4
Engine number	AJT 119232