





report date: 2024-03-29

General information

Make	MAZDA
Model	5 TS2
Colour	Blue
Year of manufacture	2007
Top speed	113 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	165 Nm at 4.000 rpm
Engine capacity	1.798 сс
Cylinders	4
Fuel type	Petrol
Consumption city	26.4 mpg
Consumption extra urban	44.8 mpg
Consumption combined	35.8 mpg
CO2 emission	190 g/km
CO2 label	I



CarCheck.co.uk page 1/17



Internet history

Entry 1

Date 2021-07-25

Pictures 22

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/17



MOT history	ΜO	Γh	nist	orv	
-------------	----	----	------	-----	--

MOT expiry date	2024-10-05
MOT pass rate	65 %
MOT passed	15
Failed MOT tests	8
Total advice items	47
Total items failed	30

MOT #23		2023-10-06 13:56
MOT test	number	902372975293
Result		✓ Passed
Next expi	ry date	2024-10-05
Advice	Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Advice	Centre seat belt removed from middle row	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Exhaust emits blue smoke during acceleration (8.2.1.2 (g))	
Advice	Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Advice	Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))	

CarCheck.co.uk page 3/17



MOT #22 2023-10-05 07:54

MOT test number 497701224291

Result × Failed Fail Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c)) Fail Nearside Rear Hydraulic brake calliper leaking (1.1.16 (b) (i)) **Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i)) Minor Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i)) Windscreen damaged and affecting the driver's view of the road (3.2 (a) (ii)) Fail Fail Brake master cylinder leaking pipe insecure (1.1.10 (b) (ii)) **Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b)) Fail Offside Front Position lamp not working (4.2.1 (a) (ii)) **Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) **Advice** Centre seat belt removed from middle row Fail Nearside Seat belt not functioning as intended middle row (7.1.2 (c)) Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i)) **Advice** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h)) Fail **Advice** Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i)) **Minor** Offside Front Headlamp lens slightly defective (4.1.1 (b) (i)) Nearside Front Position lamp not working (4.2.1 (a) (ii)) Fail Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Exhaust emits blue smoke during acceleration (8.2.1.2 (g))

CarCheck.co.uk page 4/17



report date: 2024-03-29

MOT test number

Result

Advice Front Suspension component corroded but not seriously weakened (5.3.3 (b) (i))

Advice Rear Suspension component corroded but not seriously weakened (5.3.3 (b) (i))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #20

MOT test number

Fesult

Advice

Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Advice

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #19 2020-11-19 19:09 368312155017 **MOT** test number Result Passed Minor Front Windscreen wiper blade defective both sides ends slight splitting (3.4 (b) (i)) **Advice** Rear Exhaust mounting defective metal hanger broken off (6.1.2 (a)) Minor Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated pin hole splits and grease seepage (6.1.7 (g) (i)) **Advice** Front Anti-roll bar pin or bush worn but not resulting in excessive movement both sides (5.3.4 (a) (i))

 MOT #18
 2019-11-11 16:43

 MOT test number
 434140989932

 Result
 ✓ Passed

CarCheck.co.uk page 5/17



MOT #17 2019-11-07 16:24

MOT test number 688442101286

Result × Failed

Fail Nearside Rear Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

Fail Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Fail Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

Fail Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))

Fail Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Fail Offside Rear Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

Fail Nearside Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #16 2019-05-15 09:54

MOT test number 636076801296

Advice Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Central Exhaust mounting defective (6.1.2 (a))

Advice Offside Front Upper Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

CarCheck.co.uk page 6/17



MOT #15 2019-05-15 09:27

MOT test number 630860784569

Result X Failed

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Front Upper Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Advice Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

Fail Nearside Front Tyre has ply or cords exposed 205/55/16 (5.2.3 (d) (ii))

Advice Central Exhaust mounting defective (6.1.2 (a))

MOT #14 2018-05-22 14:17

MOT test number 313245323141

MOT #13 2018-05-21 14:06

MOT test number 475997083714

Result × Failed

Fail Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Fail Front Brake lining(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Fail Rear Brake lining(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #12 2017-04-06 10:12

MOT test number 809672377838

Result
✓ Passed

Advice Knock in front suspension

CarCheck.co.uk page 7/17



report date: 2024-03-29

MOT #11	2017-04-05 07:48
MOT test number	120679192335
Result	× Failed
Fail Windscreen wiper does not clear the windscreen effectively both (8.2.2)	
Fail Coil spring broken both rear (2.4.C.1a)	
Advice Knock in front suspension	
Fail Windscreen washer provides insufficient washer liquid (8.2.3)	
Fail Tyre tread depth below requirements of 1.6mm both rear (4.1.E.1)	
Fail Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)	
Fail Front Brakes imbalanced across an axle (3.7.B.5b)	

MOT #10	2016-04-01 08:19
MOT test number	586930173219
Result	✓ Passed
MOT #9	2015-04-02 12:20
MOT test number	807812095019
Result	✓ Passed
MOT #8	2015-03-31 09:48
MOT test number	589600195012
Result	× Failed
Fail Nearside Rear Shock absorber has a serious fluid leak (2.7.3)	

MOT #7	2014-04-11 11:36
MOT test number	816481404136
Result	✓ Passed
Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)	

CarCheck.co.uk page 8/17



report date: 2024-03-29

MOT test number

Result

Fail Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

Fail Offside Rear Shock absorber has a serious fluid leak (2.7.3)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Notice Centre rear exhaust heat shield loose

MOT #5 2013-04-11 11:28 **MOT** test number 468691803184 Result ✓ Passed **MOT #4** 2012-03-29 16:50 **MOT** test number 389579182031 Result ✓ Passed **Notice** Nearside front tyre tread worn to 1.6mm [LEGAL AT TIME TEST] **Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT test number
629847382067

Result
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Notice Nearside front tyre tread worn to 1.6mm [LEGAL AT TIME TEST]

Fail Nearside Front Lower Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)

 MOT #2
 2011-04-08 15:32

 MOT test number
 686338391025

 Result
 ✓ Passed

CarCheck.co.uk page 9/17



report date: 2024-03-29

MOT test number

Result

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 10/17



Tax & MOT check



Tax status	Valid until 1 October
Days left	154
MOT expiry date	5 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-

CarCheck.co.uk page 11/17



report date: 2024-03-29

Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 12/17



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 13/17



report date: 2024-03-29

Owner	historv
OWNER	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,

For how long did the current and previous owner(s) have this MAZDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full	

THE STATE OF THE S	

	More info >
Plate changes	
See in this check if this MAZDA had different number plates.	
Number of plates	
Current registration	OK SIES
Plate since	
Current registration	UK NE
Plate since	
	More info >

CarCheck.co.uk page 14/17



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 15/17



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2007-09-27
Last registration	2023-10-06
Complete history	See info



Registration #1	2007-09-27	29 mi
Registration #2	2010-09-03	25.176 mi
Registration #3	2011-04-08	30.112 mi
Registration #4	2012-03-27	37.125 mi
Registration #5	2012-03-29	37.125 mi
Registration #6	2013-04-11	43.902 mi
Registration #7	2014-04-10	51.425 mi
Registration #8	2014-04-11	51.431 mi
Registration #9	2015-03-31	59.819 mi
Registration #10	2015-04-02	59.865 mi
Registration #11	2016-04-01	67.668 mi
Registration #12	2017-04-05	75.145 mi
Registration #13	2017-04-06	75.146 mi
Registration #14		71.777 es
Registration #15		11.177 es
Registration #16		11.177 es
Registration #17		11.177 es
Registration #18		11.777 es
Registration #19		11.777 ea
Registration #20		11.777 ea
Registration #21		
Registration #21 Registration #22		0.074
		1.77 4
Registration #22		11.777 es 11.777 es



Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1755 mm
Height	1655 mm
Length	4505 mm
Wheel base	2750 mm
Kerb weight	1395 kg
Max. allowed weight	2090 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	L8 20216854

CarCheck.co.uk page 17/17