



report date: 2024-03-28

General information

Make	KIA
Model	SORENTO CRDI XE
Colour	Blue
Year of manufacture	2006
Top speed	104 mph
0 - 60 mph	11.9 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	138 BHP
Max. torque	313 Nm at 2.000 rpm
Engine capacity	2.497 cc
Cylinders	4
Fuel type	Diesel
Consumption city	23.9 mpg
Consumption extra urban	38.7 mpg
Consumption combined	31.7 mpg
CO2 emission	223 g/km
CO2 label	K






Internet history

Entry 1

Date	2021-09-15
Pictures	6
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2025-03-25
MOT pass rate	76 %
MOT passed	16
Failed MOT tests	5
Total advice items	71
Total items failed	2

MOT #21	2024-03-26 16:54
MOT test number	954887570122
Result	✓ Passed
Next expiry date	2025-03-25
Advice	Offside Rear Vehicle structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security inner and outer sill panels (6.2.2 (d) (i))
Advice	Front Anti-roll bar pin or bush worn but not resulting in excessive movement roll bar inner d-bushes (5.3.4 (a) (i))
Minor	Headlamp lens slightly defective both headlamps in poor condition (4.1.1 (b) (i))
Advice	Nearside Rear Vehicle structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security inner and outer sill panels (6.2.2 (d) (i))
Advice	Front Oil leak, but not excessive diff (8.4.1 (a) (i))
Advice	Front Prop shaft joint worn, but not excessively prop front u/j (6.1.7 (c) (i))

**MOT #20**

2024-03-20 10:36

**MOT test number**

743403309782

**Result**

✗ Failed

**Advice** Front Prop shaft joint worn, but not excessively prop front u/j (6.1.7 (c) (i))**MAJOR** Offside Rear Rear fog lamp not working (4.5.1 (a) (ii))**Minor** Headlamp lens slightly defective both headlamps in poor condition (4.1.1 (b) (i))**MAJOR** Offside Front Upper Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Offside Rear Vehicle structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security inner and outer sill panels (6.2.2 (d) (i))**Advice** Front Anti-roll bar pin or bush worn but not resulting in excessive movement roll bar inner d-bushes (5.3.4 (a) (i))**MAJOR** Nearside Front Upper Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Nearside Rear Vehicle structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security inner and outer sill panels (6.2.2 (d) (i))**Advice** Front Oil leak, but not excessive diff (8.4.1 (a) (i))**MOT #19**

2023-03-20 16:39

**MOT test number**

766397621522

**Result**

✓ Passed

**Advice** Shock absorbers has a reduced damping effect rear shocks are soft and o/s/r damp (5.3.2 (d))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))**Advice** Exhaust mounting defective one mount broken and slight blow at rusty joint (6.1.2 (a))**Advice** Suspension component mounting prescribed area is corroded but not considered excessive n/s and o/s inner and outer sills rusty and weak at rear (5.3.6 (a) (i))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Fluid leak, but not excessive oil on diff and steering rack (8.4.1 (a) (i))

**MOT #18**

2023-03-20 10:00

**MOT test number**

981732658421

**Result****✗ Failed**

- Advice** Fluid leak, but not excessive oil on diff and steering rack (8.4.1 (a) (i))
- Advice** Shock absorbers has a reduced damping effect rear shocks are soft and o/s/r damp (5.3.2 (d))
- Advice** Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Exhaust mounting defective one mount broken and slight blow at rusty joint (6.1.2 (a))
- DANGEROUS** Nearside Front Upper Suspension arm ball joint likely to become detached (5.3.4 (a) (ii))
- Advice** Suspension component mounting prescribed area is corroded but not considered excessive n/s and o/s inner and outer sills rusty and weak at rear (5.3.6 (a) (i))
- MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #17**

2022-03-22 12:30

**MOT test number**

807279824502

**Result****✓ Passed**

- Advice** Oil level low
- Advice** Fluid leak, but not excessive oil on front diff and steering rack n/s (8.4.1 (a) (i))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #16**

2022-03-21 12:27

**MOT test number**

512837571980

**Result****✗ Failed****MAJOR** Offside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Headlight motors buss when adjusted off of the 0 position**MAJOR** Brake pipe excessively corroded both front to rear and both rear brake pipes (1.1.11 (c))**DANGEROUS** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))**MAJOR** Brake lever has insufficient reserve travel (1.1.2 (a))**MAJOR** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**MAJOR** Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))**Advice** Oil level low**Advice** Fluid leak, but not excessive oil on front diff and steering rack n/s (8.4.1 (a) (i))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #15**

2021-03-12 08:51

**MOT test number**

337433957941

**Result****✓ Passed****Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Upper Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #14**

2021-03-12 08:50

**MOT test number**

186806675111

**Result****✗ Failed****Pass with rectification** Windscreen wiper does not clear the windscreen effectively Both (3.4 (b) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Pass with rectification** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Nearside Front Upper Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #13**

2020-03-11 10:46

**MOT test number**

357061782988

**Result****✓ Passed****Advice** Oil leak, but not excessive auto box cooler (8.4.1 (a) (i))**Advice** Offside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #12**

2019-03-22 17:33

**MOT test number**

987688265012

**Result****✓ Passed****Advice** Rear Anti-roll bar pin or bush worn but not resulting in excessive movement both (5.3.4 (a) (i))**Advice** Front Anti-roll bar pin or bush worn but not resulting in excessive movement both (5.3.4 (a) (i))

**MOT #11** 2019-03-22 14:51**MOT test number** 331560882042**Result** ✗ Failed**Advice** Rear Anti-roll bar pin or bush worn but not resulting in excessive movement both (5.3.4 (a) (i))**MAJOR** Nearside Rear Parking brake inoperative on one side (1.4.1 (a))**MAJOR** Offside Position lamp not working (4.2.1 (a))**Advice** Front Anti-roll bar pin or bush worn but not resulting in excessive movement both (5.3.4 (a) (i))**MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))**MAJOR** Offside Side repeater incorrect colour (4.4.3 (a))**MOT #10** 2018-09-13 10:47**MOT test number** 332837715212**Result** ✓ Passed**MOT #9** 2017-09-13 12:01**MOT test number** 580669083517**Result** ✓ Passed**MOT #8** 2016-09-19 10:39**MOT test number** 537733855374**Result** ✓ Passed**MOT #7** 2015-09-24 10:30**MOT test number** 166683920469**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)



**MOT #6** 2014-09-18 13:48**MOT test number** 746671664283**Result** ✓ Passed**Advice** Offside Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #5** 2013-09-16 12:25**MOT test number** 806959453209**Result** ✓ Passed**Advice** Offside Rear Anti-roll bar has slight play in a pin/bush (2.4.G.2)**Advice** Nearside Rear Anti-roll bar has slight play in a pin/bush (2.4.G.2)**MOT #4** 2012-09-21 12:53**MOT test number** 566205362261**Result** ✓ Passed**MOT #3** 2011-09-15 13:01**MOT test number** 937798351246**Result** ✓ Passed**MOT #2** 2010-09-16 13:01**MOT test number** 804689850268**Result** ✓ Passed**MOT #1** 2009-09-17 12:22**MOT test number** 381610069260**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
25 March 2025

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	154
<b>MOT expiry date</b>	25 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	K
<b>Single payment (12 months)</b>	£ 395,00,-
<b>Single six month payment</b>	£ 217,25,-
<b>Total payable by 12 monthly instalments</b>	£ 414,75,-



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	<b>FL56AOH</b>
Plate since	2019-09-28
Current registration	<b>FL56AOH</b>
Plate since	2019-09-28

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2006-09-30
Last registration	2024-03-26
Complete history	<a href="#">See info</a>



Registration #1	2006-09-30	20 mi
Registration #2	2009-09-17	27.556 mi
Registration #3	2010-09-16	36.404 mi
Registration #4	2011-09-15	46.076 mi
Registration #5	2012-09-21	57.494 mi
Registration #6	2013-09-16	66.079 mi
Registration #7	2014-09-18	75.021 mi
Registration #8	2015-09-24	85.806 mi
Registration #9	2016-09-19	94.912 mi
Registration #10	2017-09-13	105.506 mi
Registration #11	2018-09-13	115.790 mi
Registration #12	2019-03-22	120.434 mi
Registration #13	2019-03-22	120.434 mi
Registration #14	2019-03-22	120.434 mi
Registration #15	2019-03-22	120.434 mi
Registration #16	2019-03-22	120.434 mi
Registration #17	2019-03-22	120.434 mi
Registration #18	2019-03-22	120.434 mi
Registration #19	2019-03-22	120.434 mi
Registration #20	2019-03-22	120.434 mi
Registration #21	2019-03-22	120.434 mi
Registration #22	2019-03-22	120.434 mi
Registration #23	2019-03-22	120.434 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1885 mm
Height	1805 mm
Length	4590 mm
Wheel base	2710 mm
Kerb weight	2079 kg
Max. allowed weight	2600 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5



Number of axles	2
Engine number	D4CB5840937