



Mercedes-Benz



report date: 2024-03-29

General information

Make	MERCEDES
Model	SPRINTER 313 CDI P/V
Colour	White
Year of manufacture	2004
Top speed	93 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	129 BHP
Max. torque	300 Nm at 1.600 rpm
Engine capacity	2.148 cc
Cylinders	4
Fuel type	Diesel





MOT history

MOT expiry date	2023-02-07
MOT pass rate	65 %
MOT passed	15
Failed MOT tests	8
Total advice items	81
Total items failed	35

MOT #23 2022-02-08 13:02

MOT test number 482072313053

Result ✓ Passed

Next expiry date 2023-02-07

Advice Nearside Front Headlamp has a product on the light source but not seriously reducing light output (4.1.4 (b))

Advice Nearside Front Driver door corroded

Advice Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #22 2022-02-08 13:02

MOT test number 498533025856

Result ✗ Failed

Advice Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

Advice Nearside Front Driver door corroded

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice Nearside Front Headlamp has a product on the light source but not seriously reducing light output (4.1.4 (b))

Pass with rectification Nearside Front Direction indicator not working (4.4.1 (a) (ii))

**MOT #21**

2021-02-05 15:38

MOT test number

170801134326

Result

✓ Passed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

MOT #20

2020-01-14 12:17

MOT test number

498542972646

Result

✓ Passed

- Advice** Front Lower Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Front Wing, Grill and Headlamp damaged.

**MOT #19**

2020-01-11 10:08

MOT test number

468396282138

Result

✗ Failed

Fail Rear Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))**Advice** Nearside Front Wing, Grill and Headlamp damaged.**Fail** Nearside Front Headlamp aim too low and too far to the right. Headlamp damaged. (4.1.2 (a))**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Nearside Rear Position lamp not working (4.2.1 (a) (ii))**Advice** Front Lower Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MOT #18**

2019-01-16 11:59

MOT test number

945221332997

Result

✓ Passed

Advice Front Bumper mountings corroded but not likely to become detached both (6.1.4 (a) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #17** 2019-01-16 11:59**MOT test number** 237566306440**Result** ✗ Failed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Pass with rectification** Offside Front Brake hose excessively twisted (1.1.12 (b) (ii))
- Advice** Front Bumper mountings corroded but not likely to become detached both (6.1.4 (a) (i))

MOT #16 2017-12-14 10:13**MOT test number** 770828320768**Result** ✓ Passed

- Advice** Nearside Front Play in steering rack inner joint(s)
- Advice** Nearside Front Seat belt damaged but not affecting the operation of the belt (5.2.2a)
- Advice** Nearside Front body damaged
- Advice** Offside Front Play in steering rack inner joint(s)
- Advice** Front Bumper insecure

**MOT #15**

2017-12-14 10:13

MOT test number

795424914993

Result**✗ Failed****Advice** Nearside Front Seat belt damaged but not affecting the operation of the belt (5.2.2a)**Pass with rectification** Nearside Front Windscreen wiper blade insecure (8.2.2)**Pass with rectification** Offside Rear Rear position lamp(s) not working (1.1.A.3b)**Advice** Offside Front Play in steering rack inner joint(s)**Advice** Front Bumper insecure**Advice** Nearside Front body damaged**Pass with rectification** Offside Rear Stop lamp not working (1.2.1b)**Advice** Nearside Front Play in steering rack inner joint(s)**MOT #14**

2017-01-09 10:48

MOT test number

799022125539

Result**✓ Passed****Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Front Body damaged**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Front Play in steering rack inner joint(s)

**MOT #13**

2017-01-09 10:48

MOT test number

966515749185

Result**✗ Failed****Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Pass with rectification** Offside Side repeater not working (1.4.A.2c)**Advice** Front Body damaged**Advice** Front Play in steering rack inner joint(s)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #12**

2015-12-31 11:13

MOT test number

106765865435

Result**✓ Passed****Advice** Offside Front Steering rack inner joint has slight play**Advice** Offside Front Headlamp deteriorated but light output not reduced (1.7.5a)**Advice** Nearside Front Steering rack inner joint has slight play**Advice** Nearside Front Headlamp deteriorated but light output not reduced (1.7.5a)

**MOT #11**

2015-12-21 12:31

MOT test number

604307770082

Result**✗ Failed**

- Fail** Exhaust has a major leak of exhaust gases (7.1.2)
- Fail** Rear Registration plate lamp not working (1.1.C.1d)
- Advice** Offside Front Headlamp deteriorated but light output not reduced (1.7.5a)
- Advice** Nearside Front Steering rack inner joint has slight play
- Fail** Exhaust noise is clearly in excess of that emitted by a similar vehicle fitted with a standard silencer in average condition (7.1.4)
- Fail** Front registration plate deteriorated (6.3.1d)
- Advice** Nearside Front Headlamp deteriorated but light output not reduced (1.7.5a)
- Fail** Nearside Side repeater excessively damaged so that it is not visible from a reasonable distance (1.4.A.2e)
- Advice** Offside Front Steering rack inner joint has slight play

MOT #10

2015-01-10 10:30

MOT test number

597920515072

Result**✓ Passed**

- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice** Nearside Front Seat belt cut but webbing not significantly weakened (5.2.2a)
- Notice** O/s/f locking mechanism cover missing
- Advice** Offside Front Direction indicator slightly discoloured (1.4.A.2f)



MOT #9

2015-01-10 10:30

MOT test number

205270915047

Result

✖ Failed

- Pass with rectification

Registration plate lamp not working (1.1.C.1d)
- Pass with rectification

Nearside Front position lamp(s) not working (1.1.A.3b)
- Advice

Front registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice

Nearside Front Seat belt cut but webbing not significantly weakened (5.2.2a)
- Pass with rectification

Nearside Front Direction indicator not working (1.4.A.2c)
- Pass with rectification

Nearside Stop lamp not working (1.2.1b)
- Pass with rectification

Offside Front position lamp(s) not working (1.1.A.3b)
- Notice

O/s/f locking mechanism cover missing
- Advice

Offside Front Direction indicator slightly discoloured (1.4.A.2f)

**MOT #8**

2014-01-06 17:30

MOT test number

529906904019

Result

✓ Passed

- Advice** Nearside Front Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)
- Advice** Offside Front Lower Front suspension ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)
- Advice** Centre Front registration plate delaminated but not likely to be misread (6.3.1d)
- Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Front Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)
- Notice** Play in steering rack inner joint(s)

MOT #7

2013-01-03 13:31

MOT test number

896663203083

Result

✓ Passed

- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #6

2012-01-03 19:00

MOT test number

889063902050

Result

✓ Passed

- Advice** Nearside Side repeater damaged, but still visible from a reasonable distance (1.4.A.2e)
- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)



MOT #5	2011-01-07 16:29
MOT test number	799237801073
Result	✓ Passed
Advice	Offside Front Direction indicators slightly discoloured (1.4.A.2f)

MOT #4	2010-01-06 17:19
MOT test number	800286900016
Result	✓ Passed

MOT #3	2010-01-05 12:12
MOT test number	233845600043
Result	✗ Failed
Fail	Offside Front Lower Anti-roll bar linkage has excessive play in a pin/bush (2.4.G.2)
Fail	Offside Front Shock absorber has negligible damping effect (2.7.5)
Fail	Offside Front Direction indicators incorrect colour (1.4.A.2f)
Fail	Parking brake lever has no reserve travel (3.1.6b)
Fail	Offside Front Suspension arm has excessive play in a ball joint (2.4.G.2)
Fail	Parking brake: efficiency below requirements (3.7.B.7)
Fail	Nearside Front Lower Anti-roll bar linkage has excessive play in a pin/bush (2.4.G.2)
Fail	Nearside Front Shock absorber has negligible damping effect (2.7.5)
Fail	Nearside Rear Shock absorber has an excessively worn bush (2.7.4)
Fail	Nearside Front Suspension arm has excessive play in a ball joint (2.4.G.2)
Fail	Nearside rear parking brake recording little or no effort (3.7.B.6a)
Fail	Nearside Front Upper Anti-roll bar linkage has excessive play in a pin/bush (2.4.G.2)



MOT #2	2009-01-02 17:12
MOT test number	801572809026
Result	✓ Passed
Advice	Rear Upper Shock absorber has a slightly worn bush (2.7.4)
Advice	Offside Front Suspension arm has slight play in a ball joint (2.4.G.2)
Advice	Nearside Front Suspension arm has slight play in a ball joint (2.4.G.2)

MOT #1	2007-09-13 14:04
MOT test number	533116957260
Result	✓ Passed
Notice	O/s front indicator bulb fade
Notice	O/s front bottom ball joint close to limit
Notice	Knock in steering
Notice	N/s front tyre worn close to limit



Tax & MOT check

✕
Untaxed

Tax expired:
25 April 2022

✕
MOT

Expired:
7 February 2023

Tax status	Expired at 25 April 2022
Days left	735 days too late
MOT expiry date	7 February 2023
Full MOT history	See MOT history



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	7
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2004-09-01
Last registration	2022-02-08
Complete history	See info



Registration #1	2004-09-01	20 mi
Registration #2	2007-09-13	89.076 mi
Registration #3	2009-01-02	96.127 mi
Registration #4	2010-01-05	106.286 mi
Registration #5	2010-01-06	106.286 mi
Registration #6	2011-01-07	117.495 mi
Registration #7	2012-01-03	129.311 mi
Registration #8	2013-01-03	142.683 mi
Registration #9	2014-01-06	159.636 mi
Registration #10	2015-01-10	171.832 mi
Registration #11	2015-12-21	181.675 mi
Registration #12	2015-12-31	182.069 mi
Registration #13	2016-01-01	182.069 mi
Registration #14	2016-01-02	182.069 mi
Registration #15	2016-01-03	182.069 mi
Registration #16	2016-01-04	182.069 mi
Registration #17	2016-01-05	182.069 mi
Registration #18	2016-01-06	182.069 mi
Registration #19	2016-01-07	182.069 mi
Registration #20	2016-01-08	182.069 mi
Registration #21	2016-01-09	182.069 mi
Registration #22	2016-01-10	182.069 mi
Registration #23	2016-01-11	182.069 mi

More info >



Additional information

Fuel tank capacity	75 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	3
Engine number	61198150923743