





General information

Make	VOLKSWAGEN
Model	CADDY C20 SWB VAN 104TDI
Colour	Silver
Year of manufacture	2007
Top speed	103 mph
0 - 60 mph	13.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	103 BHP
Max. torque	250 Nm at 1.900 rpm
Engine capacity	1.896 cc
Cylinders	4
Fuel type	Diesel







Internet history	
Entry 1	
Date	2021-07-30
Pictures	0
Listing price	View report

source: cargurus.co.uk



MOT history

MOT expiry date	2020-01-13
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	33
Total items failed	4

MOT #13	2019-01-14 08:33
MOT test number	807302205795
Result	✓ Passed
Next expiry date	2020-01-13
Minor Nearside Rear Registration plate lamp inoperative in the case of multiple (4.7.1 (b) (i))	lamps or light sources
Advice Nearside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice (i)) Rear Anti-roll bar pin or bush worn but not resulting in excessive movement both side (5.3.4 (a)	
Advice Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e)))
Advice Os and ns front rear suspension arm bushes slight wear.	
Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))	



MW56RVR report date: 2024-03-29

MOT #12	2019-01-11 18:24
MOT test number	347193878514
Result	🗙 Failed
Advice Os and ns front rear suspension arm bushes slight wear.	
Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))	
Advice Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamp (4.7.1 (b) (i))	os or light sources
Advice Rear Anti-roll bar pin or bush worn but not resulting in excessive movement I (i))	both side (5.3.4 (a)
Fail Windscreen washer provides insufficient washer liquid (3.5 (a))	
Advice Nearside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #11	2018-01-04 12:51
MOT test number	245205029452
Result	✓ Passed
Advice Nearside Front Suspension arm rubber bush deteriorated but not resulting in rear (2.4.G.2)	excessive movement
Advice Windscreen has a stone chip with in zone A	
Advice Nearside Front Shock absorber has slight corrosion to the casing (2.7.2a)	
Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in errear (2.4.G.2)	xcessive movement





MOT #10	2018-01-03 14:49
MOT test number	307383375638
Result	🗙 Failed
Advice Nearside Front Suspension arm rubber bush deteriorated but not resulting rear (2.4.G.2)	in excessive movement
Fail Nearside Rear Registration plate lamp not working (1.1.C.1d)	
Advice Windscreen has a stone chip with in zone A	
Advice Nearside Front Shock absorber has slight corrosion to the casing (2.7.2a)	
Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in rear (2.4.G.2)	excessive movement
Advice Nearside Rear slight brake bind	

MOT #9	2016-1	2-15 10:49
MOT test	number 5870	039538547
Result		✓ Passed
Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)	
Advice	Offside Rear Shock absorber has a light misting of oil (2.7.3)	

MOT #8		2016-01-13 14:17
MOT test	number	229306175854
Result		✓ Passed
Advice	Front Windscreen has damage to an area less than a 10mm circle within zone 'A	(8.3.1a)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Rear Exhaust has a minor leak of exhaust gases (7.1.2)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	



mws6RvR report date: 2024-03-29

MOT #7	2016-01-13 14:17
MOT test number	142416442842
Result	× Failed
Pass with rectification	Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
Advice Rear Exhaust ha	s a minor leak of exhaust gases (7.1.2)
Advice Offside Front Ty	e worn close to the legal limit (4.1.E.1)
Pass with rectification (8.2.2)	Nearside Front Windscreen wiper does not clear the windscreen effectively
Advice Front Windscree	n has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
Advice Nearside Front T	yre worn close to the legal limit (4.1.E.1)

MOT #6	2015-01-19 15:09
MOT test number	358989215086
Result	✓ Passed
MOT #5	2014-01-14 09:06
MOT test number	177234014410
Result	✓ Passed
MOT #4	2013-01-14 10:04
MOT test number	796314813044
Result	✓ Passed
MOT #3	2012-01-17 10:24
MOT test number	119987112063
Result	✓ Passed





MOT #2		2011-01-24 12:34
MOT test	number	728344421076
Result		✓ Passed
Advice (2.4.G.2)	Offside Rear Anti-roll bar rubber bush deteriorated but not resulting in e	excessive movement
Advice Nearside Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movemer (2.4.G.2)		n excessive movement
MOT #1		2010-02-04 12:39
MOT toot	number	101005520000

MOT test number 101895530000
Result ✓ Passed



MW56RVR report date: 2024-03-29

Tax & MOT check

X Untaxed	Х MOT
Tax expired: 6 November 2019	Expired: 13 January 2020
Tax status	Expired at 6 November 2019
Days left	1636 days too late
MOT expiry date	13 January 2020
Full MOT history	See MOT history





Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FE C
Category	Lame
Туре	
Damage 2	AMPLE
Damage 2	E E E E
Date	*
Category	AMP
Туре	

Extra VOLKSWAGEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.700
Auction value	4 10.000
Average private trade value	4 10 700

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	
Plate since	
Format maintration	
Carrient registration	
Parla since	





Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2007-02-13
Last registration	2019-01-14
Complete history	See info



Registration #1	2007-02-13	14 mi
Registration #2	2010-02-04	40.975 mi
Registration #3	2011-01-24	54.616 mi
Registration #4	2012-01-17	70.923 mi
Registration #5	2013-01-14	88.653 mi
Registration #6	2014-01-14	105.752 mi
Registration #7	2015-01-19	120.024 mi
Registration #8	2016-01-13	133.708 mi
Registration #9		11.707 mi
Registration #10		11.117 est
Registration #11		11.707 mi
Registration #12		11.777 esi
Registration #13		11.707 mi
Registration #14		11.777 esi
Registration #15		11.707 mi

More info \rightarrow





Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	2062 mm
Length	4405 mm
Additional information	
Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	3
Engine number	BLS 258417