



A057TWJ

report date: 2024-03-29

General information

Make	CITROEN
Model	DISPATCH 1000 L1H1 SWB P/V HDI 120
Colour	White
Year of manufacture	2007
Gearbox	6 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	300 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-09-14
Pictures	5
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-07-18
MOT pass rate	58 %
MOT passed	14
Failed MOT tests	10
Total advice items	107
Total items failed	16

MOT #24	2023-07-19 11:09
MOT test number	670760903178
Result	✓ Passed
Next expiry date	2024-07-18

MOT #23	2023-06-20 14:53
MOT test number	270243122210
Result	✗ Failed

DANGEROUS Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))

MAJOR Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

MAJOR Parking brake efficiency below requirements (1.4.2 (a) (i))

MAJOR Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

MAJOR Offside Integral body structure corroded to the extent that the rigidity of the assembly is significantly reduced Inner and outer sill holes (6.1.1 (c) (i))

DANGEROUS Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))

MAJOR Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

MAJOR Nearside Rear Position lamp not working (4.2.1 (a) (ii))

MAJOR Nearside Integral body structure corroded to the extent that the rigidity of the assembly is significantly reduced Inner and outer sill multiple holes (6.1.1 (c) (i))

**MOT #22**

2022-05-20 17:42

MOT test number

635883473694

Result

✓ Passed

- Advice** Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))
- Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
- Advice** Rear Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))
- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #21**

2022-05-19 13:03

MOT test number

578817705202

Result**✗ Failed****Advice** Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MAJOR** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))**Advice** Rear Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))**MAJOR** Nearside Outer Integral body structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting sill (6.2.2 (d) (i))**Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))**MAJOR** Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MAJOR** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**MAJOR** Offside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MAJOR** Nearside Rear Position lamp not working (4.2.1 (a) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MAJOR** Nearside Rear Body component damaged and likely to cause injury (6.2.1 (a) (i))**Advice** Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))**MAJOR** Front Anti-roll bar linkage ball joint excessively worn both (5.3.4 (a) (i))**Advice** Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))**MAJOR** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**MAJOR** Front Position lamp not working both (4.2.1 (a) (ii))

**MOT #20**

2022-05-18 11:42

MOT test number

585483560967

Result**✗ Failed****MAJOR** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MAJOR** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MAJOR** Hazard warning switch inoperative (4.4.2 (a) (ii))**Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))**MAJOR** Nearside Front Headlamp aim too low (4.1.2 (a))**MAJOR** Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MAJOR** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))**MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MAJOR** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**MAJOR** Nearside Rear Body component damaged and likely to cause injury light cluster (6.2.1 (a) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MAJOR** Nearside Rear Position lamp not working (4.2.1 (a) (ii))**Minor** Nearside Rear Rear fog lamp with a multiple light source up to 1/2 not functioning (4.5.1 (a) (i))**MAJOR** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Advice** Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MAJOR** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Oil added to carry out m.o.t

MAJOR Offside Front Headlamp aim too low (4.1.2 (a))

MAJOR Offside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

MAJOR Offside Rear Body component damaged and likely to cause injury (6.2.1 (a) (i))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))

MAJOR Offside Front Position lamp not working (4.2.1 (a) (ii))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))

MAJOR Nearside Integral body structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting sill (6.2.2 (d) (i))

DANGEROUS Offside Rear Outer Tyre has ply or cords exposed (5.2.3 (d) (ii))

**MOT #19** 2021-04-20 15:20**MOT test number** 698231437957**Result** ✓ Passed**MOT #18** 2021-04-20 15:20**MOT test number** 634013967692**Result** ✗ Failed**Pass with rectification** Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #17** 2020-05-05 11:48**MOT test number** 359923670033**Result** ✓ Passed**Advice** Nearside Service brake requirements only just met. It would appear that the braking system requires adjustment or repair (1.2.1 (c))**MOT #16** 2019-05-08 14:45**MOT test number** 100990947676**Result** ✓ Passed**Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**MOT #15** 2019-05-08 08:57**MOT test number** 720611155662**Result** ✗ Failed**MAJOR** Offside Front Anti-roll bar pin or bush excessively worn (5.3.4 (a) (i))**MAJOR** Nearside Front Anti-roll bar pin or bush excessively worn (5.3.4 (a) (i))**Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

**MOT #14** 2018-05-11 13:45**MOT test number** 424708920273**Result** ✓ Passed**Advice** Heavy undersealed in several places underside**MOT #13** 2017-04-20 12:34**MOT test number** 112308563234**Result** ✓ Passed**MOT #12** 2016-05-10 13:31**MOT test number** 672760361909**Result** ✓ Passed**Advice** O/s/r hand and foot brakes could be better**Advice** Front discs worn and pitted**Advice** Offside Front Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Advice** O/s/r brake binding**MOT #11** 2015-05-19 09:27**MOT test number** 517209135135**Result** ✓ Passed**Notice** Non obligatory mirror damaged

**MOT #10** 2015-05-13 12:23**MOT test number** 416533235141**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Non obligatory mirror damaged**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Offside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)**MOT #9** 2014-07-28 10:22**MOT test number** 697759804274**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Notice** N/s wiper blade starting to split**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Surface corrosion on sills/inner sills**Advice** Offside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**MOT #8** 2013-07-27 11:57**MOT test number** 606188303218**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)

**MOT #7** 2013-07-26 10:12**MOT test number** 679597703252**Result** ✗ Failed**Fail** Nearside Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Fail** Nearside rear brake recording little or no effort (3.7.B.5a)**Advice** Nearside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)**MOT #6** 2012-07-30 17:31**MOT test number** 239552712260**Result** ✓ Passed**Notice** Non obligatory mirror damaged**Notice** O/s wiper blade starting to split**MOT #5** 2012-07-30 12:06**MOT test number** 305662312282**Result** ✗ Failed**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Notice** Non obligatory mirror damaged**Fail** Offside rear parking brake recording little or no effort (3.7.B.6a)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Notice** O/s wiper blade starting to split



MOT #4	2011-07-20 14:39
MOT test number	338421701265
Result	✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Notice	Nearside front door mirror glass cracked not affecting view to rear

MOT #3	2011-07-20 13:14
MOT test number	737021901239
Result	✗ Failed
Pass with rectification	Nearside Rear Direction indicators incorrect colour (1.4.A.2f)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Notice	Nearside front door mirror glass cracked not affecting view to rear
Fail	Brake pedal anti-slip provision missing (3.3.A.1b)

MOT #2	2010-09-14 12:44
MOT test number	632547850260
Result	✓ Passed

MOT #1	2010-09-14 09:51
MOT test number	282937450293
Result	✗ Failed
Fail	Offside Rear Rear fog lamp not working (1.3.2b)
Advice	Offside Rear Brake pad(s) wearing thin (3.5.1g)
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Advice	Nearside Rear Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
18 July 2024

Tax status	Valid until 1 November
-------------------	------------------------

Days left	185
------------------	-----

MOT expiry date	18 July 2024
------------------------	--------------

Full MOT history	See MOT history
-------------------------	---------------------------------



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	0
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2007-09-22
Last registration	2023-07-19
Complete history	See info



Registration #1	2007-09-22	18 mi
Registration #2	2010-09-14	53.755 mi
Registration #3	2010-09-14	53.755 mi
Registration #4	2011-07-20	63.250 mi
Registration #5	2011-07-20	63.250 mi
Registration #6	2012-07-30	78.186 mi
Registration #7	2012-07-30	78.187 mi
Registration #8	2013-07-26	88.393 mi
Registration #9	2013-07-27	88.394 mi
Registration #10	2014-07-28	161.324 mi
Registration #11	2015-05-13	107.880 mi
Registration #12	2015-05-19	107.984 mi
Registration #13	2016-05-10	119.085 mi
Registration #14	2016-05-10	119.085 mi
Registration #15	2016-05-10	119.085 mi
Registration #16	2016-05-10	119.085 mi
Registration #17	2016-05-10	119.085 mi
Registration #18	2016-05-10	119.085 mi
Registration #19	2016-05-10	119.085 mi
Registration #20	2016-05-10	119.085 mi
Registration #21	2016-05-10	119.085 mi
Registration #22	2016-05-10	119.085 mi
Registration #23	2016-05-10	119.085 mi
Registration #24	2016-05-10	119.085 mi
Registration #25	2016-05-10	119.085 mi
Registration #26	2016-05-10	119.085 mi

More info >



Dimensions & weight

Width	2194 mm
Length	4805 mm

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	3
Engine number	DYUL4026007