



DY06KOH

report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	TOURAN TDI S 7 STR (90BHP)
Colour	Blue
Year of manufacture	-
Top speed	106 mph
0 - 60 mph	14.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	210 Nm at 1.800 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	47.1 mpg



**MOT history**

<b>MOT #18</b>	2020-06-30 14:32
<b>MOT test number</b>	428604534039
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2021-07-18
<b>Advice</b>	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

<b>MOT #17</b>	2019-06-22 15:59
<b>MOT test number</b>	881388335977
<b>Result</b>	✓ Passed
<b>Minor</b>	Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

<b>MOT #16</b>	2019-06-22 10:57
<b>MOT test number</b>	194851687298
<b>Result</b>	✗ Failed
<b>Advice</b>	Rear Brake disc worn, pitted or scored, but not seriously weakened Replacement Recommended! (1.1.14 (a) (ii))
<b>Fail</b>	Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
<b>Fail</b>	Brake performance not tested due to worn pads at rear! (1.2.1 (g))
<b>Advice</b>	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
<b>Minor</b>	Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
<b>Advice</b>	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
<b>Fail</b>	Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
<b>Fail</b>	Rear Exhaust emissions test not completed because smoke levels are significantly in excess of the specified limit values Diesel System cleaner Recommended! (8.2.2.2 (f))
<b>Fail</b>	Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))



MOT #152018-07-07 10:16

MOT test number415917993268

Result

✓ Passed

- Advice

Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Bush at front of arm (5.3.4 (a) (i))
- Advice

Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Bush at rear of arm (5.3.4 (a) (i))
- Advice

Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice

Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice

Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Bush at front of arm (5.3.4 (a) (i))
- Advice

Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Bush at rear of arm (5.3.4 (a) (i))
- Advice

Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

**MOT #14**

2018-07-06 13:00

**MOT test number**

935159007944

**Result**

✗ Failed

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Bush at rear of arm (5.3.4 (a) (i))

**Fail** Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

**Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Bush at front of arm (5.3.4 (a) (i))

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Bush at rear of arm (5.3.4 (a) (i))

**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Fail** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))

**Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Bush at front of arm (5.3.4 (a) (i))

**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #13**

2017-07-01 11:32

**MOT test number**

172705194446

**Result**

✓ Passed

**Advice** Nearside Front Lower Suspension arm has slight play in a pin/bush (2.4.G.2)

**Advice** Offside Front Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

**Advice** Offside Front Lower Suspension arm has slight play in a pin/bush (2.4.G.2)

**MOT #12**

2016-07-19 12:32

MOT test number

639456858866

Result

✔ Passed



<b>MOT #11</b>	2016-07-19 10:23
<b>MOT test number</b>	904628767360
<b>Result</b>	✗ Failed
<b>Fail</b>	Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)

<b>MOT #10</b>	2015-11-03 12:05
<b>MOT test number</b>	233873214836
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
<b>Advice</b>	Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
<b>Advice</b>	Rear seat(s) stowed not allowing full inspection of adult belt(s)
<b>Advice</b>	Nearside Front Lower Suspension arm has slight play in a pin/bush (2.4.G.2)

<b>MOT #9</b>	2014-11-21 17:04
<b>MOT test number</b>	866265524390
<b>Result</b>	✓ Passed
<b>Advice</b>	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
<b>Advice</b>	Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
<b>Advice</b>	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
<b>Advice</b>	Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

<b>MOT #8</b>	2014-03-01 10:35
<b>MOT test number</b>	146950464472
<b>Result</b>	✓ Passed

<b>MOT #7</b>	2013-03-15 09:34
<b>MOT test number</b>	447834373098
<b>Result</b>	✓ Passed

**MOT #6** 2012-03-03 12:18**MOT test number** 948943962020**Result** ✓ Passed**Advice** Nearside Side repeater damaged, but still visible from a reasonable distance (1.4.A.2e)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #5** 2012-03-03 10:25**MOT test number** 289483262093**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Side repeater damaged, but still visible from a reasonable distance (1.4.A.2e)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Rear passenger door cannot be opened from outside the vehicle (6.2.B.1c)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #4** 2011-03-17 15:24**MOT test number** 666606771050**Result** ✓ Passed**MOT #3** 2011-03-17 15:24**MOT test number** 999966071024**Result** ✗ Failed**Pass with rectification** Nearside Rear Rear position lamp(s) not working (1.1.A.3b)



MOT #2	2010-03-03 09:44
MOT test number	111622760493
Result	✓ Passed
Notice	Rear tyres worn on inner edges
Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT #1	2009-03-03 14:47
MOT test number	184502769477
Result	✓ Passed
Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)





Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>XXXX</b>
Plate since	2024-03-29
Current registration	 <b>XXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2006-03-31
Last registration	2020-06-30
Complete history	<a href="#">See info</a>



Registration #1	2006-03-31	10 mi
Registration #2	2009-03-03	30.084 mi
Registration #3	2010-03-03	39.225 mi
Registration #4	2011-03-17	45.342 mi
Registration #5	2012-03-03	50.385 mi
Registration #6	2012-03-03	50.385 mi
Registration #7	2013-03-15	57.801 mi
Registration #8	2014-03-01	64.225 mi
Registration #9	2014-11-21	69.219 mi
Registration #10	2015-03-03	75.217 mi
Registration #11	2015-03-03	75.217 mi
Registration #12	2015-03-03	75.217 mi
Registration #13	2015-03-03	75.217 mi
Registration #14	2015-03-03	75.217 mi
Registration #15	2015-03-03	75.217 mi
Registration #16	2015-03-03	75.217 mi
Registration #17	2015-03-03	75.217 mi
Registration #18	2015-03-03	75.217 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1794 mm
Height	1635 mm
Length	4407 mm
Wheel base	2678 mm
Max. allowed weight	2210 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Engine number

BRU 097436