



LR58RHJ

report date: 2024-03-29

General information

Make	CITROEN
Model	DISPATCH 1000 L1H1 SWB P/V HDI 90
Colour	White
Year of manufacture	2008
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	180 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-10-27
Pictures	6
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-03-21
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	25
Total items failed	13

MOT #172024-03-22 15:33

MOT test number589525468523

Result✓ Passed

Next expiry date2025-03-21

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #162023-03-20 14:45

MOT test number608271144980

Result✓ Passed

Advice Central Exhaust mounting defective (6.1.2 (a))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

MOT #152021-10-29 07:53

MOT test number684789156444

Result✓ Passed

Advice Oil leak, but not excessive (8.4.1 (a) (i))



MOT #14	2020-09-02 11:57
MOT test number	915228375987
Result	✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #13	2019-09-10 10:14
MOT test number	623171343084
Result	✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #12	2018-09-12 16:16
MOT test number	816199345013
Result	✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #11	2018-09-12 14:28
MOT test number	917469845982
Result	✗ Failed
Fail	Offside Headlamp aim too high (4.1.2 (a))
Fail	Central Exhaust silencer insecure (8.1.1 (b) (i))
Fail	Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps and offside (4.7.1 (b) (ii))
Fail	Nearside Position lamp not working (4.2.1 (a))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #10	2017-08-30 16:43
MOT test number	921624294632
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #9** 2016-09-03 09:55**MOT test number** 875511069170**Result** ✓ Passed**MOT #8** 2015-09-11 10:18**MOT test number** 995414762184**Result** ✓ Passed**MOT #7** 2014-08-30 10:51**MOT test number** 128632144214**Result** ✓ Passed**Advice** Nearside Front Suspension arm has slight play in a ball joint (2.4.G.2)**Notice** Number plate lamp internal bulb cover missing**Notice** Near side wiper blade worn**Notice** Near side front tyre outer side wall cut no cords visible**MOT #6** 2013-09-11 16:38**MOT test number** 466834953222**Result** ✓ Passed**Advice** Offside Front Suspension arm has slight play in a ball joint (2.4.G.2)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #5** 2013-09-11 16:38**MOT test number** 488034553255**Result** ✗ Failed**Pass with rectification** Offside Stop lamp not working (1.2.1b)**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Offside Front Suspension arm has slight play in a ball joint (2.4.G.2)**MOT #4** 2012-09-10 12:48**MOT test number** 866394052258**Result** ✓ Passed**Advice** Nearside Rear position lamp(s) damaged, but still visible from a reasonable distance (1.1.A.3d)**MOT #3** 2012-09-10 12:48**MOT test number** 307464052296**Result** ✗ Failed**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** Nearside Rear position lamp(s) damaged, but still visible from a reasonable distance (1.1.A.3d)**Pass with rectification** Centre Stop lamp not working (1.2.1b)**MOT #2** 2011-09-17 10:00**MOT test number** 477120761256**Result** ✓ Passed**Advice** Nearside Front Anti-roll bar rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Front Anti-roll bar rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)



MOT #12011-09-17 10:00

MOT test number428250161227

Result

Failed

Advice

Nearside Front Anti-roll bar rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)

Pass with rectification

Nearside Front Headlamp aim too high (1.8)

Pass with rectification

Nearside Rear Direction indicators not working (1.4.A.2c)

Advice

Offside Front Anti-roll bar rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)

Pass with rectification

Offside Front Headlamp aim too high (1.8)



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
21 March 2025

Tax status		Valid until 1 June
Days left		33
MOT expiry date		21 March 2025
Full MOT history		See MOT history



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	LR58RHJ
Plate since	2019-03-29
Current registration	LR58RHJ
Plate since	2019-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2008-09-17
Last registration	2024-03-22
Complete history	See info



Registration #1	2008-09-17	17 mi
Registration #2	2011-09-17	47.691 mi
Registration #3	2012-09-10	46.080 mi
Registration #4	2013-09-11	69.201 mi
Registration #5	2014-08-30	90.078 mi
Registration #6	2015-09-11	102.511 mi
Registration #7	2016-09-03	112.329 mi
Registration #8	2017-08-30	131.506 mi
Registration #9	2018-08-30	150.684 mi
Registration #10	2019-08-30	169.862 mi
Registration #11	2020-08-30	189.040 mi
Registration #12	2021-08-30	208.218 mi
Registration #13	2022-08-30	227.396 mi
Registration #14	2023-08-30	246.574 mi
Registration #15	2024-03-22	265.752 mi
Registration #16	2024-03-22	284.930 mi

More info >



Dimensions & weight

Width	2194 mm
Height	1942 mm
Length	4805 mm
Kerb weight	1661 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Engine number	JBAZ0006051