





General information

Make	VOLKSWAGEN
Model	POLO BLUEMOTION 2 TDI (80BHP)
Colour	Silver
Year of manufacture	-
Top speed	109 mph
0 - 60 mph	12.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	80 BHP
Max. torque	195 Nm at 1.800 rpm
Cylinders	3
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	83.1 mpg
Consumption combined	91.1 mpg



MOT history

MOT #13	2021-05-11 16:49
MOT test number	296573790381
Result	✓ Passed
Next expiry date	2022-05-10

MOT #12		2020-03-26 12:05
MOT test	number	708674611538
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge Wearing unevenly inn	ner edge. (5.2.3 (e))
Advice Nearside Front Tyre worn close to legal limit/worn on edge Inner edge is wearing unevenly. (5.2.3 (e))		
Advice perishing (Offside Rear Tyre slightly damaged/cracking or perishing Inner and outer edge (cracking) (5.2.3 (d) (ii))	showing signs of

MOT #11	2019-03-19 12:01
MOT test number	104066573037
Result	✓ Passed
Advice Both front tyres have low tread on the inner/outer edges	

MOT #10	2019-03-19 09:52
MOT test number	677636384291
Result	🗙 Failed
Fail Fuel system component leaking excessively or a risk of fire rear of engine (6.1.3 (b) (ii)) Advice Both front tyres have low tread on the inner/outer edges Fail Undertray likely to become detached (6.2.1 (a) (ii))	

MOT #9	2018-03-19 12:14
MOT test number	555778430813
Result	✓ Passed



MOT #8		2017-03-21 10:32
MOT test	number	110653803362
Result		✓ Passed
Advice	Offside front tyre has very low tread on the inner edge	
Advice	Nearside front tyre has low tread on the inner edge	

MOT #7	2016-03-18 16:19
MOT test number	721994263261
Result	✓ Passed

МОТ #6	2016-03-18 12:03
MOT test number	165210873894
Result	🗙 Failed
Fail Nearside Stop lamp not working (1.2.1b)	
Fail Rear Brakes imbalanced across an axle Axle 2 (3.7.B.5b)	
Fail Rear brake application uneven offside brake is slow to operate (3.7.B.2)	

MOT #5		2015-03-17 10:53
MOT test	number	897146275076
Result		✓ Passed
Advice (2.4.G.2)	Offside Front Suspension arm rubber bush deteriorated but not resultin	ng in excessive movement
Advice (2.4.G.2)	Nearside Front Suspension arm rubber bush deteriorated but not result	ing in excessive movement

МОТ #4	2014-03-24 14:28
MOT test number	176963284042
Result	✓ Passed

HJ08PZY report date: 2024-03-29



🗸 Passed



MOT #3	2013-03-26 11:54
MOT test number	599215183007
Result	✓ Passed
MOT #2	2012-03-27 13:59
MOT test number	875677982085
Result	✓ Passed
MOT #1	2011-03-22 14:57
MOT test number	127721881434

Result





Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FETO
Category	Lamp
Туре	
Damage 2	AMPLE
Damage 2	E CUT-S
Date	*
Category	AMPT
Туре	

Extra VOLKSWAGEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.700
Auction value	4 10.000
Average private trade value	4 10 700

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	
Plate since	
Format maintration	
Carrient registration	
Parla since	





Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2008-03-27
Last registration	2021-05-11
Complete history	<u>See info</u>



Registration #1	2008-03-27	20 mi
Registration #2	2011-03-22	14.052 mi
Registration #3	2012-03-27	18.334 mi
Registration #4	2013-03-26	24.730 mi
Registration #5	2014-03-24	32.703 mi
Registration #6	2015-03-17	40.251 mi
Registration #7	2016-03-18	45.831 mi
Registration #8		11.117 est
Registration #8 Registration #9		11.577 es
-		01.000 est 01.000 est 01.000 est
Registration #9		01.000 est 01.000 est 01.000 est 01.000 est
Registration #9 Registration #10		0.000 es
Registration #9 Registration #10 Registration #11		0.000 es 0.000 es 0.000 es 0.000 es 0.000 es 0.000 es

More info >





Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
60567	
50569	

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1650 mm
Height	1467 mm
Length	3916 mm
Wheel base	2466 mm
Kerb weight	1267 kg
Max. allowed weight	1550 kg
Additional information	
Fuel tank capacity	45
Fuel delivery	Direct Injection
Number of doors	3

Number of seats	5
Number of axles	2
Engine number	BMS026274