



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TOURAN TDI SE 5 STR
Colour	Black
Year of manufacture	2004
Top speed	110 mph
0 - 60 mph	13.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	99 BHP
Max. torque	250 Nm at 1.900 rpm
Engine capacity	1.896 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	47.1 mpg
CO2 emission	162 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-02-06
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2024-04-19
MOT pass rate	68 %
MOT passed	15
Failed MOT tests	7
Total advice items	75
Total items failed	25

MOT #22 2023-04-20 12:46

MOT test number 572466013589

Result ✓ Passed

Next expiry date 2024-04-19

Advice Offside Front Shock absorbers has light misting of oil (5.3.2 (b))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #21 2023-04-06 10:14

MOT test number 667649988151

Result ✗ Failed

Fail Nearside Front Shock absorbers has an excessively worn bush top mount (5.3.2 (c))

Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Front Shock absorbers has light misting of oil (5.3.2 (b))

MOT #20 2022-03-11 13:32

MOT test number 835440360993

Result ✓ Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Rear Coil spring corroded Both (5.3.1 (b) (i))

**MOT #19**

2022-03-08 14:49

MOT test number

501512788069

Result

✗ Failed

- Fail** Offside Rear Position lamp not working (4.2.1 (a) (ii))
- Fail** Nearside Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Fail** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))
- Fail** Nearside Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Fail** Brake performance not tested (1.2.1 (g))

MOT #18

2021-03-13 13:41

MOT test number

450233609790

Result

✓ Passed

- Advice** Rear Coil spring corroded both rear (5.3.1 (b) (i))
- Minor** Offside Front Headlamp lens slightly defective side mirror indicator lens (4.1.1 (b) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement lower arm front bush slight play (5.3.4 (a) (i))
- Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement both front lower arm rear bush (5.3.4 (a) (i))

**MOT #17**

2021-03-12 10:40

MOT test number

859976576844

Result**✗ Failed**

Advice Front Suspension arm pin or bush worn but not resulting in excessive movement both front lower arm rear bush (5.3.4 (a) (i))

Advice Rear Coil spring corroded both rear (5.3.1 (b) (i))

Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

Fail Brake servo defective or ineffective (1.1.10 (a) (i))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement lower arm front bush slight play (5.3.4 (a) (i))

Fail Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

Advice Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Minor Offside Front Headlamp lens slightly defective side mirror indicator lens (4.1.1 (b) (i))

MOT #16

2019-03-28 15:54

MOT test number

277591025055

Result**✓ Passed**

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Nearside Rear Tyre worn out of shape

**MOT #15**

2019-03-28 09:06

MOT test number

184505498167

Result**✗ Failed**

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Fail Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))

Fail Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Nearside Rear Tyre worn out of shape

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

Fail Offside Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #14

2018-04-04 14:20

MOT test number

670065008341

Result**✓ Passed**

Advice Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Both rear shockabsorbers in poor condtion

**MOT #13** 2018-04-04 08:51**MOT test number** 910528034031**Result** ✗ Failed**Fail** Offside Front Brake hose excessively deteriorated (3.6.B.4d)**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Both rear shockabsorbers in poor condtion**Fail** Nearside Front Brake hose excessively deteriorated (3.6.B.4d)**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #12** 2017-03-29 12:37**MOT test number** 207976436192**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #11** 2016-04-14 12:09**MOT test number** 625359188849**Result** ✓ Passed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Engine cover and undertrays fitted

**MOT #10**

2016-04-14 11:20

MOT test number

955920436847

Result

✗ Failed

- Advice** Engine cover and undertrays fitted
- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)
- Fail** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Offside Headlamp aim too low (1.8)

MOT #9

2015-04-01 16:51

MOT test number

337671995064

Result

✓ Passed

- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Notice** Under-trays fitted obscuring some underside components
- Advice** Offside Front Direction indicator slightly discoloured (1.4.A.2f)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (2.4.A.3)
- Advice** Offside Rear Suspension spring mounting prescribed area is corroded but not considered excessive (2.4.A.3)
- Advice** Offside Rear Subframe mounting prescribed area is corroded but not considered excessive (2.4.A.3)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Engine covers fitted obscuring some components in the engine bay
- Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (2.4.A.3)
- Advice** Offside Rear Seat belt flexible stalk damaged but not likely to lead to failure under load (5.2.4a)
- Advice** Nearside Rear Suspension spring mounting prescribed area is corroded but not considered excessive (2.4.A.3)
- Advice** Nearside Rear Subframe mounting prescribed area is corroded but not considered excessive (2.4.A.3)

**MOT #8**

2015-04-01 15:30

MOT test number

589511495078

Result**✗ Failed**

Advice Offside Rear Subframe mounting prescribed area is corroded but not considered excessive (2.4.A.3)

Fail Offside Front Upper Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Notice Under-trays fitted obscuring some underside components

Advice Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (2.4.A.3)

Fail Nearside Rear Direction indicator incorrect colour (1.4.A.2f)

Advice Offside Rear Seat belt flexible stalk damaged but not likely to lead to failure under load (5.2.4a)

Advice Nearside Rear Suspension spring mounting prescribed area is corroded but not considered excessive (2.4.A.3)

Pass with rectification Nearside Headlamp aim too high and too far to the right. (1.8)

Advice Nearside Rear Subframe mounting prescribed area is corroded but not considered excessive (2.4.A.3)

Fail Nearside Front Upper Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)

Advice Front Brake pad(s) wearing thin (3.5.1g)

Advice Offside Front Direction indicator slightly discoloured (1.4.A.2f)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Notice Engine covers fitted obscuring some components in the engine bay

Advice Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (2.4.A.3)

Fail Offside Rear Direction indicator incorrect colour (1.4.A.2f)

Advice Offside Rear Suspension spring mounting prescribed area is corroded but not considered excessive (2.4.A.3)

Pass with rectification Offside Headlamp aim too high (1.8)

**MOT #7** 2014-04-08 09:03**MOT test number** 799548494096**Result** ✓ Passed**MOT #6** 2013-04-11 08:47**MOT test number** 307461203141**Result** ✓ Passed**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #5** 2012-04-17 08:49**MOT test number** 895678002111**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2011-03-28 09:05**MOT test number** 366637581087**Result** ✓ Passed**Notice** Offside rear seat belt buckle outer trim missing - Still functions as intended.**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #3** 2010-04-07 09:17**MOT test number** 361467790096**Result** ✓ Passed**Notice** Nearside rear tyre slightly out of shape.



MOT #2	2009-03-18 09:09
MOT test number	813337379013
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2008-03-26 11:54
MOT test number	633696688074
Result	✓ Passed
Notice	Child seat fitted not allowing full inspection of adult belt
Notice	NEAR SIDE AND OFF SIDE FRONT TYRES WEARING ON INNER EDG.
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✕
Untaxed

Tax expired:
6 August 2023

✕
MOT

Expired:
19 April 2024

Tax status	Expired at 6 August 2023
Days left	266 days too late
MOT expiry date	19 April 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 HY54TWX
Plate since	2019-06-29
Current registration	 HY54TWX
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2004-09-01
Last registration	2023-04-20
Complete history	See info



Registration #1	2004-09-01	17 mi
Registration #2	2008-03-26	35.557 mi
Registration #3	2009-03-18	41.853 mi
Registration #4	2010-04-07	48.500 mi
Registration #5	2011-03-28	55.331 mi
Registration #6	2012-04-17	62.081 mi
Registration #7	2013-04-11	69.644 mi
Registration #8	2014-04-08	77.874 mi
Registration #9	2015-04-01	86.098 mi
Registration #10	2015-04-01	86.098 mi
Registration #11	2016-04-14	101.630 mi
Registration #12	2016-04-14	101.631 mi
Registration #13	2016-04-14	101.631 mi
Registration #14	2016-04-14	101.631 mi
Registration #15	2016-04-14	101.631 mi
Registration #16	2016-04-14	101.631 mi
Registration #17	2016-04-14	101.631 mi
Registration #18	2016-04-14	101.631 mi
Registration #19	2016-04-14	101.631 mi
Registration #20	2016-04-14	101.631 mi
Registration #21	2016-04-14	101.631 mi
Registration #22	2016-04-14	101.631 mi
Registration #23	2016-04-14	101.631 mi
Registration #24	2016-04-14	101.631 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2066 mm
Height	1635 mm
Length	4391 mm
Wheel base	2677 mm
Kerb weight	1498 kg
Max. allowed weight	2160 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Engine number	AVQ 050944