



Mercedes-Benz

TOK938Y

report date: 2024-03-29

General information

Make	MERCEDES
Model	300 TE-24
Colour	Brown
Year of manufacture	1989
Top speed	139 mph
Gearbox	4 speed automatic

Engine & fuel consumption

Power	231 BHP
Max. torque	135 Nm at 4.600 rpm
Engine capacity	2.962 cc
Cylinders	6
Fuel type	Petrol



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-25
Pictures	10
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2021-11-03
MOT pass rate	56 %
MOT passed	15
Failed MOT tests	12
Total advice items	76
Total items failed	25

MOT #27	2020-10-15 08:54
MOT test number	638760479121
Result	✓ Passed
Next expiry date	2021-11-03
Advice	Front suspension arm bushes perished but no excessive movement
Advice	Both front suspension strut boots split deteriorated

MOT #26	2020-10-15 08:54
MOT test number	758525450364
Result	✗ Failed
Advice	Both front suspension strut boots split deteriorated
Pass with rectification	Nearside Front Headlamp aim too low (4.1.2 (a))
Advice	Front suspension arm bushes perished but no excessive movement
Pass with rectification	Nearside Front Headlamp levelling device inoperative (4.1.5 (a))

MOT #25	2019-10-29 11:31
MOT test number	580874691622
Result	✓ Passed

**MOT #24** 2019-10-10 09:04**MOT test number** 769289491841**Result** ✗ Failed**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**MOT #23** 2018-10-10 11:56**MOT test number** 624478803879**Result** ✓ Passed**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #22** 2018-10-10 09:18**MOT test number** 963579409602**Result** ✗ Failed**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Fail** Offside Side repeater not working (4.4.1 (a) (ii))**MOT #21** 2017-10-20 10:51**MOT test number** 492527239399**Result** ✓ Passed**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**Advice** Both rear shock absorber top bushes perished slightly**Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)

**MOT #20**

2017-10-19 11:20

MOT test number

350535069996

Result**✗ Failed**

- Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)
- Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)
- Advice** Both rear shock absorber top bushes perished slightly
- Fail** Exhaust emissions carbon monoxide content excessive (7.3.B.1a)

MOT #19

2016-11-04 11:57

MOT test number

144070759755

Result**✓ Passed**

- Advice** Light corrosion on front brake pipes
- Advice** Coolant leak Radiator

MOT #18

2016-05-18 10:26

MOT test number

615426417798

Result**✗ Failed**

- Advice** Nearside Front Front wheel bearing has slight play (2.5.A.3c)
- Advice** Nearside Rear Fluid suspension unit interconnecting pipe corroded but not seriously weakened (2.4.D.3)
- Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)
- Advice** Offside Rear coil spring corroded (2.4.C.1b)
- Advice** Nearside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)
- Advice** Offside Rear Fluid suspension unit interconnecting pipe corroded but not seriously weakened (2.4.D.3)
- Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)
- Fail** Nearside Rear coil spring broken (2.4.C.1a)

**MOT #17**

2015-05-07 17:02

MOT test number

516987725176

Result

✓ Passed

- Advice** Offside Rear Fluid suspension unit interconnecting pipe corroded but not seriously weakened (2.4.D.3)
- Advice** Nearside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)
- Advice** Offside Front Macpherson strut has slight play in the sliding bush or gland (2.5.B.1b)
- Advice** Nearside Rear Fluid suspension unit interconnecting pipe corroded but not seriously weakened (2.4.D.3)
- Advice** Power steering pipe(s) or hose(s) has slight seepage (2.3.3b)
- Advice** Nearside Front Macpherson strut has slight play in the sliding bush or gland (2.5.B.1b)

MOT #16

2015-05-07 17:02

MOT test number

259937725405

Result

✗ Failed

- Advice** Offside Front Macpherson strut has slight play in the sliding bush or gland (2.5.B.1b)
- Pass with rectification** Exhaust emissions carbon monoxide content excessive (7.3.B.1a)
- Advice** Nearside Rear Fluid suspension unit interconnecting pipe corroded but not seriously weakened (2.4.D.3)
- Advice** Power steering pipe(s) or hose(s) has slight seepage (2.3.3b)
- Advice** Nearside Front Macpherson strut has slight play in the sliding bush or gland (2.5.B.1b)
- Pass with rectification** Rear fog lamp tell tale not working (1.3.1b)
- Advice** Offside Rear Fluid suspension unit interconnecting pipe corroded but not seriously weakened (2.4.D.3)
- Advice** Nearside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)

**MOT #15**

2014-03-14 13:07

MOT test number

199853974047

Result

✓ Passed

- Notice** Under-trays fitted obscuring some underside components
- Advice** Nearside Front Upper Shock absorber has a slightly worn bush (2.7.4)
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Front wheel bearing has slight play (2.5.A.3c)
- Advice** Offside Front Upper Shock absorber has a slightly worn bush (2.7.4)
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Offside Front wheel bearing has slight play (2.5.A.3c)

MOT #14

2014-03-06 12:08

MOT test number

779145664036

Result

✗ Failed

- Fail** Offside Outer Rear Anti-roll bar has excessive play in a pin/bush (2.4.G.2)
- Fail** Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)
- Advice** Offside Front Upper Shock absorber has a slightly worn bush (2.7.4)
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Fail** Nearside Outer Front Anti-roll bar has excessive play in a pin/bush (2.4.G.2)
- Advice** Offside Front wheel bearing has slight play (2.5.A.3c)
- Fail** Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)
- Notice** Under-trays fitted obscuring some underside components
- Advice** Nearside Front Upper Shock absorber has a slightly worn bush (2.7.4)
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Front wheel bearing has slight play (2.5.A.3c)

**MOT #13**

2013-03-18 16:25

MOT test number

525537173079

Result

✓ Passed

Advice Nearside Front Lower Anti-roll bar has slight play in a pin/bush (2.4.G.2)**Advice** Offside Front Lower Anti-roll bar has slight play in a pin/bush (2.4.G.2)**MOT #12**

2012-02-23 11:16

MOT test number

109624852043

Result

✓ Passed

Notice Some corrosion of rear self-levelling suspension pipes.**Advice** Nearside Front Lower Front suspension has slight movement at a suspension ball joint (2.5.A.1c)**Advice** Steering damper slight oil seepage (2.2.C.1f)**Advice** Power steering pipe(s) or hose(s) has slight seepage from a joint (2.3.3b)**MOT #11**

2011-02-08 15:26

MOT test number

419809231009

Result

✓ Passed

Notice Slight laminar corrosion front lower suspension arm prescribed areas.**Advice** Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)**Notice** Slight coolant leak top of radiator.**Notice** Slight oil leak rear differential.**Notice** Some corrosion of rear self levelling suspension pipes.**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**MOT #10** 2011-02-04 16:52**MOT test number** 165805931046**Result** ✗ Failed**Fail** Rear Exhaust has a major leak of exhaust gases (7.1.2)**Notice** Slight oil leak rear differential.**Advice** Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)**Notice** Slight coolant leak top of radiator.**Notice** Some corrosion of rear self levelling suspension pipes.**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Notice** Slight laminar corrosion front lower suspension arm prescribed areas.**MOT #9** 2010-02-18 12:08**MOT test number** 243759340089**Result** ✓ Passed**MOT #8** 2010-02-15 14:55**MOT test number** 120756340475**Result** ✗ Failed**Notice** Rust offside inner wing**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Fail** Registration plate fitted to the front does not have black characters on a white background (6.3.2a)**Notice** Rear number plate poor**MOT #7** 2009-02-23 15:39**MOT test number** 333244359053**Result** ✓ Passed**Notice** Connecting pipes to self-levelling shock absorbers corroded.

**MOT #6** 2009-02-20 14:50**MOT test number** 114061959084**Result** ✗ Failed**Fail** Offside Rear Brake hose ferrule excessively corroded (3.6.B.4e)**Fail** Nearside Rear Brake hose ferrule excessively corroded (3.6.B.4e)**Notice** Connecting pipes to self-levelling shock absorbers corroded.**Pass with rectification** Nearside Headlamp aim too far to the right (1.8)**MOT #5** 2008-02-20 17:43**MOT test number** 424721658083**Result** ✓ Passed**MOT #4** 2008-02-15 13:04**MOT test number** 461466448052**Result** ✗ Failed**Notice** FRONT WIPER BLADE STARTING TO SPLIT**Fail** Nearside Front Brake hose bulging under pressure (3.6.B.3)**Fail** Exhaust emissions carbon monoxide content excessive (7.3.B.1a)**Fail** Nearside Front Brake hose leaking (3.6.A.1)**Notice** REAR WIPER BLADE POOR**Fail** Offside Front Brake hose bulging under pressure (3.6.B.3)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #3** 2007-02-15 18:05**MOT test number** 173496247076**Result** ✓ Passed



MOT #2	2007-02-07 14:45
MOT test number	263678137067
Result	✗ Failed
Fail	Parking brake: efficiency below requirements (3.7.D.4)
Fail	Parking brake lever has no reserve travel (3.1.6b)
Fail	Offside Parking brake recording little or no effort (3.7.D.3a)
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
Notice	OFFSIDE REAR TYRE 2.7MM NEARSIDE REAR TYRE 2.1MM 1956515V MICHELIN PILOT
Fail	Nearside Parking brake recording little or no effort (3.7.D.3a)

MOT #1	2006-02-13 16:22
MOT test number	201964846075
Result	✓ Passed
Notice	NEARSIDE REAR TYRE 3.4MM OFFSIDE REAR TYRE 3.8MM FRONT NUMBER PLATE CRACKED 2 STEERING STOP CAPS SPLIT NEARSIDE HANDBRAKE EFFORT JUST IN LIMIT



Tax & MOT check

✕
Untaxed

Tax expired:
27 June 2021

✕
MOT

Expired:
3 November 2021

Tax status	Expired at 27 June 2021
Days left	1037 days too late
MOT expiry date	3 November 2021
Full MOT history	See MOT history



Damage history


Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	 TOK938Y
Plate since	2024-03-29
Current registration	 TOK938Y
Plate since	2024-03-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	28
First mileage registration	1989-12-31
Last registration	2020-10-15
Complete history	See info



Registration #1	1989-12-31	29 mi
Registration #2	2006-02-13	153.902 mi
Registration #3	2007-02-07	161.371 mi
Registration #4	2007-02-15	161.371 mi
Registration #5	2008-02-15	165.863 mi
Registration #6	2008-02-20	165.900 mi
Registration #7	2009-02-20	167.345 mi
Registration #8	2009-02-23	167.353 mi
Registration #9	2010-02-15	168.768 mi
Registration #10	2010-02-18	168.788 mi
Registration #11	2011-02-04	170.769 mi
Registration #12	2011-02-08	170.769 mi
Registration #13	2012-02-23	172.381 mi
Registration #14	2013-03-18	173.995 mi
Registration #15	2014-03-20	175.510 mi
Registration #16	2015-03-20	177.025 mi
Registration #17	2016-03-20	178.540 mi
Registration #18	2017-03-20	180.055 mi
Registration #19	2018-03-20	181.570 mi
Registration #20	2019-03-20	183.085 mi
Registration #21	2020-03-20	184.600 mi
Registration #22	2021-03-20	186.115 mi
Registration #23	2022-03-20	187.630 mi
Registration #24	2023-03-20	189.145 mi
Registration #25	2024-03-20	190.660 mi
Registration #26	2025-03-20	192.175 mi

Registration #27	2025-05-20	25,000,000
Registration #28	2025-05-20	25,000,000

More info >



Dimensions & weight

Width	1884 mm
Height	1490 mm
Length	4765 mm

Additional information

Engine number	10398322181787
---------------	----------------