





## General information

Make	PEUGEOT
Model	307 ZEST
Colour	Silver
Year of manufacture	-
Top speed	107 mph
0 - 60 mph	12.8 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	90 BHP
Max. torque	133 Nm at 3.250 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	53.3 mpg
Consumption combined	43.5 mpg





## Internet history

Entry 1

Date

2021-12-17

8

Pictures

Listing price

View report



source: autotrader.co.uk



## MOT history

MOT #24	2022-01-20 18:24
MOT test number	739004359372
Result	✓ Passed
Next expiry date	2023-01-31
<b>Advice</b> Rear Service brake requirements only just met. It would appear that the braking adjustment or repair (1.2.1 (c))	g system requires
Minor Nearside Front Battery insecure but not likely to fall from carrier (4.13 (a) (i))	
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (	(ii))
Advice Rear Engine mounting damaged but not to excess yellow marked (6.1.8 (a) (i))	
Advice Play in steering rack inner joint(s)	
<b>Minor</b> Offside Rear Registration plate lamp inoperative in the case of multiple lamps or (4.7.1 (b) (i))	light sources
Advice Oil leak, but not excessive (8.4.1 (a) (i))	



**MOT #23** 2022-01-18 11:38 **MOT test number** 110152983105 Result × Failed **Advice** Play in steering rack inner joint(s) Fail Nearside Front Direction indicator not working (4.4.1 (a) (ii)) Nearside Front Battery insecure but not likely to fall from carrier (4.13 (a) (i)) Minor **Advice** Rear Engine mounting damaged but not to excess yellow marked (6.1.8 (a) (i)) Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c)) Fail Fail Nearside Front Headlamp insecure (4.1.1 (c)) Advice Rear Service brake requirements only just met. It would appear that the braking system requires adjustment or repair (1.2.1 (c)) Fail Nearside Rear Position lamp not working (4.2.1 (a) (ii)) Fail Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt both front upper (5.3.4 (b) (ii)) Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) Fail Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i)) Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Fail Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b)) **Advice** Oil leak, but not excessive (8.4.1 (a) (i))

W53YRV

report date: 2024-03-29



MOT #22

Result

Advice

**MOT test number** 

CAR CHECK	KW53YRV	
	report date: 2024-03-29	
	2021-02-01 17:13	
number	913264176689	
	✓ Passed	
Oil leak, but not excessive (8.4.1 (a) (i))		

Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
--------	--

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice	Nearside Front Headlamp secured by tie raps
Advice	Play in steering rack inner joint(s)
Minor	Front Anti-roll bar linkage ball joint dust cover severely deteriorated Both sides (5.3.4 (b) (i))
Advice system re	Rear Service brake imbalance requirements only just met. It would appear that the braking equires adjustment or repair. (1.2.1 (b) (i))
Advice	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Minor	Battery insecure but not likely to fall from carrier (4.13 (a) (i))
Advice	Nearside Front Indicator stalk slightly flimsy



<b>KW53</b>	YRV
report date:	2024-03-29

MOT #21	2	021-02-01 13:46
MOT test	number	862029546817
Result		🗙 Failed
Advice	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Minor	Battery insecure but not likely to fall from carrier (4.13 (a) (i))	
Advice	Nearside Front Headlamp secured by tie raps	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
<b>Minor</b> (4.7.1 (b)	Offside Rear Registration plate lamp inoperative in the case of multiple lamps or ligh (i))	nt sources
<b>Fail</b> R	Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
Minor	Front Anti-roll bar linkage ball joint dust cover severely deteriorated Both sides (5.3.	4 (b) (i))
Advice	Nearside Front Indicator stalk slightly flimsy	
Advice	Play in steering rack inner joint(s)	
Advice system re	Rear Service brake imbalance requirements only just met. It would appear that the equires adjustment or repair. (1.2.1 (b) (i))	braking

MOT #20		2019-11-05 19:40
MOT test	number	394260861757
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Lower Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	



**KW53YRV** report date: 2024-03-29

MOT #19		2019-11-05 19:40
MOT test number		823412904999
Result		🗙 Failed
Advice Nearside Rear B	rake pad(s) wearing thin (1.1.13 (a) (ii))	
Pass with rectification	Offside Rear Registration plate lamp inoperative in the	e case of a single lamp or
all lamps (4.7.1 (b) (ii))		
Advice Oil leak, but not	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice Offside Front Ty	vice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))		
Pass with rectification	Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))	
Advice Offside Front Lo	wer Anti-roll bar linkage ball joint has slight play (5.3.4	(a) (i))
Advice Nearside Front	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #18	2018-11-05 18:15
MOT test	<b>number</b> 630576608379
Result	✓ Passed
<b>Minor</b> (4.7.1 (b)	Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (i))
<b>Advice</b> (a) (i))	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4
Advice	Front Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Upper Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice	Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))



**KW53YRV** report date: 2024-03-29

MOT #17	2017-04-15 14:14
MOT test number	940128239361
Result	✓ Passed
Advice Front Tyre worn close to the legal limit nsf osf (4.1.E.1)	
Advice Various parts of body corroded has not weakened structure.	

MOT #16		2017-04-15 14:14
MOT test number		871177365629
Result		🗙 Failed
Advice Front Tyre worn	close to the legal limit nsf osf (4.1.E.1)	
Pass with rectification	Front Headlamp aim beam image obviously incorrect (1.8.A.1b)	1
Advice Various parts of	body corroded has not weakened structure.	

MOT #15		2016-04-22 10:36
MOT test	number	486794310860
Result		✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Rear Tyre worn close to the legal limit both (4.1.E.1)	

MOT #14		2015-03-01 17:46
MOT test	number	106980965488
Result		✓ Passed
Advice	Offside Front Anti-roll bar has slight play in a ball joint (2.4.G.2)	
Notice	Play in steering rack inner joint(s)	
Advice	Brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Notice	Engine covers fitted obscuring some components in the engine bay	
Advice	Brake pad(s) wearing thin (3.5.1g)	



**KW53YRV** report date: 2024-03-29

MOT #13	2015-03-01 17:46
MOT test number	697000665098
Result	× Failed
<b>Pass with rectification</b> Front position lamp(s) not working (1.1.A.3b)	
<b>Notice</b> Play in steering rack inner joint(s)	
Advice Brake pad(s) wearing thin (3.5.1g)	
Advice Offside Front Anti-roll bar has slight play in a ball joint (2.4.G.2)	
<b>Notice</b> Engine covers fitted obscuring some components in the engine bay	
Pass with rectificationNearside Rear Stop lamp not working (1.2.1b)	
Advice Brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	

MOT #12		2014-03-08 16:58
MOT test	number	389797764037
Result		✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #11	2014-03-08 16:58
MOT test number	179817164086
Result	🗙 Failed
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice Rear Tyre worn close to the legal limit (4.1.E.1)	
Pass with rectificationOffside Front Front position lamp(s) not working (1.1.A.3b)	
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	





MOT #10	2013-03-06 16:4	5
MOT test I	number 51521556304	3
Result	✓ Passe	d
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Advice	Nearside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)	
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	

МОТ #9	2012-01-20 09:57
MOT test number	366890922025
Result	✓ Passed
Notice Oil leak	

МОТ #8		2012-01-17 11:55
MOT test number		655307412087
Result		🗙 Failed
Pass with rectification	Registration plate lamp not illuminating the registration p	late (1.1.C.1e)
Fail Offside Rear Tyre t	read depth below requirements of 1.6mm (4.1.E.1)	
Notice Oil leak		
<b>Advice</b> Offside Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)		
Pass with rectification	Registration plate lamp not working (1.1.C.1d)	
Advice Nearside Front	Tyre worn close to the legal limit (4.1.E.1)	
Notice Non obligatory r	nirror damaged	





MOT #7	2010-11-23 14:36
MOT test number	692267020310
Result	Passed
AdviceOffside Rear Tyre worn close to the legal limit (4.1.E.1)NoticeNearside door mirror loose	
MOT #6	2010-11-22 14:40

# MOT #6

MOT test number	320926020325
Result	🗙 Failed
Notice Nearside door mirror loose	
<b>Fail</b> Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)	
Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Fail Rear Rear fog lamp not working (1.3.2b)	
<b>Fail</b> Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)	

MOT #5		2009-11-27 17:11
MOT test	number	442771539307
Result		✓ Passed
Advice	Rear Brake pad(s) wearing thin (3.5.1g)	
MOT #4		2009-01-19 14:56

MOT test	number	861009619095
Result		✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Advice	Rear Brake pad(s) wearing thin (3.5.1g)	



	report date: 2024-03-29
MOT #3	2009-01-15 10:28
MOT test number	691515519071
Result	🗙 Failed
<b>Fail</b> Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)	
FailOffside Front position lamp(s) not working (1.1.A.3b)	
Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1	i)
Fail Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)	
Fail Nearside Headlamp aim too high (1.8)	
Advice Rear Brake pad(s) wearing thin (3.5.1g)	

МОТ #2	2007-11-20 15:24
MOT test number	623294427308
Result	Passed
<b>Notice</b> Child seat fitted not allowing full inspection of adult belt	

MOT #1	2006-12-05 15:33
MOT test number	322349436392
Result	✓ Passed

**KW53YRV** 





#### Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <u>here</u> for the results.

Lawe
AMPL
AMP

#### Extra PEUGEOT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	6.00.000
Auction value	4 10.000
Average private trade value	4 11 711





## Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

******	
**********	
*******	
******	
**********	
*******	
	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Current registration	
Plate since	





#### Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





## Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2004-02-09
Last registration	2022-01-20
Complete history	See info



Registration #1	2004-02-09	19 mi
Registration #2	2006-12-05	39.284 mi
Registration #3	2007-11-20	49.847 mi
Registration #4	2009-01-15	58.601 mi
Registration #5	2009-01-19	58.680 mi
Registration #6	2009-11-27	66.972 mi
Registration #7	2010-11-22	75.101 mi
Registration #8	2010-11-23	75.142 mi
Registration #9	2012-01-17	82.904 mi
Registration #10	2012-01-20	82.927 mi
Registration #11	2013-03-06	91.373 mi
Registration #12	2014-03-08	100.014 mi
Registration #13		11.777 esi
Registration #14		11.777 est
Registration #15		11.227 est
Registration #15 Registration #16		10.207 est
		11.777 est 11.777 est 11.777 est
Registration #16		10.202 est 10.202 est 10.202 est 10.202 est
Registration #16 Registration #17		11.777 es 11.777 es 11.777 es 11.777 es 11.777 es
Registration #16 Registration #17 Registration #18		00.000 est 0.000 est 0.000 est 0.000 est 0.000 est 0.000 est
Registration #16 Registration #17 Registration #18 Registration #19		00.000 est 0.000 est 0.000 est 0.000 est 0.000 est 0.000 est 0.000 est
Registration #16 Registration #17 Registration #18 Registration #19 Registration #20		10.202 est 0.202 est 0.202 est 0.202 est 0.202 est 0.202 est 0.202 est
Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21		10.000 est 10.000
Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #22		10.000 est 10.000

More info >





### Car features

S0225	Air conditioning
\$0295	
50482	
S0501	
\$0566	
\$0567	
S0569	

## Safety ratings

Number of seats CarCheck.co.uk

**NCAP** rating

Video

see crash video



Dimensions & weight	
Width	1746 mm
Height	1512 mm
Length	4202 mm
Wheel base	2608 mm
Kerb weight	1170 kg
Max. allowed weight	1639 kg
Additional information	
Fuel tank capacity	60 I
Fuel delivery	Multi-Point Injection
Number of doors	5

5

page 18/18