



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TRANSPORTER T28 SWB PBV P/V 102TDI
Colour	White
Year of manufacture	2009
Gearbox	5 speed Manual

Engine & fuel consumption

Power	101 BHP
Max. torque	250 Nm at 2.000 rpm
Engine capacity	1.896 cc
Cylinders	4
Fuel type	Diesel
Consumption city	28.0 mpg
Consumption extra urban	40.9 mpg
Consumption combined	40.9 mpg



LABEL UNKNOWN



Internet history

Entry 2

Date	2022-06-18
Pictures	0
Listing price	View report

source: cargurus.co.uk

Entry 1

Date	2021-07-31
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-07-23
MOT pass rate	63 %
MOT passed	12
Failed MOT tests	7
Total advice items	46
Total items failed	17

MOT #192023-07-24 09:03

MOT test number812949875328

Result✓ Passed

Next expiry date2024-07-23

- Advice

Underside of van rusty
- Advice

Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
- Minor

Nearside Front Windscreen damaged but not adversely affecting driver's view lower corner (3.2 (a) (i))
- Advice

Offside Rear Shock absorbers has slight external damage to the casing (5.3.2 (b))
- Advice

Nearside Rear Shock absorbers has slight external damage to the casing (5.3.2 (b))
- Minor

Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice

Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #18**

2023-07-17 13:13

MOT test number

194848297255

Result

✗ Failed

- Advice** Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
- Advice** Offside Rear Shock absorbers has slight external damage to the casing (5.3.2 (b))
- Minor** Nearside Front Windscreen damaged but not adversely affecting driver's view lower corner (3.2 (a) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Rear Shock absorbers has slight external damage to the casing (5.3.2 (b))
- Advice** Underside of van rusty
- Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Fail** Nearside Front Subframe mounting prescribed area excessively corroded significantly reducing structural strength (5.3.6 (a) (i))
- Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #17

2022-07-15 10:41

MOT test number

772985756846

Result

✓ Passed

- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #16

2021-07-13 16:11

MOT test number

627620931945

Result

✓ Passed

- Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #15**

2021-07-13 08:35

MOT test number

970677158383

Result**✗ Failed**

Fail Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Minor Nearside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #14

2020-07-08 08:39

MOT test number

495308287655

Result**✓ Passed**

Advice Oil leak, but not excessive (8.4.1 (a) (i))

MOT #13

2020-07-07 11:22

MOT test number

957020250868

Result**✗ Failed**

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Fail Offside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))

Advice Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Fail Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #12

2019-07-06 08:52

MOT test number

179383825019

Result**✓ Passed**

Advice Oil leak, but not excessive engine (8.4.1 (a) (i))

Minor Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #11** 2018-07-16 13:05**MOT test number** 291899144603**Result** ✓ Passed**Advice** Undertrays fitted obscuring some components.**MOT #10** 2018-07-14 08:48**MOT test number** 854943555316**Result** ✗ Failed**Fail** Nearside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Undertrays fitted obscuring some components.**Fail** Nearside Front Position lamp not working (4.2.1 (a))**Fail** Offside Rear Brake pipe excessively corroded (1.1.11 (c))**MOT #9** 2017-07-15 08:40**MOT test number** 563008509154**Result** ✓ Passed**Advice** Brake pipes obscured by fuel tank**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #8** 2016-07-23 10:02**MOT test number** 418422124802**Result** ✓ Passed**Advice** Under trays fitted obscuring some components

**MOT #7**

2015-07-22 10:28

MOT test number

437293205227

Result

✓ Passed

- Notice** Nail in nearside rear tyre
- Notice** Engine covers fitted obscuring some components in the engine bay
- Notice** Under-trays fitted obscuring some underside components
- Notice** Vehicle's internal headlight adjuster altered to recheck lights

MOT #6

2014-07-19 10:54

MOT test number

868560504266

Result

✓ Passed

- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** Vehicle's internal headlight adjuster altered to recheck lights
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Advice** Nearside Front Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)

MOT #5

2014-07-19 10:31

MOT test number

568420204249

Result

✗ Failed

- Fail** Nearside Seat belt affected by an insecure seat fixing (5.2.1b)
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Advice** Nearside Front Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)
- Fail** Exhaust emits an excessive level of metered smoke (7.4.B.3a)
- Fail** Nearside Front position lamp(s) not working (1.1.A.3b)
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** Vehicle's internal headlight adjuster altered to recheck lights

**MOT #4** 2013-07-23 12:04**MOT test number** 399764203225**Result** ✓ Passed**MOT #3** 2013-07-18 15:39**MOT test number** 965009993163**Result** ✗ Failed

- Fail** Registration plate lamp not working (1.1.C.1d)
- Fail** Offside Front position lamp(s) not working (1.1.A.3b)
- Fail** Windscreen washer provides insufficient washer liquid (8.2.3)
- Fail** Nearside Front position lamp(s) not working (1.1.A.3b)
- Fail** Offside Stop lamp not working (1.2.1b)

MOT #2 2012-06-13 14:47**MOT test number** 776545962179**Result** ✓ Passed

- Notice** Rear discs lipped
- Advice** Offside Front Seat belt cut but webbing not significantly weakened (5.2.2a)

MOT #1 2012-06-12 14:54**MOT test number** 546814162171**Result** ✗ Failed

- Fail** Rear Stop lamp not working (1.2.1b)
- Notice** Rear discs lipped
- Advice** Offside Front Seat belt cut but webbing not significantly weakened (5.2.2a)



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
23 July 2024

Tax status	Valid until 1 September
-------------------	-------------------------

Days left	125
------------------	-----

MOT expiry date	23 July 2024
------------------------	--------------

Full MOT history	See MOT history
-------------------------	---------------------------------



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 ND09YAG
Plate since	2024-03-28
Current registration	 ND09YAG
Plate since	2024-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2009-06-09
Last registration	2023-07-24
Complete history	See info



Registration #1	2009-06-09	29 mi
Registration #2	2012-06-12	36.458 mi
Registration #3	2012-06-13	36.458 mi
Registration #4	2013-07-18	42.062 mi
Registration #5	2013-07-23	42.062 mi
Registration #6	2014-07-19	55.540 mi
Registration #7	2014-07-19	55.546 mi
Registration #8	2015-07-22	69.624 mi
Registration #9	2016-07-23	82.978 mi
Registration #10	2017-07-15	97.751 mi
Registration #11	2018-07-14	112.939 mi
Registration #12	2019-06-20	125.277 mi
Registration #13	2019-06-20	125.277 mi
Registration #14	2019-06-20	125.277 mi
Registration #15	2019-06-20	125.277 mi
Registration #16	2019-06-20	125.277 mi
Registration #17	2019-06-20	125.277 mi
Registration #18	2019-06-20	125.277 mi
Registration #19	2019-06-20	125.277 mi
Registration #20	2019-06-20	125.277 mi
Registration #21	2019-06-20	125.277 mi
Registration #22	2019-06-20	125.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1904 mm
Height	2170 mm
Length	4890 mm
Wheel base	3000 mm
Kerb weight	1817 kg
Max. allowed weight	2800 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of seats	3

Number of axles	2
Engine number	BRS 138217