



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	BORA HIGHLINE TDI (100BHP)
Colour	Silver
Year of manufacture	2005
Top speed	117 mph
0 - 60 mph	12.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	240 Nm at 1.800 rpm
Engine capacity	1.896 cc
Cylinders	4
Fuel type	Diesel
Consumption city	41.5 mpg
Consumption extra urban	64.2 mpg
Consumption combined	53.3 mpg
CO2 emission	143 g/km
CO2 label	F






Internet history

Entry 1

Date	2021-06-23
Pictures	21
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2024-11-23
MOT pass rate	65 %
MOT passed	15
Failed MOT tests	8
Total advice items	95
Total items failed	27

MOT #23	2023-11-24 16:11
MOT test number	581402101756
Result	✓ Passed
Next expiry date	2024-11-23
Minor	Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #22**

2023-11-22 09:16

**MOT test number**

457953955215

**Result****✗ Failed**

**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**Fail** Offside Stop lamp(s) emits other than a steady red light (4.3.3 (a) (ii))

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Fail** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

**Fail** Offside Rear Outer Suspension component mounting prescribed area excessively damaged significantly reducing structural strength Sill (5.3.6 (a) (i))

**Minor** Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))

**Fail** Nearside Stop lamp(s) emits other than a steady red light (4.3.3 (a) (ii))

**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

**Fail** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

**MOT #21**

2022-11-21 13:39

**MOT test number**

589955427792

**Result**

✓ Passed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #20**

2022-11-21 13:39

**MOT test number**

633697575597

**Result**

✗ Failed

- Advice** Offside Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Pass with rectification** Nearside Track rod end ball joint dust cover insecure so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))
- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Pass with rectification** Offside Rear Position lamp not working (4.2.1 (a) (ii))
- Pass with rectification** Offside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))



MOT #192021-11-24 12:47

MOT test number383184217425

Result		✓ Passed
Advice	Central Exhaust has a minor leak of exhaust gases tin plate repair and minor leak (6.1.2 (a))	
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice	Nearside Front plastic inner wing loose	
Advice	Offside Rear Brake pipe corroded, covered in grease or other material corrosion (1.1.11 (c))	
Advice	Front Exhaust has a minor leak of exhaust gases near cat (6.1.2 (a))	
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material corrosion (1.1.11 (c))	
Advice	Nearside Rear Service brake binding but not excessively (1.2.1 (f))	

**MOT #18**

2021-11-15 10:59

**MOT test number**

930381261555

**Result****✗ Failed**

- Fail** Offside Front Upper Macpherson strut top bush or bearing has excessive wear or free play (5.3.4 (a) (i))
- Advice** Central Exhaust has a minor leak of exhaust gases tin plate repair and minor leak (6.1.2 (a))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Fail** Nearside Steering rack gaiter missing or no longer prevents the ingress of dirt insecure (2.1.3 (g) (ii))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material corrosion (1.1.11 (c))
- Advice** Front Exhaust has a minor leak of exhaust gases near cat (6.1.2 (a))
- Fail** Offside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front plastic inner wing loose
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material corrosion (1.1.11 (c))
- Fail** Offside Steering rack gaiter missing or no longer prevents the ingress of dirt torn (2.1.3 (g) (ii))
- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))

**MOT #17**

2020-11-18 09:40

**MOT test number**

483384125093

**Result****✓ Passed**

- Advice** Exhaust backbox outer skin rotten but no exhaust leak
- Advice** Nearside Front Brake pad sensor disconnected
- Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))
- Minor** Offside Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

**MOT #16**

2020-11-10 11:20

**MOT test number**

267241564997

**Result**

✗ Failed

**Advice** Exhaust backbox outer skin rotten but no exhaust leak**Fail** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))**Minor** Offside Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**Advice** Nearside Front Brake pad sensor disconnected**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MOT #15**

2019-10-23 11:20

**MOT test number**

613125287322

**Result**

✓ Passed

**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside Front Brake pad warning wire not connected**Advice** Front Direction indicator slightly discoloured Both (4.4.3 (a))**Advice** Front Brake hose slightly deteriorated Both (1.1.12 (b) (ii))**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Offside Front Seat belt buckle slightly damaged Still operating correctly but slightly worn (7.1.2 (d))**Minor** Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Exhaust backbox outer skin rotten but no exhaust leak**Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

**MOT #14**

2018-08-29 09:39

**MOT test number**

950624357078

**Result**

✓ Passed

**Minor** Offside Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt small end not secured (2.1.3 (g) (i))

**Minor** Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #13**

2018-08-24 08:46

**MOT test number**

327776155580

**Result**

✗ Failed

**Minor** Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**Fail** Offside Front Suspension component pin or bush excessively worn strut top bearing play (5.3.4 (a) (i))

**Minor** Offside Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt small end not secured (2.1.3 (g) (i))

**Fail** Offside Rear Sub-frame pin or bush excessively worn axle pivot bush separated (5.3.4 (a) (i))

**Minor** Nearside Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt small end not secured (2.1.3 (g) (i))

**Fail** Nearside Rear Sub-frame pin or bush excessively worn axle pivot bush separated (5.3.4 (a) (i))



MOT #12

2017-08-16 13:15

MOT test number

512666290302

Result

✓ Passed

- Advice

Nearside Rear Lower Front suspension has slight movement at a wishbone pin or bush (2.5.A.1c)
- Advice

Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice

Offside Front Headlamp deteriorated but light output not reduced (1.7.5a)
- Advice

Offside Front Lower Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Advice

Offside Rear coil spring corroded (2.4.C.1b)
- Advice

Offside Rear Lower Front suspension has slight movement at a wishbone pin or bush (2.5.A.1c)
- Advice

Nearside Front Power steering pipe(s) or hose(s) has slight seepage from a joint (2.3.3b)
- Advice

Nearside Front Headlamp deteriorated but light output not reduced (1.7.5a)
- Advice

Offside Front Upper Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Advice

Nearside Rear coil spring corroded (2.4.C.1b)
- Advice

Offside Front Upper Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**MOT #11**

2017-08-16 09:30

**MOT test number**

100492765372

**Result****✗ Failed****Pass with rectification** Offside Front Headlamp aim too low (1.8)**Advice** Offside Front Upper Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Offside Front Headlamp deteriorated but light output not reduced (1.7.5a)**Advice** Nearside Rear Lower Front suspension has slight movement at a wishbone pin or bush (2.5.A.1c)**Advice** Offside Rear coil spring corroded (2.4.C.1b)**Advice** Nearside Front Power steering pipe(s) or hose(s) has slight seepage from a joint (2.3.3b)**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Front Front position lamp(s) not working (1.1.A.3b)**Advice** Offside Front Lower Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Nearside Front Headlamp deteriorated but light output not reduced (1.7.5a)**Advice** Offside Rear Lower Front suspension has slight movement at a wishbone pin or bush (2.5.A.1c)**Advice** Nearside Rear coil spring corroded (2.4.C.1b)**Fail** Central Front Exhaust has a major leak of exhaust gases (7.1.2)**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Front Upper Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

**MOT #10** 2016-08-26 11:39**MOT test number** 674757203559**Result** ✓ Passed**Advice** Offside Rear coil spring corroded (2.4.C.1b)**Advice** Nearside Rear coil spring corroded (2.4.C.1b)**Advice** Rear exhaust box deteriorated**MOT #9** 2015-08-20 15:16**MOT test number** 595712035209**Result** ✓ Passed**MOT #8** 2015-08-19 14:44**MOT test number** 888411935201**Result** ✗ Failed**Fail** Nearside Front Steering rack gaiter split (2.2.D.2d)**Fail** Offside Front Track rod end ball joint has excessive play (2.2.B.1f)**MOT #7** 2014-06-02 12:28**MOT test number** 236433854499**Result** ✓ Passed**Advice** Offside Front Track rod end ball joint dust cover deteriorated, but preventing the ingress of dirt (2.2.C.1c)**MOT #6** 2012-11-28 14:00**MOT test number** 615553132302**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

**MOT #5** 2011-12-01 13:45**MOT test number** 245355531366**Result** ✓ Passed

- Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Rear Lower coil spring corroded (2.4.C.1b)
- Advice** Rear Exhaust has part of the system slightly deteriorated (7.1.1a)
- Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Rear Lower coil spring corroded (2.4.C.1b)

**MOT #4** 2010-08-26 14:40**MOT test number** 561928430260**Result** ✓ Passed**MOT #3** 2010-08-22 12:49**MOT test number** 973404630233**Result** ✗ Failed

- Fail** Nearside Front Steering system excessively rough (2.2.D.1)

**MOT #2** 2009-05-27 12:44**MOT test number** 332407749175**Result** ✓ Passed**MOT #1** 2008-06-05 15:45**MOT test number** 252107258109**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 April 2025

✓  
**MOT**  
**Expires:**  
23 November 2024

<b>Tax status</b>	Valid until 1 April
<b>Days left</b>	336
<b>MOT expiry date</b>	23 November 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>BT05WTY</b>
Plate since	2019-03-29
Current registration	 <b>BT05WTY</b>
Plate since	2019-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2005-06-07
Last registration	2023-11-24
Complete history	<a href="#">See info</a>



Registration #1	2005-06-07	11 mi
Registration #2	2008-06-05	24.766 mi
Registration #3	2009-05-27	33.333 mi
Registration #4	2010-08-22	521.091 mi
Registration #5	2010-08-26	52.091 mi
Registration #6	2011-12-01	61.595 mi
Registration #7	2012-11-28	67.807 mi
Registration #8	2014-06-02	77.161 mi
Registration #9	2015-08-19	83.848 mi
Registration #10	2015-08-20	83.848 mi
Registration #11	2016-08-26	86.566 mi
Registration #12	2017-08-16	89.245 mi
Registration #13	2017-08-16	89.245 mi
Registration #14	2018-08-16	92.924 mi
Registration #15	2019-08-16	96.603 mi
Registration #16	2020-08-16	100.282 mi
Registration #17	2021-08-16	103.961 mi
Registration #18	2022-08-16	107.640 mi
Registration #19	2023-08-16	111.319 mi
Registration #20	2023-08-16	111.319 mi
Registration #21	2023-08-16	111.319 mi
Registration #22	2023-08-16	111.319 mi
Registration #23	2023-08-16	111.319 mi
Registration #24	2023-08-16	111.319 mi
Registration #25	2023-08-16	111.319 mi



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2018 mm
Height	1446 mm
Length	4376 mm
Wheel base	2519 mm
Kerb weight	1427 kg
Max. allowed weight	1830 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	4

Number of seats	5
Engine number	ATD 691729