



report date: 2024-03-28

General information

Make	MAZDA
Model	5 TS2
Colour	Blue
Year of manufacture	2008
Top speed	116 mph
0 - 60 mph	12.4 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	144 BHP
Max. torque	185 Nm at 4.000 rpm
Engine capacity	1.999 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.0 mpg
Consumption extra urban	44.1 mpg
Consumption combined	34.4 mpg
CO2 emission	198 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-09-13
Pictures	10
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-09-19
MOT pass rate	64 %
MOT passed	14
Failed MOT tests	8
Total advice items	55
Total items failed	21

MOT #22	2023-09-11 15:34
MOT test number	229183862142
Result	✓ Passed
Next expiry date	2024-09-19

MOT #21	2023-09-11 11:15
MOT test number	665564434890
Result	✗ Failed
Fail	Offside Front Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))

MOT #20	2022-09-20 13:32
MOT test number	529423537264
Result	✓ Passed
Advice	Screw nearside rear tyre
Advice	Nearside Front Outer Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

**MOT #19**

2022-09-14 09:05

MOT test number

805159937157

Result**✗ Failed****Fail** Brake pedal has insufficient reserve travel (1.1.2 (a))**Advice** Nearside Rear one of two plate lamps inop**Fail** Exhaust has a major leak of exhaust gases back box (6.1.2 (a))**Advice** I strongly advise this vehicle should not be driven from this moment onwards due to brake pedal creeping from a fluid leak**Advice** Nearside Front Outer Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Fail** Offside Front Headlamp light intensity severely reduced (4.1.4 (a))**Fail** Offside Front Lower Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Advice** Screw nearside rear tyre**Fail** Central Exhaust system insecure mounting detached (6.1.2 (a))**Fail** Nearside Rear Brake hose leaking on a hydraulic braking system (1.1.12 (c) (ii))**Fail** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**MOT #18**

2021-09-15 16:21

MOT test number

991084821815

Result**✓ Passed****Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Minor** Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #17**

2020-11-06 16:52

MOT test number

664644349202

Result

✓ Passed

- Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Center exhaust hanging bracket broken
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Off side front road wheel deteriorated

MOT #16

2020-11-02 15:38

MOT test number

854708136341

Result

✗ Failed

- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Fail** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Center exhaust hanging bracket broken
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Fail** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Advice** Off side front road wheel deteriorated

MOT #15

2019-11-22 08:50

MOT test number

731182920238

Result

✓ Passed

- Advice** Front anti roll bar mounts worn

**MOT #14**

2019-01-04 10:42

MOT test number

456702388201

Result

✓ Passed

Advice

Rear Coil spring corroded (5.3.1 (b) (i))

MOT #13

2019-01-03 11:04

MOT test number

947364929434

Result

✗ Failed

Fail

Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice

Rear Coil spring corroded (5.3.1 (b) (i))

Fail

Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #12

2018-01-15 14:27

MOT test number

165173666276

Result

✓ Passed

Advice

Rear Inner Anti-roll bar has slight play in a pin/bush both sides (2.4.G.2)

Advice

Front Inner Suspension arm rubber bush deteriorated but not resulting in excessive movement both sides (2.4.G.2)

Advice

Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

Advice

Exhaust has a minor leak of exhaust gases rear silencer (7.1.2)

**MOT #11**

2017-01-13 12:07

MOT test number

994008009953

Result

✓ Passed

- Advice** Offside Rear Lower Suspension arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Rear Inner Tie bar/rod has slight play in a pin/bush (2.4.G.2)
- Advice** Offside Rear Lower Tie bar/rod has slight play in a pin/bush (2.4.G.2)
- Advice** Nearside Rear Lower Suspension arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Rear Lower Tie bar/rod has slight play in a pin/bush (2.4.G.2)
- Advice** Offside Rear Lower Tie bar/rod has slight play in a pin/bush (2.4.G.2)

MOT #10

2017-01-12 11:03

MOT test number

835802451323

Result

✗ Failed

- Advice** Offside Rear Lower Suspension arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Rear Inner Tie bar/rod has slight play in a pin/bush (2.4.G.2)
- Advice** Offside Rear Lower Tie bar/rod has slight play in a pin/bush (2.4.G.2)
- Fail** Nearside Front Lower Suspension arm rubber mounting deteriorated resulting in excessive movement (2.4.G.2)
- Advice** Nearside Rear Lower Suspension arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Rear Lower Tie bar/rod has slight play in a pin/bush (2.4.G.2)
- Advice** Offside Rear Lower Tie bar/rod has slight play in a pin/bush (2.4.G.2)
- Fail** Offside Front position lamp(s) not working (1.1.A.3b)
- Fail** Nearside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)
- Fail** Offside Front Lower Suspension arm rubber mounting deteriorated resulting in excessive movement (2.4.G.2)

**MOT #9** 2016-01-15 11:53**MOT test number** 865961140761**Result** ✓ Passed**MOT #8** 2015-01-13 10:47**MOT test number** 179383015032**Result** ✓ Passed**MOT #7** 2015-01-13 10:47**MOT test number** 968413415025**Result** ✗ Failed**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #6** 2014-01-15 17:17**MOT test number** 867095314043**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**MOT #5** 2014-01-15 10:50**MOT test number** 777745914074**Result** ✗ Failed**Notice** Under-trays fitted obscuring some underside components**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #4** 2013-01-14 13:00**MOT test number** 229094113032**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Under-trays fitted obscuring some underside components**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)**MOT #3** 2013-01-14 12:50**MOT test number** 206924213016**Result** ✗ Failed**Fail** Offside Rear Wheel nut(s) missing (4.2.A.1e)**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Under-trays fitted obscuring some underside components



MOT #2	2012-01-16 11:36
MOT test number	168966012092
Result	✓ Passed
Notice	Vehicle's internal headlight adjuster altered to recheck lights
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Notice	Engine covers fitted obscuring some components in the engine bay
Notice	Passenger seat(s) missing at time of test
Notice	Under-trays fitted obscuring some underside components

MOT #1	2011-01-12 10:15
MOT test number	525072211023
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
19 September 2024

Tax status	Valid until 1 January
Days left	246
MOT expiry date	19 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-




Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2008-01-15
Last registration	2023-09-11
Complete history	See info



Registration #1	2008-01-15	27 mi
Registration #2	2011-01-12	42.353 mi
Registration #3	2012-01-16	57.032 mi
Registration #4	2013-01-14	64.942 mi
Registration #5	2013-01-14	64.942 mi
Registration #6	2014-01-15	75.757 mi
Registration #7	2014-01-15	75.757 mi
Registration #8	2015-01-13	89.794 mi
Registration #9	2016-01-15	107.245 mi
Registration #10	2017-01-12	111.017 mi
Registration #11	2017-01-13	111.019 mi
Registration #12	2018-01-15	118.976 mi
Registration #13	2019-01-15	121.017 mi
Registration #14	2019-01-15	121.017 mi
Registration #15	2019-01-15	121.017 mi
Registration #16	2019-01-15	121.017 mi
Registration #17	2019-01-15	121.017 mi
Registration #18	2019-01-15	121.017 mi
Registration #19	2019-01-15	121.017 mi
Registration #20	2019-01-15	121.017 mi
Registration #21	2019-01-15	121.017 mi
Registration #22	2019-01-15	121.017 mi
Registration #23	2019-01-15	121.017 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1755 mm
Height	1665 mm
Length	4505 mm
Wheel base	2750 mm
Max. allowed weight	2150 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	LF10510608