





General information

Make	MERCEDES
Model	SPRINTER 309 CDI MWB P/V
Colour	Silver
Year of manufacture	2007
Gearbox	6 speed Manual

Engine & fuel consumption

Power	88 BHP
Max. torque	220 Nm at 1.400 rpm
Engine capacity	2.148 сс
Cylinders	4
Fuel type	Diesel







Internet history

Entry	1

Date

2021-07-13

Pictures

3

Listing price

View report







source: cargurus.co.uk



MOT history

MOT expiry date	2024-09-10
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	45
Total items failed	4

MOT #18	2023-09-11	07:09
MOT test	number 1866095	28522
Result	🗸 F	Passed
Next expi	2024	-09-10
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Nearside Front Service brake binding but not excessively (1.2.1 (f))	
Advice	Front Headlamp has a product on the lens but not seriously reducing light output both (4.1.4	(b))
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Rear Service brake binding but not excessively (1.2.1 (f))	
Advice	Offside Front Service brake binding but not excessively (1.2.1 (f))	



WU07VDC report date: 2024-03-28

MOT #17	2023-08-31 07:41
MOT test	number 744066138971
Result	× Failed
Advice	Nearside Rear Service brake binding but not excessively (1.2.1 (f))
MAJOR	Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
MAJOR	Front Exhaust has a major leak of exhaust gases Front flexi (6.1.2 (a))
Advice	Nearside Front Service brake binding but not excessively (1.2.1 (f))
Advice	Front Headlamp has a product on the lens but not seriously reducing light output both (4.1.4 (b))
MAJOR	Emissions unable to be completed (8.2.2.2 (e))
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
MAJOR	Offside Front Service brake excessively binding (1.2.1 (f))

MOT #16		2022-08-12 13:55
MOT test	number	268482922931
Result		✓ Passed
Advice	Nearside Front Service brake binding but not excessively (1.2.1 (f))	
Advice	Offside Front Service brake binding but not excessively (1.2.1 (f))	

MOT #15		2022-08-11 12:55
MOT test	number	723161726494
Result		× Failed
Advice	Nearside Front Service brake binding but not excessively (1.2.1 (f))	
MAJOR	Fuel system component leaking (6.1.3 (b) (i))	
Advice	Offside Front Service brake binding but not excessively (1.2.1 (f))	
MAJOR	Nearside Rear Position lamp not working (4.2.1 (a) (ii))	





MOT #14		2021-08-11 07:29
MOT test	number	542256113645
Result		✓ Passed
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))	
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #13		2019-12-13 11:25
MOT test	number	892390987072
Result		✓ Passed
Advice	Nearside Front Direction indicator slightly discoloured (4.4.3 (a))	
Advice	Water in n/s headlamp	
Advice	Wipers smeary	

MOT #12		2018-09-25 08:45
MOT test	number	797585627006
Result		✓ Passed
Advice (5.3.4 (a) (Nearside Rear Anti-roll bar linkage pin or bush worn but not resulting in (excessive movement
Advice	Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))	
Advice (a) (i))	Offside Rear Anti-roll bar linkage pin or bush worn but not resulting in ex	cessive movement (5.3.4
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.	.14 (a) (ii))

MOT #11	2017-09-22 07:56
MOT test number	207904078661
Result	✓ Passed





MOT #10	2016-09-27 15:12
MOT test number	371701753198
Result	✓ Passed
Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
MOT #9	2016-09-27 08:43
MOT test number	766309651403
Result	🗙 Failed
Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Fail Offside Rear fog lamp not working (1.3.2b)	

MOT #8	2015-09-10 13:46
MOT test number	973811384958
Result	✓ Passed
Advice Nearside Rear Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)	

MOT #7	2015-09-03 00:00
MOT test number	732239628468
Result	🗙 Failed
Advice Nearside Rear Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2) Fail Nearside Front Suspension arm ball joint dust cover excessively deteriorated prevents the ingress of dirt (2.4.G.2)	so that it no longer

МОТ #6	2014-09-17 09:36
MOT test number	358490264461
Result	✓ Passed
Advice Nearside Front Lower Suspension arm ball joint dust cover damaged, but dirt (2.4.G.2)	preventing the ingress of
Advice Offside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)





MOT #5		2013-09-27 12:46
MOT test	number	417860373243
Result		✓ Passed
MOT #4		2012-09-21 12:13
MOT test	number	379005862235
Result		✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Notice	Both side repeater lamp lenses damaged	
MOT #3		2011-09-07 10:28
MOT #3 MOT test	number	2011-09-07 10:28 908290451200
	number	
MOT test	number O/s/f lower suspension ball joint slight lift/play	908290451200
MOT test Result		908290451200
MOT test Result Notice	O/s/f lower suspension ball joint slight lift/play	908290451200
MOT test Result Notice Notice	O/s/f lower suspension ball joint slight lift/play N/s siderepeater(door mirror) lens missing	908290451200

Notice	N/s/f tyre wearing/bald on outer edge(just acceptable)

MOT #2	2010-09-29 12:56
MOT test number	252002670268
Result	✓ Passed





MOT #1	2010-09-29 11:26
MOT test number	304322670421
Result	🗙 Failed
NoticeBoth indicator side repeater lenses damagedFailNearside Headlamp aim aimed so that it dazzles other road users (1.8.A.1a)	



WU07VDC report date: 2024-03-28

Tax & MOT check

√ Taxed	√ МОТ
Tax due: 1 May 2025	Expires: 10 September 2024
Tax status	Valid until 1 May
Days left	368
MOT expiry date	10 September 2024
Full MOT history	See MOT history





Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPLE
Date	
Category	AMPL.
Туре	

Extra MERCEDES salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.11.111
Auction value	4 10.000
Average private trade value	4 11 711

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And and a second s	

	More info >
Plate changes	
See in this check if this MERCEDES had different number plates.	
Number of plates	
Current registration	
Plate since	
Current registration	
Plate since	1910.25.29





Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-04-16
Last registration	2023-09-11
Complete history	See info



Registration #1	2007-04-16	14 mi
Registration #2	2010-09-29	52.419 mi
Registration #3	2010-09-29	52.422 mi
Registration #4	2011-09-07	63.901 mi
Registration #5	2012-09-21	78.247 mi
Registration #6	2013-09-27	90.990 mi
Registration #7	2014-09-17	102.465 mi
Registration #8	2015-09-03	113.058 mi
Registration #9	2015-09-10	113.065 mi
Registration #10	2016-09-27	124.594 mi
Registration #11		11.707 est
Registration #12		11.777 esi
Registration #13		11.707 est
Registration #14		11.777 esi
Registration #15		11.707 mi
Registration #16		11.777 esi
Registration #17		11.777 esi
Registration #18		11.117 est
Registration #19		11.777 mi
Registration #20		10.207 est





WU07VDC report date: 2024-03-28

Safety ratings

NCAP rating

Video

see crash video

Dimensions & weight	
Width	1960 mm
Height	2820 mm
Length	5910 mm
Wheel base	3665 mm
Kerb weight	2085 kg
Max. allowed weight	3500 kg
Additional information	
Additional information Fuel tank capacity	75 l
	75 l Direct Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Direct Injection
Fuel tank capacity Fuel delivery Number of seats	Direct Injection 3