





General information

Make	VOLKSWAGEN
Model	POLO MATCH (80BHP)
Colour	White
Year of manufacture	2008
Top speed	109 mph
0 - 60 mph	12.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	80 BHP
Max. torque	132 Nm at 3.800 rpm
Engine capacity	1.390 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	53.3 mpg
Consumption combined	43.5 mpg
CO2 emission	150 g/km
CO2 label	F







Internet history

Entry	1
Date	

Pictures

2021-05-28

13

Listing price

View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-11-30
MOT pass rate	59 %
MOT passed	13
Failed MOT tests	9
Total advice items	61
Total items failed	15

MOT #22	2023-12-01 13:10
MOT test number	401240496495
Result	✓ Passed
Next expiry date	2024-11-30

MOT #21	2022-05-30 09:28
MOT test number	565708863543
Result	✓ Passed

MOT #20	2022-05-30 09:28
MOT test number	552892198184
Result	× Failed
Pass with rectification	Nearside Headlamp aim too low (4.1.2 (a))
Pass with rectification	Front Windscreen washer provides insufficient washer liquid (3.5 (a))
Pass with rectification	Offside Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #19	2021-05-26 12:57
MOT test number	966402109010
Result	✓ Passed



Η	K0	8	Μ	F	U
	report	date	: 202	24-0	3-28

MOT #18		2020-12-10 15:47
MOT test	number	625447583831
Result		✓ Passed
Advice	Offside Rear Brake hose has slight corrosion to ferrule $(1.1.12 (f) (i))$	
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
Advice	Suspension component corroded but not seriously weakened Rea beam corro	oded (5.3.3 (b) (i))
Advice	Nearside Front Play in steering rack inner joint(s)	
MOT #17		2020-12-08 10:06
MOThest		271104510052

MOT test	number 271104519053
Result	× Failed
MAJOR	Emissions not tested Due to major leak of exhaust gasses (8.2.1.2 (d))
Advice	Suspension component corroded but not seriously weakened Rea beam corroded (5.3.3 (b) (i))
Advice	Nearside Front Play in steering rack inner joint(s)
MAJOR	Exhaust has a major leak of exhaust gases From front flexi pipe and backbox (6.1.2 (a))
MAJOR	Offside Rear Wheel bearing has excessive play (5.1.3 (a) (i))
Advice	Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))



HK08MFU report date: 2024-03-28

MOT #16		2019-09-09 13:49
MOT test	number	929337614972
Result		✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))	
Advice	Power steering pipe/hose slightly corroded (2.1.5 (g) (i))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))	





MOT #15		2019-08-30 09:06
MOT test	number	865863960069
Result		🗙 Failed
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1	.1.14 (a) (ii))
MAJOR	Parking brake lever has excessive movement indicating incorrect adjustment (1	.1.6 (c))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Suspension arm corroded but not seriously weakened (5.3.3 (b)	(i))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))	
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1	.14 (a) (ii))
Advice	Power steering pipe/hose slightly corroded (2.1.5 (g) (i))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #14	2018-08-29 12:30
MOT test number	375064641053
Result	✓ Passed
Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))	
Minor Nearside Front Electrical wiring slightly deteriorated (4.11 (b) (i))	
Advice Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))	
Minor Nearside Front Brake hose slightly chafed (1.1.12 (b) (i))	
Advice Power steering pipe/hose slightly corroded (2.1.5 (g) (i))	



HK08MFU report date: 2024-03-28

MOT #13	2018-08-29 09:30
MOT test number	330550505334
Result	🗙 Failed
Advice Power steering pipe/hose slightly corroded (2.1.5 (g) (i))	
Minor Nearside Front Electrical wiring slightly deteriorated (4.11 (b) (i))	
DANGEROUS Fuel system component leaking excessively or a risk of fire filter (6.1.3	(b) (ii))
Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))	
Minor Nearside Front Brake hose slightly chafed (1.1.12 (b) (i))	
Advice Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b)	(i))

MOT #12		2017-09-01 10:42
MOT test	number	401008121063
Result		✓ Passed
Advice	Power steering pipe(s) or hose(s) slightly corroded (2.3.2)	
Advice	Oil leak sump rusty	

MOT #11	2016-08-31 15:49
MOT test number	144629144531
Result	✓ Passed

MOT #10	2016-08-26 09:03
MOT test number	673945030630
Result	🗙 Failed
Fail Parking brake lever has no reserve travel (3.1.6b)	
Fail Parking brake: efficiency below requirements (3.7.B.7)	
Fail Offside Rear rear brake binding (3.7.B.1)	



Η	KC)8	Μ	F	U
	repor	t dat	e: 20	24-0	3-28

МОТ #9	2015-08-26 17:24
MOT test number	309498035214
Result	✓ Passed
Advice Nearside Front Lower Suspension arm rubber bush deteriorated but not resulti movement (2.4.G.2)	ing in excessive
Advice Offside Front Lower Suspension arm rubber bush deteriorated but not resulting movement (2.4.G.2)	g in excessive
MOT #8	2015-08-26 12:19
MOT test number	728458935247
Result	🗙 Failed
Fail Windscreen washer provides insufficient washer liquid (8.2.3)	
Fail Offside Rear rear brake binding (3.7.B.1)	
Advice Nearside Front Lower Suspension arm rubber bush deteriorated but not resulti movement (2.4.G.2)	ing in excessive
FailParking brake lever has no reserve travel (3.1.6b)	
Fail Parking brake: efficiency below requirements (3.7.B.7)	
Advice Offside Front Lower Suspension arm rubber bush deteriorated but not resulting movement (2.4.G.2)	g in excessive

MOT #7		2014-08-29 16:01
MOT test	number	197351244273
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice (2.4.G.2)	Offside Front Suspension arm rubber bush deteriorated but not resulting in exc	essive movement
Advice	Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice (2.4.G.2)	Nearside Front Suspension arm rubber bush deteriorated but not resulting in ex	cessive movement





MOT #6	2014-08-29 10:07
MOT test number	846021044298
Result	🗙 Failed
Fail Nearside Front Tyre has a lump, caused by separation or partial failure of its stru	cture (4.1.D.1b)
Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in ex (2.4.G.2)	cessive movement
Advice Front Brake pad(s) wearing thin (3.5.1g)	
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Fail Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)	
Advice Nearside Front Suspension arm rubber bush deteriorated but not resulting in (2.4.G.2)	excessive movement
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #5	2013-06-20 14:52
MOT test number	356351873135
Result	🗸 Passed
 Advice Offside Front Suspension arm has slight play in a pin/bush (2.4.G.2) Advice Nearside Front Suspension arm has slight play in a pin/bush (2.4.G.2) 	

MOT #4		2013-06-20 14:52
MOT test number		999231973181
Result		🗙 Failed
Pass with rectificationAdviceOffside Front Su	Offside Headlamp aim too low (1.8) spension arm has slight play in a pin/bush (2.4.G.2)	
Advice Nearside Front S	Suspension arm has slight play in a pin/bush (2.4.G.2)	

MOT #3	2012-06-29 14:46
MOT test number	285891682144
Result	✓ Passed





MOT #2	2012-06-29 11:14
MOT test number	257261282407
Result	🗙 Failed
Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	

MOT #1	2011-06-14 10:03
MOT test number	815975361184
Result	✓ Passed



Tax & MOT check

✓ Taxed Tax due: 1 December 2024	MOT Expires: 30 November 2024
Tax status	Valid until 1 December
Days left	216
MOT expiry date	30 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-





Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPLE
Damage 2	E CAT ON
Date	*
Category	AMP
Туре	

Extra VOLKSWAGEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.700
Auction value	4 10.000
Average private trade value	4 10 700

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second s	
and the second sec	

And a second s	
	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	
Carrent registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2008-07-03
Last registration	2023-12-01
Complete history	<u>See info</u>



Registration #1	2008-07-03	10 mi
Registration #2	2011-06-14	20.404 mi
Registration #3	2012-06-29	28.205 mi
Registration #4	2012-06-29	28.205 mi
Registration #5	2013-06-20	36.237 mi
Registration #6	2014-08-29	47.746 mi
Registration #7	2014-08-29	47.746 mi
Registration #8	2015-08-26	55.304 mi
Registration #9	2015-08-26	55.304 mi
Registration #10	2016-08-26	58.826 mi
Registration #11	2016-08-31	58.827 mi
Registration #12	2017-09-01	61.120 mi
Registration #13		11.777 esi
Registration #14		11.117 esi
Registration #15		11.777 esi
Registration #16		11.777 esi
Registration #17		11.777 esi
Registration #18		11.777 esi
Registration #19		11.777 esi
Registration #20		11.317 est
Registration #21		11.117 esi
Registration #22		11.117 est
Registration #23		11.277 esi
-		

More info >





Car features

S0225	Air conditioning
\$0295	
50482	
S0501	
S0566	
\$0567	
S0569	

Safety ratings

NCAP rating

Video

**** see crash video



Dimensions & weight

Width	1650 mm
Height	1467 mm
Length	3916 mm
Wheel base	2466 mm
Max. allowed weight	1580 kg

Additional information

Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
CarCheck.co.uk	page 17/17

Engine number

BUD538829