




report date: 2024-03-28

General information

Make	LAND ROVER
Model	DEFENDER TD5 COUNTY HARD TOP
Colour	Green
Year of manufacture	2005
Top speed	132 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	136 BHP
Max. torque	315 Nm at 1.950 rpm
Engine capacity	2.495 cc
Cylinders	5
Fuel type	Diesel
Consumption city	22.6 mpg
Consumption extra urban	32.1 mpg
Consumption combined	28.3 mpg






Internet history

Entry 1

Date	2021-07-29
Pictures	21
Listing price	View report



source: [cargurus.co.uk](https://www.cargurus.co.uk)



MOT history

MOT expiry date	2024-08-23
MOT pass rate	61 %
MOT passed	17
Failed MOT tests	11
Total advice items	59
Total items failed	15

MOT #28 2023-08-03 15:17

MOT test number 243009207621

Result ✓ Passed

Next expiry date 2024-08-23

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Tyre wheel/tyre protruding beyond wheel arch (5.2.3 (f))

MOT #27 2023-07-27 15:32

MOT test number 525783254106

Result ✗ Failed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- MAJOR** Nearside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))
- Advice** Nearside Front SPILT PIN NOT FITTED
- Advice** Tyre wheel/tyre protruding beyond wheel arch (5.2.3 (f))
- MAJOR** Nearside Steering linkage ball joint ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt Steering box arm (2.1.3 (g) (ii))



MOT #26 2022-08-24 12:32

MOT test number 199944558729

Result ✓ Passed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** (Front hub seals leaking)
- Minor** Central Rear Upper Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #25 2022-08-08 10:42

MOT test number 681147894923

Result ✗ Failed

- Minor** Steering linkage ball joint ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt drop arm (2.1.3 (g) (i))
- Advice** All wheels protruding arches
- MAJOR** Windscreen washer provides insufficient washer liquid (3.5 (a))
- MAJOR** Exhaust emissions exceed level of metered smoke for a turbo charged engine (8.2.2.2 (b))
- Advice** Front swivel joints damp
- MAJOR** Horn not working (7.7 (a))
- Advice** Offside front daytime running light not working
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

MOT #24 2021-08-12 15:19

MOT test number 789715521131

Result ✓ Passed

- Advice** Offside Front Swivel joint has a slight leak
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Front Swivel joint has a slight leak



MOT #23 2021-08-12 15:19

MOT test number 872594867806

Result ✗ Failed

Pass with rectification Nearside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Offside Front Swivel joint has a slight leak

Pass with rectification Offside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

Advice Nearside Front Swivel joint has a slight leak

MOT #22 2020-08-05 12:48

MOT test number 634835571996

Result ✓ Passed

Advice O/s/f and n/s/f swivel joints slight leak of oil

Advice Offside Rear Tyre slightly damaged/cracking or perishing cracking in tread 2802 (5.2.3 (d) (ii))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Minor Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing cracking in tread 1405 (5.2.3 (d) (ii))

Advice Oil leak, but not excessive transfer box oil leak (8.4.1 (a) (i))

Minor Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))



MOT #21 2020-08-05 12:48

MOT test number 360603356372

Result ✗ Failed

- Pass with rectification** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing cracking in tread 2802 (5.2.3 (d) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Minor** Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
- Advice** O/s/f and n/s/f swivel joints slight leak of oil
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing cracking in tread 1405 (5.2.3 (d) (ii))
- Advice** Oil leak, but not excessive transfer box oil leak (8.4.1 (a) (i))
- Minor** Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

MOT #20 2019-08-01 10:08

MOT test number 655224973366

Result ✓ Passed

- Advice** Oil leak, but not excessive transfer box (8.4.1 (a) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing cracking and dated 1406 (5.2.3 (d) (ii))
- Advice** Nearside Front axle swivel joint slight weap of oil
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing cracking and dated 2802 (5.2.3 (d) (ii))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material to flexi hose (1.1.11 (c))
- Advice** Offside Front axle swivel joint slight weap of oil

MOT #19 2018-08-10 13:10

MOT test number 759121975725

Result ✓ Passed



MOT #18	2018-08-09 09:24
MOT test number	511330758209
Result	✗ Failed
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Minor	Windscreen wiper blade defective both (3.4 (b) (i))
Advice	Nearside Rear Nail in tyre
MAJOR	Offside Outer Track rod end ball joint has excessive play (2.1.3 (b) (i))
MAJOR	Nearside Outer Track rod end ball joint has excessive play (2.1.3 (b) (i))

MOT #17	2018-04-27 11:53
MOT test number	127399356728
Result	✓ Passed

MOT #16	2017-04-26 08:26
MOT test number	580932184044
Result	✓ Passed

MOT #15	2016-04-30 09:31
MOT test number	607331929154
Result	✓ Passed

MOT #14	2016-04-29 08:26
MOT test number	154881506222
Result	✗ Failed
Fail	Offside Rear Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)

MOT #13	2015-04-30 13:26
MOT test number	738130725141
Result	✓ Passed



MOT #12	2014-03-11 09:32
MOT test number	929520474073
Result	✓ Passed

MOT #11	2014-03-11 09:32
MOT test number	197850374011
Result	✗ Failed
Pass with rectification	Nearside Front position lamp(s) not working (1.1.A.3b)
Pass with rectification	Offside Headlamp has a product on the lens so that the light output is severely reduced (1.7.5a)
Pass with rectification	Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
Pass with rectification	Nearside Headlamp has a product on the lens so that the light output is severely reduced (1.7.5a)
Pass with rectification	Offside Registration plate lamp not working (1.1.C.1d)
Pass with rectification	Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #10	2013-03-14 16:55
MOT test number	929763873008
Result	✓ Passed

MOT #9	2013-03-14 14:54
MOT test number	105193273065
Result	✗ Failed
Fail	Nearside Front Track rod end ball joint has excessive play (2.2.B.1f)

MOT #8	2012-01-11 15:26
MOT test number	435061512072
Result	✓ Passed
Advice	Nearside Front Brake pad(s) wearing thin (3.5.1g)
Advice	Offside Front Brake pad(s) wearing thin (3.5.1g)



MOT #7	2011-05-06 12:11
MOT test number	936896021130
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #6	2011-05-06 12:11
MOT test number	127976121127
Result	✗ Failed
Pass with rectification	Registration plate lamp not working (1.1.C.1d)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Front Brake pad(s) wearing thin (3.5.1g)

MOT #5	2010-05-17 14:28
MOT test number	683457730133
Result	✓ Passed

MOT #4	2010-05-17 10:43
MOT test number	283377030193
Result	✗ Failed
Pass with rectification	Nearside Front position lamp(s) not working (1.1.A.3b)
Fail	Windscreen washer provides insufficient washer liquid (8.2.3)

MOT #3	2009-05-26 11:46
MOT test number	993536549164
Result	✓ Passed



MOT #2	2008-05-27 09:44
MOT test number	862788648164
Result	✓ Passed
Advice	Nearside Headlamp not in good working order but not adversely affecting beam image (1.2.4a)

MOT #1	2008-05-27 09:44
MOT test number	152928748181
Result	✗ Failed
Pass with rectification	Nearside Headlamp aim too high (1.8)
Advice	Nearside Headlamp not in good working order but not adversely affecting beam image (1.2.4a)



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
23 August 2024

Tax status Valid until 1 October

Days left 156

MOT expiry date 23 August 2024

Full MOT history [See MOT history](#)




Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many owners did this LAND ROVER have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this LAND ROVER had different number plates.

Number of plates	1
Current registration	YX18 BJK
Plate since	2019-03-28
Current registration	YX18 BJK
Plate since	2019-03-28

More info >



Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.
If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.
Download the premium report here and check if this LAND ROVER is financed.


Table with 2 columns: Field Name (Finance company, Date of agreement, Agreement type, Agreement term, Agreement number, Contact info) and Value (blurred).

More info >



Mileage check

Odometer	In miles
Mileage registrations	27
First mileage registration	2005-05-31
Last registration	2023-08-03
Complete history	See info



Registration #1	2005-05-31	10 mi
Registration #2	2008-05-27	30.286 mi
Registration #3	2009-05-26	38.974 mi
Registration #4	2010-05-17	49.163 mi
Registration #5	2010-05-17	49.163 mi
Registration #6	2011-05-06	562.502 mi
Registration #7	2012-01-11	60.029 mi
Registration #8	2013-03-14	73.752 mi
Registration #9	2013-03-14	73.752 mi
Registration #10	2014-03-11	82.310 mi
Registration #11	2015-04-30	85.889 mi
Registration #12	2016-04-29	88.461 mi
Registration #13	2016-04-30	88.479 mi
Registration #14	2017-04-26	91.416 mi
Registration #15	2018-05-01	95.377 mi
Registration #16	2018-05-01	95.377 mi
Registration #17	2018-05-01	95.377 mi
Registration #18	2018-05-01	95.377 mi
Registration #19	2018-05-01	95.377 mi
Registration #20	2018-05-01	95.377 mi
Registration #21	2018-05-01	95.377 mi
Registration #22	2018-05-01	95.377 mi
Registration #23	2018-05-01	95.377 mi
Registration #24	2018-05-01	95.377 mi
Registration #25	2018-05-01	95.377 mi
Registration #26	2018-05-01	95.377 mi

[More info >](#)



Dimensions & weight

Width	1790 mm
Height	2128 mm
Length	3880 mm
Wheel base	2360 mm
Kerb weight	1800 kg
Max. allowed weight	2400 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of seats	2
Number of axles	2
Engine number	15PU4111B