





report date: 2024-03-29

General information

Make	AUDI
Model	TT S3 QUATTRO
Colour	Blue
Year of manufacture	2002
Top speed	151 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	221 BHP
Max. torque	280 Nm at 2.200 rpm
Engine capacity	1.781 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	21.6 mpg
Consumption combined	39.8 mpg
CO2 emission	226 g/km
CO2 label	L



CarCheck.co.uk page 1/17



report date: 2024-03-29

MOT history

MOT	2020 12 10
MOT expiry date	2020-12-10
MOT pass rate	61 %
MOT passed	14
Failed MOT tests	9
Total advice items	78
Total items failed	29

MOT #23		2019-06-11 16:12
MOT test	number	849247195621
Result		✓ Passed
Next expi	ry date	2020-12-10
Advice Offside Front Tyre worn close to legal limit/worn on edge worn on outer edge (5.2.3 (e))		
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #22	201	9-06-07 15:16
MOT test	number 7	58068161943
Result		X Failed
Advice	Offside Front Tyre worn close to legal limit/worn on edge worn on outer edge (5.2.3 (e	2))
MAJOR	Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))	
MAJOR	MAJOR Offside Front Suspension arm pin or bush excessively worn back bush (5.3.4 (a) (i))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
MAJOR	Offside Headlamp has a product on the lens so that the light output is severely reduce	ed (4.1.4 (b))
Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement back bush (5.3.4 (a) (i))		

CarCheck.co.uk page 2/17



MOT #21

DS02HKK

report date: 2024-03-29

2018-05-26 10:57

MOT test number

Result

Advice Offside Front Coil spring corroded (5.3.1 (b) (i))

Advice Offside Front Lower Suspension arm pip or bush were but not resulting in excessive movement.

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Front level sensor inoperative

Advice Nearside Front Coil spring corroded (5.3.1 (b) (i))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #20 2018-05-21 15:10

MOT test number 353609375470

Result × Failed

MAJOR Power steering pipe/hose excessively corroded (2.1.5 (g) (i))

Advice Front level sensor inoperative

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MAJOR Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MAJOR Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

DANGEROUS Nearside Front Undertray likely to become detached (6.2.1 (a) (ii))

Advice Offside Front Coil spring corroded (5.3.1 (b) (i))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MAJOR Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Nearside Front Coil spring corroded (5.3.1 (b) (i))

CarCheck.co.uk page 3/17



report date: 2024-03-29

MOT #19 2017-05-03 16:26

MOT test number 699054969205

Result ✓ Passed

Advice Oil leak

Advice Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)

Advice Engine cover fitted

Advice Rear height adjustor arm broken

Advice Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)

Advice Both wiper blades poor and splitting on ends

Advice Nearside Front Brake pipe slightly corroded to front hose (3.6.B.2c)

Advice Nearside Rear tyre close to marker bars

CarCheck.co.uk page 4/17



report date: 2024-03-29

MOT #18 2017-04-28 11:55

MOT test number 980882105539

Result × Failed **Advice** Nearside Rear Brake pipe slightly corroded front to rear pipe in front of hose (3.6.B.2c) Advice Oil leak **Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2) Rear height adjustor arm broken **Advice** Fail Offside Rear Brake pipe excessively corroded front to rear pipe in front of hose (3.6.B.2c) **Advice** Both wiper blades poor and splitting on ends Fail Offside Rear Brake pipe excessively corroded link pipe to caliper (3.6.B.2c) Fail Offside Headlamp aim too low ***FRONT HEADLIGHT HEIGHT ADJUSTER ROD BROKEN*** (1.8) Advice Nearside Rear tyre close to marker bars Advice Nearside Front Brake pipe slightly corroded to front hose (3.6.B.2c) Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive Advice movement rear bush (2.4.G.2) Fail Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g) Fail Nearside Rear Brake pipe excessively corroded link pipe to caliper (3.6.B.2c)

Fail Nearside Headlamp aim too low ***FRONT HEADLIGHT HEIGHT ADJUSTER ROD BROKEN**** (1.8)

Engine cover fitted **Advice**

CarCheck.co.uk page 5/17



report date: 2024-03-29

MOT #17 2016-04-21 16:07

MOT test number 254335662952

Result Passed

Advice Oil leak

Advice Offside Rear tyre has cuts in outer side wall

Advice Offside Front tyre has cuts in outer side wall

Advice Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive

movement rear bush (2.4.G.2)

Advice Rear height adjustor arm broken

Advice Nearside Front tyre has cuts in outer side wall

Advice Engine covers fitted

Advice Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive

movement rear bush (2.4.G.2)

CarCheck.co.uk page 6/17



report date: 2024-03-29

MOT #16 2016-04-11 16:05

MOT test number 932492911390

Result X Failed

Fail Offside Headlamp aim too high (1.8)

Fail Nearside Front Outer Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

Advice Rear height adjustor arm broken

Advice Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)

Advice Nearside Front tyre has cuts in outer side wall

Advice Engine covers fitted

Fail Nearside Headlamp aim too high (1.8)

Fail Nearside Front Inner Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

Advice Oil leak

Advice Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)

Advice Offside Rear tyre has cuts in outer side wall

Advice Offside Front tyre has cuts in outer side wall

MOT #15 2015-04-16 11:59

MOT test number 509666005115

Result \(\sqrt{Passed} \)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Notice Eml light on

Notice Nail in nearside rear tyre

CarCheck.co.uk page 7/17



report date: 2024-03-29

MOT #14 2015-04-15 11:58

MOT test number 138775305131

Result X Failed

Fail Nearside Rear coil spring broken (2.4.C.1a)

Notice Nail in nearside rear tyre

Fail Hazard warning lamps inoperative (1.4.B.1b)

Advice Front Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.C.1a)

Fail Offside Rear coil spring broken (2.4.C.1a)

Notice Eml light on

Fail Offside Rear Registration plate lamp not working (1.1.C.1d)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Rear Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.C.1b)

Fail Nearside Front Tyre has ply or cords exposed (4.1.D.1b)

MOT #13 2014-03-26 14:14

MOT test number 878595984029

Result

Passed

MOT #12 2013-04-03 11:28

MOT test number 857723893044

Result ✓ Passed

CarCheck.co.uk page 8/17



MOT #10

DS02HKK

report date: 2024-03-29

2012-03-24 10:27

MOT #11 2013-03-30 16:03 **MOT** test number 907499883007 Result × Failed Fail Nearside Registration plate lamp insecure (1.1.C.1c) Notice Wheel nuts are not visable Fail Offside Front position lamp(s) not working (1.1.A.3b) Notice Engine covers fitted obscuring some components in the engine bay Fail Nearside Front Macpherson strut has excessive movement at the upper attachment (2.5.A.1c) **Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Nearside Registration plate lamp not working (1.1.C.1d) Fail Fail Nearside Front position lamp(s) not working (1.1.A.3b) Notice Under-trays fitted obscuring some underside components Fail Offside Front Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a) Offside Front Macpherson strut has excessive movement at the upper attachment (2.5.A.1c) Fail

number	459704082069
	✓ Passed
	2011-03-28 12:03
number	396297181088
	✓ Passed
Oil at minimum level	
Wipers deteriorating	
Washer fluid low	
Tyre pressures were low - set prior to test	
	number Oil at minimum level Wipers deteriorating Washer fluid low

CarCheck.co.uk page 9/17



report date: 2024-03-29

MOT #8	2010-04-02 15:28
MOT test number	681772690040
Result	✓ Passed
MOT #7	2010-04-02 12:26
MOT test number	803872890098
Result	× Failed
Fail Offside Registration plate lamp not working (1.1.C.1d)	
Fail Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Fail Nearside Front brake disc excessively pitted (3.5.1h)	
Fail Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)	
Fail Nearside Front brake disc excessively pitted (3.5.1h)	

MOT #6	2009-03-16 16:12
MOT test number	792525979023
Result	✓ Passed
MOT #5	2009-03-13 15:58
MOT test number	510502679023
Result	X Failed
Advice Offside Front brake disc slightly pitted (3.5.1h)	
Advice Nearside Front brake disc slightly pitted (3.5.1h)	
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Fail Nearside Rear coil spring incomplete (2.4.C.1a)	

MOT #4	2008-03-18 15:24
MOT test number	124848178038
Result	✓ Passed

CarCheck.co.uk page 10/17



report date: 2024-03-29

MOT test number

Result

Fail Front Anti-roll bar fractured (2.4.G.1)

Advice Nearside Front brake disc slightly pitted (3.5.1h)

Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Offside Front brake disc slightly pitted (3.5.1h)

MOT #2	2007-03-21 12:52
MOT test number	243280587058
Result	✓ Passed
MOT #1	2006-03-21 10:59
MOT test number	504440586059
Result	✓ Passed

CarCheck.co.uk page 11/17



report date: 2024-03-29

Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 12/17



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 13/17



report date: 2024-03-29

Owner history

*	
For how long did the current and previous owner(s) have this AUDI? How many owners d Check it in the premium report and see all owner registrations. Download the full report	

manuse .	

	More info >
Plate changes	
See in this check if this AUDI had different number plates.	
Number of plates	
Current registration	NK NK
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 14/17



report date: 2024-03-29

Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 15/17



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2002-03-28
Last registration	2019-06-11
Complete history	See info



Registration #1	2002-03-28	10 mi
Registration #2	2006-03-21	24.550 mi
Registration #3	2007-03-21	28.772 mi
Registration #4	2008-03-18	31.438 mi
Registration #5	2008-03-18	31.438 mi
Registration #6	2009-03-13	35.764 mi
Registration #7	2009-03-16	35.770 mi
Registration #8	2010-04-02	42.513 mi
Registration #9	2010-04-02	42.513 mi
Registration #10	2011-03-28	48.624 mi
Registration #11	2012-03-24	59.590 mi
Registration #12	2013-03-30	74.688 mi
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		0.77 44
Registration #21		11.777 es
Registration #22		11.77 44
Registration #23		11.777 es
Registration #24		11.777 au

More info >



DS02HKK report date: 2024-03-29

Car features

50225	Air conditionin
50295	
50482	
60501	
60566	
60567	
60569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1904 mm
Height	1415 mm
Length	4159 mm
Wheel base	2519 mm
Kerb weight	1420 kg

Additional information

Fuel tank capacity	62 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of axles	2
Engine number CarCheck.co.uk	BAM 037674 page 17/17