



TI38STA

report date: 2024-03-28

General information

Make	LAND ROVER
Model	DEFENDER PICK-UP TD5
Colour	Yellow
Year of manufacture	1999
Gearbox	5 speed Manual

Engine & fuel consumption

Power	127 BHP
Engine capacity	2.500 cc
Cylinders	5
Fuel type	Diesel




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-02-01
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-02-12
MOT pass rate	68 %
MOT passed	19
Failed MOT tests	9
Total advice items	63
Total items failed	28

MOT #28	2024-02-08 09:15
MOT test number	551739808491
Result	✓ Passed
Next expiry date	2025-02-12
Advice	Offside Front hub sphere slight oil leak
Advice	Nearside Front Service brake binding but not excessively (1.2.1 (f))
Advice	All four wheels protrude the vehicle

MOT #27	2023-02-10 09:30
MOT test number	408610142695
Result	✓ Passed
Advice	Slight oil leak from steering box
Advice	Slight play in nsf swivel joint
Advice	Nearside Front outrigger holed

**MOT #26**

2023-02-08 09:57

MOT test number

504896364005

Result

✗ Failed

Advice Nearside Front outrigger holed**Advice** Slight oil leak from steering box**Advice** Slight play in nsf swivel joint**Fail** Steering linkage ball joint ball joint dust cover insecure so that it no longer prevents the ingress of dirt drop arm (2.1.3 (g) (ii))**MOT #25**

2022-02-11 14:30

MOT test number

423771437598

Result

✓ Passed

Advice Engine oil leak**Advice** Power steering component has slight seepage from a component box (2.1.5 (a))**Advice** N/s/f outrigger holed**MOT #24**

2022-02-10 10:43

MOT test number

611251731012

Result

✗ Failed

Advice Engine oil leak**Fail** Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Fail** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** N/s/f outrigger holed**Advice** Power steering component has slight seepage from a component box (2.1.5 (a))**MOT #23**

2021-02-13 11:04

MOT test number

934500878343

Result

✓ Passed

**MOT #22** 2019-11-06 10:57**MOT test number** 579724011455**Result** ✓ Passed**MOT #21** 2019-11-04 12:10**MOT test number** 527429360761**Result** ✗ Failed**Fail** Offside Front Intermediate drop arm insecure (2.1.3 (a) (i))**Fail** Rear Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced cross member outer face (6.1.1 (c) (i))**MOT #20** 2018-11-16 16:28**MOT test number** 730965103532**Result** ✓ Passed**MOT #19** 2018-04-10 08:01**MOT test number** 486101744018**Result** ✓ Passed**MOT #18** 2018-04-05 09:20**MOT test number** 439273491208**Result** ✗ Failed**Fail** Nearside Rear Vehicle structure has excessive corrosion, seriously affecting its strength within 30cm of the body mountings at front of cross member (6.1.B.2)**Fail** Offside Rear Vehicle structure has excessive corrosion, seriously affecting its strength within 30cm of the body mountings (6.1.B.2)**Fail** Steering box has relative movement between sector shaft and the drop arm (2.2.B.1b)

**MOT #17**

2017-04-12 09:33

MOT test number

500207736583

Result

✓ Passed

Advice General under body corrosion**Advice** Minor misting of oil from front and rear diffs**MOT #16**

2016-06-16 14:44

MOT test number

867167771697

Result

✓ Passed

Advice Under body corrosion**Advice** Rear both tyres perished**MOT #15**

2016-06-10 08:37

MOT test number

585835761200

Result

✗ Failed

Fail Nearside Front Outer Vehicle structure has excessive corrosion, seriously affecting its strength within 30cm of the body mountings out rigger x2 patches (6.1.B.2)**Advice** Under body corrosion**Fail** Offside Rear Vehicle structure has an unsatisfactory modification, seriously affecting its strength within 30cm of the body mountings cross member (6.1.B.2)**Fail** Offside Front Macpherson strut corroded and seriously weakened (2.4.G.1)**Advice** Rear both tyres perished**Fail** Offside Front Outer Vehicle structure has excessive corrosion, seriously affecting its strength within 30cm of the body mountings out rigger x5 patches (6.1.B.2)**Fail** Nearside Front Macpherson strut corroded and seriously weakened (2.4.G.1)

**MOT #14**

2015-06-08 16:55

MOT test number

795539655132

Result

✓ Passed

- Advice** Nearside Seat belt stitching slightly frayed (5.2.2b)
- Notice** Underside of vehicle has been undersealed
- Advice** Offside Seat belt damaged but webbing not significantly weakened (5.2.2a)
- Advice** Ball joint has slight play (2.2.B.1f)

MOT #13

2015-05-29 11:19

MOT test number

326549445101

Result

✗ Failed

- Fail** Nearside Front Vehicle structure has excessive corrosion, seriously affecting its strength within 30cm of the body mountings (6.1.B.2)
- Fail** Offside Front Vehicle structure has excessive corrosion, seriously affecting its strength within 30cm of the body mountings (6.1.B.2)
- Advice** Nearside Seat belt stitching slightly frayed (5.2.2b)
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Offside Front Tie bar/rod rubber bush deteriorated resulting in excessive movement (2.4.G.2)
- Notice** Underside of vehicle has been undersealed
- Fail** Nearside Front Vehicle structure has excessive corrosion, seriously affecting its strength within 30cm of the body mountings (6.1.B.2)
- Advice** Offside Seat belt damaged but webbing not significantly weakened (5.2.2a)
- Advice** Ball joint has slight play (2.2.B.1f)
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

**MOT #12**

2014-05-21 17:20

MOT test number

386721044184

Result

✓ Passed

Advice Nearside Front Lower Shock absorber has a slightly worn bush (2.7.4)**Notice** Oil leak**Notice** Recently wax oiled**Notice** All out riggers corroded**Advice** Offside Front Lower Shock absorber has a slightly worn bush (2.7.4)**Notice** Intercooler deteriorated**Notice** General underbody corrosion**MOT #11**

2013-06-18 14:28

MOT test number

898419263161

Result

✓ Passed

Notice Oil leak**Notice** General under body corrosion**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Brake pipe slightly corroded (3.6.B.2c)**Notice** Vehicle undersealed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Brake pipe slightly corroded (3.6.B.2c)

**MOT #10**

2013-06-06 10:38

MOT test number

638657153105

Result**✗ Failed****Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Brake pipe slightly corroded (3.6.B.2c)**Fail** Nearside Front Vehicle structure has excessive corrosion, seriously affecting its strength within 30cm of the body mountings (6.1.B.2)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Oil leak**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)**Advice** Nearside Brake pipe slightly corroded (3.6.B.2c)**Notice** General under body corrosion**Fail** Nearside Rear Brake pad(s) insecure (3.5.1g)**Notice** Switch button for windscreen washers missing but still able to operate**Advice** Parking brake lever has little reserve travel (3.1.6b)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Vehicle undersealed**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)**MOT #9**

2012-05-25 11:58

MOT test number

508726642178

Result**✓ Passed**

**MOT #8** 2012-05-21 14:23**MOT test number** 618042442148**Result** ✗ Failed

- Fail** Hazard warning lamps inoperative (1.4.B.1b)
- Fail** Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)
- Fail** Hazard warning tell tale not working correctly (1.4.B.1e)

MOT #7 2011-06-06 15:17**MOT test number** 775527751118**Result** ✓ Passed

- Notice** Both Sides Front Lower Suspension Arms Front Bushes Worn.
- Advice** Power steering component(s) has slight seepage from a component (2.3.3b)
- Notice** Front To Rear Brake Pipes Corroded @ Union connections To Flexible Hoses.
- Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)

MOT #6 2010-05-14 14:12**MOT test number** 231814730461**Result** ✓ Passed**MOT #5** 2009-04-17 13:03**MOT test number** 261127709137**Result** ✓ Passed

- Advice** Nearside Front Bonded suspension unit deteriorated but can function as intended (2.4.F.3)
- Advice** Brake pipe slightly corroded (3.6.B.2c)

**MOT #4** 2008-05-01 13:01**MOT test number** 251672028164**Result** ✓ Passed**Advice** Brake pipe slightly corroded (3.6.B.2c)**MOT #3** 2008-04-30 12:46**MOT test number** 114111628108**Result** ✗ Failed**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Brake pipe slightly corroded (3.6.B.2c)**Fail** Nearside Front Front wheel bearing has excessive play (2.5.A.3c)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2007-02-12 15:47**MOT test number** 760303247033**Result** ✓ Passed**MOT #1** 2006-05-04 11:16**MOT test number** 934964226159**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
12 February 2025

Tax status		Valid until 1 February
Days left		278
MOT expiry date		12 February 2025
Full MOT history		See MOT history



Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many owners did this LAND ROVER have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this LAND ROVER had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this LAND ROVER is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	30
First mileage registration	1999-08-09
Last registration	2024-02-08
Complete history	See info



Registration #1	1999-08-09	13 mi
Registration #2	2006-05-04	52.956 mi
Registration #3	2007-02-12	55.088 mi
Registration #4	2008-04-30	58.478 mi
Registration #5	2008-05-01	58.487 mi
Registration #6	2009-04-17	61.308 mi
Registration #7	2010-05-14	64.742 mi
Registration #8	2011-06-06	69.005 mi
Registration #9	2012-05-21	72.512 mi
Registration #10	2012-05-25	72.686 mi
Registration #11	2013-06-06	75.636 mi
Registration #12	2013-06-18	75.642 mi
Registration #13	2014-05-21	78.415 mi
Registration #14	2015-05-29	79.264 mi
Registration #15	2015-06-08	79.268 mi
Registration #16	2016-06-08	81.277 mi
Registration #17	2017-06-08	83.286 mi
Registration #18	2018-06-08	85.295 mi
Registration #19	2019-06-08	87.304 mi
Registration #20	2020-06-08	89.313 mi
Registration #21	2021-06-08	91.322 mi
Registration #22	2022-06-08	93.331 mi
Registration #23	2023-06-08	95.340 mi
Registration #24	2024-02-08	97.349 mi
Registration #25	2024-02-08	97.349 mi
Registration #26	2024-02-08	97.349 mi

Registration #27	2025-25-25	25,252 442
Registration #28	2025-25-25	25,252 442
Registration #29	2025-25-25	25,252 442
Registration #30	2025-25-25	25,252 442

More info >



Safety ratings

NCAP rating



Video

[see crash video](#)



Additional information

Fuel delivery

Direct Injection

Number of doors

2

Engine number

10PA 37184