



report date: 2024-03-28

General information

| | |
|---------------------|----------------------------|
| Make | VOLKSWAGEN |
| Model | TOURAN TDI S 7 STR (90BHP) |
| Colour | Silver |
| Year of manufacture | - |
| Top speed | 106 mph |
| 0 - 60 mph | 14.9 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 89 BHP |
| Max. torque | 210 Nm at 1.800 rpm |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 37.7 mpg |
| Consumption extra urban | 53.3 mpg |
| Consumption combined | 47.1 mpg |



LABEL UNKNOWN



MOT history

| | |
|------------------|--|
| MOT #19 | 2020-10-09 14:22 |
| MOT test number | 119872379359 |
| Result | ✓ Passed |
| Next expiry date | 2021-10-08 |
| Advice | Front Registration plate deteriorated but not likely to be misread (0.1 (b)) |
| Advice | Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Advice | Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Advice | Oil leak, but not excessive (8.4.1 (a) (i)) |

| | |
|-----------------|--|
| MOT #18 | 2020-10-08 10:31 |
| MOT test number | 870783639162 |
| Result | ✗ Failed |
| MAJOR | Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii)) |
| MAJOR | Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b)) |
| Advice | Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Advice | Front Registration plate deteriorated but not likely to be misread (0.1 (b)) |
| Minor | Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) |
| Advice | Oil leak, but not excessive (8.4.1 (a) (i)) |
| Advice | Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| MAJOR | Supplementary restraint system warning lamp indicates a fault (7.1.6 (a)) |

| | |
|-----------------|--|
| MOT #17 | 2019-09-20 13:11 |
| MOT test number | 711597491691 |
| Result | ✓ Passed |
| Advice | Front Suspension arm pin or bush worn but not resulting in excessive movement x2 (5.3.4 (a) (i)) |

**MOT #16**

2019-09-18 15:35

MOT test number

951868869901

Result

✗ Failed

- MAJOR** Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))
- Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement x2 (5.3.4 (a) (i))
- MAJOR** Exhaust emissions exceed level of metered smoke for a turbo charged engine (8.2.2.2 (b))
- MAJOR** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
- Advice** Front Anti-roll bar ball joint has slight play x2 (5.3.4 (a) (i))

MOT #15

2018-09-29 10:42

MOT test number

395188573089

Result

✓ Passed

- Minor** Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** N/s front shock damp
- Advice** Oil leak

MOT #14

2018-09-29 07:32

MOT test number

118578020992

Result

✗ Failed

- Advice** N/s front shock damp
- MAJOR** Driver's airbag obviously inoperative (7.1.5 (c))
- Minor** Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Oil leak
- MAJOR** Offside Rear Position lamp not working (4.2.1 (a))



MOT #13

2017-10-03 16:00

MOT test number

627749606285

Result

✓ Passed

- Advice

Front reg plate deteriorating
- Advice

Front brake discs inner edges corroding lipped
- Advice

Rear brake hoses slightly deteriorated
- Advice

Nearside front tyre inner edge worn low middle 3 mm
- Advice

Noisy c/v joints
- Advice

Rear middle seat belt buckle cover missing
- Advice

Offside rear tyre cracked inner edge worn low

MOT #12

2017-10-03 12:19

MOT test number

392283025909

Result

✗ Failed

- Advice

Nearside front tyre inner edge worn low middle 3 mm
- Fail

Nearside Front coil spring broken (2.4.C.1a)
- Advice

Front reg plate deteriorating
- Advice

Front brake discs inner edges corroding lipped
- Advice

Offside rear tyre cracked inner edge worn low
- Fail

Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Advice

Noisy c/v joints
- Advice

Rear middle seat belt buckle cover missing
- Advice

Rear brake hoses slightly deteriorated

**MOT #11** 2016-09-15 16:09**MOT test number** 557281932774**Result** ✓ Passed**Advice** Nearside Rear Inner Tyre worn close to the legal limit in parts (4.1.E.1)**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #10** 2015-09-29 12:15**MOT test number** 346763157853**Result** ✓ Passed**Advice** Offside Front Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**MOT #9** 2015-09-29 12:15**MOT test number** 737776063611**Result** ✗ Failed**Pass with rectification** Nearside Stop lamp not working (1.2.1b)**Advice** Offside Front Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**MOT #8** 2014-09-23 13:48**MOT test number** 545306964211**Result** ✓ Passed**Notice** Rear brake pads wearing thin**Notice** Under-trays fitted obscuring some underside components**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Notice** Oil leak at engine**Notice** Engine covers fitted obscuring some components in the engine bay

**MOT #7** 2013-05-27 11:04**MOT test number** 376377843121**Result** ✓ Passed**MOT #6** 2012-04-26 14:05**MOT test number** 526147212112**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2011-04-15 09:44**MOT test number** 216175501141**Result** ✓ Passed**MOT #4** 2011-03-19 13:50**MOT test number** 448538271077**Result** ✗ Failed**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Nearside Rear Direction indicators incorrect colour (1.4.A.2f)**Fail** Nearside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Rear Direction indicators incorrect colour (1.4.A.2f)**Fail** Offside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)



| | |
|-----------------|--|
| MOT #3 | 2010-05-17 11:13 |
| MOT test number | 560687830179 |
| Result | ✓ Passed |
| MOT #2 | 2009-05-28 12:15 |
| MOT test number | 194908749106 |
| Result | ✓ Passed |
| MOT #1 | 2009-05-28 11:29 |
| MOT test number | 263618549185 |
| Result | ✗ Failed |
| Fail | Offside Front Tyre has ply or cords exposed (4.1.D.1b) |



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

| | |
|----------------------|---|
| Number of plates | 1 |
| Current registration |  XXXXXX |
| Plate since | 2020-01-01 |
| Current registration |  XXXXXX |
| Plate since | 2020-01-01 |

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

| | | |
|-------------------|----------|------|
| Finance company | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type | XXXXXXXX | XXXX |
| Agreement term | XXXXXXXX | XXXX |
| Agreement number | XXXXXXXX | XXXX |
| Contact info | XXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 20 |
| First mileage registration | 2006-05-26 |
| Last registration | 2020-10-09 |
| Complete history | See info |



| | | |
|------------------|------------|------------|
| Registration #1 | 2006-05-26 | 22 mi |
| Registration #2 | 2009-05-28 | 28.741 mi |
| Registration #3 | 2009-05-28 | 28.743 mi |
| Registration #4 | 2010-05-17 | 35.289 mi |
| Registration #5 | 2011-03-19 | 40.632 mi |
| Registration #6 | 2011-04-15 | 40.640 mi |
| Registration #7 | 2012-04-26 | 53.107 mi |
| Registration #8 | 2013-05-27 | 67.460 mi |
| Registration #9 | 2014-09-23 | 87.910 mi |
| Registration #10 | 2015-09-29 | 99.901 mi |
| Registration #11 | 2016-05-20 | 111.892 mi |
| Registration #12 | 2017-05-20 | 123.883 mi |
| Registration #13 | 2018-05-20 | 135.874 mi |
| Registration #14 | 2019-05-20 | 147.865 mi |
| Registration #15 | 2020-05-20 | 159.856 mi |
| Registration #16 | 2021-05-20 | 171.847 mi |
| Registration #17 | 2022-05-20 | 183.838 mi |
| Registration #18 | 2023-05-20 | 195.829 mi |
| Registration #19 | 2024-05-20 | 207.820 mi |
| Registration #20 | 2025-05-20 | 219.811 mi |

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1794 mm |
| Height | 1635 mm |
| Length | 4407 mm |
| Wheel base | 2678 mm |
| Max. allowed weight | 2210 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 60 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 7 |

Engine number

BRU 097436