



TOYOTA



report date: 2024-03-28

General information

Make	TOYOTA
Model	PREVIA D-4D T SPIRIT 7STR
Colour	Silver
Year of manufacture	-
Top speed	109 mph
0 - 60 mph	13.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	250 Nm at 3.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	31.4 mpg
Consumption extra urban	46.3 mpg
Consumption combined	39.2 mpg



LABEL UNKNOWN

**MOT history**

MOT #22	2022-03-30 12:11
MOT test number	939128510729
Result	✓ Passed
Next expiry date	2023-03-29
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #21	2021-03-19 14:26
MOT test number	930147203766
Result	✓ Passed

MOT #20	2019-12-06 11:41
MOT test number	544960301765
Result	✓ Passed

- Advice** Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Minor** Nearside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))
- Advice** Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))

**MOT #19**

2019-12-06 11:41

MOT test number

624009262083

Result**✗ Failed**

- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Minor** Nearside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice** Nearside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice** Offside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Pass with rectification** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

**MOT #18**

2018-12-05 12:30

MOT test number

874049156334

Result

✓ Passed

- Advice** Offside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))
- Minor** Nearside Front Lower Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Oil leak, but not excessive from sump gasket (8.4.1 (a) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #17**

2018-12-05 12:30

MOT test number

183977801365

Result**✗ Failed**

- Advice** Offside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))
- Advice** Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Minor** Nearside Front Lower Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))
- Advice** Nearside Front Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Oil leak, but not excessive from sump gasket (8.4.1 (a) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #16**

2017-12-05 12:36

MOT test number

950294034165

Result

✓ Passed

- Advice** Offside Front Headlamp deteriorated but light output not reduced (1.7.5a)
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Rear coil spring corroded (2.4.C.1b)
- Advice** Nearside Front Headlamp deteriorated but light output not reduced (1.7.5a)
- Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Offside Rear coil spring corroded (2.4.C.1b)

MOT #15

2016-11-29 12:40

MOT test number

779351486192

Result

✓ Passed

- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #14**

2015-12-07 13:36

MOT test number

410469325510

Result

✓ Passed

Advice Nearside Rear axle bush is worn**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Offside Rear axle bush is worn**MOT #13**

2014-12-05 13:15

MOT test number

287309334355

Result

✓ Passed

Advice Front Brake pad(s) wearing thin (3.5.1g)**Notice** Rear axle bushes deteriorated but not resulting in excessive movement**MOT #12**

2013-12-06 13:50

MOT test number

607350143382

Result

✓ Passed

Notice Offside number plate lamp is dim.**Notice** Oil leak**Notice** Both front lower suspension arm bushs are split.**Notice** High level stop light not working.**Notice** Nearside lower corner of windscreen is cracked.**Notice** Aux belt is lose.**Notice** Both front outer cv joint are noisy.**Notice** Rear coil springs are corroded.**Notice** Small crackin in offside rear light.

**MOT #11**

2013-12-04 13:35

MOT test number

508908333311

Result**✗ Failed**

- Notice** Small crackin in offside rear light.
- Notice** Both front lower suspension arm bushs are split.
- Fail** Nearside Headlamp excessively deteriorated so that the light output is severely reduced (1.7.5a)
- Notice** Aux belt is lose.
- Notice** High level stop light not working.
- Notice** Both front outer cv joint are noisy.
- Notice** Nearside lower corner of windscreen is cracked.
- Notice** Rear coil springs are corroded.
- Notice** Offside number plate lamp is dim.
- Notice** Oil leak
- Advice** Offside Headlamp deteriorated but light output not reduced (1.7.5a)

MOT #10

2012-12-04 14:59

MOT test number

277829032347

Result**✓ Passed**

- Notice** Oil leak
- Advice** Nearside Front Lower Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Notice** Centre rear seat-belt slow retracting

**MOT #9** 2012-12-04 14:59**MOT test number** 975039732379**Result** ✗ Failed**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Nearside Front Lower Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Notice** Oil leak**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Nearside Rear Registration plate lamp not working (1.1.C.1d)**Notice** Centre rear seat-belt slow retracting**MOT #8** 2012-11-26 14:41**MOT test number** 338141132394**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Fail** Nearside Stop lamp not working (1.2.1b)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Registration plate lamp not working (1.1.C.1d)**MOT #7** 2011-12-01 12:26**MOT test number** 658305931321**Result** ✓ Passed**MOT #6** 2010-12-02 14:47**MOT test number** 381656730379**Result** ✓ Passed

**MOT #5** 2010-12-02 12:30**MOT test number** 921606630371**Result** ✗ Failed**Fail** Registration plate lamp not working (1.1.C.1d)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #4** 2009-12-03 11:04**MOT test number** 903517339356**Result** ✓ Passed**MOT #3** 2008-12-04 15:20**MOT test number** 454249538402**Result** ✓ Passed**MOT #2** 2008-12-03 15:45**MOT test number** 683218638304**Result** ✗ Failed**Advice** Nearside Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Fail** Centre Rear Seat belt damaged sufficient to obstruct correct operation of the belt (5.2.2a)**Fail** Offside Front Headlamp aim too high (1.8)**Advice** Offside Front brake disc slightly scored (3.5.1h)**Fail** Nearside Front Headlamp aim aimed so that it dazzles other road users (1.8.A.1a)**Advice** Nearside Front brake disc slightly scored (3.5.1h)**MOT #1** 2007-08-11 13:54**MOT test number** 512653427263**Result** ✓ Passed



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	GV04BFP
Plate since	2019-09-29
Current registration	GV04BFP
Plate since	2019-09-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2004-03-24
Last registration	2022-03-30
Complete history	See info



Registration #1	2004-03-24	12 mi
Registration #2	2007-08-11	30.971 mi
Registration #3	2008-12-03	40.092 mi
Registration #4	2008-12-04	40.092 mi
Registration #5	2009-12-03	53.421 mi
Registration #6	2010-12-02	63.145 mi
Registration #7	2010-12-02	63.154 mi
Registration #8	2011-12-01	67.511 mi
Registration #9	2012-11-26	70.795 mi
Registration #10	2012-12-04	70.951 mi
Registration #11	2013-12-04	75.008 mi
Registration #12	2014-12-04	75.008 mi
Registration #13	2015-12-04	75.008 mi
Registration #14	2016-12-04	75.008 mi
Registration #15	2017-12-04	75.008 mi
Registration #16	2018-12-04	75.008 mi
Registration #17	2019-12-04	75.008 mi
Registration #18	2020-12-04	75.008 mi
Registration #19	2021-12-04	75.008 mi
Registration #20	2022-03-30	75.008 mi
Registration #21	2022-03-30	75.008 mi
Registration #22	2022-03-30	75.008 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1800 mm
Height	1845 mm
Length	4750 mm
Wheel base	2900 mm
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	87 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	6
Number of axles	2

Engine number

1CD0386524