





report date: 2024-03-29

General information

Make	MAZDA
Model	5 FURANO LIMITED EDITION
Colour	Red
Year of manufacture	2006
Gearbox	5 speed Manual

Engine & fuel consumption

Power	144 BHP
Max. torque	185 Nm at 4.500 rpm
Engine capacity	1.999 сс
Cylinders	4
Fuel type	Petrol
Consumption city	25.7 mpg
Consumption extra urban	42.8 mpg
Consumption combined	34.4 mpg
CO2 emission	198 g/km
CO2 label	J



CarCheck.co.uk page 1/18



report date: 2024-03-29

Internet history

Entry 1

Date	2022-02-16	
Pictures	1	
Listing price	<u>View report</u>	



source: autotrader.co.uk

CarCheck.co.uk page 2/18



report date: 2024-03-29

MOT history

MOT expiry date	2023-03-10
MOT pass rate	65 %
MOT passed	15
Failed MOT tests	8
Total advice items	79
Total items failed	19

MOT #23	2022-03-11 11:44
MOT test	number 240684610762
Result	✓ Passed
Next exp	iry date 2023-03-10
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Minor (i))	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b)
Advice (i))	Nearside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a)
Advice	Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice (i))	Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a)
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Minor	Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Advice	Offside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice (a) (i))	Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))

CarCheck.co.uk page 3/18



report date: 2024-03-29

MOT #22 2022-03-10 11:13

MOT test number 457235082011

Result X Failed

Fail Nearside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength (5.3.6 (a) (i))

Advice Offside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Exhaust has a minor leak of exhaust gases (6.1.2 (a))

Fail Exhaust emits excessive dense blue smoke during acceleration (8.2.1.2 (g))

Advice Nearside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Minor Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Fail Offside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength (5.3.6 (a) (i))

Fail Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

Advice Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))

CarCheck.co.uk page 4/18



report date: 2024-03-29

MOT #21 2021-03-09 14:06

MOT test number 475566800168

Result ✓ Passed **Advice** Nearside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii)) **Advice** Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) **Advice** Nearside Rear Upper Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) **Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Nearside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) Advice Nearside Rear Inner Vehicle structure is corroded but structural rigidity is not significantly reduced sill (6.1.1 (c) (i)) **Advice** Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Advice Nearside Rear Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Offside Rear Upper Suspension arm pin or bush worn but not resulting in excessive movement Advice (5.3.4 (a) (i)) Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) **Advice** Offside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement

(5.3.4 (a) (i))

Advice Offside Rear Inner Vehicle structure is corroded but structural rigidity is not significantly reduced sill (6.1.1 (c) (i))

CarCheck.co.uk page 5/18



report date: 2024-03-29

MOT #20 2021-03-09 09:08

MOT test number 329358130660

Result

× Failed

Advice Nearside Rear Inner Vehicle structure is corroded but structural rigidity is not significantly reduced sill (6.1.1 (c) (i))

Advice Nearside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

Advice Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Upper Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Fail Nearside Rear Inner Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Offside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Rear Inner Vehicle structure is corroded but structural rigidity is not significantly reduced sill (6.1.1 (c) (i))

Advice Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Rear Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Rear Upper Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Fail Offside Rear Inner Tyre has ply or cords damaged (5.2.3 (d) (ii))

Advice Nearside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #19 2020-03-02 13:13

MOT test number 901557214899

Result \(\sqrt{Passed} \)

Advice Front Brake disc worn, pitted or scored, but not seriously weakened times two (1.1.14 (a) (ii))

CarCheck.co.uk page 6/18



report date: 2024-03-29

MOT #18 2020-02-29 09:55 **MOT** test number 510278635551 Result × Failed Fail Front Brakes imbalanced across an axle (1.2.1 (b) (i)) Fail Parking brake efficiency below requirements (1.4.2 (a) (i)) **Advice** Front Brake disc worn, pitted or scored, but not seriously weakened times two (1.1.14 (a) (ii)) Fail Front Windscreen washer provides insufficient washer liquid (3.5 (a)) Fail Nearside Rear Parking brake inoperative on one side (1.4.1 (a)) Fail Offside Rear Service brake excessively binding (1.2.1 (f)) Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii)) Fail Fail Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))

MOT #17

MOT test number

Result

Advice Nearside Rear trailing arm bush worn

Advice Offside Rear trailing arm bush worn

MOT #16

MOT test number

Fasult

Advice Offside Rear trailing arm bush worn

Pass with rectification Nearside Front Position lamp not working (4.2.1 (a))

Advice Nearside Rear trailing arm bush worn

CarCheck.co.uk page 7/18



Advice

(2.4.G.2)

BP550TV

report date: 2024-03-29

MOT #15 2018-01-15 08:21 **MOT test number** 306664613524 Result ✓ Passed MOT #14 2017-01-16 13:33 **MOT** test number 554937647338 Result ✓ Passed **Advice** Nearside Rear tyre stepped on inner edge Advice Nearside Rear Radius arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)Advice Offside Rear tyre stepped on inner edge

Offside Rear Radius arm rubber bush deteriorated but not resulting in excessive movement

MOT #13		2017-01-16 13:27
MOT test	number	742921563032
Result		✓ Passed
Advice	Nearside Rear tyre stepped on inner edge	
Advice (2.4.G.2)	Nearside Rear Radius arm rubber mounting deteriorated but not resulting	in excessive movement
Advice	Offside Rear tyre stepped on inner edge	
Advice (2.4.G.2)	Offside Rear Radius arm rubber mounting deteriorated but not resulting in	n excessive movement

CarCheck.co.uk page 8/18



report date: 2024-03-29

MOT #12 2017-01-16 09:33 **MOT test number** 356844522221 Result × Failed **Advice** Nearside Rear Radius arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)Fail Nearside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2) **Advice** Offside Rear tyre stepped on inner edge **Advice** Offside Rear Radius arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)Advice Nearside Rear tyre stepped on inner edge

MOT #11		2016-01-18 10:55
MOT test	number	919669487696
Result		✓ Passed
Advice	Offside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)	
Advice	Nearside Front Tyre worn close to the legal limit 2mm (4.1.E.1)	

MOT #10		2015-02-09 10:51
MOT test number		976370945044
Result		✓ Passed
MOT #9		2015-02-09 10:51
MOT test number		136550745448
Result		X Failed
Pass with rectification	Front Headlamp aim too high (1.8)	

MOT #8	2014-01-20 17:10
MOT test number	968980324007
Result	✓ Passed

CarCheck.co.uk page 9/18



report date: 2024-03-29

MOT #7 2014-01-20 10:52

MOT test number 549720224034

Result X Failed

Advice Offside Front Suspension arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)

Fail Nearside Front Suspension arm rubber mounting bonding deteriorated resulting in excessive movement (2.4.G.2)

MOT #6 2013-01-16 11:18

MOT test number 486146913057

Result ✓ Passed

Notice Passenger seat(s) missing at time of test

Notice N/s front tyre wearing thin on inner edge

Notice O/s rear tyre wearing unevenly (steped)

Notice N/s rear tyre wearing on inner edge

MOT #5 2013-01-16 11:18

MOT test number 458216513050

Result X Failed

Notice N/s front tyre wearing thin on inner edge

Notice O/s rear tyre wearing unevenly (steped)

Notice N/s rear tyre wearing on inner edge

Notice Passenger seat(s) missing at time of test

Pass with rectification Nearside Registration plate lamp not working (1.1.C.1d)

MOT #4 2012-01-20 13:18

MOT test number 116250622018

Result
✓ Passed

Notice REAR EXHAUST HEAT SHIELD INSECURE

CarCheck.co.uk page 10/18



report date: 2024-03-29

MOT #3	2011-02-16 09:31
MOT test number	115107741001
Result	✓ Passed
MOT #2	2010-05-24 15:24
MOT test number	404794840110
Result	✓ Passed
Notice Nail in rear tyre	

 MOT #1
 2009-05-27 12:31

 MOT test number
 852277449114

 Result
 ✓ Passed

CarCheck.co.uk page 11/18



report date: 2024-03-29

Tax & MOT check



Tax expired: 28 November 2022

X MOT

Expired: 10 March 2023

Tax status	Expired at 28 November 2022
Days left	519 days too late
MOT expiry date	10 March 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-

CarCheck.co.uk page 12/18



report date: 2024-03-29

Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 13/18



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 14/18



report date: 2024-03-29

Owner	history
	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,

e mier metery	
For how long did the current and previous owner(s) have this MAZDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full research	

	More info >
Plate changes	
See in this check if this MAZDA had different number plates.	
Number of plates	
Current registration	AIS UK
Plate since	
Current registration	AIR AIR
Plate since	
	More info >

CarCheck.co.uk page 15/18



BP550TV report date: 2024-03-29

Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 16/18



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2006-01-31
Last registration	2022-03-11
Complete history	See info



Registration #1	2006-01-31	28 mi
Registration #2	2009-05-27	29.958 mi
Registration #3	2010-05-24	37.678 mi
Registration #4	2011-02-16	41.404 mi
Registration #5	2012-01-20	48.704 mi
Registration #6	2013-01-16	59.254 mi
Registration #7	2014-01-20	69.112 mi
Registration #8	2014-01-20	69.112 mi
Registration #9	2015-02-09	75.532 mi
Registration #10	2016-01-18	82.819 mi
Registration #10		
Registration #11	2017-01-16	49.771 mi
•	2017-01-16 2017-01-16	49.771 mi 49.771 mi
Registration #11		
Registration #11 Registration #12	2017-01-16	
Registration #11 Registration #12 Registration #13	2017-01-16	
Registration #11 Registration #12 Registration #13 Registration #14	2017-01-16	
Registration #11 Registration #12 Registration #13 Registration #14 Registration #15	2017-01-16	
Registration #11 Registration #12 Registration #13 Registration #14 Registration #15 Registration #16	2017-01-16	
Registration #11 Registration #12 Registration #13 Registration #14 Registration #15 Registration #16 Registration #17	2017-01-16	
Registration #11 Registration #12 Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18	2017-01-16	
Registration #11 Registration #12 Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19	2017-01-16	
Registration #11 Registration #12 Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20	2017-01-16	

More info >

CarCheck.co.uk page 17/18



report date: 2024-03-29

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1755 mm
Height	1665 mm
Length	4505 mm
Wheel base	2750 mm
Max. allowed weight	2100 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	7
Engine number	LF 162759

CarCheck.co.uk page 18/18