



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	FOX URBAN FOX
Colour	Grey
Year of manufacture	-
Top speed	92 mph
0 - 60 mph	17.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	55 BHP
Max. torque	108 Nm at 3.000 rpm
Cylinders	3
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg



LABEL UNKNOWN



MOT history

MOT #22	2022-11-24 17:13
MOT test number	623921037904
Result	✓ Passed
Next expiry date	2023-11-23
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Advice	Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice	Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #21	2022-10-11 08:46
MOT test number	459305962762
Result	✗ Failed
Fail	Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
Fail	Nearside Front Inner Track rod end ball joint has excessive play (2.1.3 (b) (i))
Fail	Emissions not tested Aborted due to excessive smoke, requires further diagnosis (8.2.1.2 (d))
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Windscreen washer provides insufficient washer liquid (3.5 (a))
Advice	Nearside Rear Light cluster damage
Fail	Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #20**

2021-09-20 20:13

MOT test number

811621929218

Result

✓ Passed

Advice

Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #19

2020-10-30 16:36

MOT test number

825592481095

Result

✓ Passed

Advice

Offside Front Suspension arm pin or bush worn but not resulting in excessive movement bush split (5.3.4 (a) (i))

Advice

Front bumper damaged

Advice

Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice

Coil spring corroded O/S/F, N/S/R and O/S/R (5.3.1 (b) (i))

Advice

Nearside Brake cable damaged but not to excess (1.1.15 (a))

Advice

Front Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice

Oil leak, but not excessive (8.4.1 (a) (i))

Advice

Play in steering rack inner joint(s)

Advice

Offside Front Brake hose slightly deteriorated badly perished (1.1.12 (b) (ii))

**MOT #18**

2020-10-30 16:36

MOT test number

380995208190

Result**✗ Failed****Pass with rectification** Offside Rear Tyre not fitted in accordance with side wall instructions (5.2.3 (i))**Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement bush split (5.3.4 (a) (i))**Pass with rectification** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Play in steering rack inner joint(s)**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Offside Front Brake hose slightly deteriorated badly perished (1.1.12 (b) (ii))**Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Nearside Brake cable damaged but not to excess (1.1.15 (a))**Advice** Front bumper damaged**Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))**Pass with rectification** Windscreen washer not working (3.5 (a))**Advice** Coil spring corroded O/S/F, N/S/R and O/S/R (5.3.1 (b) (i))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))



MOT #17

2019-09-20 07:51

MOT test number

207999338044

Result		✓ Passed
Advice	Front bumper damaged (lower / centre)	
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))	
Advice	Offside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))	
Advice	Nearside Brake cable damaged but not to excess (1.1.15 (a))	
Advice	Coil spring corroded O/S/F, N/S/R and O/S/R (5.3.1 (b) (i))	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Play in steering rack inner joint(s)	
Advice	Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))	

**MOT #16**

2019-09-17 15:39

MOT test number

334786648711

Result**✗ Failed**

- Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Fail** Windscreen washer not working (3.5 (a))
- Advice** Play in steering rack inner joint(s)
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Coil spring corroded O/S/F, N/S/R and O/S/R (5.3.1 (b) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Front bumper damaged (lower / centre)
- Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Fail** Nearside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))
- Fail** Nearside Front Brake hose excessively deteriorated (1.1.12 (b) (ii))
- Advice** Nearside Brake cable damaged but not to excess (1.1.15 (a))

**MOT #15**

2019-02-04 16:27

MOT test number

414233975240

Result

✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))
- Advice** Coil spring corroded N/S/R and O/S/R (5.3.1 (b) (i))
- Advice** Play in steering rack inner joint(s)
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge 3mm and perished (5.2.3 (e))
- Minor** Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #14

2019-02-04 16:27

MOT test number

560426029277

Result

✗ Failed

- Minor** Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Play in steering rack inner joint(s)
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))
- Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge 3mm and perished (5.2.3 (e))
- Advice** Coil spring corroded N/S/R and O/S/R (5.3.1 (b) (i))

**MOT #13**

2017-11-03 12:58

MOT test number

205652154943

Result

✓ Passed

Advice

Offside Rear tyre worn on inner edge

MOT #12

2017-11-02 10:52

MOT test number

158193987034

Result

✗ Failed

Fail

Nearside Outer Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

Advice

Offside Rear tyre worn on inner edge

Fail

Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)

Fail

Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Fail

Offside Front Suspension arm rubber bush deteriorated resulting in excessive movement rear bush (2.4.G.2)

Fail

Windscreen washer provides insufficient washer liquid (8.2.3)

Fail

Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #11

2016-11-04 12:58

MOT test number

729183843922

Result

✓ Passed

Advice

Unable to test any components visible from boot

Advice

Oil leak

Advice

Unable to open boot

Advice

Nearside Front Play in steering rack inner joint(s)

**MOT #10**

2016-11-04 09:39

MOT test number

271621976834

Result

✗ Failed

Fail Offside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)

Advice Nearside Front Play in steering rack inner joint(s)

Advice Unable to open boot

Fail Nearside Suspension arm rubber mounting deteriorated resulting in excessive movement (2.4.G.2)

Advice Oil leak

Advice Unable to test any components visible from boot

MOT #9

2015-11-11 15:03

MOT test number

567633331724

Result

✓ Passed

Advice Offside Front Anti-roll bar linkage ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

MOT #8

2014-10-31 16:39

MOT test number

418664204373

Result

✓ Passed

Advice Offside Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

Notice Play in steering rack inner joint(s)

Notice Nearside rear tyre perished but not showing cords

Advice Nearside Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

Notice Vehicle's internal headlight adjuster altered to recheck lights

**MOT #7**

2014-10-31 09:40

MOT test number

406464104490

Result**✗ Failed****Fail** Offside Front Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Nearside Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Notice** Vehicle's internal headlight adjuster altered to recheck lights**Fail** Nearside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Notice** Play in steering rack inner joint(s)**Advice** Offside Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Notice** Nearside rear tyre perished but not showing cords**MOT #6**

2013-11-04 11:20

MOT test number

155698703349

Result**✓ Passed****Advice** Nearside Front Road wheel slightly damaged (4.2.A.1a)**Notice** Child seat fitted not allowing full inspection of adult belt**Notice** Vehicle's internal headlight adjuster altered to recheck lights**Notice** Items removed from driver's view prior to test**Notice** Under-trays fitted obscuring some underside components**Notice** Nearside front wheel trim slightly damaged

**MOT #5** 2013-11-04 11:20**MOT test number** 957438803300**Result** ✗ Failed**Pass with rectification** Nearside Front Headlamp aim too low (1.8)**Notice** Under-trays fitted obscuring some underside components**Notice** Nearside front wheel trim slightly damaged**Pass with rectification** Offside Rear Rear fog lamp not working (1.3.2b)**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Nearside Front Road wheel slightly damaged (4.2.A.1a)**Notice** Vehicle's internal headlight adjuster altered to recheck lights**Notice** Items removed from driver's view prior to test**MOT #4** 2012-11-14 10:23**MOT test number** 226679012391**Result** ✓ Passed**Notice** Both rear tyres cracking and perishing**Notice** Offside front tyre wearing low and cracking**Advice** Offside Front Anti-roll bar linkage ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)**MOT #3** 2011-11-14 12:56**MOT test number** 225738711305**Result** ✓ Passed**MOT #2** 2011-05-03 17:00**MOT test number** 277403521458**Result** ✓ Passed



MOT #1	2010-04-27 16:57
MOT test number	893997910106
Result	✓ Passed
<div>NoticeBoth tear tyre walls starting to perish</div>	



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 VA56 HSV
Plate since	2019-06-29
Current registration	 VA56 HSV
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2007-02-05
Last registration	2022-11-24
Complete history	See info



Registration #1	2007-02-05	27 mi
Registration #2	2010-04-27	26.684 mi
Registration #3	2011-05-03	32.462 mi
Registration #4	2011-11-14	34.887 mi
Registration #5	2012-11-14	39.585 mi
Registration #6	2013-11-04	46.575 mi
Registration #7	2014-10-31	54.306 mi
Registration #8	2014-10-31	54.306 mi
Registration #9	2015-11-11	62.558 mi
Registration #10	2016-11-04	71.581 mi
Registration #11	2016-11-04	71.582 mi
Registration #12	2016-11-04	71.582 mi
Registration #13	2016-11-04	71.582 mi
Registration #14	2016-11-04	71.582 mi
Registration #15	2016-11-04	71.582 mi
Registration #16	2016-11-04	71.582 mi
Registration #17	2016-11-04	71.582 mi
Registration #18	2016-11-04	71.582 mi
Registration #19	2016-11-04	71.582 mi
Registration #20	2016-11-04	71.582 mi
Registration #21	2016-11-04	71.582 mi
Registration #22	2016-11-04	71.582 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1660 mm
Height	1544 mm
Length	3828 mm
Wheel base	2465 mm
Kerb weight	1069 kg
Max. allowed weight	1480 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	BMD 313622