



Mercedes-Benz

FL06PYF

report date: 2024-03-28

General information

Make	MERCEDES-BENZ
Model	VITO 109 CDI LONG P/V
Colour	Red
Year of manufacture	-
Gearbox	6 speed Manual

Engine & fuel consumption

Power	88 BHP
Max. torque	240 Nm at 1.400 rpm
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-12-30
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT #23 2022-10-27 08:20

MOT test number 779592903427

Result ✗ Failed

- MAJOR** Offside Front Position lamp not working (4.2.1 (a) (ii))
- MAJOR** Offside Stop lamp(s) not working (4.3.1 (a) (ii))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- MAJOR** Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))
- DANGEROUS** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Nearside Front tyre on 1.6mm only 195/65x16 /104/102t
- MAJOR** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))
- Advice** Fuel injector leaking
- MAJOR** Offside Headlamp aim projected beam image is obviously incorrect headlight damp (4.1.2 (c))
- Minor** Nearside Rear Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- MAJOR** Steering box leaking to the extent that oil is dripping cooler pipe leaking (2.1.1 (e) (ii))
- Advice** Front brake pads on 3mm only
- MAJOR** Nearside Front Front passenger door cannot be opened from outside the vehicle (6.2.3 (a))
- DANGEROUS** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Rear brake discs corroded

**MOT #22**

2021-09-08 16:19

**MOT test number**

465773593582

**Result**

✓ Passed

**Minor** Offside Front Position lamp light intensity obviously reduced (4.2.3 (a) (i))**Minor** Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Rear Exhaust emits excessive smoke or vapour but not likely to obscure the vision of other road users (8.2.2.2 (c))**MOT #21**

2021-09-07 10:27

**MOT test number**

665597603139

**Result**

✗ Failed

**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MAJOR** Offside Front Parking brake lever missing handle missing (1.1.6 (d))**Minor** Offside Front Position lamp light intensity obviously reduced (4.2.3 (a) (i))**Minor** Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))**Advice** Rear Exhaust emits excessive smoke or vapour but not likely to obscure the vision of other road users (8.2.2.2 (c))**MOT #20**

2020-07-29 17:04

**MOT test number**

957518052154

**Result**

✓ Passed

**Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))**Advice** Offside Parking brake lever defective but can be satisfactorily operated (1.1.6 (d))

**MOT #19** 2020-07-29 17:04**MOT test number** 516794444455**Result** ✗ Failed**Advice** Offside Parking brake lever defective but can be satisfactorily operated (1.1.6 (d))**Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))**Pass with rectification** Nearside Headlamp aim too high and too far to the right. (4.1.2 (a))**MOT #18** 2019-07-30 14:35**MOT test number** 360512057160**Result** ✓ Passed**Advice** Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))**Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))**MOT #17** 2018-08-02 16:47**MOT test number** 844624974459**Result** ✓ Passed**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Offside Front Anti-roll bar pin or bush worn but not resulting in excessive movement d bush (5.3.4 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Nail in tyre unrepairable**Advice** Nearside Front Anti-roll bar pin or bush worn but not resulting in excessive movement d bush (5.3.4 (a) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #16**

2018-07-31 16:33

**MOT test number**

955460049305

**Result****✗ Failed****DANGEROUS** Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MAJOR** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Anti-roll bar pin or bush worn but not resulting in excessive movement d bush (5.3.4 (a) (i))**MAJOR** Offside Rear Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MAJOR** Driver's seat with a defective structure (6.2.5 (a) (i))**Minor** Nearside Rear Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))**MAJOR** Offside Headlamp insecure (4.1.1 (c))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Offside Front Anti-roll bar pin or bush worn but not resulting in excessive movement d bush (5.3.4 (a) (i))**Advice** Offside Rear Nail in tyre unrepairable**MAJOR** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**MAJOR** Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))**MOT #15**

2017-07-24 15:10

**MOT test number**

968656453989

**Result****✓ Passed****Advice** Parking brake just met requirements**Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)



MOT #14	2017-07-21 13:42
MOT test number	808611190176
Result	✗ Failed
Advice	Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)
Advice	Brake warning light on
Advice	Rear Brake pad(s) wearing thin (3.5.1g)
Fail	Offside Stop lamp not working (1.2.1b)
Fail	Nearside Headlamp insecure (1.7.3)
Advice	Parking brake just met requirements
Fail	Offside Rear Coil spring not correctly located (2.4.C.2)

MOT #13	2016-08-01 11:42
MOT test number	683194230570
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Both front tyres worn on outer edge & have slight sidewall damage
Advice	Centre Propshaft universal joint worn Play is excessive
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #12**

2016-07-30 10:57

**MOT test number**

418911780388

**Result****✗ Failed**

- Fail** Offside Front Brake hose excessively deteriorated (3.6.B.4d)
- Fail** Nearside Registration plate lamp not working (1.1.C.1d)
- Advice** Offside Front Outer Tyre worn close to the legal limit (4.1.E.1)
- Fail** Nearside Front Anti-roll bar rubber mounting deteriorated resulting in excessive movement (2.4.G.2)
- Advice** Offside Rear Inner Tyre worn close to the legal limit (4.1.E.1)
- Advice** Centre Propshaft universal joint worn Play is excessive
- Fail** Nearside Front Brake hose excessively deteriorated (3.6.B.4d)
- Advice** Centre Stop lamp has light sources not illuminating, but not more than 50% (1.2.1b)
- Advice** Nearside Front Outer Tyre worn close to the legal limit (4.1.E.1)
- Fail** Nearside Headlamp insecure (1.7.3)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Fail** Offside Front Anti-roll bar rubber mounting deteriorated resulting in excessive movement (2.4.G.2)
- Fail** Front brake binding (3.7.B.1)

**MOT #11**

2015-07-30 14:14

**MOT test number**

599651615216

**Result****✓ Passed**



**MOT #10** 2015-07-30 09:32**MOT test number** 256041015239**Result** ✗ Failed**Fail** Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Offside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**MOT #9** 2014-07-31 15:24**MOT test number** 336592114208**Result** ✓ Passed**Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**MOT #8** 2013-07-31 14:49**MOT test number** 407472113203**Result** ✓ Passed**Advice** Front Brake hose slightly deteriorated (3.6.B.4d)**MOT #7** 2013-07-31 10:28**MOT test number** 788652613260**Result** ✗ Failed**Fail** Offside Rear coil spring broken (2.4.C.1a)**Advice** Front Brake hose slightly deteriorated (3.6.B.4d)**MOT #6** 2012-07-26 12:32**MOT test number** 809208602218**Result** ✓ Passed**Notice** Brake pad wear indicator illuminated but unable to view pads

**MOT #5** 2012-07-26 09:35**MOT test number** 689528302227**Result** ✗ Failed**Fail** Windscreen wiper does not clear the windscreen effectively (8.2.2)**Notice** Brake pad wear indicator illuminated but unable to view pads**Fail** Registration plate lamp not working (1.1.C.1d)**MOT #4** 2011-08-01 12:49**MOT test number** 725883811236**Result** ✓ Passed**MOT #3** 2010-03-23 16:23**MOT test number** 640072980062**Result** ✓ Passed**Advice** Brake pad(s) wearing thin (3.5.1g)**Advice** Brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2009-03-18 12:09**MOT test number** 654677379060**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #1** 2009-03-18 12:09**MOT test number** 274067479002**Result** ✗ Failed**Pass with rectification** Offside Registration plate lamp not working (1.1.5c)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How many owners did this MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES-BENZ had different number plates.

Number of plates	1
Current registration	 <b>FL06PYF</b>
Plate since	2024-03-28
Current registration	 <b>FL06PYF</b>
Plate since	2024-03-28

More info >



Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES-BENZ is financed.


Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2006-04-10
Last registration	2022-10-27
Complete history	<a href="#">See info</a>



Registration #1	2006-04-10	25 mi
Registration #2	2009-03-18	78.642 mi
Registration #3	2010-03-23	107.019 mi
Registration #4	2011-08-01	123.792 mi
Registration #5	2012-07-26	131.838 mi
Registration #6	2012-07-26	131.838 mi
Registration #7	2013-07-31	139.534 mi
Registration #8	2013-07-31	139.534 mi
Registration #9	2014-07-31	148.676 mi
Registration #10	2015-07-30	158.827 mi
Registration #11	2015-07-30	158.827 mi
Registration #12	2016-07-30	168.117 mi
Registration #13	2016-07-30	168.117 mi
Registration #14	2016-07-30	168.117 mi
Registration #15	2016-07-30	168.117 mi
Registration #16	2016-07-30	168.117 mi
Registration #17	2016-07-30	168.117 mi
Registration #18	2016-07-30	168.117 mi
Registration #19	2016-07-30	168.117 mi
Registration #20	2016-07-30	168.117 mi
Registration #21	2016-07-30	168.117 mi
Registration #22	2016-07-30	168.117 mi
Registration #23	2016-07-30	168.117 mi
Registration #24	2016-07-30	168.117 mi

More info >



Car features

The MERCEDES-BENZ factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MERCEDES-BENZ factory list for this vehicle [here](#).

More info >

Additional information

Fuel tank capacity	75 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Engine number	64698350216006