



report date: 2024-03-28

General information

Make	FORD
Model	GALAXY ZETEC TDCI (125PS)
Colour	Silver
Year of manufacture	-
Top speed	116 mph
0 - 60 mph	11.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	123 BHP
Max. torque	285 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	35.3 mpg
Consumption extra urban	53.3 mpg
Consumption combined	44.8 mpg



LABEL UNKNOWN

**MOT history**

MOT #18	2021-01-18 10:33
MOT test number	580942750321
Result	✓ Passed
Next expiry date	2022-01-17
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #17	2018-10-26 10:29
MOT test number	975353277321
Result	✓ Passed
Advice	Nearside Track rod end ball joint has slight play (2.1.3 (b) (i))
Advice	Under trays fitted
Advice	Play in steering rack inner joint(s)
Minor	Nearside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Engine covers fitted

**MOT #16**

2018-10-22 11:51

MOT test number

534202892605

Result**✗ Failed**

- Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Offside Rear Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))
- Advice** Under trays fitted
- Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))
- Fail** Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Rear Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Advice** Engine covers fitted
- Advice** Nearside Track rod end ball joint has slight play (2.1.3 (b) (i))
- Fail** Electronic stability control warning lamp indicates a fault (7.12 (e))
- Advice** Play in steering rack inner joint(s)
- Minor** Nearside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm inner edge (5.2.3 (e))
- Fail** Emissions not tested (8.2.2.2 (e))



MOT #152017-09-08 08:13

MOT test number739708429726

Result

Passed

- Advice

Bonnet catch broken
- Advice

Oil leak
- Advice

Offside front brake fluctuating, but not excessively (3.7.B.3)
- Advice

Engine light on
- Advice

Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Advice

Nearside front brake fluctuating, but not excessively (3.7.B.3)

**MOT #14**

2017-09-01 12:13

MOT test number

300423849915

Result**✗ Failed****Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Fail** Offside Front Macpherson strut has excessive movement in the upper support bearing assembly (2.5.B.1b)**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Electronic stability system warning lamp indicates a fault (3.4.1c)**Advice** Engine light on**Fail** Rear Exhaust has a major leak of exhaust gases (7.1.2)**Advice** Nearside front brake fluctuating, but not excessively (3.7.B.3)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Rear Trailing arm has excessive play in a pin/bush (2.4.G.2)**Fail** Offside Headlamp not working on dipped beam (1.7.5a)**Fail** Nearside Stop lamp not working (1.2.1b)**Fail** Nearside Front Suspension arm has excessive play in a pin/bush (2.4.G.2)**Fail** Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)**Advice** Oil leak**Fail** Offside Front Suspension arm has excessive play in a pin/bush (2.4.G.2)**Advice** Bonnet catch broken**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Rear Tie bar/rod has excessive play in a ball joint (2.4.G.2)**Advice** Offside front brake fluctuating, but not excessively (3.7.B.3)



MOT #13

2016-06-21 15:52

MOT test number

540848732764

Result

✓ Passed

- Advice

Oil leak
- Advice

Back box
- Advice

Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Advice

Engine light on
- Advice

Nearside Front Strut bearing tight
- Advice

Offside Front Oil leak entering Braking area
- Advice

Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice

Window screen Cracked but not in zone A,B

**MOT #12**

2016-06-14 08:38

MOT test number

462677762593

Result**✗ Failed****Advice** Engine light on**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Front Strut bearing tight**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Front Oil leak entering Braking area**Fail** Offside Rear Trailing arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Advice** Window screen Cracked but not in zone A,B**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Oil leak**Fail** Registration plate lamp not working (1.1.C.1d)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Back box**Fail** Electronic stability system warning lamp indicates a fault (3.4.1c)**Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)



MOT #11	2016-06-02 10:28
MOT test number	260252779637
Result	✗ Failed

Fail Registration plate lamp not working (1.1.C.1d)

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Fail Parking brake: efficiency below requirements (3.7.B.7)

Fail Parking brake lever has no reserve travel (3.1.6b)

Fail Offside Rear Trailing arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)

Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

Fail Offside Front Tyre tread depth below requirements of 1.6mm edge (4.1.E.1)

Advice Covers and trays fitted not allowing full inspection

Fail Offside Front brake disc contaminated by oil (3.5.1h)

Fail Electronic stability system warning lamp indicates a fault t c (3.4.1c)

Fail Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Advice Nearside sill damage !!!!

Advice Nearside Steering system slightly rough top bearing (2.2.D.1)

Advice Brake hydraulic reservoir fluid close to minimum level (3.6.G.1b)

Fail Offside Front position lamp(s) not working (1.1.A.3b)

Fail Front Brakes imbalanced across an axle 36% (3.7.B.5b)

Fail Nearside Rear Trailing arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

Fail Nearside Front Tyre tread depth below requirements of 1.6mm edge (4.1.E.1)

Advice Engine light on dash (fault)

Fail Nearside Rear Anti-roll bar has excessive play in a ball joint (2.4.G.2)

Fail Centre obligatory indirect vision device insecure open lid (8.1.1)

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm edge (4.1.E.1)

Advice Bad oil leak

Fail Offside Steering system excessively rough top bearing (2.2.D.1)

Fail Nearside Front position lamp(s) not working (1.1.A.3b)

Fail Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Advice Exhaust corroded

Fail Rear Brakes imbalanced across an axle 45% (3.7.B.5b)



MOT #10

2015-06-09 14:22

MOT test number

389660365118

Result		✓ Passed
Notice	Exhaust flexi worn	
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)	
Notice	Rear exhaust box corroded	
Notice	Engine light on.... acquires further inspection	
Notice	Play in steering rack inner joint(s)	
Notice	BAD OIL LEAK!!!!	
Advice	Rear coil spring corroded (2.4.C.1b)	
Notice	Both front tyres worn on edges of the tread	
Notice	Engine covers fitted obscuring some components in the engine bay	
Notice	Items removed from driver's view prior to test	
Advice	Rear Brake pad(s) wearing thin (3.5.1g)	

**MOT #9**

2015-06-06 11:09

MOT test number

739297055157

Result**✗ Failed**

- Notice** Engine covers fitted obscuring some components in the engine bay
- Notice** Items removed from driver's view prior to test
- Fail** Electronic stability system warning lamp indicates a fault (3.4.1c)
- Notice** Exhaust flexi worn
- Fail** Offside Rear Tyre has ply or cords exposed (4.1.D.1b)
- Notice** Rear exhaust box corroded
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Notice** Engine light on.... acquires further inspection
- Advice** Rear coil spring corroded (2.4.C.1b)
- Notice** Play in steering rack inner joint(s)
- Notice** BAD OIL LEAK!!!!
- Fail** Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)
- Notice** Both front tyres worn on edges of the tread
- Fail** Offside Front Steering arm has relative movement at its fixings (2.2.B.1h)
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)



MOT #8

2014-06-06 15:32

MOT test number

475387154125

Result		✓ Passed
Notice	Near side front shock absorber not cushioning	
Notice	Engine covers fitted obscuring some components in the engine bay	
Advice	Nearside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)	
Notice	Near side of screen has damage but not within the swept area	
Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)	
Notice	Near side front tyre is low on the edges of tread	
Notice	Rear shock absorbers cushioning is soft	
Notice	Oil leak	
Notice	Play in steering rack inner joint(s)	
Advice	Offside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)	
Notice	Near side outer sill slightly distorted	

**MOT #7**

2014-06-04 15:41

MOT test number

519265954187

Result**✗ Failed**

- Fail** Nearside Headlamp aim too low (1.8)
- Notice** Rear shock absorbers cushioning is soft
- Fail** Offside Front suspension ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)
- Fail** Parking brake lever has no reserve travel (3.1.6b)
- Notice** Oil leak
- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Fail** Offside Stop lamp not working (1.2.1b)
- Notice** Play in steering rack inner joint(s)
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Notice** Near side outer sill slightly distorted
- Advice** Offside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
- Notice** Near side front shock absorber not cushioning
- Fail** Offside rear brake binding (3.7.B.1)
- Fail** Electronic stability system warning lamp indicates a fault (3.4.1c)
- Fail** Nearside Front suspension has serious deterioration of the bonding between metal and flexible material of an upper support bearing (2.5.B.3a)
- Fail** Nearside Stop lamp not working (1.2.1b)
- Notice** Engine covers fitted obscuring some components in the engine bay
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Fail** Centre Exhaust has a major leak of exhaust gases (7.1.2)
- Notice** Near side of screen has damage but not within the swept area
- Advice** Nearside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
- Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Notice** Near side front tyre is low on the edges of tread

**MOT #6** 2014-03-22 11:55**MOT test number** 316441684030**Result** ✗ Failed**Fail** Offside Stop lamp not working (1.2.1b)**Fail** Nearside Rear Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**Fail** Fuel system component leaking (7.2.3)**Advice** Offside Front Macpherson strut has slight movement in the upper support bearing assembly (2.5.B.1b)**Fail** Front brake disc in such a condition that it is seriously weakened (3.5.1i)**Notice** Exhaust heat shield insecure**Fail** Offside Rear Seat belt damaged sufficient to significantly weakened the webbing (5.2.2a)**Fail** Centre Exhaust has a major leak of exhaust gases (7.1.2)**Fail** Steering system has excessive free play detected at the steering wheel (steering rack fitted) (2.2.A.1b)**Advice** Nearside Front Macpherson strut has slight movement in the upper support bearing assembly (2.5.B.1b)**Fail** Offside Rear brake disc in such a condition that it is seriously weakened (3.5.1i)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Windscreen cracked not inside the swept area**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Notice** Flywheel vibrating excessively**Fail** Nearside Inner Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**MOT #5** 2013-02-05 13:25**MOT test number** 157536133406**Result** ✓ Passed**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**Notice** Both rear radius arm bushes starting to become unbonded

**MOT #4** 2012-02-15 17:30**MOT test number** 459166242030**Result** ✓ Passed**Notice** Engine oil leak**Notice** Offside front tyre worn on edges quite badly**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2012-02-14 16:22**MOT test number** 117595142092**Result** ✗ Failed**Fail** Nearside Outer Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Notice** Engine oil leak**Fail** Exhaust has a major leak of exhaust gases (7.1.2)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Offside front tyre worn on edges quite badly**MOT #2** 2008-03-13 16:36**MOT test number** 652693578089**Result** ✓ Passed**MOT #1** 2007-12-12 15:45**MOT test number** 410826547456**Result** ✓ Passed



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	WV08LVS
Plate since	2019-09-28
Current registration	WV08LVS
Plate since	2019-09-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2007-12-12
Last registration	2021-01-18
Complete history	See info



Registration #1	2007-12-12	5 mi
Registration #2	2008-03-13	5 mi
Registration #3	2012-02-14	251.318 mi
Registration #4	2012-02-15	251.329 mi
Registration #5	2013-02-05	288.758 mi
Registration #6	2014-03-22	337.422 mi
Registration #7	2014-06-04	73.252 mi
Registration #8	2014-06-06	73.252 mi
Registration #9	2015-06-06	81.994 mi
Registration #10	2015-06-06	81.994 mi
Registration #11	2015-06-06	81.994 mi
Registration #12	2015-06-06	81.994 mi
Registration #13	2015-06-06	81.994 mi
Registration #14	2015-06-06	81.994 mi
Registration #15	2015-06-06	81.994 mi
Registration #16	2015-06-06	81.994 mi
Registration #17	2015-06-06	81.994 mi
Registration #18	2015-06-06	81.994 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	2154 mm
Height	1736 mm
Length	4820 mm
Wheel base	2850 mm
Kerb weight	1807 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Engine number	8K54165
---------------	---------