





## General information

Make	MAZDA
Model	2 TS2
Colour	Green
Year of manufacture	2011
Top speed	107 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	84 BHP
Max. torque	122 Nm at 3.500 rpm
Engine capacity	1.349 cc
Cylinders	4
Fuel type	Petrol
Consumption city	40.9 mpg
Consumption extra urban	67.3 mpg
Consumption combined	54.3 mpg
CO2 emission	119 g/km
CO2 label	С







# Internet history

Entry 2	
Date	2021-06-14
Pictures	19
Listing price	View report



source: autotrader.co.uk

Date

Pictures

Listing price

2021-05-23 14


View report



source: autotrader.co.uk









## MOT history

MOT expiry date	2023-09-04
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	30
Total items failed	7

MOT #13	2022-09-05 15:57
MOT test number	465040433418
Result	✓ Passed
Next expiry date	2023-09-04

MOT #12		2021-01-15 09:27
MOT test	number	918354173889
Result		✓ Passed
Advice	Both rear tyres misshaping	
Advice	Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))	
Advice	Play in steering rack inner joint(s) Steering rack	

MOT #11	2020-02-06 17:47
MOT test number	253188216710
Result	✓ Passed
Advice Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))	

MOT #10	2019-09-28 11:36
MOT test number	893160535101
Result	✓ Passed
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	



SV61ZSG report date: 2024-03-29

MOT #9		2019-09-28 11:36
MOT test number		934419852074
Result		🗙 Failed
Advice Offside Rear Ty	re worn close to legal limit/worn on edge (5.2.3 (e))	
Pass with rectification	Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))	

MOT #8		2018-10-03 07:58
MOT test	number	276599157115
Result		🗸 Passed
Advice	Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))	
Advice	Sump rotten	
Advice	Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))	
Advice	Nearside Front Shock absorbers light misting of oil or has limited damping effect	: (5.3.2 (b))

MOT #7	2018-09-29 09:22
MOT test number	986450403535
Result	× Failed
Advice Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))	
Advice Sump rotten	
<b>Fail</b> Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))	
FailNearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))	
Advice Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))	
Advice Nearside Front Shock absorbers light misting of oil or has limited damping e	effect (5.3.2 (b))
<b>Fail</b> Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))	



SV61ZSG
report date: 2024-03-29

MOT #6		2017-09-29 14:02
MOT test	number	464049808449
Result		✓ Passed
Advice	Nearside Front Shock absorber has a light misting of oil (2.7.3)	
Advice	Engine covers fitted not allowing full inspection	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #5	2017-09-29 14:02
MOT test number	932916922878
Result	🗙 Failed
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice Nearside Front Shock absorber has a light misting of oil (2.7.3)	
<b>Pass with rectification</b> Offside Headlamp not working on dipped beam (1.7.5a)	
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice Engine covers fitted not allowing full inspection	

MOT #4		2016-07-28 14:09
MOT test	number	599134109577
Result		✓ Passed
Advice	Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)	
Advice	Advice Nearside Rear wheel bearing is very slightly rough when rotated	
Advice rearmost b	Offside Front Suspension arm rubber bush deteriorated but not resulting i bush displaced upwards (2.4.G.2)	n excessive movement





MOT #3		2016-07-28 14:09
MOT test number		270977535999
Result		🗙 Failed
Advice Nearside Rear R	oad wheel with a slightly distorted bead rim (4.2.A.1	la)
Pass with rectification	Windscreen washer provides insufficient washer li	quid (8.2.3)
<b>Advice</b> Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rearmost bush displaced upwards (2.4.G.2)		
Advice Nearside Rear w	heel bearing is very slightly rough when rotated	
Pass with rectification	Nearside Headlamp aim beam image obviously ind	correct (1.8.A.1b)

MOT #2		2015-07-01 11:56
MOT test	number	146942985130
Result		✓ Passed
Notice	Items removed from driver's view prior to test	
Notice	Under-trays fitted obscuring some underside components	

MOT #1	2014-07-29 16:38
MOT test number	528170414251
Result	✓ Passed





### Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEIDO
Category	4. ARMPE
Туре	
Damage 2	AMPL
	F Stores
Date	1.E
Category	ante
Туре	

#### Extra MAZDA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





### Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	6 10.200
Auction value	4 10.000
Average private trade value	4 11 200





## Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	
***********	
*******	
*******	
**********	
********	
	More info >
Plate changes	
See in this check if this MAZDA had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	
	More info >





### Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-11-18
Last registration	2022-09-05
Complete history	See info



Registration #1	2011-11-18	6 mi
Registration #2	2014-07-29	18.326 mi
Registration #3	2015-07-01	31.177 mi
Registration #4	2016-07-28	46.075 mi
Registration #5	2016-07-28	46.075 mi
Registration #6	2017-09-29	57.886 mi
Registration #7	2017-09-29	57.886 mi
Registration #8	2018-09-29	65.055 mi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		01.777 est
Registration #15		11.777 mi
Registration #16		11.777 est



Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1695 mm
Height	1475 mm
Length	3885 mm
Wheel base	2490 mm
Kerb weight	1025 kg
Max. allowed weight	1455 kg
Additional information	
Additional information Fuel tank capacity	42
	42 l Multi-Point Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Multi-Point Injection
Fuel tank capacity Fuel delivery Number of doors	Multi-Point Injection 3