





report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	TOURAN TDI S 5STR
Colour	Silver
Year of manufacture	2005
Top speed	110 mph
0 - 60 mph	13.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	103 BHP
Max. torque	250 Nm at 1.900 rpm
Engine capacity	1.896 сс
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	47.1 mpg
CO2 emission	162 g/km
CO2 label	G



CarCheck.co.uk page 1/18



report date: 2024-03-29

Internet history

Entry 1

Date 2021-10-26

Pictures 3

Listing price <u>View report</u>







source: autotrader.co.uk

CarCheck.co.uk page 2/18



report date: 2024-03-29

MOT history

MOT expiry date	2024-10-12
MOT pass rate	71 %
MOT passed	17
Failed MOT tests	7
Total advice items	71
Total items failed	25

MOT #24	2023-10-13 16:18
MOT test number	128829355382
Result	✓ Passed
Next expiry date	2024-10-12
Advice Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))	
Advice Front Headlamp has a product on the lens but not seriously reducing light output both sides (4.1.4 (b))	
Advice Rear Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))	
Advice Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))	
Minor Front Windscreen wiper blade defective (3.4 (b) (i))	

MOT #23		2022-10-05 13:24
MOT test	number	379682776436
Result		✓ Passed
Advice	Front Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))	
Advice	Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))	
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))	

CarCheck.co.uk page 3/18



report date: 2024-03-29

MOT #22 2021-09-21 11:10

MOT test number 582917670234

Result ✓ Passed

Minor Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Offside Front Suspension arm modified but not seriously weakened (5.3.3 (c) (i))

Minor Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

MOT #21 2020-10-06 11:28

MOT test number 950771460397

Result \square Passed

MOT #20 2019-10-31 15:03

MOT test number 709949614704

Result ✓ Passed

Advice Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #19 2018-10-25 10:55

MOT test number 928930433443

Result

Passed

Advice Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #18 2017-11-09 13:41

MOT test number 686179686717

Result \rightarrow Passed

Advice Nearside Rear tyre, tread area slightly deteriorated

CarCheck.co.uk page 4/18



report date: 2024-03-29

MOT #17 2017-11-09 13:41

MOT test number 536680221357

Result X Failed

Pass with rectification Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)

Advice Nearside Rear tyre, tread area slightly deteriorated

MOT #16 2017-02-25 12:07

MOT test number 269257497375

Result
✓ Passed

MOT #15 2016-03-25 10:53

MOT test number 922086824959

Result \(\sqrt{Passed} \)

Advice Undertray covers fitted.

Advice Rear coil spring corroded n/s and o/s (2.4.C.1b)

MOT #14 2015-09-14 16:48

MOT test number 545525209005

Result \(\sqrt{Passed} \)

Advice Front number plate cracked

Advice Nearside Rear coil spring corroded (2.4.C.1b)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Ns mirror glass cracked

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 5/18



Result

PF05YAO

report date: 2024-03-29

X Failed

MOT #13 2015-09-08 13:45

MOT test number 869201055633

Advice Nearside Rear coil spring corroded (2.4.C.1b)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Ns mirror glass cracked

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Fail Nearside Front Outer Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

Fail Offside Front Road wheel bead rim badly distorted (4.2.A.1a)

Fail Offside Rear coil spring broken (2.4.C.1a)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Front number plate cracked

Fail Offside Stop lamp not working (1.2.1b)

Fail Nearside Front Road wheel bead rim badly distorted (4.2.A.1a)

MOT #12 2014-09-20 12:28

MOT test number 968443464293

Result ✓ Passed

Advice Offside Inner Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Notice Service light on

Advice Nearside Inner Rear Tyre worn close to the legal limit (4.1.E.1)

Notice ESP LIGHT ON DASH

Advice Nearside Outer Rear Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk page 6/18



report date: 2024-03-29

MOT #11 2014-09-18 14:06

MOT test number 308641264411

Result X Failed

Fail Front Windscreen washer provides insufficient washer liquid (8.2.3)

Fail Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Fail Nearside Outer Front constant velocity joint is insecure (2.5.C.1b)

Advice Offside Inner Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Notice Service light on

Advice Nearside Inner Rear Tyre worn close to the legal limit (4.1.E.1)

Fail Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Fail Nearside Inner Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)

Fail Nearside Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)

Notice ESP LIGHT ON DASH

Advice Nearside Outer Rear Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk page 7/18



report date: 2024-03-29

MOT #10 2013-08-23 12:05

MOT test number 805375633206

Result ✓ Passed Notice Child seat fitted not allowing full inspection of adult belt **Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2) Notice Ns mirror damaged Advice Front Brake pad(s) wearing thin (3.5.1g) Notice Nsf headlamp - top holders broken Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Notice Under-trays fitted obscuring some underside components Notice Nsr tyre - cut on the outer wall, inner shoulder slightly worn, has a nail. Notice Items removed from driver's view prior to test Advice Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2) Notice ESP warning light staying ON (electronic stability program) Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Notice Osf headlamp - top holders broken Notice Engine covers fitted obscuring some components in the engine bay

CarCheck.co.uk page 8/18



report date: 2024-03-29

× Failed

MOT #9 2013-08-22 12:52

MOT test number 748014133296

Result

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

Notice Nsf headlamp - top holders broken

Notice Child seat fitted not allowing full inspection of adult belt

Fail Nearside Outer Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

Notice Under-trays fitted obscuring some underside components

Advice Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Notice Nsr tyre - cut on the outer wall, inner shoulder slightly worn, has a nail.

Notice Items removed from driver's view prior to test

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Fail Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

Notice ESP warning light staying ON (electronic stability program)

Fail Offside Outer Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

Notice Osf headlamp - top holders broken

Advice Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Notice Engine covers fitted obscuring some components in the engine bay

Advice Front Brake pad(s) wearing thin (3.5.1g)

Fail Windscreen washer provides insufficient washer liquid (8.2.3)

Notice Ns mirror damaged

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

CarCheck.co.uk page 9/18



MOT #7

PF05YAO

report date: 2024-03-29

2011-08-31 16:16

MOT #8	2012-08-31 10:22
MOT test number	109474342211
Result	✓ Passed
Notice Traction control light on	
Notice Child seats in rear seats	

MOT test number	426403041295
Result	✓ Passed
MOT #6	2010-08-16 16:32
MOT test number	812728320247
Result	✓ Passed
MOT #5	2010-08-16 16:08
MOT test number	702808120244
Result	X Failed
Fail Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)	
Fail Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)	

MOT #4	2009-08-04 16:01
MOT test number	862006919243
Result	✓ Passed

CarCheck.co.uk page 10/18



report date: 2024-03-29

MOT #3	2009-08-04 10:42
MOT test number	882196719265
Result	≍ Failed
Fail Offside Front Tyre has ply or cords exposed (4.1.D.1b)	
Fail Nearside Front Tyre has ply or cords exposed (4.1.D.1b)	
Fail Nearside Stop lamp not working (1.2.1b)	

MOT #2	2008-07-09 11:48
MOT test number	683261098175
Result	✓ Passed
MOT #1	2008-07-09 11:27

MOT te	st number	863991698199
Result		× Failed
Fail	Nearside Stop lamp not working (1.2.1b)	
Fail	Front registration plate deteriorated (6.3.1d)	
Fail	Offside Stop lamp not working (1.2.1b)	

CarCheck.co.uk page 11/18



PF05YA0 report date: 2024-03-29

Tax & MOT check



Tax expired: 31 December 2023

Expires: 12 October 2024

Tax status

Days left

MOT expiry date

Full MOT history

Expired at 31 December 2023

121 days too late
12 October 2024

See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 12/18



report date: 2024-03-29

Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1


Date	
Category	
Туре	

Damage 2

Damage 2	
Date	
Category	



Extra VOLKSWAGEN salvage check





Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 13/18



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 14/18



report date: 2024-03-29

More info >

Owner history For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this VOLKSWAGEN had different number plates. mber of plates. -

CarCheck.co.uk page 15/18



report date: 2024-03-29

Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 16/18



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2005-06-25
Last registration	2023-10-13
Complete history	See info



Registration #1	2005-06-25	7 mi
Registration #2	2008-07-09	26.822 mi
Registration #3	2008-07-09	26.822 mi
Registration #4	2009-08-04	36.746 mi
Registration #5	2009-08-04	36.746 mi
Registration #6	2010-08-16	42.791 mi
Registration #7	2010-08-16	42.791 mi
Registration #8	2011-08-31	51.204 mi
Registration #9	2012-08-31	57.390 mi
Registration #10	2013-08-22	63.053 mi
Registration #11	2013-08-23	63.053 mi
Registration #12	2014-09-18	70.718 mi
Registration #13	2014-09-20	70.718 mi
Registration #14		71.777 es
Registration #15		11.777 es
Registration #16		71.777 es
Registration #17		11.777 es
Registration #18		71.777 es
Registration #19		71.777 es
Registration #20		71.777 es
Registration #21		71.777 es
Registration #22		71.777 es
Registration #23		11.777 es
Registration #24		11.777 es
Registration #25		11.777 es
Registration #26		111,7177 ess

CarCheck.co.uk page 17/18



PF05YA0 report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	2066 mm
Height	1635 mm
Length	4391 mm
Wheel base	2677 mm
Kerb weight	1498 kg
Max. allowed weight	2210 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
CarChaeleeeule	no and 10/10

CarCheck.co.uk page 18/18

Number of seats	7
Engine number	BKC 732958