



HYUNDAI




report date: 2024-03-29

General information

Make	HYUNDAI
Model	I800 CRDI STYLE
Colour	Silver
Year of manufacture	2012
Top speed	112 mph
0 - 60 mph	14.4 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	168 BHP
Max. torque	440 Nm at 2.500 rpm
Engine capacity	2.497 cc
Cylinders	4
Fuel type	Diesel
Consumption city	25.2 mpg
Consumption extra urban	38.7 mpg
Consumption combined	32.1 mpg
CO2 emission	231 g/km
CO2 label	L





Internet history

Entry 2

Date	2021-08-27
Pictures	20
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 1

Date	2021-08-26
Pictures	20
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-06-29
MOT pass rate	58 %
MOT passed	15
Failed MOT tests	11
Total advice items	58
Total items failed	33

MOT #26 2023-06-30 11:26

MOT test number 191131217725

Result ✓ Passed

Next expiry date 2024-06-29

**Advice** Nearside Rear Valve stem slightly damaged (5.2.3 (j))

**Advice** Offside Front Play in steering rack inner joint(s)

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**Advice** Offside Rear Valve stem slightly damaged (5.2.3 (j))

MOT #25 2023-06-30 10:23

MOT test number 858299448467

Result ✗ Failed

**Advice** Nearside Rear Valve stem slightly damaged (5.2.3 (j))

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**Advice** Offside Rear Valve stem slightly damaged (5.2.3 (j))

**Advice** Offside Front Play in steering rack inner joint(s)

**Fail** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))

**MOT #24**

2023-06-15 08:32

**MOT test number**

681335475835

**Result**

✗ Failed

- Fail** Nearside Windscreen washer not working (3.5 (a))
- Advice** Offside Rear Valve stem slightly damaged (5.2.3 (j))
- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Fail** Exhaust on a vehicle fitted with a diesel particulate filter emits visible smoke of any colour (8.2.2.2 (d))
- Advice** Offside Front Play in steering rack inner joint(s)
- Fail** Offside Windscreen washer not working (3.5 (a))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Rear Valve stem slightly damaged (5.2.3 (j))
- Fail** Front Tyre(s) of different sizes are fitted on the same axle. (5.2.3 (b))
- Advice** Child Seat fitted not allowing full inspection of adult belt x2
- Fail** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))
- Pass with rectification** Offside Headlamp aim too high (4.1.2 (a))

**MOT #23**

2022-05-11 09:41

**MOT test number**

404696910955

**Result**

✓ Passed

- Advice** Front Play in steering rack inner joint(s) both sides
- Advice** Central Front exhaust flexi section outer skin deteriorated
- Advice** Central Front Lower Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt middle row seat (directly behind driver seat)

**MOT #22**

2022-05-07 14:45

**MOT test number**

736098592913

**Result**

✗ Failed

**Advice** Front Play in steering rack inner joint(s) both sides**Fail** Offside Front Headlamp aim too high (4.1.2 (a))**Advice** Central Front Lower Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt middle row seat (directly behind driver seat)**Fail** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Central Front exhaust flexi section outer skin deteriorated**Fail** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))**Fail** Nearside Rear Position lamp not working (4.2.1 (a) (ii))**MOT #21**

2021-05-13 15:35

**MOT test number**

405384296854

**Result**

✓ Passed

**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Play in steering rack inner joint(s)

**MOT #20**

2021-05-13 15:35

**MOT test number**

604852277681

**Result****✗ Failed****Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Play in steering rack inner joint(s)**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Pass with rectification** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**MOT #19**

2020-10-30 09:19

**MOT test number**

960949276767

**Result****✓ Passed****MOT #18**

2020-10-30 09:19

**MOT test number**

556631282523

**Result****✗ Failed****Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))**Pass with rectification** Offside Headlamp aim too high (4.1.2 (a))**MOT #17**

2020-08-07 15:39

**MOT test number**

599499534890

**Result****✓ Passed****Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #16** 2019-10-11 10:56**MOT test number** 188928558516**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))**MOT #15** 2019-10-10 15:07**MOT test number** 831512581026**Result** ✗ Failed**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))**Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #14** 2019-03-14 16:41**MOT test number** 692742318563**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #13**

2019-03-11 17:05

**MOT test number**

389420595041

**Result****✗ Failed****Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))**Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #12**

2018-10-03 08:17

**MOT test number**

310609355107

**Result****✓ Passed****Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))**MOT #11**

2018-09-26 16:31

**MOT test number**

514983140694

**Result****✗ Failed****Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Fail** Nearside Rear Parking (secondary brake) on a single line braking system has no recorded effort at a wheel (1.3.1 (a) (ii))**Fail** Nearside Rear Parking (secondary brake) on a single line braking system grabbing severely (1.3.1 (c))**Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))



**MOT #10** 2018-04-06 10:08**MOT test number** 271965044222**Result** ✓ Passed**Advice** Engine malfunction warning lamp indicates a fault**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #9** 2018-04-06 10:08**MOT test number** 255515094921**Result** ✗ Failed**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Engine malfunction warning lamp indicates a fault**Pass with rectification** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Offside Headlamp aim too low (1.8)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #8** 2017-09-29 16:18**MOT test number** 748060820809**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Vehicles internal headlight adjuster altered to recheck lights

**MOT #7** 2017-09-28 14:58**MOT test number** 661120015103**Result** ✗ Failed**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Vehicles internal headlight adjuster altered to recheck lights**Fail** Offside Headlamp aim aimed so that it dazzles other road users (1.8.A.1a)**MOT #6** 2017-04-05 16:47**MOT test number** 645358174326**Result** ✓ Passed**MOT #5** 2017-04-05 16:47**MOT test number** 614928523046**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too low (1.8)**Pass with rectification** Nearside Front Headlamp aim too low (1.8)**MOT #4** 2016-09-29 07:27**MOT test number** 531839480555**Result** ✓ Passed**MOT #3** 2015-09-25 13:03**MOT test number** 878314829558**Result** ✓ Passed



MOT #2	2014-09-29 17:15
MOT test number	196142074268
Result	✓ Passed

MOT #1	2013-09-30 17:25
MOT test number	887673473212
Result	✓ Passed

**Advice** Front Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
29 June 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	126
<b>MOT expiry date</b>	29 June 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	L
<b>Single payment (12 months)</b>	£ 675,00,-
<b>Single six month payment</b>	£ 371,25,-
<b>Total payable by 12 monthly instalments</b>	£ 708,75,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	LV62CXK
Plate since	2019-03-29
Current registration	LV62CXK
Plate since	2019-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >





Mileage check

Odometer	In miles
Mileage registrations	29
First mileage registration	2012-09-07
Last registration	2023-06-30
Complete history	<a href="#">See info</a>



Registration #1	2012-09-07	10 mi
Registration #2	2013-09-30	14.302 mi
Registration #3	2014-09-29	22.401 mi
Registration #4	2015-09-25	35.583 mi
Registration #5	2016-09-29	48.829 mi
Registration #6	2017-04-05	56.629 mi
Registration #7	2017-04-05	56.629 mi
Registration #8	2017-09-28	66.285 mi
Registration #9	2017-09-29	66.285 mi
Registration #10	2018-04-06	72.417 mi
Registration #11	2018-04-06	72.417 mi
Registration #12	2018-09-26	80.354 mi
Registration #13	2018-10-03	80.354 mi
Registration #14	2019-03-11	86.444 mi
Registration #15	2019-03-14	86.518 mi
Registration #16	2019-09-29	92.557 mi
Registration #17	2019-09-29	92.557 mi
Registration #18	2019-09-29	92.557 mi
Registration #19	2019-09-29	92.557 mi
Registration #20	2019-09-29	92.557 mi
Registration #21	2019-09-29	92.557 mi
Registration #22	2019-09-29	92.557 mi
Registration #23	2019-09-29	92.557 mi
Registration #24	2019-09-29	92.557 mi
Registration #25	2019-09-29	92.557 mi
Registration #26	2019-09-29	92.557 mi

Registration #27	2025-25-25	25,252,442
Registration #28	2025-25-25	25,252,442
Registration #29	2025-25-25	25,252,442

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1920 mm
Height	1925 mm
Length	5125 mm
Wheel base	3200 mm
Kerb weight	2270 kg
Max. allowed weight	3030 kg

Additional information

Fuel tank capacity	75 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	8

Engine number	D4CBC068188
---------------	-------------