





## General information

Make	VAUXHALL
Model	TIGRA SXI AC 16V
Colour	Red
Year of manufacture	-
Top speed	107 mph
0 - 60 mph	11.8 seconds
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	89 BHP
Max. torque	125 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	35.3 mpg
Consumption extra urban	56.5 mpg
Consumption combined	46.3 mpg





# Internet history

Entry	1

Date Pictures 2021-09-28

13

Listing price

View report



source: autotrader.co.uk



## MOT history

MOT #13		2022-04-14 11:49
MOT test nu	mber	323254403312
Result		✓ Passed
Next expiry o	date	2023-04-13
<b>Advice</b> N	learside Front Outer brake pad squeal shim insecure	
Minor Wi	indscreen damaged but not adversely affecting driver's view (3.2 (a) (i	))
Advice Na (a) (ii))	learside Front Brake disc worn, pitted or scored, but not seriously weak	kened inner surface (1.1.14
Advice St	Steering rack has slight free play detected at steering wheel (2.3 (a) (i))	
<b>Advice</b> N	learside Front Nail in tyre	
<b>Advice</b> O	Offside Front Outer Track rod end ball joint has slight play close to exce	ss (2.1.3 (b) (i))
<b>Advice</b> O	Offside headlamp beam image slightly incorrect	
<b>Advice</b> N	learside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Minor Ne	earside Front Inner Drive shaft joint constant velocity boot severely det	eriorated (6.1.7 (g) (i))
Advice Fr	ront Exhaust has a minor leak of exhaust gases flexible section separa	ted (6.1.2 (a))
<b>Advice</b> Pl	Play in steering rack inner joint(s)	
Advice 0	Offside Front fuel pipe corroded near ARB mounting	



macoupy contract the second se

MOT #12 2022-0	04-12 14:59
MOT test number 631	1042692687
Result	🗙 Failed
Minor Offside Side repeater flashing more than 120 times a minute (4.4.4 (a))	
Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened inner surfation (a) (ii))	ace (1.1.14
Advice Offside Front Outer Track rod end ball joint has slight play close to excess (2.1.3 (b) (i))	
Advice Nearside Front Nail in tyre	
Advice Offside Front fuel pipe corroded near ARB mounting	
FailOffside Front Direction indicator not working (4.4.1 (a) (ii))	
Advice Nearside Front Outer brake pad squeal shim insecure	
FailOffside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Fail Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	
<b>Minor</b> Offside Rear Direction indicator flashing more than 120 times a minute (4.4.4 (a))	
Advice Offside Front Tyre slightly damaged lump in outer wall (5.2.3 (d) (ii))	
Advice Front Exhaust has a minor leak of exhaust gases flexible section separated (6.1.2 (a))	
Advice Items removed from driver's view prior to test	
Minor Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7	(g) (i))
<b>Fail</b> Offside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))	
Advice Play in steering rack inner joint(s)	
Advice Offside headlamp beam image slightly incorrect	
Fail Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
Advice Steering rack has slight free play detected at steering wheel (2.3 (a) (i))	
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	





MOT #11	2021-04-10 10:49	
MOT test number	181468859071	
Result	✓ Passed	
MOT #10	2019-10-15 12:05	
MOT test number	684686039376	
Result	✓ Passed	
Advice Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))		
Advice Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))		
МОТ #9	2019-10-15 12:05	

MOT test number	451350064611	
Result	🗙 Failed	
Pass with rectification all lamps (4.7.1 (b) (ii))	Nearside Rear Registration plate lamp inoperative in the case of a single lamp or	
Advice Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))		
Pass with rectificationOffside Rear Registration plate lamp inoperative in the case of a single lamp orall lamps (4.7.1 (b) (ii))		
Advice Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))		

MOT #8		2018-10-04 10:31
MOT test	number	595919892263
Result		✓ Passed
Advice (i)) Advice	Offside Front Suspension arm pin or bush worn but not resulting in exc Nearside Front Suspension arm pin or bush worn but not resulting in ex	
(a) (i))		

MOT #7	2017-10-14 10:35
MOT test number	619102718955
Result	✓ Passed



**MA09WFY** report date: 2024-03-28

MOT #6	2017-10-14 10:35
MOT test number	974693618010
Result	× Failed
Pass with rectification	Offside Front Headlamp aim too low (1.8)
Pass with rectification	Nearside Front Headlamp aim too low (1.8)
Pass with rectification	Offside Rear Brake cable has wires broken and is significantly weakened (3.5.1b)

MOT #5	2016-10-18 08:14
MOT test number	547620657262
Result	✓ Passed
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	

МОТ #4	2015-10-16 08:33
MOT test number	924097650590
Result	✓ Passed

MOT #3	2014-09-17 09:57
MOT test number	215520864292
Result	✓ Passed

MOT #2	2013-09-20 11:34
MOT test number	666993463215
Result	✓ Passed

MOT #1	2012-09-18 11:51
MOT test number	578442862235
Result	✓ Passed
NoticeLong handbrake travel but reserve still metNoticeTiming chain noisy	





### Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	VAMPLE
Date	
Category	AMP
Туре	

#### Extra VAUXHALL salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





### Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





## Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

**********	
AND	
**********	
NUMBER OF CONTRACTOR OF CONTRA	
	More info >
Plate changes	
See in this check if this VAUXHALL had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





### Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2009-06-08
Last registration	2022-04-14
Complete history	<u>See info</u>



Registration #1	2009-06-08	26 mi
Registration #2	2012-09-18	32.423 mi
Registration #3	2013-09-20	39.261 mi
Registration #4	2014-09-17	47.001 mi
Registration #5	2015-10-16	55.323 mi
Registration #6	2016-10-18	63.952 mi
Registration #7	2017-10-14	70.991 mi
Registration #8	2017-10-14	70.991 mi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 mi
Registration #15		11.777 mi



**MA09WFY** report date: 2024-03-28

Safety ratings

NCAP rating

Video

see crash video



1707 mm
1494 mm
3999 mm
2511 mm
1102 kg
1615 kg
45 I
Multi-Point Injection
5
5
19SC2680