



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TRANSPORTER T30 SWB P/V 130TDI
Colour	White
Year of manufacture	2005
Top speed	104 mph
0 - 60 mph	15.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	128 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	2.460 cc
Cylinders	5
Fuel type	Diesel




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-07
Pictures	20
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-02-21
MOT pass rate	68 %
MOT passed	17
Failed MOT tests	8
Total advice items	69
Total items failed	16

MOT #25	2024-02-15 14:51
MOT test number	116687225011
Result	✓ Passed
Next expiry date	2025-02-21

MOT #24	2023-02-22 09:58
MOT test number	780990550201
Result	✓ Passed

MOT #23	2022-02-11 13:37
MOT test number	898561879652
Result	✓ Passed

MOT #22	2021-01-21 09:59
MOT test number	236516941566
Result	✓ Passed
Advice	Offside Rear Outer tyre sidewall starting to crack/perish
Advice	Nearside Rear Outer tyre sidewall starting to crack/perish
Advice	Offside Rear Service brake fluctuating, but not excessively (1.2.1 (e))
Advice	Both exhaust silencers in poor condition

**MOT #21**

2021-01-21 09:17

MOT test number

790857108087

Result**✗ Failed**

- Advice** Nearside Rear Outer tyre sidewall starting to crack/perish
- Advice** Both exhaust silencers in poor condition
- Advice** Offside Rear Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Offside Rear Outer tyre sidewall starting to crack/perish
- MAJOR** Exhaust emissions exceed level of metered smoke for a turbo charged engine (8.2.2.2 (b))

MOT #20

2020-02-04 10:38

MOT test number

516308556087

Result**✓ Passed**

- Advice** Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Central exhaust box corroded
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Rear exhaust box corroded

**MOT #19**

2020-02-03 09:22

MOT test number

224462702942

Result**✗ Failed**

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- MAJOR** Offside Rear Upper Shock absorbers has an excessively worn bush (5.3.2 (c))
- Advice** Central exhaust box corroded
- Advice** Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))
- MAJOR** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Nearside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c))
- Advice** Rear exhaust box corroded

MOT #18

2019-01-29 09:54

MOT test number

703033704894

Result**✓ Passed**

- Advice** Offside Rear Brake pipe corroded, covered in grease or other material to flexihose (1.1.11 (c))
- Advice** Both silencers outer casing corroding
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material to flexihose (1.1.11 (c))

MOT #17

2018-01-29 14:42

MOT test number

994888636223

Result**✓ Passed**

- Advice** Nearside Rear Brake has a very slight bind.
- Advice** Offside Rear Tyre perished.
- Advice** Central Rear Upper Stop lamp has light sources not illuminating, but not more than 50% (1.2.1b)
- Advice** Nearside Rear Tyre perished.
- Advice** Central Both centre and rear exhaust silencers outer skin corroded.

**MOT #16** 2017-02-15 10:43**MOT test number** 822667683758**Result** ✓ Passed**MOT #15** 2017-02-13 14:08**MOT test number** 647728749406**Result** ✗ Failed

Fail Offside Outer Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

MOT #14 2016-08-01 12:11**MOT test number** 421357171085**Result** ✓ Passed

- Advice** Center and rear exhaust outer skin corroding
- Advice** Both rear number plates are working but very dim
- Advice** Offside Front Headlamp has a product on the lens but not seriously reducing light output (1.7.5a)
- Advice** Oil leak
- Advice** Lower gearbox mount slight play
- Advice** Nearside Front Headlamp has a product on the lens but not seriously reducing light output (1.7.5a)
- Advice** O/S/F CV boot has pin hole
- Advice** Heat shiel loose for exhaust

**MOT #13**

2016-07-18 11:36

MOT test number

615896421642

Result**✗ Failed**

- Advice** Lower gearbox mount slight play
- Fail** Offside Stop lamp not working (1.2.1b)
- Fail** Windscreen has damage to the swept area in excess of a 40mm circle outside zone 'A' (8.3.1d)
- Advice** Both rear number plates are working but very dim
- Advice** Offside Front Headlamp has a product on the lens but not seriously reducing light output (1.7.5a)
- Fail** Offside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)
- Advice** Oil leak
- Fail** Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)
- Fail** Offside Front Anti-roll bar rubber bush deteriorated resulting in excessive movement D bush (2.4.G.2)
- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Advice** Nearside Front Headlamp has a product on the lens but not seriously reducing light output (1.7.5a)
- Advice** Center and rear exhaust outer skin corroding
- Fail** Offside Front position lamp(s) not working (1.1.A.3b)
- Advice** O/S/F CV boot has pin hole
- Fail** Offside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)
- Advice** Heat shiel loose for exhaust
- Fail** Nearside Front Anti-roll bar rubber bush deteriorated resulting in excessive movement D bush (2.4.G.2)

**MOT #12** 2015-12-08 15:49**MOT test number** 856081617354**Result** ✓ Passed**Advice** Offside Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt pinholed (2.5.C.1a)**Advice** Offside Front Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)**Advice** Nearside Front Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)**MOT #11** 2015-12-08 15:49**MOT test number** 559585299010**Result** ✗ Failed**Advice** Nearside Front Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)**Advice** Offside Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt pinholed (2.5.C.1a)**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**Advice** Offside Front Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)**MOT #10** 2014-08-05 11:25**MOT test number** 245837814213**Result** ✓ Passed**MOT #9** 2014-08-05 11:25**MOT test number** 348027214212**Result** ✗ Failed**Pass with rectification** Nearside Front All position lamps not working (1.1.A.3b)**MOT #8** 2013-05-04 13:47**MOT test number** 196584323155**Result** ✓ Passed

**MOT #7** 2012-07-23 10:38**MOT test number** 495295502281**Result** ✓ Passed**Notice** Oil leak**Notice** Nearside front tyre split on outer wall**MOT #6** 2012-07-23 10:38**MOT test number** 705425002296**Result** ✗ Failed**Notice** Oil leak**Pass with rectification** Offside Windscreen washer provides insufficient washer liquid (8.2.3)**Notice** Nearside front tyre split on outer wall**Pass with rectification** Nearside Windscreen washer provides insufficient washer liquid (8.2.3)**Pass with rectification** Nearside Stop lamp not working (1.2.1b)**MOT #5** 2011-08-03 10:17**MOT test number** 929125611264**Result** ✓ Passed**MOT #4** 2010-07-13 09:27**MOT test number** 863494990103**Result** ✓ Passed

**MOT #3**

2009-08-04 15:19

MOT test number

111226519211

Result

✓ Passed

- Advice** Rear brake disc slightly pitted (3.5.1h)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Front brake disc slightly pitted (3.5.1h)
- Notice** Vechile has two holes drilled in the rear floor
- Advice** Offside Rear Upper Shock absorber has a slightly worn bush (2.7.4)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #2

2009-07-31 14:17

MOT test number

634062319273

Result

✗ Failed

- Notice** N/S/R tyre has screw in outer side wall (leaking)
- Fail** Nearside Rear Upper Shock absorber has an excessively worn bush (2.7.4)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Rear brake disc slightly pitted (3.5.1h)
- Advice** Offside Rear Upper Shock absorber has a slightly worn bush (2.7.4)
- Notice** Vechile has two holes drilled in the rear floor
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Front brake disc slightly pitted (3.5.1h)
- Advice** Nearside Rear Lower Shock absorber has a slightly worn bush (2.7.4)



MOT #1	2008-09-11 13:47
MOT test number	582005358217
Result	✓ Passed
Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
21 February 2025

Tax status	Valid until 1 June
-------------------	--------------------

Days left	34
------------------	----

MOT expiry date	21 February 2025
------------------------	------------------

Full MOT history	See MOT history
-------------------------	---------------------------------



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history


For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 LF55ZWZ
Plate since	2019-06-29
Current registration	 LF55ZWZ
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2005-09-07
Last registration	2024-02-15
Complete history	See info



Registration #1	2005-09-07	19 mi
Registration #2	2008-09-11	40.605 mi
Registration #3	2009-07-31	43.069 mi
Registration #4	2009-08-04	43.069 mi
Registration #5	2010-07-13	49.464 mi
Registration #6	2011-08-03	64.113 mi
Registration #7	2012-07-23	68.836 mi
Registration #8	2013-05-04	73.248 mi
Registration #9	2014-08-05	94.517 mi
Registration #10	2015-12-08	111.402 mi
Registration #11	2015-12-08	111.402 mi
Registration #12	2016-07-18	115.106 mi
Registration #13	2016-08-01	115.118 mi
Registration #14	2016-08-01	115.118 mi
Registration #15	2016-08-01	115.118 mi
Registration #16	2016-08-01	115.118 mi
Registration #17	2016-08-01	115.118 mi
Registration #18	2016-08-01	115.118 mi
Registration #19	2016-08-01	115.118 mi
Registration #20	2016-08-01	115.118 mi
Registration #21	2016-08-01	115.118 mi
Registration #22	2016-08-01	115.118 mi
Registration #23	2016-08-01	115.118 mi
Registration #24	2016-08-01	115.118 mi
Registration #25	2016-08-01	115.118 mi



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2175 mm
Height	1940 mm
Length	4707 mm

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	3
Engine number	AXD 073865