





General information	
Make	LAND ROVER
Model	DEFENDER HT TDI 95
Colour	Green
Year of manufacture	1995
Gearbox	-Manual

# Engine & fuel consumption

Power	111 BHP	0 < 101 A
Engine capacity	2.495 cc	404 400 B
linders	4	121 - 140 P
el type	Diesel	141 - 165 F G
		400 405

225+





Internet history	
Entry 1	
Date	2021-07-14
Pictures	0
Listing price	View report

source: autotrader.co.uk





# MOT history

MOT expiry date	2018-08-08
MOT pass rate	68 %
MOT passed	13
Failed MOT tests	6
Total advice items	45
Total items failed	29

MOT #19	2018-08-29 13:24
MOT test number	443245831952
Result	✓ Passed
Next expiry date	2019-08-28

MOT #18	2017-08-04 10:36
MOT test number	840104407121
Result	✓ Passed

MOT #17		2016-08-09 10:27
MOT test	number	384112277007
Result		✓ Passed
Advice	Offside Ball joint dust cover damaged, but preventing the ingress of dirt Id	er (2.2.C.1c)
Advice	Nearside Front Ball joint dust cover deteriorated, but preventing the ingres	s of dirt (2.2.C.1c)

MOT #16	2015-08-07 12:06
MOT test number	508459015223
Result	✓ Passed





	2014-06-27 10:45
MOT test number	705308374177
Result	✓ Passed
Advice Nearside Front Lower Axle swivel joint has slight play (2.5.A.3b)	
Advice Nearside Front Drag link end ball joint has slight play (2.2.B.1f)	
Advice Nearside Seat belt stitching slightly frayed (5.2.2b)	
Advice Offside Front wheel bearing has slight play (2.5.A.3c)	
Advice Offside Front Drag link end ball joint has slight play (2.2.B.1f)	

MOT #14	2013-05-28 13:43
MOT test number	716558443177
Result	✓ Passed
Advice Offside Front wheel bearing has slight play (2.5.A.3c)	
MOT #13	2013-05-23 09:51
MOT #13 MOT test number	2013-05-23 09:51 465523943113
MOT test number	465523943113





MOT #12		2012-05-30 17:12
MOT test	number	276891952186
Result		✓ Passed
Advice	Steering column universal joint has slight play (2.1.5)	
Notice	Low readings on rear brakes service and park	
Notice	Possible oil leak into parking brake drum from transfer box	
Notice	Both rear discs corroded	
Notice	Oil leak	





MOT #11 2012-05-23 12:54
<b>MOT test number</b> 548064042108
Result X Failed
Fail       Offside Front wheel bearing has excessive play (2.5.A.3c)
Notice Both rear discs corroded
Fail       Offside Track rod end ball joint has excessive play (2.2.B.1f)
Notice Oil leak
Fail       Offside Headlamp aim too high (1.8)
Fail       Rear Brake pipe fouled by moving parts (3.6.B.2a)
<b>Fail</b> Nearside Front Tyre not fitted in accordance with side wall instructions (4.1.D.1f)
<b>Advice</b> Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)
FailNearside Front wheel bearing has excessive play (2.5.A.3c)
Fail       Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Notice Low readings on rear brakes service and park
Fail       Registration plate lamp not working (1.1.C.1d)
<b>Fail</b> Nearside Track rod end ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.2.C.1c)
Notice Possible oil leak into parking brake drum from transfer box
Fail       Nearside Headlamp aim too low (1.8)
Advice Steering column universal joint has slight play (2.1.5)
<b>Fail</b> Offside Front Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)





2010-06-22 16:20

960973270168

МОТ #10	2011-06-21 13:09
MOT test number	266912071147
Result	✓ Passed
AdviceNearside Front wheel bearing has slight play (2.5.A.3c)AdviceOffside Track rod end ball joint has slight play (2.2.B.1f)	

# MOT #9

### **MOT test number**

Result		✓ Passed
Notice	Small movement in nsf whell bearing	
Notice	No tell tale for hand brkae	
Notice	Rear lights white caps but showing right colurs	
Notice	Nsr shocker has a washer missing	
Notice	Perjetion of rear outside jack bolts	
Notice	Brake padal rubber wearing thin	
Notice	All front tie bar bushes and radius arm bushes are pesrihed	





MOT #8	2010-06-18 14:14
MOT test number	412649060169
Result	🗙 Failed
Fail       Parking brake: efficiency below requirements (3.7.B.7)	
<b>Notice</b> Close to fail limits drop arm ball jiont has a lot of play	
FailTowbar retaining device missing (6.6.3a)	
<b>Notice</b> Nsr shocker has a washer missing	
Fail       Nearside Rear Direction indicator not working (1.4.A.2c)	
Notice No tell tale for hand brkae	
<b>Notice</b> Both prop uj have play in them	
Fail       Windscreen washer provides insufficient washer liquid (8.2.3)	
<b>Notice</b> Rear lights white caps but showing right colurs	
<b>Notice</b> Perjetion of rear outside jack bolts	
Fail       Nearside Passenger's seat insecure (6.2.A.1)	
<b>Notice</b> All front tie bar bushes and radius arm bushes are pesrihed	
Fail     An item not tested (Manual)	
Notice Large wheels fitted	
Fail     Horn not working (1.6.2a)	
<b>Notice</b> Brake padal rubber wearing thin	
Notice Small movement in nsf whell bearing	
Fail Driver's seat insecure (6.2.A.1)	





MOT #7	2009-05-15 14:17
MOT test number	691285739165
Result	✓ Passed
<b>Notice</b> SLIGHT PLAY IN BOTH FRONT HUB BEARINGS /SLIGHT WEAR IN STEERING /WASHER A BIT WEAK	DROP ARM BALL JOINT
MOT #6	2009-05-15 09:00
MOT test number	321395239126
Result	🗙 Failed
Fail       Rear registration plate missing (6.3.1a)	
<b>Fail</b> Front registration plate missing (6.3.1a)	

**Notice** SLIGHT PLAY IN BOTH FRONT HUB BEARINGS /SLIGHT WEAR IN STEERING DROP ARM BALL JOINT /WASHER A BIT WEAK

MOT #5		2008-06-13 11:24
MOT test	number	680845068128
Result		✓ Passed
Notice	Oil leak	
Notice	Rear underside of vehicle showing signs of corrosion	





MOT #4	2008-06-10 12:56
MOT test number	631962568190
Result	🗙 Failed
Fail       Windscreen washer provides insufficient washer liquid (8.2.3)	
Notice Oil leak	
Fail       Nearside Rear Suspension component mounting prescribed area is excessively corror	led (2.4.A.3)
Fail       Front Ball joint has excessive play (2.2.B.1f)	
Fail       Rear Registration plate lamp not working (1.1.C.1d)	
Fail       Offside Front Brake pipe excessively corroded (3.6.B.2c)	
<b>Notice</b> Rear underside of vehicle showing signs of corrosion	
Fail Offside Rear Suspension component mounting prescribed area is excessively corroder	d (2.4.A.3)

MOT #3	2007-06-04 09:22
MOT test number	830875357123
Result	✓ Passed

MOT #2	2007-06-01 14:31
MOT test number	434492757151
Result	🗙 Failed
<b>Fail</b> Front Drag link end ball joint has excessive play (2.2.B.1f)	

MOT #1	2006-06-07 12:59
MOT test number	373838156145
Result	✓ Passed





#### Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FE C
Category	 Lamp
Туре	
Damage 2	AMPLE
Date	 4
Category	 AMPLI
Туре	W CON

#### Extra LAND ROVER salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





#### Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 10.200

More info  $\rightarrow$ 





......

## Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many owners did this LAND ROVER have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

******	
**********	
********	
*******	
Mor	e info >
Plate changes	

Number of plates

Current registration

Plata since

More info >





#### Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LAND ROVER is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info  $\rightarrow$ 





# Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	1995-11-20
Last registration	2018-08-29
Complete history	See info



Registration #1	1995-11-20	27 mi
Registration #2	2006-06-07	124.729 mi
Registration #3	2007-06-01	133.950 mi
Registration #4	2007-06-04	134.055 mi
Registration #5	2008-06-10	143.125 mi
Registration #6	2008-06-13	143.140 mi
Registration #7	2009-05-15	146.543 mi
Registration #8	2009-05-15	146.543 mi
Registration #9	2010-06-18	153.365 mi
Registration #10	2010-06-22	153.365 mi
Registration #11	2011-06-21	161.084 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		11.777 esi
Registration #17		10.200 mil
Registration #18		11.777 est
Registration #18 Registration #19		11.577 est 11.577 est
-		0.000 est 0.000 est 0.000 est

More info >





## Additional information

Fuel delivery	Direct Injection
Number of axles	2
Engine number	16LA27641