



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	TOURAN MATCH TDI
Colour	Silver
Year of manufacture	2009
Top speed	111 mph
0 - 60 mph	13.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	104 BHP
Max. torque	250 Nm at 1.900 rpm
Engine capacity	1.896 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	47.1 mpg
CO2 emission	155 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-07-11
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-07-13
MOT pass rate	57 %
MOT passed	12
Failed MOT tests	9
Total advice items	88
Total items failed	24

MOT #212023-07-08 11:23

MOT test number337601719555

Result✓ Passed

Next expiry date2024-07-13

- Advice**Offside Rear Seat belt buckle slightly damaged Case damaged (7.1.2 (d))
- Advice**Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))
- Advice**Nearside Rear Tyre worn close to legal limit/worn on edge Worn on inner edge and tyre is perished (5.2.3 (e))
- Minor**Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice**Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))

**MOT #20**

2023-07-04 15:02

MOT test number

603042059968

Result

✗ Failed

- Fail** Nearside Rear Parking brake inoperative on one side (1.4.1 (a))
- Fail** Offside Headlamp aim unable to be tested (4.1.2 (b))
- Advice** Offside Rear Seat belt buckle slightly damaged Case damaged (7.1.2 (d))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge Worn on inner edge and tyre is perished (5.2.3 (e))
- Minor** Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #19

2022-07-14 16:01

MOT test number

405420288751

Result

✓ Passed

- Advice** Offside Rear Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Rear Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Rear Seat belt buckle slightly damaged buckle outer casing missing (7.1.2 (d))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #18**

2022-07-14 14:30

MOT test number

204417837468

Result**✗ Failed**

- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Rear Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Rear Seat belt buckle slightly damaged buckle outer casing missing (7.1.2 (d))
- Advice** Nearside Rear Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Fail** Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #17

2022-07-05 14:14

MOT test number

618769767078

Result**✗ Failed**

- Fail** Nearside Rear Upper Suspension arm pin or bush excessively worn trailing arm front bush (5.3.4 (a) (i))
- Fail** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))
- Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
- Fail** Nearside Brake cable guide defective and affecting operation (1.1.15 (d))
- Advice** Offside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement trailing arm front bush (5.3.4 (a) (i))
- Advice** Offside Rear Seat belt buckle slightly damaged (7.1.2 (d))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Fail** Stop lamp(s) not working high level (4.3.1 (a) (ii))

**MOT #16**

2021-07-12 10:31

MOT test number

608856176160

Result

✓ Passed

Advice

Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4

(a) (i))

Advice

Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a)

(i))

MOT #15

2021-06-14 11:52

MOT test number

808347585772

Result

✗ Failed

Advice

Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice

Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a)

(i))

Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))

Advice

Nearside Non obligatory mirror damaged loose

Advice

Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice

Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice

Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4

(a) (i))

Advice

Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice

Nearside Rear Nail in tyre

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail

Nearside Front Road wheel fixing missing (5.2.1 (a) (i))

Advice

Oil leak, but not excessive (8.4.1 (a) (i))

Fail

Nearside Side repeater with a multiple light source more than 1/2 not functioning (4.4.1 (a) (ii))



MOT #14

2020-11-05 15:17

MOT test number

184269847474

Result

✓ Passed

- Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice

Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice

Nearside Rear Nail in tyre
- Advice

Oil leak, but not excessive engine (8.4.1 (a) (i))
- Advice

Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice

Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice

Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice

Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice

Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #13**

2020-11-05 09:24

MOT test number

206644257817

Result**✗ Failed**

- Advice** Oil leak, but not excessive engine (8.4.1 (a) (i))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Fail** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Nearside Rear Nail in tyre
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))
- Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Minor** Nearside Rear Tyre obviously under inflated (5.2.3 (l))

**MOT #12**

2019-10-31 09:19

MOT test number

569635635406

Result

✓ Passed

- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** High level brake light not working
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #11

2018-10-26 09:14

MOT test number

294469960021

Result

✓ Passed

- Minor** Nearside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Offside Rear tyre wearing low on inner edge
- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #10

2017-10-19 09:18

MOT test number

822503113009

Result

✓ Passed

- Advice** Front tyres wearing on inner edges
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Rear tyres wearing on inner edges
- Advice** Rear brake discs corroded

**MOT #9**

2017-10-19 09:18

MOT test number

982113720700

Result**✗ Failed****Pass with rectification** Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)**Advice** Rear brake discs corroded**Advice** Front tyres wearing on inner edges**Pass with rectification** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Rear tyres wearing on inner edges**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**MOT #8**

2016-10-24 14:13

MOT test number

710202939087

Result**✓ Passed****Advice** Front Suspension arm has slight play in a track control arm inner bush both (2.5.B.2b)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #7**

2016-10-24 11:20

MOT test number

272923966990

Result**✗ Failed****Advice** Offside Rear Rear position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)**Fail** Offside Rear Tyre has ply or cords exposed (4.1.D.1b)**Advice** Front Suspension arm has slight play in a track control arm inner bush both (2.5.B.2b)**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #6** 2015-09-24 11:08**MOT test number** 746394254132**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #5** 2015-09-24 11:08**MOT test number** 251287486421**Result** ✗ Failed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Pass with rectification** Offside Rear Tyre not fitted in accordance with side wall instructions (4.1.D.1f)**MOT #4** 2014-09-30 10:58**MOT test number** 958683174269**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #3** 2013-10-16 15:23**MOT test number** 149999383283**Result** ✓ Passed**MOT #2** 2012-12-04 10:04**MOT test number** 786509432374**Result** ✓ Passed**Notice** Non obligatory mirror damaged**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)



MOT #12012-12-03 13:18

MOT test number966548032346

Result

Failed

- Fail

Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Notice

Non obligatory mirror damaged
- Advice

Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
13 July 2024

Tax status	Valid until 1 March
Days left	305
MOT expiry date	13 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 GL59RKF
Plate since	2024-03-29
Current registration	 GL59RKF
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2009-12-22
Last registration	2023-07-08
Complete history	See info



Registration #1	2009-12-22	23 mi
Registration #2	2012-12-03	56.888 mi
Registration #3	2012-12-04	56.591 mi
Registration #4	2013-10-16	67.505 mi
Registration #5	2014-09-30	75.383 mi
Registration #6	2015-09-24	84.121 mi
Registration #7	2015-09-24	84.121 mi
Registration #8	2016-10-24	98.237 mi
Registration #9	2016-10-24	98.238 mi
Registration #10	2017-10-19	106.536 mi
Registration #11	2017-10-19	106.536 mi
Registration #12	2018-10-26	110.212 mi
Registration #13	2019-05-29	121.277 mi
Registration #14	2019-05-29	121.277 mi
Registration #15	2019-05-29	121.277 mi
Registration #16	2019-05-29	121.277 mi
Registration #17	2019-05-29	121.277 mi
Registration #18	2019-05-29	121.277 mi
Registration #19	2019-05-29	121.277 mi
Registration #20	2019-05-29	121.277 mi
Registration #21	2019-05-29	121.277 mi
Registration #22	2019-05-29	121.277 mi
Registration #23	2019-05-29	121.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1794 mm
Height	1635 mm
Length	4391 mm
Wheel base	2678 mm
Kerb weight	2210 kg
Max. allowed weight	2210 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	7
Number of axles	2
Engine number	BXE C57284