





General information

Make	RENAULT
Model	KANGOO EXPRESSION DCI 86 E4
Colour	Blue
Year of manufacture	-
Top speed	98 mph
0 - 60 mph	11.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	83 BHP
Max. torque	200 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	47.9 mpg
Consumption extra urban	57.6 mpg
Consumption combined	53.3 mpg





Internet history

Entry 1

Date Pictures 2021-10-31

17

Listing price

View report



source: autotrader.co.uk



MOT history

MOT #26	2021-10-27 11:05
MOT test number	281642915314
Result	✓ Passed
Next expiry date	2022-10-26
Advice Nearside handbrake poor	

MOT #25	202	1-01-28 17:19
MOT test	number 8	11853102667
Result		🗸 Passed
Advice	Rear Brake hose has slight corrosion to ferrule BOTH (1.1.12 (f) (i))	
Advice (i))	Offside Front Suspension arm pin or bush worn but not resulting in excessive moveme	ent (5.3.4 (a)
Advice (a) (i))	Nearside Front Suspension arm pin or bush worn but not resulting in excessive mover	ment (5.3.4

MOT #24	2021-01-28 10:08
MOT test	number 704999225674
Result	× Failed
Advice (a) (i))	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
MAJOR	Rear Exhaust system insecure (6.1.2 (a))
Advice	Rear Brake hose has slight corrosion to ferrule BOTH (1.1.12 (f) (i))
Advice (i))	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a)
MAJOR	Offside Stop lamp(s) adversely affected by the operation of another lamp (4.3.3 (b))
MAJOR	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #23	2020-01-20 14:52
MOT test number	696658550017
Result	✓ Passed
CarCheck.co.uk	page 3/18



BF55CSO
report date: 2024-03-28

MOT #22		2020-01-20 13:09
MOT test number		354068040439
Result		🗙 Failed
MAJOR	Brake lever has insufficient reserve travel (1.1.2 (a))	
MAJOR	Offside Front Position lamp not working (4.2.1 (a) (ii))	
MAJOR	Offside Rear Wheel bearing has excessive play (5.1.3 (a) (i))	
MAJOR	Nearside Front Position lamp not working (4.2.1 (a) (ii))	
MAJOR	Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2	(c))

MOT #21		2019-01-21 16:18
MOT test	number	693667722372
Result		✓ Passed
Advice (i))	Offside Front Suspension arm pin or bush worn but not resulting in excessive mo	ovement (5.3.4 (a)
Advice	Offside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))	
Minor	Nearside Outer Drive shaft joint constant velocity boot severely deteriorated (6.1	.7 (g) (i))
Advice (a) (i))	Nearside Front Suspension arm pin or bush worn but not resulting in excessive r	novement (5.3.4
Advice	Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))	
Advice	Clutch very stiff	





MOT #20	2019-01-21 10:54
MOT test	number 382705736614
Result	× Failed
Advice (i))	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a)
Advice	Offside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))
Advice	Clutch very stiff
Advice (a) (i))	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4
Advice	Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
DANGE	ROUS Nearside Rear Tyre has ply or cords damaged (5.2.3 (d) (ii))
Minor	Nearside Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
MAJOR	Nearside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))

MOT #19		2018-01-22 14:48
MOT test	number	778580538443
Result		✓ Passed
Advice	Engine cover	
Advice	Clutch very stiff	
Advice	Undertray	



MOT #18	2018-01-22 10:04
MOT test number	583401552489
Result	🗙 Failed
Advice Clutch very stiff	
Advice Undertray	
Fail Offside Front Suspension arm has excessive play in a ball joint (2.4.G.2)	
Advice Front Brake pad(s) wearing thin (3.5.1g)	
Advice Engine cover	
Fail Offside Stop lamp adversely affected by the operation of another lamp (1.2.1f)	

MOT #17		2017-01-19 14:10
MOT test	number	703379723225
Result		✓ Passed
Advice	Offside Rear Brake hose has slight corrosion to ferrules (3.6.B.4e)	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Stop lamp slightly affected by the operation of another lamp (1.2.1f)	
Advice	Offside Front Front suspension has slight play in a lower suspension ball joint (2.	5.B.1a)

MOT #16		2017-01-19 10:58
MOT test	number	753552894495
Result		🗙 Failed
Advice	Stop lamp slightly affected by the operation of another lamp (1.2.1f)	
Advice	Offside Front Front suspension has slight play in a lower suspension ball joint	(2.5.B.1a)
Fail N	earside Rear passenger door cannot be opened from outside the vehicle (6.2.B.	.1c)
Advice	Offside Rear Brake hose has slight corrosion to ferrules (3.6.B.4e)	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	





MOT #15		2016-01-19 17:18
MOT #15		842680938877
	number	
Result		✓ Passed
Advice	Engine cover	
Advice	Offside Front Suspension arm has slight play in a ball joint (2.4.G.2)	
Advice (2.4.G.2)	Offside Front Suspension arm rubber bush deteriorated but not resulting in excess	sive movement
Advice	Under tray	
MOT #14		2016-01-19 10:51
MOT test		748157477875
Result		
Result		🗙 Failed
Pass wit		
1 455 111	ith rectification Offside Front position lamp(s) not working (1.1.A.3b)	
	ith rectificationOffside Front position lamp(s) not working (1.1.A.3b)Offside Front Anti-roll bar linkage rubber mounting deteriorated resulting in excessive	e movement
Fail Of		
Fail Of (2.4.G.2) Advice	Offside Front Anti-roll bar linkage rubber mounting deteriorated resulting in excessive	
Fail Of (2.4.G.2) Of Advice (2.4.G.2) Advice Of Fail Ne	Offside Front Anti-roll bar linkage rubber mounting deteriorated resulting in excessive Offside Front Suspension arm rubber bush deteriorated but not resulting in excess	sive movement
FailOf(2.4.G.2)Advice(2.4.G.2)AdviceFailNeprevents til	Offside Front Anti-roll bar linkage rubber mounting deteriorated resulting in excessive Offside Front Suspension arm rubber bush deteriorated but not resulting in excess Under tray	sive movement

Advice Offside Front Suspension arm has slight play in a ball joint (2.4.G.2)

MOT #13		2015-01-26 16:38
MOT test	number	457256625095
Result		✓ Passed
Notice	Engine covers fitted obscuring some components in the engine bay	
Notice	Under-trays fitted obscuring some underside components	



MOT #12	2015-01-26 10:07
MOT test number	126306525413
Result	🗙 Failed
Fail Offside Front Anti-roll bar linkage fractured (2.4.G.1)	
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Notice Engine covers fitted obscuring some components in the engine bay	
Fail Nearside Front constant velocity joint gaiter insecure to the extent that it no longer ingress of dirt etc (2.5.C.1a)	er prevents the
Fail Nearside Rear wheel bearing rough when rotated (2.6.1)	
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Notice Under-trays fitted obscuring some underside components	
Advice Front Brake pad(s) wearing thin (3.5.1g)	

MOT #11	2014-02-17 14:13
MOT test	number 736028444073
Result	✓ Passed
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Notice	Engine covers fitted obscuring some components in the engine bay
Advice movemen	Nearside Front Anti-roll bar linkage rubber mounting deteriorated but not resulting in excessive t (2.4.G.2)
Notice	Under-trays fitted obscuring some underside components
Notice	Play in steering rack inner joint(s)
Notice	Child seat fitted not allowing full inspection of adult belt

BF55CSO

report date: 2024-03-28





MOT #10		2014-02-17 12:07
MOT test n	umber	987658844069
Result		🗙 Failed
Notice	Child seat fitted not allowing full inspection of adult belt	
Advice movement	Nearside Front Anti-roll bar linkage rubber mounting deteriorated but not res (2.4.G.2)	ulting in excessive
Notice	Engine covers fitted obscuring some components in the engine bay	
Notice	Play in steering rack inner joint(s)	
Fail Off	side Track rod end ball joint has excessive play (2.2.B.1f)	
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened	(3.5.1i)
Notice	Under-trays fitted obscuring some underside components	

MOT #9		2013-02-07 14:35
MOT test nu	ımber	155248433425
Result		✓ Passed
Notice	Inder-trays fitted obscuring some underside components	
Advice	Nearside Steering rack gaiter deteriorated (2.2.D.2d)	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	



MOT #8	2013-02-07 10:34
MOT test number	129538333081
Result	🗙 Failed
Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Fail Nearside Track rod end ball joint has excessive play (2.2.B.1f)	
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice Nearside Steering rack gaiter deteriorated (2.2.D.2d)	
Pass with rectification Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)
Fail Offside Front constant velocity joint gaiter deteriorated to the extent that it no ingress of dirt etc (2.5.C.1a)	o longer prevents the
Fail Offside Front coil spring incomplete (2.4.C.1a)	
Notice Under-trays fitted obscuring some underside components	
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #7		2012-02-06 10:05
MOT test	number	887977232029
Result		✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Steering rack gaiter deteriorated (2.2.D.2d)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Track rod end ball joint has slight play (2.2.B.1f)	







MOT #6		2011-01-31 10:13
MOT test	number	218521331040
Result		✓ Passed
Advice	Power steering pump has slight seepage from a seal (2.3.3b)	
Notice	Child seat fitted not allowing full inspection of adult belt	
Notice	Offside rear tyre cracking	

MOT #5	2011-01-31 10:13
MOT test number	137421031422
Result	🗙 Failed
Pass with rectification Offside Front position lamp(s) not working (1.1.A.3)	b)
Notice Child seat fitted not allowing full inspection of adult belt	
Advice Power steering pump has slight seepage from a seal (2.3.3b)	
Notice Offside rear tyre cracking	

MOT #4		2010-01-27 12:11
MOT test	number	210317420086
Result		✓ Passed
Notice	Both nearside tyres cracking	
Advice	Power steering pump has slight seepage from a seal (2.3.3b)	
Notice	Oil leak	





MOT #3		2010-01-27 12:11
MOT test number		580427320007
Result		🗙 Failed
Advice Power steering p	oump has slight seepage from a seal (2.3.3b)	
Notice Both nearside ty	res cracking	
Pass with rectification	Offside Registration plate lamp not working (1.1.5c)	
Notice Oil leak		
Pass with rectification	Nearside Registration plate lamp not working (1.1.5c)	
MOT #2		2009-02-19 12:43

MOT test number	703660359036
Result	✓ Passed

MOT #1	2008-09-11 13:40
MOT test number	444015458265
Result	✓ Passed





Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEIDO
Category	4. ARMPE
Туре	
Damage 2	AMPL
	F Stores
Date	1.E
Category	ante
Туре	

Extra RENAULT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 10.200

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

NUMBER OF TAXABLE PARTY	

NUMBER OF CONTRACTOR OF CONTRA	

	More info >
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2005-09-01
Last registration	2021-10-27
Complete history	See info



Registration #1	2005-09-01	13 mi
Registration #2	2008-09-11	16.466 mi
Registration #3	2009-02-19	22.251 mi
Registration #4	2010-01-27	32.621 mi
Registration #5	2011-01-31	43.328 mi
Registration #6	2012-02-06	55.346 mi
Registration #7	2013-02-07	67.202 mi
Registration #8	2013-02-07	67.202 mi
Registration #9	2014-02-17	79.413 mi
Registration #10	2014-02-17	79.413 mi
Registration #11	2015-01-26	89.953 mi
Registration #12	2015-01-26	89.954 mi
Registration #13	2016-01-19	99.533 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		11.777 esi
Registration #17		11.777 mi
Registration #18		11.777 esi
Registration #19		11.777 mi
Registration #20		11.777 est
Registration #21		11.777 mi
Registration #22		11.777 esi
Registration #23		11.777 mi
Registration #24		11.777 mi
Registration #25		11.777 mi
Registration #26		11.777 esi

CarCheck.co.uk

More info >





Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1672 mm
Height	1855 mm
Length	4035 mm
Wheel base	2605 mm
Kerb weight	1125 kg
Max. allowed weight	1630 kg
Additional information	
Fuel tank capacity	50 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 18/18