





General information

Make	VOLKSWAGEN
Model	TOURAN MATCH TDI
Colour	Silver
Year of manufacture	-
Top speed	111 mph
0 - 60 mph	13.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	104 BHP
Max. torque	250 Nm at 1.900 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	47.1 mpg





Internet history

Entry	1

Date Pictures 2021-02-06

10

Listing price

View report



source: autoonline.co.uk



MOT history

MOT #16		2019-10-22 12:08
MOT test	number	769881474415
Result		✓ Passed
Next expi	ry date	2020-10-21
Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weal	kened (1.1.14 (a) (ii))

MOT #15	2019-10-21 08:30
MOT test number	369361753300
Result	🗙 Failed
Fail Nearside Rear Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))	
Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1	1.14 (a) (ii))
Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
Fail Offside Front Brake disc in such a condition that it is seriously weakened (1.1.14	(a) (ii))
Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened	(1.1.14 (a) (ii))

MOT #14		2019-05-17 09:39
MOT test	number	583903524447
Result		✓ Passed
Advice	Offside Front inner wheel arch cover is missing	
Advice	Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	





MOT #13		2018-11-02 10:34
MOT test	number	919851401039
Result		✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Brake disc worn, pitted or scored, but not seriously weakened fronts (1.1.14 (a) (ii))
Advice	Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Advice	Slight cracking and play in both front wishbones back bushes	
Advice	Brake pad(s) wearing thin front inners (1.1.13 (a) (ii))	
Advice	Slight cracking and play in lower engine mounting	

MOT #12	2018-10-17 10:32
MOT test number	845930932456
Result	🗙 Failed
Fail Windscreen washer not working (3.5 (a))	
Fail Offside Rear Inner Suspension arm pin or bush excessively worn rear arm inner bush	sh (5.3.4 (a) (i))
Advice Brake disc worn, but not excessively fronts (1.1.14 (a) (i))	
Advice Slight play in lower engine mounting	
Fail Offside Front Position lamp not working (4.2.1 (a))	
Fail Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))	
Minor Offside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorate	d (5.3.4 (b) (i))
Fail Offside Obligatory mirror seriously damaged, affecting the rear view (3.3 (b) (ii))	
Advice Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Fail Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))	





MOT #11	2018-05-22 14:07
MOT test number	677858352030
Result	✓ Passed
Advice Nearside Front Tyre worn close to legal limit/worn on edge inner edge (5.	2.3 (e))
Advice Rear Brakes imbalanced requirements only just met. It would appear that requires adjustment or repair. (1.2.1 (b) (i))	t the braking system
Advice Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Advice Offside Rear Lower Suspension arm pin or bush worn but not resulting in inner bush (5.3.4 (a) (i))	excessive movement
Advice Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.	3 (e))
Advice Oil leak, but not excessive (8.4.1 (a) (i))	
Advice Slight cracking and play in lower engine mount	
Advice Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	

MOT #10	2018-05-21 15:04
MOT test number	201038832650
Result	🗙 Failed
Fail Nearside Front Tyre tread depth below requirements of 1.6mm inner edge Michelin	(5.2.3 (e))
Advice Offside Rear Lower Suspension arm pin or bush worn but not resulting in excess inner bush (5.3.4 (a) (i))	ive movement
Advice Slight cracking and play in lower engine mount	
Advice Rear Brakes imbalanced requirements only just met. It would appear that the brace requires adjustment or repair. (1.2.1 (b) (i))	raking system
Advice Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Advice Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))	
Fail Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))	
Fail Windscreen washer provides insufficient washer liquid (3.5 (a))	
Advice Oil leak, but not excessive (8.4.1 (a) (i))	
Advice Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	



MOT #9		2017-11-15 11:59
MOT test r	number	717980398734
Result		✓ Passed
Advice	Airbag light taped over	
Advice	Nearside Rear Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)	
MOT #8		2017-11-09 13:35

MOT te	st number	577014027939
Result		🗙 Failed
Fail	Supplementary Restraint System warning lamp indicates a fault (5.4.2)	
Fail	Offside Front Suspension arm has excessive play in a pin/bush (2.4.G.2)	
Fail	Offside Headlamp not working on main beam (1.7.5a)	
Advic	e Nearside Rear Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)	
Fail	Nearside Side repeater not working (1.4.A.2c)	
Fail	Windscreen washer provides insufficient washer liquid (8.2.3)	
Fail ingress	Offside Front Front constant velocity joint gaiter damaged to the extent that it no long of dirt etc (2.5.C.1a)	er prevents the
Fail	Horn not loud enough to be heard by another road user (1.6.2b)	
Fail	Offside Rear coil spring broken (2.4.C.1a)	
Fail	Offside Front Direction indicator not working (1.4.A.2c)	
Fail	Offside Front position lamp(s) not working (1.1.A.3b)	

MOT #7	2016-11-03 16:49
MOT test number	402627450154
Result	✓ Passed
Advice Slight misting of oil on n/s/r shocker	





MOT #6		2016-01-25 14:59
MOT test number		797135518994
Result		✓ Passed
MOT #5		2016-01-25 14:59
MOT test number		905024140483
Result		🗙 Failed
Pass with rectification	Front Driver's airbag obviously defective (5.4.1)	

MOT #4	2015-02-13 10:53
MOT test number	706064745074
Result	✓ Passed
Notice Wiper blades poor	

MOT #3		2014-02-15 11:58
MOT test r	number	829776444069
Result		✓ Passed
Advice Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1) Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Autree	onside front fyle worn close to the legal mine (4.1.2.1)	

MOT #2		2014-02-15 11:58
MOT test number		767606444080
Result		🗙 Failed
Pass with rectification	Nearside Registration plate lamp not working (1.1.C.1d)	
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)		
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)		





MOT #1	2013-03-30 10:51
MOT test number	966109683086
Result	✓ Passed





Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FETTOR
Category	Lamp
Туре	
Damage 2	AMPLE
Date	
Date	OLE .
Category	AM
Туре	

Extra VOLKSWAGEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.700
Auction value	4 10.000
Average private trade value	4 10 700





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

ANALY AND A ANALY	
	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate sites	





Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-05-11
Last registration	2019-10-22
Complete history	See info



Registration #1	2010-05-11	12 mi
Registration #2	2013-03-30	61.965 mi
Registration #3	2014-02-15	87.955 mi
Registration #4	2015-02-13	102.809 mi
Registration #5	2016-01-25	43.048 mi
Registration #6	2016-01-25	107.995 mi
Registration #7	2016-11-03	108.529 mi
Registration #8	2017-11-09	154.164 mi
Registration #9	2017-11-15	154.927 mi
Registration #10		11.777 esi
Registration #11		11.777 esi
Registration #12		11.777 esi
Registration #13		11.777 esi
Registration #14		11.777 esi
Registration #15		11.777 esi
Registration #16		11.777 est
Registration #17		11.777 est





Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating

CarCheck.co.uk

Video

see crash video



Dimensions & weight	
Width	1794 mm
Height	1635 mm
Length	4391 mm
Wheel base	2678 mm
Kerb weight	2210 kg
Max. allowed weight	2210 kg
Additional information	
Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	7
Number of axles	2
Engine number	BXE C99289