





General information

Make	ΤΟΥΟΤΑ
Model	COROLLA VERSO D-4D T3
Colour	Black
Year of manufacture	-
Top speed	122 mph
0 - 60 mph	9.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	310 Nm at 2.800 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	35.3 mpg
Consumption extra urban	53.3 mpg
Consumption combined	44.8 mpg





Internet history

Entry 2	
Date	2021-12-16
Pictures	37
Listing price	View report



source: cargurus.co.uk

Entry 1

Date

Pictures

Listing price

2021-12-15 38

View report

source: autotrader.co.uk











MOT history



GK07SXS report date: 2024-03-29

MOT #2	2023-12-20 12:26
MOT te	st number 456600945788
Result	× Failed
Fail	Offside Rear Service brake excessively fluctuating (1.2.1 (e))
Fail	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Advic	e Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Fail insecur	Fuel tank exhaust shield missing where fitted as original equipment creating a risk of fire heat shield e likely for become detached (6.1.3 (e))
Fail	Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
Fail	Nearside Rear Axle swivel pins and bushes swivel pin and/or bush excessively worn (5.1.2 (b) (i))
Minor	• Nearside Rear Obligatory mirror slightly loose held by tape (3.3 (b) (i))
Fail	Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
Fail	Front Windscreen wiper does not clear the windscreen effectively pair (3.4 (b) (ii))
Fail	Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
Advic	e Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))
Advic	e Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
Advic	e Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advic	e Inner steering arms have slight play
Fail	Offside Front Position lamp not working (4.2.1 (a) (ii))
Fail	Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))
Fail	Offside Rear Axle swivel pins and bushes swivel pin and/or bush excessively worn (5.1.2 (b) (i))
Fail	Front Windscreen washer provides insufficient washer liquid (3.5 (a))
Advic	e Seats 6 and 7 folded down
Advic	e Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))
Advic	• Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Fail	Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))





МОТ #19	2023-01-10 17:22
MOT test number	874606141126
Result	✓ Passed
AdviceNearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))AdviceRear axle bushes in poor condition	

MOT #18

мот	test	number
-----	------	--------

Result		🗸 Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside front for light insecure	
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	

MOT #17

MOT test number

2021-12-17 11:18 545454595479

345744474806

Result

✓ Passed

MOT #16		2019-10-29 09:04
MOT test	number	642686526520
Result		✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Central Front Play in steering rack inner joint(s)	
Advice	Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))	





MOT #15	2019-10-29 09:03
MOT test number	476215366909
Result	🗙 Failed
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))	
Fail Nearside Rear Road wheel fixings not compatible (5.2.2 (d))	
Fail Offside Front Position lamp missing (4.2.1 (a) (ii))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))	
Advice Central Front Play in steering rack inner joint(s)	

MOT #14		2018-10-16 14:07
MOT test	number	753009609548
Result		✓ Passed
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #13		2017-09-20 16:29
MOT test	number	770420277699
Result		Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Rear Brake lining(s) wearing thin (3.5.1g)	



MOT #12	2017-09-20 10:46
MOT test number	630351934781
Result	🗙 Failed
Fail Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)	
Fail Registration plate lamp not working (1.1.C.1d)	
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Fail Electronic stability system warning lamp indicates a fault (3.4.1c)	
Advice Rear Brake lining(s) wearing thin (3.5.1g)	

MOT #11

2016-09-20 13:32 582724191067

🗸 Passed

GK07SXS

report date: 2024-03-29

MOT test number

Result

MOT #	10	2016-09-20 11:43
MOT te	st number	162338353464
Result		🗙 Failed
Fail	Registration plate lamp not working (1.1.C.1d)	
Fail	Nearside Headlamp aim too low (1.8)	
Fail	Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)	
Fail	Windscreen wiper does not clear the windscreen effectively (8.2.2)	
Fail	Offside Headlamp aim too low (1.8)	



GK07SXS
report date: 2024-03-29

MOT #9		2015-08-27 16:56
MOT test	number	984277466355
Result		✓ Passed
Advice	Valve stem slightly damaged n/s/f and o/s/f (4.1.D.1e)	
Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1)	a)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #8	2015-08-27 15:53	
MOT test number	563476219438	
Result	🗙 Failed	
Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3	3.1a)	
Advice Valve stem slightly damaged n/s/f and o/s/f (4.1.D.1e)		
Fail Nearside Registration plate lamp not working (1.1.C.1d)		
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)		

МОТ #7	2014-09-03 09:47
MOT test number	635096644285
Result	✓ Passed

MOT #6		2014-09-03 09:47
MOT test number		528196444210
Result		🗙 Failed
Pass with rectification	Nearside Registration plate lamp not working (1.1.C.1d)	





MOT #5	2013-09	9-20 14:48
MOT test	a number 4794	53563220
Result		🗸 Passed
Advice	Brake hydraulic reservoir fluid close to minimum level (3.6.G.1b)	
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)	
Advice	Rear Brake pad(s) wearing thin (3.5.1g)	
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)	
Advice	Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	





MOT #4		2013-09-20 14:48
MOT test number		845793963297
Result		🗙 Failed
Pass with rectification	Nearside Registration plate lamp not working (1.1.C.1d)	
Advice Brake hydraulic	reservoir fluid close to minimum level (3.6.G.1b)	
Pass with rectification	Rear registration plate deteriorated (6.3.1d)	
Advice Windscreen has	damage to an area less than a 40mm circle outside zone 'A' (8.3.	1d)
Advice Rear Brake pad(s) wearing thin (3.5.1g)	
Pass with rectification	Offside Front position lamp(s) not working (1.1.A.3b)	
Advice Offside Front bra	ake disc worn, pitted or scored, but not seriously weakened (3.5.1	.i)
Pass with rectification	Offside Registration plate lamp not working (1.1.C.1d)	
Advice Windscreen has	damage to an area less than a 10mm circle within zone 'A' (8.3.1	a)
Advice Front Brake pad	(s) wearing thin (3.5.1g)	
Pass with rectification	Nearside Front position lamp(s) not working (1.1.A.3b)	
Advice Nearside Front b	orake disc worn, pitted or scored, but not seriously weakened (3.5	.1i)

MOT #3	2012-09-07 13:5	5
MOT test	number 49714185222	5
Result	✓ Passe	d
Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)	
Notice	Both rear tyres have some stepping in tread indicating structure is failing	
Advice	Front Brake pad(s) wearing thin (3.5.1g)	





MOT #2	2011-09-07 12:00
MOT test number	458210151205
Result	✓ Passed
Notice Windscreen has slight damage	
MOT #1	2010-04-22 10:51
MOT test number	164392310126
Result	✓ Passed
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	





Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEI
Category	Lamp
Туре	
Damage 2	AMPL
Damage 2	E Stand
Date	*
Category	A SUPP.
Туре	

Extra TOYOTA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

xxxxxxxx	

	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	,
Current registration	
Plate since	
Carrent registration	
Plate since	
	More info >





Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-03-15
Last registration	2023-12-20
Complete history	See info



Registration #1	2007-03-15	15 mi
Registration #2	2010-04-22	64.286 mi
Registration #3	2011-09-07	93.179 mi
Registration #4	2012-09-07	113.315 mi
Registration #5	2013-09-20	138.216 mi
Registration #6	2014-09-03	153.451 mi
Registration #7	2015-08-27	173.218 mi
Registration #8	2015-08-27	173.218 mi
Registration #9	2016-09-20	117.732 mi
Registration #10	2016-09-20	117.732 mi
Registration #11	2017-09-20	180.596 mi
Registration #12		11.777 est
Registration #13		11.777 est
Registration #14		11.777 est
Registration #15		11.777 est
Registration #16		11.777 est
Registration #17		11.777 est
Registration #18		11.777 est
Registration #19		11.777 mi
Registration #20		01.777 est
Registration #21		11.117 mi

More info >





Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

**** see crash video



Dimensions & weight	
Width	1770 mm
Height	1660 mm
Length	4360 mm
Wheel base	2750 mm
Kerb weight	1495 kg
Max. allowed weight	2160 kg
Additional information	
Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 17/17

Number of axles	2
Engine number	2AD521824