






report date: 2024-03-29

General information

Make	LAND ROVER	
Model	DEFENDER TD XS STATION WAGON	
Colour	Black	
Year of manufacture	2010	
Top speed	82 mph	
Gearbox	6 speed Manual	

Engine & fuel consumption

Power	121 BHP	
Max. torque	360 Nm at 2.000 rpm	
Engine capacity	2.402 cc	
Cylinders	4	
Fuel type	Diesel	
Consumption city	20.8 mpg	
Consumption extra urban	29.7 mpg	
Consumption combined	25.4 mpg	



CarCheck.co.uk page 1/15



SN60FLB report date: 2024-03-29

Internet history

Entry 1

Date 2022-07-20

Pictures 36

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/15



SN60FLB report date: 2024-03-29

MOT history

MOT expiry date	2024-08-02
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	46
Total items failed	13

CarCheck.co.uk page 3/15



report date: 2024-03-29

MOT #14	2022 00 01 07.52
MOT #14	2023-08-01 07:53

MOT test number 740216936611

Next expiry date 2024-08-02

Advice Nearside Rear Coil spring mounting corroded but not seriously weakened (5.3.1 (b) (i))

Advice Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

Advice Front axle corroded

Advice Rear Vehicle structure slightly corroded within 30cm of towbar mounting (6.1.6 (i) (i))

Advice Offside Front Coil spring corroded (5.3.1 (b) (i))

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Offside Front Seat belt slightly damaged (7.1.2 (b) (i))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice Offside Front Coil spring mounting corroded but not seriously weakened (5.3.1 (b) (i))

Advice Offside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c))

Advice Offside Rear Coil spring mounting corroded but not seriously weakened (5.3.1 (b) (i))

Advice Nearside Front Coil spring corroded (5.3.1 (b) (i))

Advice Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Nearside Front Coil spring mounting corroded but not seriously weakened (5.3.1 (b) (i))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c))

CarCheck.co.uk page 4/15



report date: 2024-03-29

MOT #13 2023-07-29 11:05

MOT test number 141029759497

Result	× Failed
Advice	Nearside Rear Coil spring mounting corroded but not seriously weakened (5.3.1 (b) (i))
Advice	Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
Advice	Rear Vehicle structure slightly corroded within 30cm of towbar mounting (6.1.6 (i) (i))
Advice	Offside Front Coil spring corroded (5.3.1 (b) (i))
Fail O	ffside Rear Vehicle structure excessively corroded within 30cm of towbar mounting (6.1.6 (i) (i))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Front Seat belt slightly damaged (7.1.2 (b) (i))
Advice	Offside Front Coil spring mounting corroded but not seriously weakened (5.3.1 (b) (i))
Advice	Offside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c))
Advice	Front axle corroded
Advice	Offside Rear Coil spring mounting corroded but not seriously weakened (5.3.1 (b) (i))
Advice	Nearside Front Coil spring corroded (5.3.1 (b) (i))
Fail N	earside Rear Vehicle structure excessively corroded within 30cm of towbar mounting (6.1.6 (i) (i))
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Nearside Front Coil spring mounting corroded but not seriously weakened (5.3.1 (b) (i))
Advice	Nearside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c))

CarCheck.co.uk page 5/15



report date: 2024-03-29

MOT #12		2022-08-03 08:29
MOT test number		902225883900
Result		✓ Passed
MOT #11		2022-08-03 08:29
MOT test number		796951349036
Result		× Failed
Pass with rectification	Nearside Front Headlamp aim too high (4.1.2 (a))	
Pass with rectification	Offside Front Headlamp aim too low (4.1.2 (a))	

MOT #10		2021-09-09 14:10
MOT test	number	526396272950
Result		✓ Passed
Advice	Brake pipe corroded, covered in grease or other material (1.1.11 (c))	
Advice	Offside Front Seat belt slightly damaged (7.1.2 (b) (i))	

MOT #9	2020-09-16 09:31
MOT test number	669400503562
Result	✓ Passed

CarCheck.co.uk page 6/15



report date: 2024-03-29

MOT #8 2020-09-10 07:43 570848224660 **MOT** test number Result × Failed Fail Front Registration plate does not conform to the specified requirements (0.1 (d)) Fail Offside Rear Brake pipe excessively corroded (1.1.11 (c)) Fail Offside Rear Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i)) Fail Steering linkage ball joint ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii)) Fail Offside Front Brake pipe excessively corroded (1.1.11 (c)) Fail Front Brake pipe excessively corroded TO REAR (1.1.11 (c))

MOT #7

MOT test number

Result

Advice

Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice

Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #6		2018-08-28 09:15
MOT test	number	323108108826
Result		✓ Passed
Advice Nearside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))		
Advice Underneath of fuel tank damp at time of test		
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))		
Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))		

CarCheck.co.uk page 7/15



(8.3.1d)

SN60FLB

report date: 2024-03-29

MOT test number

195232861223

Result

Advice
Both side facing rear seats have been removed before mot test

Offside Windscreen has damage to an area less than a 40mm circle outside zone 'A' appox 10mm

MOT test number

Result

Advice

Both side facing rear seats have been removed before mot test

Fail Offside Windscreen has damage to the swept area in excess of a 40mm circle outside zone 'A' appox 10 mm (8.3.1d)

Pass with rectification

Offside Headlamp aim too high (1.8)

Pass with rectification

Nearside Headlamp aim too high (1.8)

MOT #3

MOT test number

273151030826

Result

Advice

Offside Front Seat belt damaged but webbing not significantly weakened (5.2.2a)

 MOT #2
 2015-09-14 14:03

 MOT test number
 355711169060

 Result
 ✓ Passed

 MOT #1
 2014-09-15 14:42

 MOT test number
 618138054242

 Result
 ✓ Passed

CarCheck.co.uk page 8/15



report date: 2024-03-29





Days left 93

MOT expiry date 2 August 2024

Full MOT history See MOT history

CarCheck.co.uk page 9/15



report date: 2024-03-29

Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date
Category
Type

Damage 2

Date

Category

Type



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



SN60FLB report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 11/15



report date: 2024-03-29

Owner history

Owner mistory	
For how long did the current and previous owner(s) have this LAND ROVER? How many of ROVER have? Check it in the premium report and see all owner registrations. Download	

	More info >
Plate changes	
See in this check if this LAND ROVER had different number plates.	
Number of plates	
Current registration	IIK SIA:
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 12/15



report date: 2024-03-29

Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LAND ROVER is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >


CarCheck.co.uk page 13/15



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-10-27
Last registration	2023-08-01
Complete history	See info



Registration #1	2010-10-27	11 mi
Registration #2	2014-09-15	22.669 mi
Registration #3	2015-09-14	26.993 mi
Registration #4	2016-08-22	30.859 mi
Registration #5	2017-09-07	36.370 mi
Registration #6	2017-09-07	36.370 mi
Registration #7	2018-08-28	40.863 mi
Registration #8	2019-09-11	47.169 mi
Registration #9		11.777 mi
Registration #10		11.777 es
Registration #11		91.777 es
Registration #12		0.00 44
Registration #13		91.777 es
Registration #14		0.00 44
Registration #15		11.777 mi
Registration #16		

More info >

CarCheck.co.uk page 14/15



report date: 2024-03-29

			_		
- 11	manc	Innc	λ.	$M \cap M$	aht
וט	mens	כווטו	CX.	$vv \subset v$	ullu

Width	1790 mm
Height	2181 mm
Length	4625 mm
Wheel base	2794 mm
Kerb weight	2111 kg
Max. allowed weight	3050 kg

Additional information

Fuel tank capacity	75 l	
Fuel delivery	Direct Injection	
Number of doors	3	
Number of seats	7	
Number of axles	2	
Engine number	100930204256244DT	

CarCheck.co.uk page 15/15