





report date: 2024-03-29

General information

Make	MERCEDES
Model	SLK 350
Colour	Silver
Year of manufacture	2005
Top speed	155 mph
0 - 60 mph	5.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	268 BHP
Max. torque	350 Nm at 5.000 rpm
Engine capacity	3.498 cc
Cylinders	6
Fuel type	Petrol
Consumption city	18.2 mpg
Consumption extra urban	36.2 mpg
Consumption combined	26.7 mpg
CO2 emission	255 g/km
CO2 label	L



CarCheck.co.uk page 1/14



report date: 2024-03-29

Internet history

Entry 1

Date 2021-07-01

Pictures 20

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-29

Μ	OT	his	tory

MOT expiry date	2024-10-16
MOT pass rate	68 %
MOT passed	15
Failed MOT tests	7
Total advice items	47
Total items failed	12

MOT #22	2023-10-17 09:18
MOT test number	731072646983
Result	✓ Passed
Next expiry date	2024-10-16

MOT #21		2023-10-17 09:18
MOT test number		972147669827
Result		X Failed
Pass with rectification	Front Headlamp aim too high both sides (4.1.2 (a))	

MOT #20	2022-06-14 16:09
MOT test number	745827377189
Result	✓ Passed
Advice Eml light on	

MOT #19	2021-06-24 11:32
MOT test number	399743854961
Result	✓ Passed

CarCheck.co.uk page 3/14



report date: 2024-03-29

MOT test number

897050022654

Result

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Nearside Front foglight glass broken

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #17 2019-04-01 09:02 **MOT** test number 624124793646 Result × Failed **DANGEROUS** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii)) Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) Offside Rear Brake pipe excessively corroded (1.1.11 (c)) **MAJOR** Advice Offside Front Inner Tyre has a cut but not deep enough to reach the ply or cords sidewall (5.2.3 (d) (i)) Advice Oil leak, but not excessive (8.4.1 (a) (i)) **MAJOR** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) Nearside Front foglight glass broken Advice **MAJOR** Nearside Rear Brake pipe excessively corroded (1.1.11 (c)) **MAJOR** Central Rear Upper Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #16		2018-04-09 11:54
MOT test	number	379348784265
Result		✓ Passed
Advice	Central exhaust brackets broken due to corrosion. exhaust still supported	
Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.	3.1a)
Advice	Central brake light not working	

CarCheck.co.uk page 4/14



report date: 2024-03-29

MOT test number

499335576050

Result

Fail Offside Front coil spring broken (2.4.C.1a)

Advice Central exhaust brackets broken due to corrosion. exhaust still supported

Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

Advice Central brake light not working

MOT #14	2017-03-29 16:2	1
MOT test	number 97503410562	6
Result	✓ Passe	d
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Advice	Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Advice	Nearside Front Side repeater damaged, but still visible from a reasonable distance (1.4.A.2e)	
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Advice	Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Advice	Offside Front Torque/reaction arm has a slightly deteriorated rubber bush (2.4.G.2)	
Advice	Central Rear Exhaust brackets have rusted away	

CarCheck.co.uk page 5/14



MOT #13

Advice

Advice

Advice

Fail

LT05SVN

report date: 2024-03-29

2017-03-29 13:56

MOT test number

Result

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Fail Offside Rear Direction indicator incorrect colour (1.4.A.2f)

Advice Central Rear Exhaust brackets have rusted away

Advice Offside Front Torque/reaction arm has a slightly deteriorated rubber bush (2.4.G.2)

Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #12 2016-04-06 13:59
MOT test number 984310901142
Result Passed

Nearside Front Side repeater damaged, but still visible from a reasonable distance (1.4.A.2e)

MOT #11 2016-04-04 15:46

MOT test number 286657469829

Result × Failed

Fail Nearside Front Lower Suspension arm has excessive play in a pin/bush inner (2.4.G.2)

Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Nearside Rear Direction indicator incorrect colour (1.4.A.2f)

MOT #10 2015-06-19 13:48

MOT test number 997310375105

Result ✓ Passed

Advice Rear registration plate deteriorated but not likely to be misread (6.3.1d)

CarCheck.co.uk page 6/14



report date: 2024-03-29

MOT #9		2014-05-31 10:56
MOT test	number	185201254130
Result		✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #8		2013-05-28 11:03
MOT test	number	285998243123
Result		✓ Passed
Advice	Offside Rear Direction indicator slightly discoloured (1.4.A.2f)	
Advice	Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)	

MOT #7	2012-05-26 11:08
MOT test number	135947242124
Result	✓ Passed
MOT #6	2011-05-24 10:16
MOT test number	177224341155
Result	✓ Passed

Notice	E,S,P light on
Notice	Both front discs in very poor condition

MOT #5	2011-05-21 10:54
MOT test number	588651141115
Result	X Failed
Notice Both front discs in very poor condition	
Notice E,S,P light on	
Fail Nearside Front coil spring fractured (2.4.C.1a)	

CarCheck.co.uk page 7/14



report date: 2024-03-29

MOT #4

MOT test number

473656750151

Result

Notice Rear number plate fading

2010-06-05 12:19

473656750151

✓ Passed

MOT #3 2010-06-05 10:24 **MOT** test number 311826650152 Result **X** Failed Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1) Pass with rectification Nearside Headlamp aim too low (1.8) Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1) Fail Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1) Notice Rear number plate fading Pass with rectification Offside Headlamp aim too low (1.8)

MOT #2

MOT test number

Result

Advice

Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice

Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice

Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

 MOT #1
 2008-06-05 14:14

 MOT test number
 624847558131

 Result
 ✓ Passed

CarCheck.co.uk page 8/14



LT05SVN report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 March
Days left	305
MOT expiry date	16 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 9/14




report date: 2024-03-29

Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	



Extra MERCEDES salvage check



Category

Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-29

More info >

Owner history

*		
For how long did the current and previous owner(s) have this MERCEDES? How many ow MERCEDES have? Check it in the premium report and see all owner registrations. Downloaner.		

	More info >	
Plate changes		
See in this check if this MERCEDES had different number plates.		
Number of plates		,
Current registration	UK	
Plate since		
Current registration	UK UK	
Plate since		

CarCheck.co.uk page 11/14



report date: 2024-03-29

Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2005-03-29
Last registration	2023-10-17
Complete history	See info



2005-03-29	29 mi
2008-06-05	13.168 mi
2009-05-29	17.142 mi
2010-06-05	25.313 mi
2010-06-05	25.313 mi
2011-05-21	28.032 mi
2011-05-24	28.032 mi
2012-05-26	29.934 mi
2013-05-28	36.688 mi
2014-05-31	45.794 mi
2015-06-19	51.048 mi
2016-04-04	56.555 mi
	71.777 es
	71.777 es
	11.777 es
	71.777 es
	11.777 es
	71.777 es
	11.777 es
	11.117 au
	2008-06-05 2010-06-05 2010-06-05 2011-05-21 2011-05-24 2012-05-26 2013-05-28 2014-05-31 2015-06-19 2016-04-04

More info >



LTO5SVN report date: 2024-03-29

Dimensions & w	eig	nt
----------------	-----	----

Width	1969 mm
Height	1296 mm
Length	4089 mm
Wheel base	2430 mm
Kerb weight	1465 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	27296330034690

CarCheck.co.uk page 14/14