





## General information

Make	MERCEDES
Model	VITO 109 CDI LONG P/V
Colour	Silver
Year of manufacture	2006
Gearbox	6 speed Manual

# Engine & fuel consumption

Power	88 BHP
Max. torque	240 Nm at 1.400 rpm
Engine capacity	2.148 сс
Cylinders	4
Fuel type	Diesel






# Internet history

Entry 1	
Date	2022-02-09
Pictures	28
Listing price	<u>View report</u>









source: autotrader.co.uk



# MOT history

MOT expiry date	2023-10-22
MOT pass rate	70 %
MOT passed	14
Failed MOT tests	6
Total advice items	22
Total items failed	17

<b>MOT #20</b> 21	022-10-08 10:35
MOT test number	367019600457
Result	🗸 Passed
Next expiry date	
Advice Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c)	)

MOT #19	2022-10-08 10:35
MOT test number	806579746150
Result	× Failed
Advice Nearside Front E	brake pipe corroded, covered in grease or other material (1.1.11 (c))
Pass with rectification	Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #18	2021-10-09 10:09
MOT test number	741324100538
Result	✓ Passed

MOT #17	2020-10-19 11:45
MOT test number	778267171437
Result	✓ Passed
Advice Supplementary restraint system warning lamp does not illuminate (7.1.6 (a))	



MOT #16	2020-10-19 10:13
MOT test number	997999059237
Result	🗙 Failed
<b>Fail</b> Rear fog lamp not working (4.5.1 (a) (ii))	
<b>Fail</b> Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))	
Fail Nearside Headlamp aim projected beam image is obviou	sly incorrect (4.1.2 (c))

MOT #15		2019-04-17 11:38
MOT test	number	365321743055
Result		✓ Passed
Advice	Supplementary restraint system warning lamp does not illuminate (7.1.6 (a))	
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c)	)

MOT #14	2018-04-19 12:44
MOT test number	739491183315
Result	✓ Passed
Advice Offside Front Brake pipe slightly corroded (3.6.B.2c)	

MOT #13	2018-04-19 12:44
MOT test number	607611288681
Result	× Failed
Pass with rectification	Offside Stop lamp not working (1.2.1b)
Pass with rectification Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)	
Pass with rectification	Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
Advice Offside Front Brake pipe slightly corroded (3.6.B.2c)	





MOT #12	2017-04-13 13:18
MOT test number	467671607246
Result	✓ Passed
Advice Cut on side wall on nearside rear tyre outer	
MOT #11	2017-04-12 14:53
MOT test number	486806940232
Result	🗙 Failed
Fail Parking brake lever has no reserve travel (3.1.6b)	
Advice Cut on side wall on nearside rear tyre outer	
Fail Parking brake: efficiency below requirements (3.7.B.7)	
<b>Fail</b> Rear parking brake recording little or no effort (3.7.B.6a)	
Fail Nearside Stop lamp not working (1.2.1b)	
MOT #10	2016-04-23 08:59
MOT test number	876396542961

MOT test number	876396542961
Result	✓ Passed
Advice Brake pipe slightly corroded front to rear and o/s front (3.6.B.2c)	
Advice Travel on handbrake lever	



MOT #9		2015-03-24 11:49
MOT test	number	125433885469
Result		✓ Passed
Advice	Offside Front Anti-roll bar has slight play in a pin/bush (2.4.G.2)	
Advice	Parking brake lever has little reserve travel (3.1.6b)	
Advice	Nearside Front Anti-roll bar has slight play in a pin/bush (2.4.G.2)	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Notice	Offside RearBrake Slight Bind	

MOT #8	2015-03-11 16:52
MOT test number	758160775015
Result	🗙 Failed
<b>Fail</b> Offside Headlamp not working on dipped beam (1.7.5a)	
Fail Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Advice Offside Front Anti-roll bar has slight play in a pin/bush (2.4.G.2)	
Advice Parking brake lever has little reserve travel (3.1.6b)	
Notice Offside RearBrake Slight Bind	
Fail Rear Exhaust has a major leak of exhaust gases (7.1.2)	
Advice Nearside Front Anti-roll bar has slight play in a pin/bush (2.4.G.2)	
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #7	2014-01-08 11:21
MOT test number	908708104054
Result	✓ Passed



MOT #6		2014-01-08 11:21
MOT test number		366858004024
Result		🗙 Failed
Pass with rectification	Registration plate lamp not working (1.1.C.1d)	
Pass with rectification	Coil spring fractured (2.4.C.1a)	
Pass with rectification	Offside Headlamp aim too high (1.8)	

MOT #5	2013-01-04 09:34
MOT test number	287344103073
Result	✓ Passed

MOT #4	2012-01-09 13:01
MOT test number	587059802037
Result	✓ Passed


MOT #3	2011-01-04 16:14
MOT test number	486284601045
Result	✓ Passed

MOT #2	2010-06-03 11:01
MOT test number	291774350442
Result	✓ Passed
Advice Offside Front Track rod end ball joint has slight play (2.2.B.1f)	

MOT #1	2009-06-01 16:14
MOT test number	802232259179
Result	✓ Passed



Tax & MOT check







### Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FE CO
Category	A RINPE
Туре	
Damage 2	AMPLE
Date	4
Category	AMPLI
Туре	W SCO

### Extra MERCEDES salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





# Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And and a second s	
**********	
*********	
**********	
********	
	More info >
	More into >
Plate changes	
See in this check if this MERCEDES had different number plates.	
Number of plates	9
Exernent registration	
Plate since	
Plate since Carrent registration	
Plate since Correct registration Plate since	1115-25-27



### Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info  $\rightarrow$ 





# Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2006-06-01
Last registration	2022-10-08
Complete history	<u>See info</u>



Registration #1	2006-06-01	6 mi
Registration #2	2009-06-01	74.265 mi
Registration #3	2010-06-03	85.622 mi
Registration #4	2011-01-04	90.254 mi
Registration #5	2012-01-09	99.774 mi
Registration #6	2013-01-04	117.224 mi
Registration #7	2014-01-08	148.320 mi
Registration #8	2015-03-11	155.291 mi
Registration #9	2015-03-24	155.291 mi
Registration #10	2016-04-23	160.609 mi
Registration #11	2017-04-12	165.149 mi
Registration #12		11.777 est
Registration #13		11.777 esi
Registration #14		11.777 est
Registration #15		11.222 esi
Registration #16		11.777 est
Registration #17		11.222 est
Registration #18		11.777 est
Registration #19		11.117 esi
Registration #20		11.117 est
Registration #21		11.777 esi

More info >



# Additional informationFuel tank capacity75 lFuel deliveryDirect InjectionNumber of doors5Number of seats3Engine number64698350216006