



Mercedes-Benz

**KU05BXA**

report date: 2024-03-29

General information

Make	MERCEDES-BENZ
Model	VITO 111 CDI COMPACT P/V
Colour	White
Year of manufacture	-
Gearbox	5 speed automatic

Engine & fuel consumption

Power	109 BHP
Max. torque	290 Nm at 1.600 rpm
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-10-04
Pictures	21
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://cargurus.co.uk)

**MOT history**

<b>MOT #24</b>	2023-06-27 11:17
<b>MOT test number</b>	413356784010
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2024-06-26
<b>Advice</b>	Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
<b>Advice</b>	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
<b>Advice</b>	Rear Brake pad(s) wearing thin both osr & nsr (1.1.13 (a) (ii))
<b>Advice</b>	Oil leak, but not excessive (8.4.1 (a) (i))
<b>Advice</b>	Nearside Rear Coil spring worn (5.3.1 (b) (i))
<b>Minor</b>	Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
<b>Advice</b>	Exhaust has a minor leak of exhaust gases (6.1.2 (a))
<b>Advice</b>	Rear Brake disc worn, but not excessively Both nsr & osr (1.1.14 (a) (i))
<b>Advice</b>	Nearside Outer Tyre slightly damaged/cracking or perishing Front and Rear (5.2.3 (d) (ii))
<b>Advice</b>	Front Headlamp has a product on the lens but not seriously reducing light output Both (4.1.4 (b))
<b>Advice</b>	Front Anti-roll bar linkage ball joint has slight play Both (5.3.4 (a) (i))

<b>MOT #23</b>	2022-06-24 15:03
<b>MOT test number</b>	563823293397
<b>Result</b>	✓ Passed
<b>Minor</b>	Nearside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))

<b>MOT #22</b>	2021-07-29 14:20
<b>MOT test number</b>	617856841895
<b>Result</b>	✓ Passed
<b>Advice</b>	Front Headlamp has a product on the lens but not seriously reducing light output Both Side (4.1.4 (b))

**MOT #21**

2020-09-29 17:03

**MOT test number**

638051621257

**Result**

✓ Passed

- Advice** Brake disc worn, pitted or scored, but not seriously weakened All four (1.1.14 (a) (ii))
- Advice** Offside Rear Lower Integral body structure is corroded but structural rigidity is not significantly reduced Sill (6.1.1 (c) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Headlamp has a product on the lens but not seriously reducing light output Both (4.1.4 (b))

**MOT #20**

2020-09-29 14:57

**MOT test number**

244779108613

**Result**

✗ Failed

- Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Headlamp has a product on the lens but not seriously reducing light output Both (4.1.4 (b))
- Fail** Nearside Front Outer Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Offside Rear Lower Integral body structure is corroded but structural rigidity is not significantly reduced Sill (6.1.1 (c) (i))
- Advice** Brake disc worn, pitted or scored, but not seriously weakened All four (1.1.14 (a) (ii))
- Fail** Nearside All direction indicators not working (4.4.1 (a) (ii))
- Fail** Nearside Rear Position lamp not working (4.2.1 (a) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Fail** Offside Front Outer Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #19** 2019-06-13 13:13**MOT test number** 386878630962**Result** ✓ Passed**Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))**Minor** Nearside Headlamp lens slightly defective (4.1.1 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #18** 2018-06-08 13:27**MOT test number** 673738201331**Result** ✓ Passed**Advice** Items removed from driver's view prior to test**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #17** 2018-06-08 11:38**MOT test number** 382490084486**Result** ✗ Failed**Fail** Brake pad(s) wear indicator illuminated (1.1.13 (a) (i))**Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Fail** Front Tyre(s) of different sizes are fitted on the same axle. (5.2.3 (b))**Advice** Items removed from driver's view prior to test**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))**Fail** Offside Front Position lamp not working (4.2.1 (a))**MOT #16** 2017-03-23 14:57**MOT test number** 709506837597**Result** ✓ Passed

**MOT #15** 2017-03-22 13:53**MOT test number** 413540039142**Result** ✗ Failed**Fail** Electronic stability system warning lamp indicates a fault (3.4.1c)**Fail** Rear position lamp(s) incorrect colour n/side and o/side reversing lamps stuck on (1.1.A.3e)**Fail** Offside Rear fog lamp not working (1.3.2b)**MOT #14** 2016-03-30 09:12**MOT test number** 163271845881**Result** ✓ Passed**MOT #13** 2016-03-30 09:12**MOT test number** 198074347276**Result** ✗ Failed**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #12** 2015-09-16 13:56**MOT test number** 912800193652**Result** ✓ Passed**Advice** Rear pads worn**Advice** Ns track rod end ball joint play**MOT #11** 2014-08-07 13:47**MOT test number** 537769914230**Result** ✓ Passed**Notice** O/s/r tyre at 2mm tread depth**Notice** Front indicators faded

**MOT #10** 2014-08-07 13:47**MOT test number** 137789014251**Result** ✗ Failed**Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)**Notice** Front indicators faded**Pass with rectification** Nearside Rear Tyre(s) incorrect because different size tyres are fitted on the same axle. (4.1.A.1a)**Notice** O/s/r tyre at 2mm tread depth**MOT #9** 2013-06-06 16:11**MOT test number** 446967753111**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #8** 2013-06-06 09:13**MOT test number** 845667253109**Result** ✗ Failed**Fail** Nearside Rear Shock absorber has a serious fluid leak (2.7.3)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Front Windscreen washer provides insufficient washer liquid (8.2.3)

**MOT #7** 2013-04-29 11:21**MOT test number** 757449513179**Result** ✗ Failed**Fail** Nearside Rear Shock absorber has a serious fluid leak (2.7.3)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**MOT #6** 2012-03-06 16:05**MOT test number** 869316862067**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2012-03-06 14:30**MOT test number** 719846162099**Result** ✗ Failed**Fail** Offside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2011-03-02 10:07**MOT test number** 137371461469**Result** ✓ Passed



MOT #3	2010-02-27 12:43
MOT test number	312508850013
Result	✓ Passed
MOT #2	2009-02-06 17:25
MOT test number	382107939099
Result	✓ Passed
MOT #1	2008-02-08 11:31
MOT test number	941829338018
Result	✓ Passed



Damage history


Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How many owners did this MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES-BENZ had different number plates.

Number of plates	1
Current registration	 <b>KU05BXA</b>
Plate since	2019-05-29
Current registration	 <b>KU05BXA</b>
Plate since	2019-05-29

More info >



Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES-BENZ is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2005-03-01
Last registration	2023-06-27
Complete history	<a href="#">See info</a>



Registration #1	2005-03-01	10 mi
Registration #2	2008-02-08	61.836 mi
Registration #3	2009-02-06	73.684 mi
Registration #4	2010-02-27	87.274 mi
Registration #5	2011-03-02	97.070 mi
Registration #6	2012-03-06	107.349 mi
Registration #7	2012-03-06	107.349 mi
Registration #8	2013-04-29	110.005 mi
Registration #9	2013-06-06	110.027 mi
Registration #10	2013-06-06	110.032 mi
Registration #11	2014-08-07	120.024 mi
Registration #12	2015-09-16	127.760 mi
Registration #13	2016-03-30	129.467 mi
Registration #14	2016-03-30	129.467 mi
Registration #15	2016-03-30	129.467 mi
Registration #16	2016-03-30	129.467 mi
Registration #17	2016-03-30	129.467 mi
Registration #18	2016-03-30	129.467 mi
Registration #19	2016-03-30	129.467 mi
Registration #20	2016-03-30	129.467 mi
Registration #21	2016-03-30	129.467 mi
Registration #22	2016-03-30	129.467 mi
Registration #23	2016-03-30	129.467 mi
Registration #24	2016-03-30	129.467 mi
Registration #25	2016-03-30	129.467 mi



Car features

The MERCEDES-BENZ factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MERCEDES-BENZ factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Additional information

Fuel tank capacity	75 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	2
Engine number	64698250107897