





General information

Make	KIA
Model	SOUL CRDI SHAKER
Colour	Cream
Year of manufacture	2009
Top speed	113 mph
0 - 60 mph	11.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	126 BHP
Max. torque	260 Nm at 1.900 rpm
Engine capacity	1.582 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	61.4 mpg
Consumption combined	45.6 mpg
CO2 emission	137 g/km
CO2 label	E







Internet history

Entry 1	
Date	2021-09-07
Pictures	27
Listing price	View report







source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-03
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	41
Total items failed	14

MOT #16	2023-07-04 15:34	
MOT test number	357980359889	
Result	✓ Passed	
Next expiry date	2024-07-03	
Advice Brake pipe corroded, covered in grease or other material all (1.1.11 (c))	
Advice Offside Front Tyre worn close to legal limit/worn on edge close to cords (5.2.3 (e))		
Advice Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))		
Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))		
Advice Sub-frame corroded but not seriously weakened front, rear and suspension arms (5.3.3 (b) (i))		
Advice Front Service brake fluctuating, but not excessively (1.2.1 (e))		
Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i	i))	





MOT #15 2023-07-04 09:26
MOT test number 742239356373
Result X Failed
FailNearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords(5.2.3 (d) (i))
Advice Sub-frame corroded but not seriously weakened front, rear and suspension arms (5.3.3 (b) (i))
Fail Nearside Rear Position lamp not working (4.2.1 (a) (ii))
Fail Parking brake efficiency below requirements (1.4.2 (a) (i))
Fail Windscreen washer provides insufficient washer liquid (3.5 (a))
Advice Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))
Fail Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Advice Offside Front Tyre worn close to legal limit/worn on edge close to cords (5.2.3 (e))
Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice Brake pipe corroded, covered in grease or other material all (1.1.11 (c))
Fail Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice Front Service brake fluctuating, but not excessively (1.2.1 (e))
Fail Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))



DY09	LRA
report date:	2024-03-28

MOT #14	2022-07-01 09:39	
MOT test number	387851391641	
Result	✓ Passed	
Advice Nearside Rear Outer Tyre slightly damaged (5.2.3 (d) (ii))		
Advice Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))		
Advice Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))		
Advice Offside Front Tyre worn close to legal limit/worn on edge Edges close to cords (5.2.3 (e))		
Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))		
Advice Rear Service brake requirements only just met. It would appear that the braking system requires adjustment or repair Hand brake (1.2.1 (c))		
Advice Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))		

MOT #13	2022-06-30 13:42
MOT test number	521297609092
Result	× Failed
Fail Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))	
Advice Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	
Advice Front Brakes imbalanced requirements only just met. It would appear that the brace requires adjustment or repair. (1.2.1 (b) (i))	raking system
Advice Offside Front Tyre worn close to legal limit/worn on edge Edges close to cords (5	5.2.3 (e))
Fail Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))	
Fail Front Windscreen washer provides insufficient washer liquid (3.5 (a))	
Advice Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))	
Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2	2.3 (d) (i))
Advice Rear Service brake requirements only just met. It would appear that the braking adjustment or repair Hand brake (1.2.1 (c))	system requires
Advice Nearside Rear Outer Tyre slightly damaged (5.2.3 (d) (ii))	
Fail Offside Front Headlamp incorrect colour (4.1.4 (a))	





MOT #12		2021-05-17 11:29
MOT test	number	529416951835
Result		✓ Passed
Advice	Park brake lever had travel	
MOT #11		2020-06-01 09:04
MOT test number 716044092395		
Result		✓ Passed
Advice	Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))	
Advice Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))		
Advice Nearside Front Play in steering rack inner joint(s)		
Advice	Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))	

MOT #10	2020-06-01 09:04	
MOT test number	463539356642	
Result	× Failed	
Pass with rectification	Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))	
Advice Nearside Front Play in steering rack inner joint(s)		
Advice Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))		
Advice Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))		
Advice Offside Front Su	Advice Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))	

МОТ #9	2019-04-06 11:24
MOT test number	930849734474
Result	✓ Passed



DY09	LRA
report date:	2024-03-28

MOT #8	2019-04-04 08:58
MOT test number	334170045676
Result	🗙 Failed
Advice Nearside Front Service brake binding but not excessively (1.2.1 (f))	
Fail Offside Front Service brake excessively binding (1.2.1 (f))	
Fail Offside Front Suspension arm ball joint excessively worn complete wish bone ball	l joint (5.3.4 (a) (i))
MOT #7	2018-04-10 09:57
MOT test number	769731129810
Result	✓ Passed
MOT #6	2017-05-02 14:20
MOT test number	830215715422
Result	✓ Passed
MOT #5	2016-03-05 09:39
MOT test number	104520274827
Result	✓ Passed
MOT #4	2015-03-18 14:22
MOT test number	869567575075
Result	✓ Passed
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #3	2014-03-21 15:27
MOT test number	877930284053
Result	✓ Passed



MOT #2 MOT test number	2013-03-23 10:51 256342783006
Result	✓ Passed
Notice O/s/r tyre lowish 3mm	
MOT #1	2012-03-24 12:11
MOT test number	186894882420
Result	✓ Passed

DY09LRA

report date: 2024-03-28



Tax & MOT check

✓ Taxed Tax due: 1 September 2024	MOT Expires: 3 July 2024
Tax status	Valid until 1 September
Days left	126
MOT expiry date	3 July 2024
Full MOT history	See MOT history
Tax calculation	

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-





Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FERRE
Category	Lamp
Туре	
Damage 2	AMPLE
Date	A.F.
Category	ante.
Туре	

Extra KIA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.11.111
Auction value	4 10.000
Average private trade value	4 11 711





Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this KIA had different number plates.	
Number of plates	,
Current registration	
Plate since	
Carrent registration	
Plate since	
	More info >





Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	



DY09LRA report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-03-28
Last registration	2023-07-04
Complete history	See info



Registration #1	2009-03-28	19 mi
Registration #2	2012-03-24	29.039 mi
Registration #3	2013-03-23	36.870 mi
Registration #4	2014-03-21	43.738 mi
Registration #5	2015-03-18	51.961 mi
Registration #6	2016-03-05	59.324 mi
Registration #7	2017-05-02	66.760 mi
Registration #8	2018-04-10	71.769 mi
Registration #9	2019-04-04	76.914 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 est
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		11.777 est
Registration #17		11.777 mi
Registration #18		11.117 esi





Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	87%
Children	86%
Pedestrian	39%
Safety systems	86%
Overall rating	77%
Video	see crash video



Dimensions & weight	
Width	1785 mm
Height	1610 mm
Length	4105 mm
Wheel base	2550 mm
Kerb weight	1345 kg
Max. allowed weight	1780 kg
Additional information	
Fuel tank capacity	48
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 15/15

Number of axles	2
Engine number	D4FB8H507496