



Mercedes-Benz

KP07EBG

report date: 2024-03-29

General information

Make	MERCEDES
Model	SPRINTER 311 CDI LWB CC
Colour	White
Year of manufacture	2007
Gearbox	6 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	280 Nm at 1.600 rpm
Engine capacity	2.148 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN

**MOT history**

MOT expiry date	2021-08-16
MOT pass rate	92 %
MOT passed	12
Failed MOT tests	1
Total advice items	35
Total items failed	2

MOT #13	2020-08-17 10:43
MOT test number	987942448553
Result	✓ Passed
Next expiry date	2021-08-16

MOT #12	2019-09-27 11:34
MOT test number	399126397063
Result	✓ Passed
Advice	Offside Front Steering linkage ball joint has slight play (2.1.3 (b) (i))
Advice	Nearside Front Steering linkage ball joint has slight play (2.1.3 (b) (i))
Advice	Nearside Anti-roll bar linkage damaged but not seriously weakened (5.3.3 (b) (i))

MOT #11	2018-09-29 13:22
MOT test number	390652454781
Result	✓ Passed
Advice	Nearside Steering linkage ball joint has slight play tierod (2.1.3 (b) (i))
Minor	Offside Front Brake hose slightly damaged (1.1.12 (b) (i))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #10** 2017-11-30 19:54**MOT test number** 681908928944**Result** ✓ Passed

Advice Offside rear parking (secondary) brake imbalance requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.6b)

Advice Offside Ball joint has slight play tierod (2.2.B.1f)

Advice Diesel seepage on engine bay

MOT #9 2016-11-26 14:01**MOT test number** 266060362108**Result** ✓ Passed**MOT #8** 2016-07-29 15:52**MOT test number** 821110096398**Result** ✓ Passed

Advice Offside Ball joint has slight play tierod (2.2.B.1f)

Advice Nearside Ball joint has slight play tierod (2.2.B.1f)

Advice Front bumper insecure

MOT #7 2015-07-29 15:47**MOT test number** 839220815286**Result** ✓ Passed

Advice Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #6**

2014-07-31 15:22

MOT test number

437742414264

Result

✓ Passed

- Advice** Nearside Ball joint has slight play (2.2.B.1f)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)
- Advice** Offside Ball joint has slight play (2.2.B.1f)
- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)

MOT #5

2013-06-19 13:25

MOT test number

476590573174

Result

✓ Passed

- Notice** Nail in offside rear tyre
- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)

MOT #4

2012-05-28 17:29

MOT test number

765969042190

Result

✓ Passed

- Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)

**MOT #3**

2012-05-28 14:08

MOT test number

925299142186

Result**✗ Failed****Fail** Nearside Stop lamp not working (1.2.1b)**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Offside Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Fail** Nearside Rear Stop lamp not working (1.2.1b)**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #2**

2011-05-26 15:09

MOT test number

106996941102

Result**✓ Passed****Advice** Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)**Advice** Front Anti-roll bar linkage rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Front Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Seat belt damaged but webbing not significantly weakened (5.2.2a)**MOT #1**

2010-05-12 15:15

MOT test number

124422030141

Result**✓ Passed****Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Rear Shock absorber has a slightly worn bush (2.7.4)**Advice** Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)



Tax & MOT check

✕
Untaxed

Tax expired:
28 February 2021

✕
MOT

Expired:
16 August 2021

Tax status	Expired at 28 February 2021
Days left	1157 days too late
MOT expiry date	16 August 2021
Full MOT history	See MOT history



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	7
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2007-05-01
Last registration	2020-08-17
Complete history	See info



Registration #1	2007-05-01	22 mi
Registration #2	2010-05-12	69.775 mi
Registration #3	2011-05-26	90.240 mi
Registration #4	2012-05-28	103.956 mi
Registration #5	2012-05-28	103.958 mi
Registration #6	2013-06-19	117.516 mi
Registration #7	2014-07-31	131.427 mi
Registration #8	2015-05-20	151.277 mi
Registration #9	2016-05-20	151.277 mi
Registration #10	2017-05-20	151.277 mi
Registration #11	2018-05-20	151.277 mi
Registration #12	2019-05-20	151.277 mi
Registration #13	2020-05-20	151.277 mi
Registration #14	2020-08-17	151.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1990 mm
Height	2820 mm
Length	6940 mm
Wheel base	4325 mm
Kerb weight	2005 kg
Max. allowed weight	3500 kg

Additional information

Fuel tank capacity	75 l
Fuel delivery	Direct Injection
Number of seats	3
Number of axles	2
Engine number	64698551333054