





General information

Make	ΤΟΥΟΤΑ
Model	AURIS VVT-I ICON TOURING SPORTS
Colour	Silver
Year of manufacture	2016
Top speed	112 mph
Gearbox	1 speed CVT

Engine & fuel consumption


Power	134 BHP
Max. torque	305 Nm at 4.400 rpm
Engine capacity	1.798 cc
Cylinders	4
Fuel type	Hybrid / Electric
Consumption combined	65.3 mpg
CO2 emission	83 g/km
CO2 label	А





Internet history

Entry 1	
Date	2021-02-04
Pictures	10
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2025-02-24
MOT pass rate	63 %
MOT passed	5
Failed MOT tests	3
Total advice items	7
Total items failed	6

MOT #8	2024-02-20 17:26
MOT test number	194469350980
Result	✓ Passed
Next expiry date	2025-02-24

MOT #7	2024-02-19 13:05
MOT test number	978262509279
Result	🗙 Failed
Fail Engine MIL inoperative or indicates a malfunction Light on (8.2.1.2 (h))	
Fail Offside Rear Service brake excessively fluctuating (1.2.1 (e))	
Fail Offside Rear Service brake excessively binding (1.2.1 (f))	
Advice Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))	

МОТ #6	2023-02-24 12:31
MOT test number	862643221736
Result	✓ Passed

MOT #5	2022-02-21 12:29
MOT test number	922721385894
Result	✓ Passed
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	





MOT #4		2022-02-21 12:29
MOT test number		746737981541
Result		🗙 Failed
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Pass with rectification	Nearside Rear Direction indicator incorrect colour (4.4.3 (a))	

MOT #3	2021-02-25 08:30
MOT test	number 615820877039
Result	✓ Passed
Advice	Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
Advice	Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #2	2021-02-20 12:44	
MOT test number	330991557028	
Result	🗙 Failed	
Fail Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c	:))	
Advice Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))		
Fail Offside Stop lamp(s) not working (4.3.1 (a) (ii))		
Advice Offside Rear Shock absorbers light misting of oil or has limited damping	effect (5.3.2 (b))	

MOT #1	2019-04-18 14:59
MOT test number	726145812246
Result	✓ Passed



Tax & MOT check

	✓ Taxed		✓ МОТ
Tax due: 1 February 2025		Expires: 24 February 2025	
Tax status			Valid until 1 February
Days left			279
MOT expiry date			24 February 2025
Full MOT history			See MOT history
Tax calculation			
Vehicle class		59	

Vehicle class	59
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable





Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	4. ARANPE
Туре	
Damage 2	AMPL
Damage 2	E CUT-S
Date	*
Category	AMP
Туре	

Extra TOYOTA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 11.111
Average private trade value	4 10 200

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2016-04-21
Last registration	2024-02-20
Complete history	See info



Registration #1	2016-04-21	19 mi
Registration #2	2019-04-18	15.178 mi
Registration #3		11.177 mi
Registration #4	2021-02-20	20.229 mi
Registration #5	2021-02-25	20.229 mi
Registration #6		11.777 esi
Registration #7		11.777 esi
Registration #8		11.177 esi
Registration #9		11.777 esi
Registration #10		

More info >





Car features

S0225	Air conditioning
S0295	
S0482	
\$0501	
\$0566	
S0567	
S0569	

Safety ratings

Number of axles

NCAP rating	****
Adult	92%
Children	84%
Pedestrian	68%
Safety systems	66%
Overall rating	83%
Video	see crash video



Dimensions & weight	
Width	1760 mm
Height	1485 mm
Length	4595 mm
Wheel base	2600 mm
Kerb weight	1425 kg
Max. allowed weight	1815 kg
Additional information	
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

2