






report date: 2024-03-28

General information

Make	CITROEN
Model	NEMO 610 LX HDI
Colour	White
Year of manufacture	2010
Top speed	94 mph
0 - 60 mph	16.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	70 BHP
Max. torque	160 Nm at 1.750 rpm
Engine capacity	1.399 сс
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg



CarCheck.co.uk page 1/17



Internet history

Entry 1


Date 2021-10-22

Pictures 13

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/17



MOT history

MOT expiry date	2024-11-17
MOT pass rate	50 %
MOT passed	11
Failed MOT tests	11
Total advice items	56
Total items failed	27

MOT #22	2023-11-07 09:14
MOT test number	729709300670
Result	✓ Passed
Next expiry date	2024-11-17
Advice Tyre worn close to legal limit/worn on edge both front (5.2.3 (e))	
Advice Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #21	2023-11-06 10:36
MOT test number	416160432788
Result	X Failed
Advice Tyre worn close to legal limit/worn on edge both front (5.2.3 (e)) Fail Offside Outer Suspension component mounting prescribed area excessive reducing structural strength sill (5.3.6 (a) (i)) Advice Oil leak, but not excessive (8.4.1 (a) (i))	ely corroded significantly

MOT #20	2022-11-18 16:20
MOT test number	665764199786
Result	✓ Passed

CarCheck.co.uk page 3/17



Fail

(7.1.1 (a) (i))

YF10RXT report date: 2024-03-28

MOT #19 2022-11-18 12:13

MOT test number 887408149607

Result X Failed

Fail Offside Seat belt anchorage prescribed area strength or continuity significantly reduced outersill (7.1.1 (a) (i))

MOT #18 2022-10-26 11:15

MOT test number 334715085062

Fail

Bonnet cannot be secured in the closed position (3.1 (b) (i))

Fail

Nearside Rear Shock absorbers has an excessively worn bush (5.3.2 (c))

Fail Nearside Rear Shock absorbers has an excessively worn bush (5.3.2 (c))

Fail Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

Fail Offside Seat belt anchorage prescribed area strength or continuity significantly reduced outersill

Fail Offside Rear Shock absorbers has an excessively worn bush (5.3.2 (c))

Fail Offside Front Direction indicator not working (4.4.1 (a) (ii))

Nearside Windscreen wiper not working (3.4 (a))

CarCheck.co.uk page 4/17



YF10RXT

report date: 2024-03-28

MOT #17 2021-10-18 14:00 472855098158 **MOT** test number ✓ Passed Result **Advice** Offside Play in steering rack inner joint(s) Advice Nearside Rear Upper Shock absorbers has a slightly worn bush bush split (5.3.2 (c)) Minor Central Windscreen damaged but not adversely affecting driver's view chip (3.2 (a) (i)) **Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i)) Nearside head light unit bracket broken Advice Advice Nearside Play in steering rack inner joint(s) Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i)) Advice **Advice** Offside Rear Upper Shock absorbers has a slightly worn bush bush split (5.3.2 (c))

MOT #16		2021-10-15 11:42
MOT test	number	549091812708
Result		× Failed
Advice	Offside Play in steering rack inner joint(s)	
Advice	Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.	2.3 (d) (i))
Advice	Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))	
Advice	Nearside Play in steering rack inner joint(s)	
Advice	Offside Rear Upper Shock absorbers has a slightly worn bush bush split (5.3.2 ((c))
Minor	Central Windscreen damaged but not adversely affecting driver's view chip (3.2	(a) (i))
	iffside Front Lower Seat belt anchorage prescribed area strength or continuity sig $7.1.1\ (a)\ (i))$	nificantly reduced
Advice	Nearside Rear Upper Shock absorbers has a slightly worn bush bush split (5.3.2	2 (c))
Advice	Nearside head light unit bracket broken	

CarCheck.co.uk page 5/17



YF10RXT

report date: 2024-03-28

MOT #15 2021-09-28 11:18

MOT test number 404904049842

Result X Failed

Fail Offside Rear Upper Shock absorbers has an excessively worn bush (5.3.2 (c))

Advice Offside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice All direction indicators slightly discoloured (4.4.3 (a))

Advice Offside Front headlight bracket broken

Fail Nearside Rear Upper Shock absorbers has an excessively worn bush (5.3.2 (c))

Advice Nearside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Fail Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

MOT #14 2020-08-28 08:51

MOT test number 500272211240

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #13 2019-08-29 08:36

MOT test number 130430504802

Result ✓ Passed

Advice Oil leak, but not excessive (8.4.1 (a) (i))

CarCheck.co.uk page 6/17



MOT #12 2019-08-28 09:38

MOT test number 233618146189

Result X Failed

Fail Offside Rear Upper Shock absorbers has an excessively worn bush (5.3.2 (c))

Fail Nearside Rear Upper Shock absorbers has an excessively worn bush (5.3.2 (c))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Fail Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

MOT #11 2018-08-17 09:51

MOT test number 828596231006

Result

Passed

Advice Front Brake Pedal Worn

Advice Not A Lot Of reserve Travel Left On Handbrake

MOT #10 2018-08-17 09:51

MOT test number 706283034362

Result X Failed

Advice Front Brake Pedal Worn

(2.5.B.1b)

Pass with rectification Offside Front Position lamp not working (4.2.1 (a))

Advice Not A Lot Of reserve Travel Left On Handbrake

MOT #9 2017-08-14 08:16

MOT test number 451599226869

Result \(\sqrt{Passed} \)

Advice Nearside Front Macpherson strut has slight movement in the upper support bearing assembly

CarCheck.co.uk page 7/17



MOT #8 2017-08-11 09:55

MOT test number 473685940280

Result X Failed

Fail Nearside Front position lamp(s) not working (1.1.A.3b)

Advice Nearside Front Macpherson strut has slight movement in the upper support bearing assembly (2.5.B.1b)

Fail Offside Front Macpherson strut has excessive movement in the upper support bearing assembly (2.5.B.1b)

MOT #7 2016-08-17 10:20

MOT test number 165088877660

Advice Nearside Rear Nail in tyre

Advice Offside Seat belt stitching slightly frayed (5.2.2b)

Advice Nearside Rear Tyre worn low on outer edge

Advice Shock absorber has a slightly worn bush Both rear (2.7.4)

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

CarCheck.co.uk page 8/17



YF10RXT

report date: 2024-03-28

MOT #6 2016-08-17 10:20 **MOT** test number 722257143892 Result × Failed **Advice** Nearside Rear Tyre worn low on outer edge **Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d) Pass with rectification Nearside Registration plate lamp not working (1.1.C.1d) Pass with rectification Power steering fluid level below minimum (2.3.1) **Advice** Shock absorber has a slightly worn bush Both rear (2.7.4) Advice Offside Seat belt stitching slightly frayed (5.2.2b) Pass with rectification Nearside Stop lamp not working (1.2.1b) **Advice** Nearside Rear Nail in tyre

MOT #5

MOT test number

806424193797

Result

Advice Nearside Rear tyre nailed

Advice Nearside Front Suspension arm has slight play in a ball joint (2.4.G.2)

MOT #4 2015-08-20 14:03 **MOT** test number 742484093663 Result × Failed Fail Windscreen washer provides insufficient washer liquid (8.2.3) Fail Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g) Fail Power steering pipe(s) or hose(s) leaking (2.3.3b) Advice Nearside Rear tyre nailed Advice Nearside Front Suspension arm has slight play in a ball joint (2.4.G.2)

CarCheck.co.uk page 9/17



Result

YF10RXT
report date: 2024-03-28

X Failed

MOT #3 2014-07-25 08:34

MOT test number 677296004247

Result \(\sqrt{Passed} \)

Advice Offside Seat belt stitching slightly frayed (5.2.2b)

MOT #2 2014-07-23 12:14

MOT test number 395244604245

Fail Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)

Advice Offside Seat belt stitching slightly frayed (5.2.2b)

MOT #1 2013-07-29 11:06

MOT test number 676930913246

Result ✓ Passed

Advice Offside Front suspension has slight play in an outer ball joint (2.5.B.2a)


Advice Nearside Front suspension has slight play in an outer ball joint (2.5.B.2a)

Advice Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

CarCheck.co.uk page 10/17



Tax & MOT check



CarCheck.co.uk page 11/17



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 12/17



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 13/17



Owner history

e mier meeory	
For how long did the current and previous owner(s) have this CITROEN? How many owner have? Check it in the premium report and see all owner registrations. Download the full	
manus .	
	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	,
Current registration	NK NK
Flate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 14/17



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info


More info >

CarCheck.co.uk page 15/17



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2010-08-16
Last registration	2023-11-07
Complete history	See info



Registration #1	2010-08-16	28 mi
Registration #2	2013-07-29	74.854 mi
Registration #3	2014-07-23	100.646 mi
Registration #4	2014-07-25	100.646 mi
Registration #5	2015-08-20	117.025 mi
Registration #6	2015-08-21	117.025 mi
Registration #7	2016-08-17	128.577 mi
Registration #8	2016-08-17	128.577 mi
Registration #9	2017-08-11	140.634 mi
Registration #10	2017-08-14	140.634 mi
Registration #11	2018-08-17	149.137 mi
Registration #12	2018-08-17	149.137 mi
Registration #13		71.777 es
Registration #14		71.777 es
Registration #15		11.177 es
Registration #16		71.777 es
Registration #17		11.177 es
Registration #18		71.777 es
Registration #19		
negistration #25		11.777 es
Registration #20		10.777 es
		10,707 esc 10,707 esc 10,707 esc
Registration #20		11.777 es 11.777 es 11.777 es
Registration #20 Registration #21		10,707 est 10,707 est 10,707 est 10,707 est

More info >



Safety ratings

NCAP rating	***
Adult	59%
Children	74%
Pedestrian	55%
Safety systems	29%
Overall rating	58%
Video	see crash video



Additional information

Fuel tank capacity	45 I
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	FD982601830

CarCheck.co.uk page 17/17