



TOYOTA

V542LGS

report date: 2024-03-28

General information

Make	TOYOTA
Model	RAV-4
Colour	Red
Year of manufacture	1999
Gearbox	-

Engine & fuel consumption

Engine capacity	1.998 cc
Fuel type	Petrol



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-08-05
Pictures	23
Listing price	View report



source: cargurus.co.uk

**MOT history**

MOT expiry date	2024-10-28
MOT pass rate	75 %
MOT passed	18
Failed MOT tests	6
Total advice items	91
Total items failed	13

MOT #24 2023-10-02 08:05**MOT test number** 571621294720**Result** Passed**Next expiry date** 2024-10-28

- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Corrosion to underside of vehicle and suspension components
- Advice** Front Lower Suspension arm corroded but not seriously weakened nearside and offside (5.3.3 (b) (i))
- Advice** Corrosion to exhaust system
- Advice** Some wear and deterioration to rear tyres
- Advice** Brake pipes coated/greased restricting inspection
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #23 2022-10-03 08:49**MOT test number** 398606200109**Result** Passed

- Advice** Corrosion to underside of vehicle suspension components
- Advice** Brake pipes coated restricting inspection
- Advice** Some corrosion to exhaust system
- Advice** Front Lower Suspension arm corroded but not seriously weakened nearside and offside (5.3.3 (b) (i))

**MOT #22**

2021-10-29 11:19

MOT test number

587064210517

Result

✓ Passed

Advice Corrosion to exhaust system**Advice** Corrosion to underside of vehicle suspension/brake components consistent with age**Advice** Brake pipes coated restricting inspection in places**MOT #21**

2021-10-28 10:09

MOT test number

828622472047

Result

✗ Failed

Advice Offside Front Service brake binding but not excessively (1.2.1 (f))**Fail** Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Corrosion to exhaust system**Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))**Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))**Advice** Corrosion to underside of vehicle suspension/brake components consistent with age**Advice** Brake pipes coated restricting inspection in places**MOT #20**

2021-03-02 16:20

MOT test number

584603117957

Result

✓ Passed

Advice Offside front shock absorber damp**Advice** Underside of vehicle rusty

**MOT #19**

2021-02-24 17:02

MOT test number

507041905625

Result

✗ Failed

Advice Nearside Front Service brake binding but not excessively (1.2.1 (f))**Advice** Offside front shock absorber damp**Advice** Underside of vehicle rusty**Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Fail** Offside Front Service brake excessively binding (1.2.1 (f))**Advice** Front brake discs rusty**Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**MOT #18**

2019-10-15 15:10

MOT test number

515994362536

Result

✓ Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Brake hose slightly deteriorated both front (1.1.12 (b) (ii))**Advice** Tyre slightly damaged/cracking or perishing both front (5.2.3 (d) (ii))**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))**MOT #17**

2018-09-17 14:20

MOT test number

169758899028

Result

✓ Passed

Advice Both front tyres perished

**MOT #16**

2017-09-01 12:54

MOT test number

108719355030

Result

✓ Passed

- Advice** Both outer bolt on sills corroded
- Advice** Front brakes binding slightly
- Advice** Front brake discs corroded
- Advice** Both front tyre treads split and perished

MOT #15

2016-09-26 11:25

MOT test number

481798083105

Result

✓ Passed

- Advice** O/s/f shock damp
- Advice** O/s side step corroded under plastic
- Advice** N/s/r tyre perished

MOT #14

2016-09-23 13:12

MOT test number

716337095399

Result

✗ Failed

- Advice** O/s side step corroded under plastic
- Advice** N/s/r tyre perished
- Fail** Nearside Headlamp aim too high (1.8)
- Advice** O/s/f shock damp
- Fail** Offside Headlamp aim too high (1.8)

**MOT #13**

2015-09-23 10:10

MOT test number

274381943201

Result

✓ Passed

Advice Offside headlamp condensated and beam image poor**Advice** Nearside rear and both front tyres perished**Advice** Corrosion to both inner rear wheel arch areas**Advice** Imbalance between rear brakes**Advice** Various underbody components corroded**Advice** Offside front shock absorber damp**MOT #12**

2014-10-28 10:25

MOT test number

615821904356

Result

✓ Passed

Notice Various underbody components corroded**Notice** Corrosion to rear inner wheel arch areas**Notice** Offside front shock absorber damp**Notice** Both front and nearside rear tyres perished

**MOT #11**

2014-10-28 10:25

MOT test number

197121204317

Result**✗ Failed****Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Notice** Offside front shock absorber damp**Notice** Both front and nearside rear tyres perished**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Notice** Various underbody components corroded**Notice** Corrosion to rear inner wheel arch areas**MOT #10**

2013-10-17 11:55

MOT test number

399840393200

Result**✓ Passed****Notice** Corrosion to offside rear and nearside rear inner wheel arches**Notice** Front suspension lower arms corroded**Notice** Rear tyres perished**Notice** Vehicle underside covered in old engine oil**Notice** Running board frames corroded

**MOT #9**

2012-11-15 16:19

MOT test number

717610322333

Result

✓ Passed

- Notice** Rear of vehicle underside damp
- Notice** Corrosion to offside rear and nearside rear inner wheel arches
- Notice** Uneven rise and fall between rear brakes close to limit - advise investigation
- Notice** Nearside headlamp aim on lower limit
- Notice** Various front suspension components corroded
- Notice** Offside front and both rear shock absorbers damp
- Notice** Windscreen damaged
- Notice** Rear wiper split
- Notice** Front brake hoses have corroded ferules

MOT #8

2011-10-10 12:30

MOT test number

387973381296

Result

✓ Passed

- Notice** Rear wiper split
- Notice** Front brake hoses have rusty ferules
- Notice** Corrosion to both rear inner wheel arches
- Notice** Front suspension lower arms corroded
- Notice** Offside front and both rear shock absorbers damp
- Notice** Offside rear tyre perished and worn on inner edge

**MOT #7** 2011-10-10 12:30**MOT test number** 219883081282**Result** ✗ Failed**Notice** Front suspension lower arms corroded**Notice** Offside front and both rear shock absorbers damp**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Notice** Offside rear tyre perished and worn on inner edge**Notice** Rear wiper split**Notice** Front brake hoses have rusty ferules**Notice** Corrosion to both rear inner wheel arches**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #6** 2010-10-06 11:11**MOT test number** 572929270263**Result** ✓ Passed**Notice** Offside rear tyre perished and worn on inner edge**Notice** Wipers poor**Notice** Offside front brake caliper damap - no leak found**Notice** Offside front additional main beam light inoperative**MOT #5** 2009-10-14 14:00**MOT test number** 353337889267**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #4** 2009-10-05 11:12**MOT test number** 711008179286**Result** ✗ Failed**Fail** Offside Rear Registration plate lamp not working (1.1.5c)**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Nearside Front Headlamp excessively damaged so that the light output is severely reduced (1.7.5a)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2008-09-30 09:06**MOT test number** 670044078228**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2007-10-08 16:10**MOT test number** 611061787296**Result** ✓ Passed**MOT #1** 2006-10-06 17:09**MOT test number** 152479076245**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
28 October 2024

Tax status		Valid until 1 October
Days left		155
MOT expiry date		28 October 2024
Full MOT history		See MOT history



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	V542LGS
Plate since	2019-09-29
Current registration	V542LGS
Plate since	2019-09-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	1999-10-05
Last registration	2023-10-02
Complete history	See info



Registration #1	1999-10-05	7 mi
Registration #2	2006-10-06	47.993 mi
Registration #3	2007-10-08	53.621 mi
Registration #4	2008-09-30	59.547 mi
Registration #5	2009-10-05	67.373 mi
Registration #6	2009-10-14	67.374 mi
Registration #7	2010-10-06	67.724 mi
Registration #8	2011-10-10	68.102 mi
Registration #9	2012-11-15	68.346 mi
Registration #10	2013-10-17	68.953 mi
Registration #11	2014-10-28	69.451 mi
Registration #12	2015-09-23	69.869 mi
Registration #13	2016-09-23	70.277 mi
Registration #14	2017-09-23	70.685 mi
Registration #15	2018-09-23	71.093 mi
Registration #16	2019-09-23	71.501 mi
Registration #17	2020-09-23	71.909 mi
Registration #18	2021-09-23	72.317 mi
Registration #19	2022-09-23	72.725 mi
Registration #20	2023-09-23	73.133 mi
Registration #21	2023-10-02	73.541 mi
Registration #22		
Registration #23		
Registration #24		

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

★★★★★

Video

[see crash video](#)



Additional information

Engine number	NOT KNOWN
---------------	-----------